

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Structural Stability Report",
    "value": "Structural_Stability_Report"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Dinesh",
    "type": "CREDITOFFICER",
    "_id": "661790eb834794131c1f0f1b",
    "lastName": "SSL",
    "mobileNo": "",
    "workMobileNo": "9082173552",
    "email": "dinesh.pal@saurab.org"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Dinesh",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```

"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc575ece84bf289ba9e82d",
  "role": "SITEENGINEER",
  "firstName": "Deepak ",
  "email": "daksh7831@gmail.com",
  "lastName": "Jain ",
  "mobileNo": "9022815908",
  "designation": "",
  "shortName": "DJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyan_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",

```

```

    "mobileNo": "9529385821",
    "designation": "",
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ]
    },
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        }
      }
    ],
    "_id": "6084131a13f01f158c6ea1f4",

```

```
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.173887078912415",
  "longitude": "72.8800737089428"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8800737089428,
    19.173887078912415
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "4/12/2024 12:00 am"
    },
    {
      "dateTime": "4/12/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Malad",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Mumbai ",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kaveri Nagari Nivara Chsl",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Nagari nivara parishad ",
  "label": false
},
"street2": {
```

```
"status": true,
"name": "Street 2",
"key": "street2",
"value": "Gen. A.K Vaidya Marg dindoshi ",
"label": false
},
"landmark": {
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
"status": true,
"name": "Wing",
"key": "wing",
"value": "B",
"label": true
},
"projectName": {
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
"status": false,
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
"status": true,
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "827/91",
"label": true
},
"hissaNo": {
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",

```



```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "15",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400065",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon(East)",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  },
  "auto": {
```

```
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
}
```

```
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```



```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": true,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
```

```
"paymentIds": [],
"_id": "67502d5abefd7f3db9042ddf",
"ownerName": "Nikita Sadanand Patil And MIR. Sadanand Patil",
"ownerPhoneNo": "9892840127",
"appAddress": "Flat no. 15, 3rd Floor, Wing - B, Kaveri Nagari Nivara CHS Goregaon
East ",
"remark": "Structural Report ",
"documents": [],
"gstNo": "",
"caseNumber": "012796",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "491110",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Dec 04 2024 10:22:18 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Nikita Sadanand Patil And MIR. Sadanand Patil",
    "phone": "9892840127",
    "ownershipShare": "",
    "email": "",
    "id": "897024"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902b5a5477d50e7dcf35f",
    "name": "externalImg_1735983797007_externalImg_1733287140879_IMG_202412
03_101300.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externalImg_1735983797007_externalI
mg_1733287140879_IMG_20241203_101300.jpg",
    "orientation": "portrait"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902b5a5477d50e7dcf360",
    "name": "externallmg_1735983797055_externallmg_1733287140887_IMG_20241203_221415.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_1735983797055_externallmg_1733287140887_IMG_20241203_221415.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902b5a5477d50e7dcf361",
    "name": "externallmg_1735983797061_externallmg_1733287140910_IMG_20241203_221424__01.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_1735983797061_externallmg_1733287140910_IMG_20241203_221424__01.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902b5a5477d50e7dcf362",
    "name": "externallmg_r_1735983797088_externallmg_r_1733287156858_TimePhoto_20241203_095744.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797088_externallmg_r_1733287156858_TimePhoto_20241203_095744.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902b5a5477d50e7dcf363",
    "name": "externallmg_r_1735983797098_externallmg_r_1733287156865_TimePhoto_20241203_095747.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797098_externallmg_r_1733287156865_TimePhoto_20241203_095747.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902b5a5477d50e7dcf364",
    "name": "externallmg_r_1735983797124_externallmg_r_1733287156870_TimePhoto_20241203_095747.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797124_externallmg_r_1733287156870_TimePhoto_20241203_095747.jpg",
    "orientation": "landscape"
  }
}
```

```
o_20241203_100216.jpg",
  "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797124_external
lmg_r_1733287156870_TimePhoto_20241203_100216.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677902b5a5477d50e7dcf365",
  "name": "externallmg_r_1735983797150_externallmg_r_1733287156911_TimePhot
o_20241203_100224.jpg",
  "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797150_external
lmg_r_1733287156911_TimePhoto_20241203_100224.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677902b5a5477d50e7dcf366",
  "name": "externallmg_r_1735983797192_externallmg_r_1733287156995_TimePhot
o_20241203_100239.jpg",
  "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797192_external
lmg_r_1733287156995_TimePhoto_20241203_100239.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677902b5a5477d50e7dcf367",
  "name": "externallmg_r_1735983797224_externallmg_r_1733287157011_TimePhot
o_20241203_100245.jpg",
  "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797224_external
lmg_r_1733287157011_TimePhoto_20241203_100245.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677902b5a5477d50e7dcf368",
  "name": "externallmg_r_1735983797163_externallmg_r_1733287156942_TimePhot
o_20241203_100227.jpg",
  "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797163_external
lmg_r_1733287156942_TimePhoto_20241203_100227.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902b5a5477d50e7dcf369",
    "name": "externallmg_r_1735983797228_externallmg_r_1733287157015_TimePhoto_20241203_100248.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983797228_externallmg_r_1733287157015_TimePhoto_20241203_100248.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf386",
    "name": "externallmg_1735983809487_Picture2.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_1735983809487_Picture2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf387",
    "name": "externallmg_1735983809511_Picture3.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_1735983809511_Picture3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf388",
    "name": "externallmg_r_1735983809294_externallmg_r_1733287157077_TimePhoto_20241203_100305.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983809294_externallmg_r_1733287157077_TimePhoto_20241203_100305.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf389",
    "name": "externallmg_r_1735983809299_externallmg_r_1733287157106_TimePhoto_20241203_101338.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983809299_externallmg_r_1733287157106_TimePhoto_20241203_101338.jpg",
    "orientation": "portrait"
  }
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf38a",
    "name": "externallmg_r_1735983809329_externallmg_r_1733287157157_TimePhoto_20241203_101437.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983809329_externallmg_r_1733287157157_TimePhoto_20241203_101437.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf38b",
    "name": "externallmg_r_1735983809303_externallmg_r_1733287157127_TimePhoto_20241203_101435.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983809303_externallmg_r_1733287157127_TimePhoto_20241203_101435.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf38c",
    "name": "externallmg_r_1735983809335_externallmg_r_1733287157182_TimePhoto_20241203_101438.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983809335_externallmg_r_1733287157182_TimePhoto_20241203_101438.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf38d",
    "name": "externallmg_r_1735983809430_externallmg_r_1733287157226_TimePhoto_20241203_101503.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983809430_externallmg_r_1733287157226_TimePhoto_20241203_101503.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677902c1a5477d50e7dcf38e",
    "name": "externallmg_r_1735983809470_externallmg_r_1733287157230_TimePhoto_20241203_101503.jpg",
    "path": "cases/67502d5abefd7f3db9042ddf/externallmg_r_1735983809470_externallmg_r_1733287157230_TimePhoto_20241203_101503.jpg",
    "orientation": "portrait"
  }
}
```

```
o_20241203_101530.jpg",
  "path": "cases/67502d5abefd7f3db9042ddf/externalImg_r_1735983809470_external
  Img_r_1733287157230_TimePhoto_20241203_101530.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677902c1a5477d50e7dcf38f",
  "name": "externalImg_r_1735983809391_externalImg_r_1733287157186_TimePhot
  o_20241203_101456.jpg",
  "path": "cases/67502d5abefd7f3db9042ddf/externalImg_r_1735983809391_external
  Img_r_1733287157186_TimePhoto_20241203_101456.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-04T10:22:18.188Z",
"updatedAt": "2025-01-04T09:43:29.890Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Structural Report No. 15, 3rd Floor, Wing - B, Kaveri Nagari
  Nivara Chsl, New/Current Survey No. 827/91, Nagari nivara parishad , Gen. A.K Vaidya
  Marg dindoshi , Village - Malad, Goregaon(East), Taluka - Borivali , Mumbai , 400065,
  State - Maharashtra, India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Nikita Sadanand Patil And MIR. Sadanand Patil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9892840127"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			