

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8ec"
    },
    "firstName": "Mahesh",
    "type": "CREDITOFFICER",
    "_id": "666c240724f3ba1343e44bea",
    "email": "bmmums0625@centralbank.co.in",
    "lastName": "Soni",
    "mobileNo": "",
    "workMobileNo": "9152012800"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Mahesh",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8ec",
  "branchCode": "280625 ",
  "type": "BRANCH",
  "name": "Opera House Branch",
  "email": "bmmumn0625@centralbank.co.in",
  "mobileNo": "022-23860466 ",
  "alternateMobileNo": "23810476",
  "address": "Bhasker Mansion, 1st Floor, Above Narottam Bhau Jewellers, 437, Dr.
Dada Saheb Bhadkamkar Marg, Opera House, Mumbai - 400 004, State -
Maharashtra, Country - India.\r\n",
  "ledgerName": "CENTRAL BANK OF INDIA - OPERA HOUSE",
  "fax": "022-23823099",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "665ac13f42f4717ae30de3d5",
  "role": "PICKUPPERSON",
  "firstName": "NIDHI",
  "email": "nidhi.kajwe97@gmail.com",
  "lastName": "KAJWE",
  "mobileNo": "8850520881",
  "shortName": "NIDHI",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": ""
}
```

```

    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        },
        {
          "title": {
            "value": "FIIV",
            "label": "FIIV"
          },
          "_id": "60af80072ffdf65bcd658652",
          "number": "CAT-I-F-1763"
        }
      ],
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      }
    }
  ],

```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.118972",
  "longitude": "72.993778"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.993778,
    19.118972
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "13/12/2024 12:00 am"
    },
    {
      "dateTime": "13/12/2024 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [
  {
```

```
    "status": "COMPLETED",
    "dateTime": "2024-12-13T19:00:30.463Z",
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": [],
  "remark": null,
  "rateMin": "25000",
  "lumpsumValue": "1",
  "rateMax": "30000",
  "areaType": {
    "Name": "Carpet",
    "Value": "Carpet",
    "name": "Carpet",
    "value": "Carpet"
  }
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "902",
  "rate": "24459",
  "yearOfConstruction": "2018",
  "compositionOfBuilding": "Ground + Stilt + 2 Podium + 1st to 33rd Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Ghansoli",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
}
```

```
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "6",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "GeeCee Cloud 36 Co-op Hsg Society Ltd",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "11",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "C",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "801",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400701",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
  "windows": {
    "label": "Powder Coated Aluminium Sliding",
    "value": "PowderCoatedAluminiumSliding"
  },
  "fittings": {
    "label": "Concealed Plumbing with Conduit & Concealed Electrical wiring",
    "value": "Concealed_Plumbing_with_Conduit_&_Concealed_Electrical_wiring"
  },
  "finishing": {
    "label": "Normal",
    "value": "Normal"
  }
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
```

```
"value": "MiddleClass"
},
"populationGroupList": {
  "label": "Urban",
  "value": "Urban"
},
"townplanApprovedByList": {
  "label": "CIDCO",
  "value": "CIDCO"
},
"asPerActualAgreement": {
  "north": "aa wing of cloud 36",
  "west": "ng grand plaza chsl / cloud 36 road",
  "south": "vinayak ews chsl",
  "east": "patil road / garden area "
},
"asPerDocumentAgreement": {
  "north": "",
  "west": "",
  "south": "",
  "east": ""
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
```

```
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Ordinary",
    "value": "Ordinary"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "CIDCO",
    "value": "CIDCO"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
}
```

```
"carParking": {
  "label": "Silt+Podium Car Parking",
  "value": "Silt+Podium_Car_Parking"
},
"constructionWorkStatus": {
  "label": "Completed",
  "value": "Completed"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2018",
  "fullDate": "1/1/2018"
},
"propertyTypeList": {
  "label": "Residential",
  "value": "Residential"
},
"planningArea": {
  "label": "Residential",
  "value": "Residential"
},
"typeOfStructure": {
  "label": "R.C.C. Framed Structure",
  "value": "R.C.C._Framed_Structure"
},
"qualityOfConstruction": {
  "label": "Normal",
  "value": "Normal"
},
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"maintenanceOfTheBuilding": {
  "label": "Normal",
  "value": "Normal"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
}
```

```
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "54",
"ageOfBuilding": "6",
"noOfBasement": "0",
"noOfPodium": "02",
"noOfAmenityFloors": "0",
"noOfFloors": "033",
"flatFloorNo": "",
"noOfLifts": "03",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "04"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```



```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "675bd46cbc26c2bda04f21e2",
"ownerName": "Mr. Sandeep Kumar Kejariwal And Mrs. Anju S Kejariwal",
"ownerPhoneNo": "9594204444",
"appAddress": "Flat No 801 8th Floor Wing-C Gee Cee Cloud 36 Plot No 6 Sector 11
Ghansoli Navi Mumbai Thane- 400701",
"remark": "Sanjay Parchani & Vanita Sanjay Parchani ",
```

```
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/675bd46cbc26c2bda04f21e2/document_1734070707667_1734070428548_AGREEMENT_DATED_16TH_JUL_2018.pdf",
    "fileName": "document_1734070707667_1734070428548_AGREEMENT_DATED_16TH_JUL_2018.pdf",
    "id": "309161",
    "uploadedBy": "665ac13f42f4717ae30de3d5",
    "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/675bd46cbc26c2bda04f21e2/document_1734070975886_1734070972363_DRAFT_AGREEMENT.pdf",
    "fileName": "document_1734070975886_1734070972363_DRAFT_AGREEMENT.pdf",
    "id": "430398",
    "uploadedBy": "665ac13f42f4717ae30de3d5",
    "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Lease Deed",
      "value": "60ae1247aa6d152c1801b2eb"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/675bd46cbc26c2bda04f21e2/document_1734071154638_1734070991963_LEASE_DEED_DATED_5TH_FEB_2020.pdf",
    "fileName": "document_1734071154638_1734070991963_LEASE_DEED_DATED_5TH_FEB_2020.pdf",
    "id": "959220",
    "uploadedBy": "665ac13f42f4717ae30de3d5",
    "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
  },
]
```

```
{
  "documentType": {
    "label": "RERA Certificate",
    "value": "60ae129faa6d152c1801b47d"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/675bd46cbc26c2bda04f21e2/
document_1734071284273_1734071281540_RERA_CERTIFICATE.pdf",
  "fileName":
"document_1734071284273_1734071281540_RERA_CERTIFICATE.pdf",
  "id": "712913",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/675bd46cbc26c2bda04f21e2/
document_1734071305191_1734071302466_OC_COPY.pdf",
  "fileName": "document_1734071305191_1734071302466_OC_COPY.pdf",
  "id": "339809",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Commencement certificate",
    "value": "61cda434c20e5901ce8d3b27"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/675bd46cbc26c2bda04f21e2/
document_1734071325821_1734071323079_CC_COPY.pdf",
  "fileName": "document_1734071325821_1734071323079_CC_COPY.pdf",
  "id": "905097",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Property Tax Bill",
```

```
    "value": "60ae126aaa6d152c1801b38b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/675bd46cbc26c2bda04f21e2/
document_1734071349031_1734071346434_PROPERTY_TAX_BILL.pdf",
  "fileName":
"document_1734071349031_1734071346434_PROPERTY_TAX_BILL.pdf",
  "id": "496010",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Share Certificate ",
    "value": "60ae1264aa6d152c1801b371"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/675bd46cbc26c2bda04f21e2/
document_1734071365576_1734071362928_SHARE_CERTIFICATE.pdf",
  "fileName":
"document_1734071365576_1734071362928_SHARE_CERTIFICATE.pdf",
  "id": "439896",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Maintenance Bill",
    "value": "60ae125eaa6d152c1801b353"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/675bd46cbc26c2bda04f21e2/
document_1734071388402_1734071385612_MAINTENANCE_BILL.pdf",
  "fileName":
"document_1734071388402_1734071385612_MAINTENANCE_BILL.pdf",
  "id": "745275",
  "uploadedBy": "665ac13f42f4717ae30de3d5",
  "createdAt": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Floor Plan",
    "value": "60ae124eaa6d152c1801b30a"
```



```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/675bd46cbc26c2bda04f21e2/
document_1738148393311_174276.pdf",
    "fileName": "document_1738148393311_174276.pdf",
    "id": "479901",
    "uploadedBy": "665ac13f42f4717ae30de3d5",
    "createdAt": "Wed Jan 29 2025 10:59:53 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013053",
"createdBy": "665ac13f42f4717ae30de3d5",
"caseHistory": [
  {
    "id": "740571",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Dec 13 2024 06:30:04 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sandeep Kumar Kejariwal And Mrs. Anju S Kejariwal",
    "phone": "9594204444",
    "ownershipShare": "",
    "email": "",
    "id": "239839"
  }
],
"proposePurchasers": [],
"siteInspection": [
  {
    "areaType": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "providedBy": {
      "label": "Owner",
      "value": "Owner"
    },
    "_id": "675c7c6bbc26c2bda04f8f56",
    "area": "905",
    "providedByName": "Mr. Sandeep Kumar Kejariwal And Mrs. Anju S Kejariwal",
    "providedByContactNo": "9594204444"
  }
]
```

```
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "811201",
    "name": "Living Room",
    "length": "1.00",
    "length1": "1",
    "length2": "00",
    "width": "1.00",
    "width1": "1",
    "width2": "00",
    "totalArea": "1.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "1.00"
  }
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f92",
    "name": "externalImg_1734116350090_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalImg_1734116350090_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f93",
    "name": "externalImg_1734116350398_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalImg_1734116350398_image.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f94",
    "name": "externallmg_1734116350637_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116350637_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f95",
    "name": "externallmg_1734116351527_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116351527_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f96",
    "name": "externallmg_1734116351569_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116351569_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f97",
    "name": "externallmg_1734116351752_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116351752_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f98",
    "name": "externallmg_1734116352592_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116352592_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "675c8438bc26c2bda04f8f99",
  "name": "externalimg_1734116352652_image.jpeg",
  "path": "cases/675bd46cbc26c2bda04f21e2/
externalimg_1734116352652_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675c8438bc26c2bda04f8f9a",
  "name": "externalimg_1734116352857_image.jpeg",
  "path": "cases/675bd46cbc26c2bda04f21e2/
externalimg_1734116352857_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675c8438bc26c2bda04f8f9b",
  "name": "externalimg_1734116353323_image.jpeg",
  "path": "cases/675bd46cbc26c2bda04f21e2/
externalimg_1734116353323_image.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675c8438bc26c2bda04f8f9c",
  "name": "externalimg_1734116354173_image.jpeg",
  "path": "cases/675bd46cbc26c2bda04f21e2/
externalimg_1734116354173_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675c8438bc26c2bda04f8f9d",
  "name": "externalimg_1734116354373_image.jpeg",
  "path": "cases/675bd46cbc26c2bda04f21e2/
externalimg_1734116354373_image.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "675c8438bc26c2bda04f8f9e",
    "name": "externallmg_1734116354516_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116354516_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8f9f",
    "name": "externallmg_1734116355417_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116355417_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8fa0",
    "name": "externallmg_1734116355781_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116355781_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8fa1",
    "name": "externallmg_1734116355893_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116355893_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8fa2",
    "name": "externallmg_1734116356117_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1734116356117_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8fa3",
```

```
    "name": "externalImg_1734116356438_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalImg_1734116356438_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8fa4",
    "name": "externalImg_1734116356580_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalImg_1734116356580_image.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675c8438bc26c2bda04f8fa5",
    "name": "externalImg_1734116356758_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalImg_1734116356758_image.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b515849234c16a2215c2b",
    "name":
"externalImg_1738232152070_WhatsApp_Image_20250130_at_124034.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalImg_1738232152070_WhatsApp_Image_20250130_at_124034.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679b515849234c16a2215c2c",
    "name":
"externalImg_1738232152075_WhatsApp_Image_20250130_at_124035_1.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalImg_1738232152075_WhatsApp_Image_20250130_at_124035_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "679b515849234c16a2215c2d",
    "name":
"externallmg_1738232152094_WhatsApp_Image_20250130_at_124035.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externallmg_1738232152094_WhatsApp_Image_20250130_at_124035.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "Sandeep Kumar Kejariwal.doc",
    "filename": "1738232130886_Sandeep_Kumar_Kejariwal.doc",
    "path": "cases/675bd46cbc26c2bda04f21e2/
externalDocuments/1738232130886_Sandeep_Kumar_Kejariwal.doc",
    "size": "7706624",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Thu Jan 30 2025 10:15:31 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"processingDocuments": [
  {
    "originalname": "ACC.pdf",
    "filename": "1738148718560_ACC.pdf",
    "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148718560_ACC.pdf",
    "size": "848987",
    "createdAt": "Wed Jan 29 2025 11:05:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "AGR.pdf",
    "filename": "1738148718579_AGR.pdf",
    "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148718579_AGR.pdf",
    "size": "17805073",
    "createdAt": "Wed Jan 29 2025 11:05:20 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1734116350090_image.jpeg",
    "filename": "1738148718953_externallmg_1734116350090_image.jpeg",
    "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148718953_externallmg_1734116350090_image.jpeg",
```

```
"size": "225259",
"createdAt": "Wed Jan 29 2025 11:05:20 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "externallmg_1734116350398_image.jpeg",
"filename": "1738148719008_externallmg_1734116350398_image.jpeg",
"path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148719008_externallmg_1734116350398_image.jpeg",
"size": "201380",
"createdAt": "Wed Jan 29 2025 11:05:20 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "externallmg_1734116350637_image.jpeg",
"filename": "1738148720495_externallmg_1734116350637_image.jpeg",
"path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148720495_externallmg_1734116350637_image.jpeg",
"size": "414389",
"createdAt": "Wed Jan 29 2025 11:05:20 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "externallmg_1734116351527_image.jpeg",
"filename": "1738148720513_externallmg_1734116351527_image.jpeg",
"path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148720513_externallmg_1734116351527_image.jpeg",
"size": "71198",
"createdAt": "Wed Jan 29 2025 11:05:20 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "MB.pdf",
"filename": "1738148732229_MB.pdf",
"path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148732229_MB.pdf",
"size": "197094",
"createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "MOU.pdf",
"filename": "1738148732236_MOU.pdf",
"path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148732236_MOU.pdf",
"size": "332592",
```



```
"createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "OC.pdf",
  "filename": "1738148732243_OC.pdf",
  "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148732243_OC.pdf",
  "size": "234006",
  "createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "PLAN.pdf",
  "filename": "1738148732291_PLAN.pdf",
  "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148732291_PLAN.pdf",
  "size": "267980",
  "createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "PLOT LEASE DEED.pdf",
  "filename": "1738148732300_PLOT_LEASE_DEED.pdf",
  "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148732300_PLOT_LEASE_DEED.pdf",
  "size": "7975695",
  "createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "PT.pdf",
  "filename": "1738148732465_PT.pdf",
  "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148732465_PT.pdf",
  "size": "404234",
  "createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "RERA.pdf",
  "filename": "1738148732543_RERA.pdf",
  "path": "cases/675bd46cbc26c2bda04f21e2/
processingDocuments/1738148732543_RERA.pdf",
  "size": "249719",
  "createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Sanjay Parchani - CBI Opera Sign & Stamp.pdf",
  "filename": "1738148733184_Sanjay_Parchani__CBI_Opera_Sign__Stamp.pdf",
  "path": "cases/675bd46cbc26c2bda04f21e2/processingDocuments/1738148733184_Sanjay_Parchani__CBI_Opera_Sign__Stamp.pdf",
  "size": "1250463",
  "createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "SHARE.pdf",
  "filename": "1738148733202_SHARE.pdf",
  "path": "cases/675bd46cbc26c2bda04f21e2/processingDocuments/1738148733202_SHARE.pdf",
  "size": "362228",
  "createdAt": "Wed Jan 29 2025 11:05:33 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=sandeep.xlsx",
  "filename": "1738148739898_Summary_Newsandeep.xlsx",
  "path": "cases/675bd46cbc26c2bda04f21e2/processingDocuments/1738148739898_Summary_Newsandeep.xlsx",
  "size": "2289335",
  "createdAt": "Wed Jan 29 2025 11:05:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "WhatsApp Image 2025-01-29 at 15.05.46.jpeg",
  "filename": "1738148739934_WhatsApp_Image_20250129_at_150546.jpeg",
  "path": "cases/675bd46cbc26c2bda04f21e2/processingDocuments/1738148739934_WhatsApp_Image_20250129_at_150546.jpeg",
  "size": "178482",
  "createdAt": "Wed Jan 29 2025 11:05:40 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
    }
  }
]
```

```
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyam_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "675d1d9874fe66bd67c4c7aa",
  "note": "require aproved plan",
  "taskId": "675bd751bc26c2bda04f25cb",
  "createdAt": "2024-12-14T05:54:32.141Z"
}
],
"createdAt": "2024-12-13T06:30:04.600Z",
"updatedAt": "2025-01-30T10:15:52.225Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 801, 8th Floor, Wing - C, GeeCee Cloud 36 Co-op
Hsg Society Ltd, Plot No. 6, Sector 11, Village - Ghansoli, 400701, State - Maharashtra,
India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "665ac13f42f4717ae30de3d5",
"contactPersonName": "Mr. Sandeep Kumar Kejariwal And Mrs. Anju S Kejariwal",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9594204444",
"briefDescOfProperty": "Living Room",
"carpetTotal": "1",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0",
"siteVisitDate": "2024-12-13"
}
```

Name	Length	Width	Total
Composition :			
Living Room	1'00"	1'00"	1.00
Other Composition :			