

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ad7dca191f7b344b003ede"
    },
    "firstName": "Shashank ",
    "type": "CREDITOFFICER",
    "_id": "65c33048b0ec7f2151fdb8bc",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7905284698",
    "email": "shashank.kumar@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9876462",
    "discussWithPerson": "Shashank ",
    "expectedFees": 4938.231,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ad7dca191f7b344b003ede",
  "name": "UBI-GOREGAON (EAST)",
  "branchCode": "",
  "mobileNo": "\"022-26863400 022-26862835\"",
  "alternateMobileNo": "",
  "email": "goregaon@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "172/73, Shree Sadan, Shantaben Estate, Goregoan (East), Mumbai -
400 063."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65dee3f79a876858ab30487f",
    "role": "SITEENGINEER",
    "firstName": "Saiprasad",
    "email": "saiprasadpatil1010@gmail.com",
    "lastName": "Patil",
    "mobileNo": "8830049996",
    "designation": "Valuation Engineer",
    "shortName": "SSP",
    "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
    "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
```

```
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.148514582657228",
```

```
"longitude": "72.84518295446192"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84518295446192,
    19.148514582657228
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "27/12/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bandivali",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Key Tech Park",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off. S. V. Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Oshiwara",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "280/B-Part",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "1102",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400102",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Jogeshwari (West)",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```



```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "676e7cca058c4f32fb6d3046",
"ownerName": "Mr. Sanjog Tiwari",
"ownerPhoneNo": "9893102468",
"appAddress": "Unit no 1102 floor 11th A-wing Key Tech Park Off S V Road Oshiwara
Jogeshwari West Mumbai 400102",
"remark": "visit time customer se Documents Leneko bole hey Bank manager sir ",
"documents": [
  {
    "documentType": {
      "label": "Search Report",
      "value": "60ae125daa6d152c1801b352"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/676e7cca058c4f32fb6d3046/
document_1735294142793_1735294140452_Sanjog_Tiwari1102.pdf",
    "fileName": "document_1735294142793_1735294140452_Sanjog_Tiwari1102.pdf",
    "id": "489593",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Dec 27 2024 10:09:13 GMT+0000 (Coordinated Universal Time)"
  }
],
```

```
"caseNumber": "013360",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "885379",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Dec 27 2024 10:09:14 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Sanjog Tiwari",
    "phone": "9893102468",
    "ownershipShare": "",
    "email": "",
    "id": "166960"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79ca",
    "name": "externalImg_1735620577251_IMG20241231WA0025.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/externalImg_1735620577251_IMG20241231WA0025.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79cb",
    "name": "externalImg_1735620577257_IMG20241231WA0026.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/externalImg_1735620577257_IMG20241231WA0026.jpg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677377e295b033db3f4d79cc",
  "name": "externallmg_1735620577264_IMG20241231WA0027.jpg",
  "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577264_IMG20241231WA0027.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677377e295b033db3f4d79cd",
  "name": "externallmg_1735620577291_IMG20241231WA0028.jpg",
  "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577291_IMG20241231WA0028.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677377e295b033db3f4d79ce",
  "name": "externallmg_1735620577296_IMG20241231WA0029.jpg",
  "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577296_IMG20241231WA0029.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677377e295b033db3f4d79cf",
  "name": "externallmg_1735620577346_IMG20241231WA0030.jpg",
  "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577346_IMG20241231WA0030.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677377e295b033db3f4d79d0",
  "name": "externallmg_1735620577375_IMG20241231WA0031.jpg",
  "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577375_IMG20241231WA0031.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d1",
    "name": "externallmg_1735620577386_IMG20241231WA0032.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577386_IMG20241231WA0032.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d2",
    "name": "externallmg_1735620577403_IMG20241231WA0033.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577403_IMG20241231WA0033.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d3",
    "name": "externallmg_1735620577406_IMG20241231WA0034.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577406_IMG20241231WA0034.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d4",
    "name": "externallmg_1735620577424_IMG20241231WA0035.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577424_IMG20241231WA0035.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d5",
    "name": "externallmg_1735620577519_IMG20241231WA0036.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620577519_IMG20241231WA0036.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "677377e295b033db3f4d79d6",
    "name": "externalimg_1735620577522_IMG20241231WA0037.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620577522_IMG20241231WA0037.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d7",
    "name": "externalimg_1735620577544_IMG20241231WA0038.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620577544_IMG20241231WA0038.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d8",
    "name": "externalimg_1735620577550_IMG20241231WA0039.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620577550_IMG20241231WA0039.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377e295b033db3f4d79d9",
    "name": "externalimg_1735620577584_IMG20241231WA0040.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620577584_IMG20241231WA0040.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fca",
    "name": "externalimg_1735620586479_IMG20241231WA0041.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620586479_IMG20241231WA0041.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "677377ea96317adb45173fcb",
    "name": "externalimg_1735620586505_IMG20241231WA0042.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620586505_IMG20241231WA0042.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fcc",
    "name": "externalimg_1735620586524_IMG20241231WA0043.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620586524_IMG20241231WA0043.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fcd",
    "name": "externalimg_1735620586528_IMG20241231WA0044.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620586528_IMG20241231WA0044.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fce",
    "name": "externalimg_1735620586552_IMG20241231WA0045.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620586552_IMG20241231WA0045.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fcf",
    "name": "externalimg_1735620586566_IMG20241231WA0046.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalimg_1735620586566_IMG20241231WA0046.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd0",
```

```
    "name": "externalImg_1735620586570_IMG20241231WA0047.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalImg_1735620586570_IMG20241231WA0047.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd1",
    "name": "externalImg_1735620586592_IMG20241231WA0048.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalImg_1735620586592_IMG20241231WA0048.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd2",
    "name": "externalImg_1735620586595_IMG20241231WA0049.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalImg_1735620586595_IMG20241231WA0049.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd3",
    "name": "externalImg_1735620586614_IMG20241231WA0050.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalImg_1735620586614_IMG20241231WA0050.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd4",
    "name": "externalImg_1735620586618_IMG20241231WA0051.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/
externalImg_1735620586618_IMG20241231WA0051.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd5",
    "name": "externalImg_1735620586638_IMG20241231WA0052.jpg",
```

```
    "path": "cases/676e7cca058c4f32fb6d3046/
externallmg_1735620586638_IMG20241231WA0052.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd6",
    "name": "externallmg_1735620586651_WhatsApp_Image_20241230_at_174141_d
2ab7aa6.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/externallmg_1735620586651_WhatsAp
p_Image_20241230_at_174141_d2ab7aa6.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd7",
    "name": "externallmg_1735620586659_WhatsApp_Image_20241230_at_174206_8
2de62e7.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/externallmg_1735620586659_WhatsAp
p_Image_20241230_at_174206_82de62e7.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677377ea96317adb45173fd8",
    "name": "externallmg_1735620586689_WhatsApp_Image_20241230_at_174245_3
766e902.jpg",
    "path": "cases/676e7cca058c4f32fb6d3046/externallmg_1735620586689_WhatsAp
p_Image_20241230_at_174245_3766e902.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-12-27T10:09:14.037Z",
"updatedAt": "2024-12-31T04:49:46.862Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```



```
},
"fullAddress": "Industrial Unit No. 1102, 11th Floor, Wing - A, Key Tech Park, CTS No.
280/B-Part, Off. S. V. Road, Oshiwara, Village - Bandivali, Jogeshwari (West), Taluka -
Andheri, Mumbai, 400102, State - Maharashtra, India",
"updatedBy": "65dee3f79a876858ab30487f",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Sanjog Tiwari",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reId": "",
"siteVisitContactNo": "9893102468"
```

}	Name	Length	Width	Total
Composition :				
Other Composition :				