

```
{
  "typeOfReport": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Manish",
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "20000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "AM161706-3",
        "label": "Chartered Engineer"
      },
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.106561386258093",
  "longitude": "72.84318367183313"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-06",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Navpada",
  }
}
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vile Parle (West), Mumbai – 400 056",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "50",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shanti Sadan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dadabhai Road ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shanti Sadan",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "TPS Vile Parle No. VI (1st Variation) (Final)",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
```

```
"monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "CASE",
"paymentStatus": "RECEIVED",
"invoiceIds": [],
"paymentIds": [
  "67654a6efe1fd12ff21499a7"
],
"_id": "6780ac70fd83f582c7532b3a",
"ownerName": "M/s. Shree Hans Realtors LLP ",
"ownerPhoneNo": "9820343346",
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. 11th Floor, Shanti
Sadan, Shanti Sadan, Plot No. 50, Dadabhai Road , Village - Navpada, Municipality
Ward No. TPS Vile Parle No. VI (1st Variation) (Final), Vile Parle (West), Mumbai – 400
056, State - Maharashtra, India",
"remark": "2nd LIE Report",
"documents": [
  {
    "documentType": {
      "value": "641d4da529e5586db05ed8e8",
      "label": "CA Certificate"
    },
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
    "fileName": "document_1736486087045_CERTIFICATE_JAN_2025.pdf",
    "path": "cases/6780ac70fd83f582c7532b3a/
document_1736486087045_CERTIFICATE_JAN_2025.pdf",
    "id": "784779",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Fri Jan 10 2025 05:15:23 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1736486108982_Car_Policy_0000000041978034.PDF",
    "path": "cases/6780ac70fd83f582c7532b3a/
document_1736486108982_Car_Policy_0000000041978034.PDF",
    "id": "118686",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Fri Jan 10 2025 05:15:23 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1736486120873_Sanction_Letter.pdf",
    "path": "cases/6780ac70fd83f582c7532b3a/
document_1736486120873_Sanction_Letter.pdf",
    "id": "636460",
    "uploadedBy": "60f91822f3dd69653a5922e3",
    "createdAt": "Fri Jan 10 2025 05:15:23 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "013591",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "607762",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Sat Dec 07 2024 07:04:13 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "M/s. Shree Hans Realtors LLP ",
"phone": "9820343346",
"ownershipShare": "",
"email": "",
"id": "658001"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6780ad43fd83f582c7532c4b",
"name": "externallmg_1736486198219_IMG_20250107_103128.jpg",
"path": "cases/6780ac70fd83f582c7532b3a/
externallmg_1736486198219_IMG_20250107_103128.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6780ad43fd83f582c7532c4c",
"name": "externallmg_1736486201345_IMG_20250107_103259.jpg",
"path": "cases/6780ac70fd83f582c7532b3a/
externallmg_1736486201345_IMG_20250107_103259.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6780ad43fd83f582c7532c4d",
"name": "externallmg_1736486201700_IMG_20250107_103321.jpg",
"path": "cases/6780ac70fd83f582c7532b3a/
externallmg_1736486201700_IMG_20250107_103321.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c4e",
  "name": "externallmg_r_1736486194016_IMG_20250107_102927.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486194016_IMG_20250107_102927.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c4f",
  "name": "externallmg_r_1736486193392_IMG_20250107_102925.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486193392_IMG_20250107_102925.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c50",
  "name": "externallmg_r_1736486192789_IMG_20250107_102919.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486192789_IMG_20250107_102919.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c51",
  "name": "externallmg_r_1736486192167_IMG_20250107_102918.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486192167_IMG_20250107_102918.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c52",
  "name": "externallmg_r_1736486194538_IMG_20250107_103025.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486194538_IMG_20250107_103025.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6780ad43fd83f582c7532c53",
    "name": "externallmg_r_1736486196035_IMG_20250107_103033.jpg",
    "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486196035_IMG_20250107_103033.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6780ad43fd83f582c7532c54",
    "name": "externallmg_r_1736486195300_IMG_20250107_103026.jpg",
    "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486195300_IMG_20250107_103026.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6780ad43fd83f582c7532c55",
    "name": "externallmg_r_1736486196495_IMG_20250107_103035.jpg",
    "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486196495_IMG_20250107_103035.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6780ad43fd83f582c7532c56",
    "name": "externallmg_r_1736486197083_IMG_20250107_103101.jpg",
    "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486197083_IMG_20250107_103101.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6780ad43fd83f582c7532c57",
    "name": "externallmg_r_1736486198123_IMG_20250107_103106.jpg",
    "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486198123_IMG_20250107_103106.jpg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c58",
  "name": "externallmg_r_1736486197314_IMG_20250107_103102.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486197314_IMG_20250107_103102.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c59",
  "name": "externallmg_r_1736486198602_IMG_20250107_103155.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486198602_IMG_20250107_103155.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c5a",
  "name": "externallmg_r_1736486199537_IMG_20250107_103201.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486199537_IMG_20250107_103201.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c5b",
  "name": "externallmg_r_1736486199192_IMG_20250107_103156.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486199192_IMG_20250107_103156.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6780ad43fd83f582c7532c5c",
  "name": "externallmg_r_1736486200055_IMG_20250107_103202.jpg",
  "path": "cases/6780ac70fd83f582c7532b3a/
externallmg_r_1736486200055_IMG_20250107_103202.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6780ad43fd83f582c7532c5d",
    "name": "externalImg_r_1736486200426_IMG_20250107_103214.jpg",
    "path": "cases/6780ac70fd83f582c7532b3a/
externalImg_r_1736486200426_IMG_20250107_103214.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6780ad43fd83f582c7532c5e",
    "name": "externalImg_r_1736486200940_IMG_20250107_103214__01.jpg",
    "path": "cases/6780ac70fd83f582c7532b3a/
externalImg_r_1736486200940_IMG_20250107_103214__01.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [
  {
    "originalname": "1st LIE Report Shanti Sadan.docx",
    "filename": "1733555177331_1st_LIE_Report_Shanti_Sadan.docx",
    "path": "cases/6780ac70fd83f582c7532b3a/
externalDocuments/1733555177331_1st_LIE_Report_Shanti_Sadan.docx",
    "size": "3040293",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Sat Dec 07 2024 07:06:17 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "1st LIE Report Shanti Sadan.docx",
    "filename": "1733555254968_1st_LIE_Report_Shanti_Sadan.docx",
    "path": "cases/6780ac70fd83f582c7532b3a/
externalDocuments/1733555254968_1st_LIE_Report_Shanti_Sadan.docx",
    "size": "3040093",
    "documentType": {
      "value": "64058cdf10de22571d01b37",
      "label": "Final Word Report"
    },
    "createdAt": "Sat Dec 07 2024 07:07:35 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {

```



```
"originalname": "1st_LIE_Report_Shanti_Sadan.pdf",
"filename": "1733563416606_1st_LIE_Report_Shanti_Sadan.pdf",
"path": "cases/6780ac70fd83f582c7532b3a/
externalDocuments/1733563416606_1st_LIE_Report_Shanti_Sadan.pdf",
"size": "2307851",
"documentType": {
  "value": "640ece6024088f0f94ee4ea8",
  "label": "Final PDF Report"
},
"createdAt": "Sat Dec 07 2024 09:23:36 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f9589345132d6a6bddcc3a"
},
{
  "originalname": "Valuation_Report_1st_LIE_Report_Shanti_Sadan.pdf",
  "filename":
"1733723975289_Valuation_Report_1st_LIE_Report_Shanti_Sadan.pdf",
  "path": "cases/6780ac70fd83f582c7532b3a/externalDocuments/1733723975289_Val
uation_Report_1st_LIE_Report_Shanti_Sadan.pdf",
  "size": "2496488",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Mon Dec 09 2024 05:59:35 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f9589345132d6a6bddcc3a"
},
{
  "path": "../CDN/cases/6780ac70fd83f582c7532b3a/
externalDocuments/1733808280494_381417.pdf",
  "filename": "1733808280494_381417.pdf",
  "documentType": {
    "organization": {
      "status": true,
      "isdelete": false,
      "_id": "5f2bdee67813470eb443deb4",
      "name": "Vastukala Consultants India Pvt. Ltd.",
      "gstNo": "18AABCT3518Q1ZZ",
      "panNo": "ABCDE1234A",
      "email": "vastukalamumbai@vastukala.com",
      "phone": "9819670183",
      "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E),
Mumbai - 400 093",
      "shortName": "VCIPL",
      "type": "ORGANIZATION",
      "city": "Mumbai",
      "ownerEmail": "umang@vastukala.org",
```

```
    "ownerName": "Umang Patel"
  },
  "_id": "60ae124daa6d152c1801b307",
  "document": {
    "documentType": "Office Copy",
    "documentDate": true,
    "to": false,
    "from": false,
    "amount": false,
    "nameOfApprovingAuthority": false,
    "number": false,
    "remarks": true,
    "caseStatus": {
      "value": "DELIVERED",
      "label": "Delivered"
    }
  },
  "createdAt": "2021-05-26T09:18:05.809Z",
  "updatedAt": "2023-06-20T10:17:50.158Z",
  "__v": 0,
  "label": "Office Copy",
  "value": "60ae124daa6d152c1801b307",
  "Name": "Office Copy",
  "Value": "60ae124daa6d152c1801b307",
  "caseStatus": {
    "value": "DELIVERED",
    "label": "Delivered"
  }
},
"createdAt": "Tue Dec 10 2024 05:24:40 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60b7177d2ffdf65bcd65882a"
}
],
"processingDocuments": [
  {
    "originalname": "1st LIE Report Shanti Sadan.xlsx",
    "filename": "1733555113436_1st_LIE_Report_Shanti_Sadan.xlsx",
    "path": "cases/6780ac70fd83f582c7532b3a/processingDocuments/1733555113436_1st_LIE_Report_Shanti_Sadan.xlsx",
    "size": "165570",
    "createdAt": "Sat Dec 07 2024 07:05:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "2447707_FurtherCC_signed.pdf",
    "filename": "1733555113447_2447707_FurtherCC_signed.pdf",
```

```
    "path": "cases/6780ac70fd83f582c7532b3a/
processingDocuments/1733555113447_2447707_FurtherCC_signed.pdf",
    "size": "164108",
    "createdAt": "Sat Dec 07 2024 07:05:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Exp. 01-04-23 to 30-11-24.pdf",
    "filename": "1733555113474_Exp_010423_to_301124.pdf",
    "path": "cases/6780ac70fd83f582c7532b3a/
processingDocuments/1733555113474_Exp_010423_to_301124.pdf",
    "size": "250116",
    "createdAt": "Sat Dec 07 2024 07:05:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Purchase Bill Peri. of 01-04-23 to 30-11-24.xlsx",
    "filename": "1733555113495_Purchase_Bill_Period_of_010423_to_301124.xlsx",
    "path": "cases/6780ac70fd83f582c7532b3a/processingDocuments/1733555113495_
Purchase_Bill_Period_of_010423_to_301124.xlsx",
    "size": "36311",
    "createdAt": "Sat Dec 07 2024 07:05:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-10T05:13:21.166Z",
"updatedAt": "2025-01-10T05:16:51.604Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "M/s. Shree Hans Realtors LLP ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9820343346",
"reportGeneratedDate": "Sat Dec 07 2024 07:06:39 GMT+0000 (Coordinated
Universal Time)",
```

"siteVisitDate": "2024-12-06",
"refCaseId": "6753f36dbefd7f3db906c86b"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
