

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a6b55cc325d356190e0942"
    },
    "firstName": "Umesh",
    "type": "CREDITOFFICER",
    "_id": "64a6b55cc325d356190e0944",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a6b55cc325d356190e0942",
  "name": "Satpur Branch",
  "branchCode": "",
  "mobileNo": "7020235315",
  "alternateMobileNo": "",
  "email": "umesh.pagar@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1 st Floor, BSNL CTTC Building, Plot No. 45-47, D-Road, MIDC, Satpur,
Nashik - 422 007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
```

```
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62724142afd7d55eddede405",
  "role": "FRONTDESK",
  "firstName": "Sanjay",
  "email": "sanjayrphadol@gmail.com",
  "lastName": "Phadol",
  "mobileNo": "9890380564",
  "designation": "",
  "shortName": "SP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62724142afd7d55eddede405/
profilePhoto_1689235732454_image.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.975528",
  "longitude": "73.792806"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "17/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Wadala ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "1 to 4",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Wadala Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near JMCT Engineering College, Khode Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "113/ 1A/ 2, to 6/ 113/ 1B/ 1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 422 006",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "678a373a290edae64f1958cc",
"ownerName": "M/s. Haidersaheb Sadruddin Khot",
"ownerPhoneNo": "8928577792",
"fullAddress": "Residential APF No. Basement Floor, Near JMCT Engineering College,
Khode Nagar, Plot No. 1 to 4, New/Current Survey No. 113/ 1A/ 2, to 6/ 113/ 1B/ 1,
Wadala Road, Village - Wadala , Taluka - Nashik, District - Nashik, Nashik, PIN Code -
422 006, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1737111228378_Archiect.pdf",
    "path": "cases/678a373a290edae64f1958cc/
document_1737111228378_Archiect.pdf",
    "id": "402813",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Fri Jan 17 2025 10:55:54 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
  },
}
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1737111248409_Building_Plan_Approval_01.pdf",
"path": "cases/678a373a290edae64f1958cc/
document_1737111248409_Building_Plan_Approval_01.pdf",
"id": "245744",
"uploadedBy": "647ed1960ab64c23c9fcf71d",
"createdAt": "Fri Jan 17 2025 10:55:54 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1737111259516_TITLEReports.pdf",
  "path": "cases/678a373a290edae64f1958cc/
document_1737111259516_TITLEReports.pdf",
  "id": "648237",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Fri Jan 17 2025 10:55:54 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1737111271472_Declaration_Form.pdf",
  "path": "cases/678a373a290edae64f1958cc/
document_1737111271472_Declaration_Form.pdf",
  "id": "897227",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Fri Jan 17 2025 10:55:54 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1737111288212_Engineer_Certificate.pdf",
  "path": "cases/678a373a290edae64f1958cc/
document_1737111288212_Engineer_Certificate.pdf",
```

```
    "id": "186611",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Fri Jan 17 2025 10:55:54 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013737",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "383203",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jan 17 2025 10:55:54 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "M/s. Haidersaheb Sadruddin Khot",
    "phone": "8928577792",
    "ownershipShare": "",
    "email": "",
    "id": "562058"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37b1290edae64f195b1c",
    "name":
"externallmg_1737111470508_WhatsApp_Image_20250115_at_115312_5.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111470508_WhatsApp_Image_20250115_at_115312_5.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a37b1290edae64f195b1d",
      "name":
"externallmg_1737111470743_WhatsApp_Image_20250115_at_115312_6.jpeg",
      "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111470743_WhatsApp_Image_20250115_at_115312_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a37b1290edae64f195b1e",
      "name":
"externallmg_1737111471021_WhatsApp_Image_20250115_at_115312_7.jpeg",
      "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111471021_WhatsApp_Image_20250115_at_115312_7.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a37b1290edae64f195b1f",
      "name":
"externallmg_1737111471318_WhatsApp_Image_20250115_at_115312_8.jpeg",
      "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111471318_WhatsApp_Image_20250115_at_115312_8.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a37b1290edae64f195b20",
      "name":
"externallmg_1737111471606_WhatsApp_Image_20250115_at_115312_9.jpeg",
      "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111471606_WhatsApp_Image_20250115_at_115312_9.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "678a37b1290edae64f195b21",
      "name":
"externallmg_1737111471972_WhatsApp_Image_20250115_at_115312_10.jpeg",
```

```
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111471972_WhatsApp_Image_20250115_at_115312_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37b1290edae64f195b22",
    "name":
"externallmg_1737111472417_WhatsApp_Image_20250115_at_115312_11.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111472417_WhatsApp_Image_20250115_at_115312_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37b1290edae64f195b23",
    "name":
"externallmg_1737111472726_WhatsApp_Image_20250115_at_115312.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111472726_WhatsApp_Image_20250115_at_115312.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37b1290edae64f195b24",
    "name":
"externallmg_1737111472917_WhatsApp_Image_20250115_at_115313_1.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111472917_WhatsApp_Image_20250115_at_115313_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37b1290edae64f195b25",
    "name":
"externallmg_1737111473257_WhatsApp_Image_20250115_at_115313.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111473257_WhatsApp_Image_20250115_at_115313.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "678a37d6290edae64f195b97",
  "name":
"externallmg_1737111505000_WhatsApp_Image_20250115_at_115310_1.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111505000_WhatsApp_Image_20250115_at_115310_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195b98",
  "name":
"externallmg_1737111505247_WhatsApp_Image_20250115_at_115310_2.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111505247_WhatsApp_Image_20250115_at_115310_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195b99",
  "name":
"externallmg_1737111505480_WhatsApp_Image_20250115_at_115310.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111505480_WhatsApp_Image_20250115_at_115310.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195b9a",
  "name":
"externallmg_1737111505778_WhatsApp_Image_20250115_at_115311_1.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111505778_WhatsApp_Image_20250115_at_115311_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195b9b",
  "name":
"externallmg_1737111506115_WhatsApp_Image_20250115_at_115311_2.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111506115_WhatsApp_Image_20250115_at_115311_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37d6290edae64f195b9c",
    "name":
"externallmg_1737111506409_WhatsApp_Image_20250115_at_115311_3.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111506409_WhatsApp_Image_20250115_at_115311_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37d6290edae64f195b9d",
    "name":
"externallmg_1737111506687_WhatsApp_Image_20250115_at_115311_4.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111506687_WhatsApp_Image_20250115_at_115311_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37d6290edae64f195b9e",
    "name":
"externallmg_1737111506958_WhatsApp_Image_20250115_at_115311_5.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111506958_WhatsApp_Image_20250115_at_115311_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37d6290edae64f195b9f",
    "name":
"externallmg_1737111507191_WhatsApp_Image_20250115_at_115311_6.jpeg",
    "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111507191_WhatsApp_Image_20250115_at_115311_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678a37d6290edae64f195ba0",
```



```
    "name":
"externallmg_1737111507501_WhatsApp_Image_20250115_at_115311_7.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111507501_WhatsApp_Image_20250115_at_115311_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba1",
  "name":
"externallmg_1737111507771_WhatsApp_Image_20250115_at_115311_8.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111507771_WhatsApp_Image_20250115_at_115311_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba2",
  "name":
"externallmg_1737111508076_WhatsApp_Image_20250115_at_115311_9.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111508076_WhatsApp_Image_20250115_at_115311_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba3",
  "name":
"externallmg_1737111508340_WhatsApp_Image_20250115_at_115311_10.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111508340_WhatsApp_Image_20250115_at_115311_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba4",
  "name":
"externallmg_1737111508547_WhatsApp_Image_20250115_at_115311.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111508547_WhatsApp_Image_20250115_at_115311.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba5",
  "name":
"externallmg_1737111508791_WhatsApp_Image_20250115_at_115312_1.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111508791_WhatsApp_Image_20250115_at_115312_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba6",
  "name":
"externallmg_1737111509000_WhatsApp_Image_20250115_at_115312_2.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111509000_WhatsApp_Image_20250115_at_115312_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba7",
  "name":
"externallmg_1737111509281_WhatsApp_Image_20250115_at_115312_3.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111509281_WhatsApp_Image_20250115_at_115312_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678a37d6290edae64f195ba8",
  "name":
"externallmg_1737111509475_WhatsApp_Image_20250115_at_115312_4.jpeg",
  "path": "cases/678a373a290edae64f1958cc/
externallmg_1737111509475_WhatsApp_Image_20250115_at_115312_4.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```

"createdAt": "2025-01-17T10:55:54.305Z",
"updatedAt": "2025-01-17T10:58:30.132Z",
"__v": 0,
"updatedBy": "647ed1960ab64c23c9fcf71d",
"addressForMap": "",
"caseReferredBy": "647ed1960ab64c23c9fcf71d",
"contactPersonName": "M/s. Haidersaheb Sadruddin Khot",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"rerald": "",
"siteVisitContactNo": "8928577792"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			