

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb35"
    },
    "firstName": "Indrajeet",
    "type": "CREDITOFFICER",
    "_id": "67039e89c691adb224f6f3dc",
    "email": "rbc.navimumbai@bankofindia.co.in",
    "lastName": "Yadav",
    "mobileNo": "0225300012",
    "workMobileNo": "9471119304"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb35",
  "branchCode": "000079",
  "type": "BRANCH",
  "name": "Retail Business center Thane ",
  "email": "rbc.navimumbai@bankofindia.co.in",
  "mobileNo": "02225331942",
  "alternateMobileNo": "02225333408",
  "address": "Bank Of India BUilding 2nd floor Shivajipath opp M H High School
Thane (WEst) 400601",
  "ledgerName": "",
  "fax": null,
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82",
  "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.203015483721252",
  "longitude": "73.13076623312114"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-27",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
```

```
    "dateTime": "2025-01-27",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-01-26",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-01-27",
    "remark": "MANUAL_IN_TASK"
  },
  {
    "status": "COMPLETED",
    "dateTime": "2025-01-26",
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  }
}
```

```
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Adivali Dhokali",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
```

```
"key": "taluka",
"value": "Ambernath",
"label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "The Vaidiki Signature",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
}
```



```
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "45/9/A",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "45/9/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
```

```
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1105",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
```

```
"status": false,
"name": "Gut No.",
"key": "GUTNo",
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 306",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_RCC_SLab",
    "label": "Proposed RCC SLab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Concealed_wiring",
    "label": "Proposed Concealed plumbing with C.P. fittings. Concealed wiring"
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
```

```
},
"general": {
  "ownership": {
    "value": "sole_ownership",
    "label": "sole ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
    "label": "Kalyan Dombivali Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Internal Road",
    "west": "Internal Road",
    "south": "Samarth Palace",
    "east": "Internal Road"
  },
  "asPerDocumentAgreement": {
    "north": "Varsha Building, Survey Number 45 Hissa Number 8",
    "west": "Survey Number 45 Hissa Number 9/2 & 9/4",
    "south": "Samrath Palace Building, Survey Number 45 Hissa Number 9/5",
    "east": "24 mtr. KDMC DP Road & Survey Number 36, Hissa Number 4"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    },
    "asPerDocument": {
      "north": "Details not available",
      "east": "Details not available",
      "south": "Details not available",
      "west": "Details not available"
    }
  }
}
```

```
    },
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "extraDetailOfProperty": "As per Approved Plan / Site information, the Composition of Flat will be 1 Bedroom + Living Room + Kitchen + 2 Toilets (i.e., 1BHK).",
  "dateOfIssusApprovePlan": "Copy of Approved Building Plan No.KDMC / TPD / BP / 27 Village / 2021 - 2022 / 26 / 58 Dated 04.07.2024 issued by Kalyan Dombivli Municipal Corporation (As Download from RERA Site)",
  "approvePlanVerified": "Yes",
  "empanelledOfApprovePlan": "No",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
```

```
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"monthlyRent": "N.A.",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction"
},
"marketability": {
"marketabilityList": {
"value": "Good",
"label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
"roof": {
"value": "Proposed_R.C.C._Slab",
"label": "Proposed R.C.C. Slab"
},
"partitions": {
"value": "Proposed_6\"_Thk._Brick_Masonry",
"label": "Proposed 6\" Thk. Brick Masonery"
},
"waterTank": {
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
}
```

```
},
"carParking": "Proposed Stilt / Open Parking",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2027",
  "fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Proposed_Standard",
  "label": "Proposed Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
```

```
"label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "As_per_RERA_Certificate",
  "label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
```



```
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "18",
"flatFloorNo": "11",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
  "area": "464.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/67976d0e4090f0a5b214d4b1/
routeMap_1738130172969_Image.png",
    "routeLat": "19.202141",
    "routeLng": "73.129701",
    "stationName": "Kalyan",
    "routeDistance": "4.1 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "sibmw",
    "name": "sibmw",
    "image": "cases/67976d0e4090f0a5b214d4b1/
routeMap_1738129312620_Image.png"
  }
]
```

```
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "0.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "0.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "InProgress",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "464.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "6798c79b49234c16a220147c",
      "name":
"externalImg_1738065819475_WhatsApp_Image_20250128_at_53119_PM.jpeg",
      "path": "cases/67976d0e4090f0a5b214d4b1/
externalImg_1738065819475_WhatsApp_Image_20250128_at_53119_PM.jpeg",
      "orientation": "landscape"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "6798c79b49234c16a2201474",
    "name":
"externallmg_1738065818852_WhatsApp_Image_20250128_at_53116_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065818852_WhatsApp_Image_20250128_at_53116_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a2201476",
    "name":
"externallmg_1738065819259_WhatsApp_Image_20250128_at_53117_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819259_WhatsApp_Image_20250128_at_53117_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a2201477",
    "name":
"externallmg_1738065819290_WhatsApp_Image_20250128_at_53117_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819290_WhatsApp_Image_20250128_at_53117_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a220147c",
    "name":
"externallmg_1738065819475_WhatsApp_Image_20250128_at_53119_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819475_WhatsApp_Image_20250128_at_53119_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a2201475",
    "name":
"externallmg_1738065819231_WhatsApp_Image_20250128_at_53116_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819231_WhatsApp_Image_20250128_at_53116_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a220147b",
    "name":
"externallmg_1738065819444_WhatsApp_Image_20250128_at_53119_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819444_WhatsApp_Image_20250128_at_53119_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a220147d",
    "name":
"externallmg_1738065819519_WhatsApp_Image_20250128_at_53120_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819519_WhatsApp_Image_20250128_at_53120_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a220147f",
    "name":
"externallmg_1738065819575_WhatsApp_Image_20250128_at_53121_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819575_WhatsApp_Image_20250128_at_53121_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6798c79b49234c16a2201480",
    "name":
"externallmg_1738065819602_WhatsApp_Image_20250128_at_53121_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819602_WhatsApp_Image_20250128_at_53121_PM.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "422.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67976d0e4090f0a5b214d4b1",
"ownerName": "Mr. Hitesh Prakash Tandalekar",
"ownerPhoneNo": "8149860266",
```

"fullAddress": "Residential Flat No. 1105, 11th Floor, Wing - C, The Vaidiki Signature, Village - Adivali Dhokali, Taluka - Ambernath, District - Thane, Kalyan (East), PIN Code - 421 306, State - Maharashtra, India",

"remark": "",

"documents": [

{

"documentType": {

"value": "60ae1256aa6d152c1801b330",

"label": "Draft Agreement for sale"

},

"inputs": {

"from": {

"value": "Promoter",

"label": "Promoter"

},

"Promoter": "M/s. Shree Jarimari Developers LLP",

"to": {

"value": "Allottee",

"label": "Allottee"

},

"Allottee": "Mr. Hitesh Prakash Tandalekar "

},

"isHardCopy": false,

"displayStatus": true,

"id": "607344",

"path": "cases/67976d0e4090f0a5b214d4b1/

document_1737977021146_Hitesh_Tandalekar__C_1105.pdf",

"fileName": "document_1737977021146_Hitesh_Tandalekar__C_1105.pdf"

},

{

"documentType": {

"value": "60ae129faa6d152c1801b47d",

"label": "RERA Certificate"

},

"inputs": {

"documentDate": "13/08/2024",

"nameOfApprovingAuthority": {

"value": "Maharashtra_Real_Estate_Regulatory_Authority",

"label": "Maharashtra Real Estate Regulatory Authority"

},

"number": {

"value": "No",

"label": "No"

},

"No": "P51700077417"

},

```
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1738126338303_RERE_Certificate.pdf",
"path": "cases/67976d0e4090f0a5b214d4b1/
document_1738126338303_RERE_Certificate.pdf",
"id": "890278",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Wed Jan 29 2025 04:52:18 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "04/07/2024",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / TPD / BP / 27 Village / 2021 - 2022 / 26 / 58"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1738127246690_CC.pdf",
"path": "cases/67976d0e4090f0a5b214d4b1/document_1738127246690_CC.pdf",
"id": "719784",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Wed Jan 29 2025 05:07:26 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "04/07/2024",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "KDMC / TPD / BP / 27 Village / 2021 - 2022 / 26 / 58"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1738127413766_Approved_Building_Plan.pdf",
"path": "cases/67976d0e4090f0a5b214d4b1/
document_1738127413766_Approved_Building_Plan.pdf",
"id": "255202",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Wed Jan 29 2025 05:10:14 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e5",
    "label": "Allotment Letter"
  },
  "inputs": {
    "remark": " for the Year Dec - 2024",
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "M/s. Shree Jarimari Developers LLP",
    "to": {
      "value": "Allottee",
      "label": "Allottee"
    },
    "Allottee": "Mr. Hitesh Prakash Tandalekar"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1738127637980_Allotment_Letter.pdf",
  "path": "cases/67976d0e4090f0a5b214d4b1/
document_1738127637980_Allotment_Letter.pdf",
  "id": "532312",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Jan 29 2025 05:13:58 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
}
```

```
"caseNumber": "013959",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "276731",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jan 27 2025 11:25:02 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Hitesh Prakash Tandalekar",
    "phone": "8149860266",
    "ownershipShare": "",
    "email": "",
    "id": "773200"
  }
],
"proposePurchasers": [
  {
    "name": "M/s. Shree Jarimari Developers LLP"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    },
    "name": {
      "label": "Flower Bed Area",
      "value": "Flower_Bed_Area"
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "0",
    "length": "0.00",
    "length1": "0",
    "length2": "00",
    "width": "0.00",
    "width1": "0",
```

```
"width2": "00",
"totalArea": "0.00",
"images": [],
"extraAreas": [],
"finalArea": "0",
"percentageBeforeTotal": "0.00",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1256aa6d152c1801b330",
    "label": "Draft Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "247176",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "422",
  "squareMeterArea": "39.2",
  "docFinalBuiltUp": "464.2",
  "docFinalBuiltUpSquareMeter": "43.120000000000005",
  "docBultupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6798c79b49234c16a2201473",
  "name":
"externalmg_1738065818833_WhatsApp_Image_20250128_at_53115_PM.jpeg",
  "path": "cases/67976d0e4090f0a5b214d4b1/
externalmg_1738065818833_WhatsApp_Image_20250128_at_53115_PM.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201474",
    "name":
"externallmg_1738065818852_WhatsApp_Image_20250128_at_53116_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065818852_WhatsApp_Image_20250128_at_53116_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201475",
    "name":
"externallmg_1738065819231_WhatsApp_Image_20250128_at_53116_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819231_WhatsApp_Image_20250128_at_53116_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201476",
    "name":
"externallmg_1738065819259_WhatsApp_Image_20250128_at_53117_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819259_WhatsApp_Image_20250128_at_53117_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201477",
    "name":
"externallmg_1738065819290_WhatsApp_Image_20250128_at_53117_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819290_WhatsApp_Image_20250128_at_53117_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201478",
    "name":
"externallmg_1738065819313_WhatsApp_Image_20250128_at_53118_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819313_WhatsApp_Image_20250128_at_53118_PM_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201479",
    "name":
"externallmg_1738065819356_WhatsApp_Image_20250128_at_53118_PM_2.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819356_WhatsApp_Image_20250128_at_53118_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a220147a",
    "name":
"externallmg_1738065819406_WhatsApp_Image_20250128_at_53118_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819406_WhatsApp_Image_20250128_at_53118_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a220147b",
    "name":
"externallmg_1738065819444_WhatsApp_Image_20250128_at_53119_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819444_WhatsApp_Image_20250128_at_53119_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a220147c",
    "name":
"externallmg_1738065819475_WhatsApp_Image_20250128_at_53119_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819475_WhatsApp_Image_20250128_at_53119_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a220147d",
```

```
    "name":
"externallmg_1738065819519_WhatsApp_Image_20250128_at_53120_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819519_WhatsApp_Image_20250128_at_53120_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a220147e",
    "name":
"externallmg_1738065819556_WhatsApp_Image_20250128_at_53120_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819556_WhatsApp_Image_20250128_at_53120_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a220147f",
    "name":
"externallmg_1738065819575_WhatsApp_Image_20250128_at_53121_PM_1.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819575_WhatsApp_Image_20250128_at_53121_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201480",
    "name":
"externallmg_1738065819602_WhatsApp_Image_20250128_at_53121_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819602_WhatsApp_Image_20250128_at_53121_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6798c79b49234c16a2201481",
    "name":
"externallmg_1738065819640_WhatsApp_Image_20250128_at_53122_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/
externallmg_1738065819640_WhatsApp_Image_20250128_at_53122_PM.jpeg",
    "orientation": "landscape"
  }
}
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AADHAR.pdf",
    "filename": "1738653251676_AADHAR.pdf",
    "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653251676_AADHAR.pdf",
    "size": "293245",
    "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "AADHAR-1.pdf",
    "filename": "1738653251683_AADHAR1.pdf",
    "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653251683_AADHAR1.pdf",
    "size": "920920",
    "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "ALLOTMENT LETTER.pdf",
    "filename": "1738653251732_ALLOTMENT_LETTER.pdf",
    "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653251732_ALLOTMENT_LETTER.pdf",
    "size": "1025673",
    "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "DRAFT AGR.pdf",
    "filename": "1738653251748_DRAFT_AGR.pdf",
    "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653251748_DRAFT_AGR.pdf",
    "size": "375736",
    "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1738065818833_WhatsApp_Image_20250128_at_53115_PM.jpeg",
    "filename": "1738653251906_externallmg_1738065818833_WhatsApp_Image_202
50128_at_53115_PM.jpeg",
    "path": "cases/67976d0e4090f0a5b214d4b1/processingDocuments/1738653251906
_externallmg_1738065818833_WhatsApp_Image_20250128_at_53115_PM.jpeg",
```

```
"size": "155653",
"createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "PAN.pdf",
  "filename": "1738653251909_PAN.pdf",
  "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653251909_PAN.pdf",
  "size": "328369",
  "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "PAN-1.pdf",
  "filename": "1738653251957_PAN1.pdf",
  "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653251957_PAN1.pdf",
  "size": "258928",
  "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "RERA.pdf",
  "filename": "1738653251975_RERA.pdf",
  "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653251975_RERA.pdf",
  "size": "709789",
  "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=HITESH.xlsx",
  "filename": "1738653252024_Summary_NewHITESH.xlsx",
  "path": "cases/67976d0e4090f0a5b214d4b1/
processingDocuments/1738653252024_Summary_NewHITESH.xlsx",
  "size": "312762",
  "createdAt": "Tue Feb 04 2025 07:14:12 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
```

```
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "6798cb317dd57116683c3fb8",
  "note": "Total Composite \t 9,000.00 \n\t\nACA\t421\nFMV\t 37,89,000.00 \nRV\t
34,10,100.00 \nDV\t 30,31,200.00 \n",
  "taskId": "67976d166258b1a576713097",
  "createdAt": "2025-01-28T12:18:57.130Z"
},
{
  "createdBy": {
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "lastName": "Kajvilkar",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shym_Photo.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "67a1be51a2b18adef0cc41e3",
  "note": "Pending for value confirmation - Total Composite 9,000.00 ACA 421 FMV
37,89,000.00 RV 34,10,100.00 DV 30,31,200.00",
  "taskId": "67976d166258b1a576713097",
  "createdAt": "2025-02-04T07:14:25.096Z"
}
],
"createdAt": "2025-01-27T11:25:02.872Z",
"updatedAt": "2025-02-22T09:29:00.250Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mr. Shivkant Yadav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
```

```
"proposePurchaserName": "M/s. Shree Jarimari Developers LLP",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "CRM",
"rerald": "",
"siteVisitContactNo": "7498648109",
"briefDescOfProperty": "",
"carpetTotal": "0.00",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"salablePercentage": "10",
"toBeAdded": "",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"extendOfSiteRemark": "RERA Carpet Area in Sq. Ft. = 346.00\nE.P. Area in Sq. Ft. =
58.00\nUsable Carpet Area in Sq. Ft. = 18.00\n",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Draft Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 422.00",
"reportGeneratedDate": "Wed Jan 29 2025 04:39:14 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-01-26",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
```

}
}

Name	Length	Width	Total
Composition :			
Other Composition :			
Flower Bed Area	0'00"	0'00"	0.00