

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66f78e7b12fe5c0dc6cd385a"
    },
    "firstName": "Nilesh ",
    "type": "CREDITOFFICER",
    "_id": "66f78f8dd531b50db98b920d",
    "email": "sbi.17500@sbi.co.in",
    "lastName": "Gunjal",
    "mobileNo": "",
    "workMobileNo": "9545015543"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2770"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "66f78e7b12fe5c0dc6cd385a",
  "name": "Dixi Barnch",
  "branchCode": "017500",
  "mobileNo": "7875758722",
  "alternateMobileNo": "18004253800",
  "email": "sbi.17500@sbi.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "HOUSE NO.22, ILKAT NO.106, T AND POST DIXI, AL.NIPHAD,
ISTT.NASIK.MAHARASHTRA 422 302"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
```

```
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
```

```
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
{
"title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.086694",
  "longitude": "73.916361"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "16/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2025-01-08",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ozar Township",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Niphad",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Row House Phase -1, \" Kalpataru Baug Phase - 1",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "off Mumbai - Agra Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "opposite Dynamic Health Club, Shivaji Nagar ",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
```



```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "Gat No.- 2658/ 1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```

```
"value": "01",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": true,
"name": "Postal Code",
"key": "postalCode",
"value": "PIN Code - 422 206",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
}
```

```
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "CASE",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67a30d26a92c39df2abd9a0a",
"ownerName": "Mr. Prafullachandra Digambar Jadhav & Mrs. Rekha
Prafullchandra Jadhav",
"ownerPhoneNo": "8793542175",
"fullAddress": "Residential Row House No. 01, Ground Floor, Wing - C, Row House
Phase -1, \ " Kalpataru Baug Phase - 1, opposite Dynamic Health Club, Shivaji Nagar ,
New/Current Survey No. Gat No.- 2658/ 1, off Mumbai - Agra Road, Village - Ozar
Township, Taluka - Niphad, District - Nashik, Nashik, PIN Code - 422 206, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1738739116648_document_1737013314279_3_BHK_ROW
_HOUSE_2.pdf",
    "path": "cases/67a30d26a92c39df2abd9a0a/document_1738739116648_document
_1737013314279_3_BHK_ROW_HOUSE_2.pdf",
    "id": "493731",
```

```
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Feb 05 2025 07:06:17 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738739130622_document_1737013373538_Rera.pdf",
  "path": "cases/67a30d26a92c39df2abd9a0a/
document_1738739130622_document_1737013373538_Rera.pdf",
  "id": "839811",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Feb 05 2025 07:06:17 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738739139756_Prafullachandra_Jadhav_3_Bhk_Rh_Wing
_C_Rh_No_01.pdf",
  "path": "cases/67a30d26a92c39df2abd9a0a/document_1738739139756_Prafullach
andra_Jadhav_3_Bhk_Rh_Wing_C_Rh_No_01.pdf",
  "id": "692656",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Feb 05 2025 07:06:17 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014134",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "718572",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 16 2025 07:42:57 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
],
"owners": [
  {
    "name": "Mr. Prafullachandra Digambar Jadhav & Mrs. Rekha
Prafullachandra Jadhav",
    "phone": "8793542175",
    "ownershipShare": "",
    "email": "",
    "id": "488800"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d635",
    "name":
"externalImg_1738739227922_WhatsApp_Image_20250204_at_105745_AM.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externalImg_1738739227922_WhatsApp_Image_20250204_at_105745_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d636",
    "name":
"externalImg_1738739228214_WhatsApp_Image_20250204_at_105746_AM.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externalImg_1738739228214_WhatsApp_Image_20250204_at_105746_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d637",
    "name":
"externalImg_1738739228509_WhatsApp_Image_20250204_at_105748_AM_1.jpeg",
```

```
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739228509_WhatsApp_Image_20250204_at_105748_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d638",
    "name":
"externallmg_1738739228748_WhatsApp_Image_20250204_at_105748_AM_2.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739228748_WhatsApp_Image_20250204_at_105748_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d639",
    "name":
"externallmg_1738739229019_WhatsApp_Image_20250204_at_105748_AM.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739229019_WhatsApp_Image_20250204_at_105748_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d63a",
    "name":
"externallmg_1738739229271_WhatsApp_Image_20250204_at_105749_AM_1.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739229271_WhatsApp_Image_20250204_at_105749_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d63b",
    "name":
"externallmg_1738739229589_WhatsApp_Image_20250204_at_105749_AM.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739229589_WhatsApp_Image_20250204_at_105749_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67a30e21c6108fdeef48d63c",
  "name":
"externallmg_1738739229870_WhatsApp_Image_20250204_at_105750_AM_1.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739229870_WhatsApp_Image_20250204_at_105750_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a30e21c6108fdeef48d63d",
  "name":
"externallmg_1738739230265_WhatsApp_Image_20250204_at_105750_AM_2.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739230265_WhatsApp_Image_20250204_at_105750_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a30e21c6108fdeef48d63e",
  "name":
"externallmg_1738739230529_WhatsApp_Image_20250204_at_105750_AM.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739230529_WhatsApp_Image_20250204_at_105750_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a30e21c6108fdeef48d63f",
  "name":
"externallmg_1738739230718_WhatsApp_Image_20250204_at_105751_AM_1.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739230718_WhatsApp_Image_20250204_at_105751_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a30e21c6108fdeef48d640",
  "name":
"externallmg_1738739230998_WhatsApp_Image_20250204_at_105751_AM_2.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739230998_WhatsApp_Image_20250204_at_105751_AM_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d641",
    "name":
"externallmg_1738739231228_WhatsApp_Image_20250204_at_105751_AM.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739231228_WhatsApp_Image_20250204_at_105751_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d642",
    "name":
"externallmg_1738739231496_WhatsApp_Image_20250204_at_105752_AM_1.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739231496_WhatsApp_Image_20250204_at_105752_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d643",
    "name":
"externallmg_1738739231720_WhatsApp_Image_20250204_at_105752_AM.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739231720_WhatsApp_Image_20250204_at_105752_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d644",
    "name":
"externallmg_1738739232019_WhatsApp_Image_20250204_at_105753_AM_1.jpeg",
    "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739232019_WhatsApp_Image_20250204_at_105753_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67a30e21c6108fdeef48d645",
```

```
    "name":
"externallmg_1738739232267_WhatsApp_Image_20250204_at_105753_AM.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739232267_WhatsApp_Image_20250204_at_105753_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a30e21c6108fdeef48d646",
  "name":
"externallmg_1738739232531_WhatsApp_Image_20250204_at_105754_AM_1.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739232531_WhatsApp_Image_20250204_at_105754_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a30e21c6108fdeef48d647",
  "name":
"externallmg_1738739232799_WhatsApp_Image_20250204_at_105754_AM_2.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739232799_WhatsApp_Image_20250204_at_105754_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67a30e21c6108fdeef48d648",
  "name":
"externallmg_1738739233065_WhatsApp_Image_20250204_at_105754_AM.jpeg",
  "path": "cases/67a30d26a92c39df2abd9a0a/
externallmg_1738739233065_WhatsApp_Image_20250204_at_105754_AM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Mr. Rahul Kushare CAI.xlsx",
  "filename": "1737013576921_Mr_Rahul_Kushare_CAI.xlsx",
  "path": "cases/67a30d26a92c39df2abd9a0a/
processingDocuments/1737013576921_Mr_Rahul_Kushare_CAI.xlsx",
  "size": "629374",
  "createdAt": "Thu Jan 16 2025 07:46:17 GMT+0000 (Coordinated Universal Time)",
```



```
"uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
  "originalname": "Mr. Rahul Dagu Kushare.doc",
  "filename": "1737013598698_Mr_Rahul_Dagu_Kushare.doc",
  "path": "cases/67a30d26a92c39df2abd9a0a/
processingDocuments/1737013598698_Mr_Rahul_Dagu_Kushare.doc",
  "size": "3256320",
  "createdAt": "Thu Jan 16 2025 07:46:42 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "6006d4ce5080a310ac1fdfc2",
      "role": "ADMIN",
      "firstName": "Jagdish ",
      "lastName": "Bhatt",
      "profilePhoto": "users\\6006d4ce5080a310ac1fdfc2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
    },
    "workType": "CHECKER",
    "display": true,
    "status": true,
    "_id": "6788bb49601c90e696214f99",
    "note": "For Outward (Task Reopen)",
    "taskId": "6788b966290edae64f1851e9",
    "createdAt": "2025-01-16T07:54:49.613Z"
  }
],
"createdAt": "2025-02-05T07:03:02.998Z",
"updatedAt": "2025-02-05T07:07:13.536Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "647ed1960ab64c23c9fcf71d",
"contactPersonName": "Mr. Arjun Kathe ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
```

"relationWithOwner": "Builder",
"rerald": "",
"siteVisitContactNo": "8793542175",
"reportGeneratedDate": "Thu Jan 16 2025 07:47:39 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2025-01-08",
"refCaseId": "6788b881601c90e696214b97"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
