

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "647ed1960ab64c23c9fcf71d",
```

```
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
```

```
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": "",
"profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.031167",
  "longitude": "73.744861"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "13/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chandsi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "off Mungsare - Chandsi Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near EISN - Ebenezer International School",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "Survey No. 62/ 1+ 62/ 2+63+64",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Residential Land and Bungalow On Plot No. 458",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code – 422 003",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67ad939ad716769af0d630ce",
"ownerName": "Shri. Ganpat Punja Sonawane & Sau. Purva Vikram Sonawane",
"ownerPhoneNo": "7709956078",
"fullAddress": "Residential Land and Building No. Residential Land and Bungalow On
Plot No. 458, Ground Floor, Near EISN - Ebenezer International School, New/Current
Survey No. Survey No. 62/ 1+ 62/ 2+63+64, off Mungsare - Chandsi Road, Village -
Chandsi, Taluka - Nashik, District - Nashik, Nashik, PIN Code – 422 003, Country –
India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1739428725116_Purva_Sonavane.pdf",
    "path": "cases/67ad939ad716769af0d630ce/
document_1739428725116_Purva_Sonavane.pdf",
    "id": "891108",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Thu Feb 13 2025 06:39:21 GMT+0000 (Coordinated Universal Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae124aaa6d152c1801b2f7",
  "label": "Any Other Document"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1739428738996_Purva_Sonawane_building_plan.pdf",
"path": "cases/67ad939ad716769af0d630ce/
document_1739428738996_Purva_Sonawane_building_plan.pdf",
"id": "867457",
"uploadedBy": "647ed1960ab64c23c9fcf71d",
"createdAt": "Thu Feb 13 2025 06:39:21 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739428749299_Purva_sonawane_valuation_.pdf",
  "path": "cases/67ad939ad716769af0d630ce/
document_1739428749299_Purva_sonawane_valuation_.pdf",
  "id": "260325",
  "uploadedBy": "647ed1960ab64c23c9fcf71d",
  "createdAt": "Thu Feb 13 2025 06:39:21 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014285",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "887412",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Feb 13 2025 06:39:22 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri. Ganpat Punja Sonawane & Sau. Purva Vikram Sonawane",
    "phone": "7709956078",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "133977"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb51",
    "name":
"externalImg_1739428832387_WhatsApp_Image_20250207_at_11724_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externalImg_1739428832387_WhatsApp_Image_20250207_at_11724_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb52",
    "name":
"externalImg_1739428832542_WhatsApp_Image_20250207_at_11726_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externalImg_1739428832542_WhatsApp_Image_20250207_at_11726_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb53",
    "name":
"externalImg_1739428832673_WhatsApp_Image_20250207_at_11728_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externalImg_1739428832673_WhatsApp_Image_20250207_at_11728_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb54",
    "name":
"externallmg_1739428832821_WhatsApp_Image_20250207_at_11731_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428832821_WhatsApp_Image_20250207_at_11731_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb55",
    "name":
"externallmg_1739428832949_WhatsApp_Image_20250207_at_11733_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428832949_WhatsApp_Image_20250207_at_11733_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb56",
    "name":
"externallmg_1739428833055_WhatsApp_Image_20250207_at_11734_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833055_WhatsApp_Image_20250207_at_11734_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb57",
    "name":
"externallmg_1739428833200_WhatsApp_Image_20250207_at_11736_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833200_WhatsApp_Image_20250207_at_11736_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb58",
    "name":
"externallmg_1739428833329_WhatsApp_Image_20250207_at_11737_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833329_WhatsApp_Image_20250207_at_11737_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb59",
    "name":
"externallmg_1739428833435_WhatsApp_Image_20250207_at_11738_PM_1.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833435_WhatsApp_Image_20250207_at_11738_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb5a",
    "name":
"externallmg_1739428833582_WhatsApp_Image_20250207_at_11738_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833582_WhatsApp_Image_20250207_at_11738_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb5b",
    "name":
"externallmg_1739428833709_WhatsApp_Image_20250207_at_11739_PM_1.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833709_WhatsApp_Image_20250207_at_11739_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb5c",
    "name":
"externallmg_1739428833813_WhatsApp_Image_20250207_at_11739_PM_2.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833813_WhatsApp_Image_20250207_at_11739_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93e336a56c9b5f66cb5d",
```

```
    "name":
"externallmg_1739428833940_WhatsApp_Image_20250207_at_11739_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428833940_WhatsApp_Image_20250207_at_11739_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93e336a56c9b5f66cb5e",
  "name":
"externallmg_1739428834048_WhatsApp_Image_20250207_at_11740_PM_1.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428834048_WhatsApp_Image_20250207_at_11740_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93e336a56c9b5f66cb5f",
  "name":
"externallmg_1739428834429_WhatsApp_Image_20250207_at_11740_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428834429_WhatsApp_Image_20250207_at_11740_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93e336a56c9b5f66cb60",
  "name":
"externallmg_1739428834745_WhatsApp_Image_20250207_at_11741_PM_1.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428834745_WhatsApp_Image_20250207_at_11741_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93e336a56c9b5f66cb61",
  "name":
"externallmg_1739428834893_WhatsApp_Image_20250207_at_11741_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428834893_WhatsApp_Image_20250207_at_11741_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93e336a56c9b5f66cb62",
  "name":
"externallmg_1739428835020_WhatsApp_Image_20250207_at_11742_PM_1.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428835020_WhatsApp_Image_20250207_at_11742_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93e336a56c9b5f66cb63",
  "name":
"externallmg_1739428835145_WhatsApp_Image_20250207_at_11742_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428835145_WhatsApp_Image_20250207_at_11742_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93fd36a56c9b5f66cbc7",
  "name":
"externallmg_1739428858569_WhatsApp_Image_20250207_at_11743_PM_1.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428858569_WhatsApp_Image_20250207_at_11743_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93fd36a56c9b5f66cbc8",
  "name":
"externallmg_1739428858651_WhatsApp_Image_20250207_at_11743_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428858651_WhatsApp_Image_20250207_at_11743_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93fd36a56c9b5f66cbc9",
  "name":
"externallmg_1739428858887_WhatsApp_Image_20250207_at_11744_PM_1.jpeg",
```



```
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428858887_WhatsApp_Image_20250207_at_11744_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbca",
    "name":
"externallmg_1739428859032_WhatsApp_Image_20250207_at_11744_PM_2.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428859032_WhatsApp_Image_20250207_at_11744_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbcb",
    "name":
"externallmg_1739428859140_WhatsApp_Image_20250207_at_11744_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428859140_WhatsApp_Image_20250207_at_11744_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbcc",
    "name":
"externallmg_1739428859309_WhatsApp_Image_20250207_at_11745_PM_1.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428859309_WhatsApp_Image_20250207_at_11745_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbcd",
    "name":
"externallmg_1739428859458_WhatsApp_Image_20250207_at_11745_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428859458_WhatsApp_Image_20250207_at_11745_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67ad93fd36a56c9b5f66cbce",
  "name":
"externallmg_1739428859562_WhatsApp_Image_20250207_at_11746_PM_1.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428859562_WhatsApp_Image_20250207_at_11746_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93fd36a56c9b5f66cbcf",
  "name":
"externallmg_1739428859835_WhatsApp_Image_20250207_at_11746_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428859835_WhatsApp_Image_20250207_at_11746_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93fd36a56c9b5f66cbd0",
  "name":
"externallmg_1739428859984_WhatsApp_Image_20250207_at_11747_PM_1.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428859984_WhatsApp_Image_20250207_at_11747_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93fd36a56c9b5f66cbd1",
  "name":
"externallmg_1739428860153_WhatsApp_Image_20250207_at_11747_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428860153_WhatsApp_Image_20250207_at_11747_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67ad93fd36a56c9b5f66cbd2",
  "name":
"externallmg_1739428860323_WhatsApp_Image_20250207_at_11748_PM.jpeg",
  "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428860323_WhatsApp_Image_20250207_at_11748_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbd3",
    "name":
"externallmg_1739428860532_WhatsApp_Image_20250207_at_11749_PM_1.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428860532_WhatsApp_Image_20250207_at_11749_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbd4",
    "name":
"externallmg_1739428860788_WhatsApp_Image_20250207_at_11749_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428860788_WhatsApp_Image_20250207_at_11749_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbd5",
    "name":
"externallmg_1739428861041_WhatsApp_Image_20250207_at_11750_PM_1.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428861041_WhatsApp_Image_20250207_at_11750_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67ad93fd36a56c9b5f66cbd6",
    "name":
"externallmg_1739428861228_WhatsApp_Image_20250207_at_11750_PM.jpeg",
    "path": "cases/67ad939ad716769af0d630ce/
externallmg_1739428861228_WhatsApp_Image_20250207_at_11750_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
```

```
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-13T06:39:22.159Z",
"updatedAt": "2025-02-13T06:41:01.668Z",
"__v": 0,
"updatedBy": "647ed1960ab64c23c9fcf71d",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Shri. Ganpat Punja Sonawane & Sau. Purva Vikram
Sonawane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "7709956078"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			