

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "677908cfa5477d50e7dcfbaf"
    },
    "firstName": "Abhishek",
    "type": "CREDITOFFICER",
    "_id": "677908f182ea0d50e10160c8",
    "email": "cb7065@canarabank.com",
    "lastName": "Arora",
    "mobileNo": "",
    "workMobileNo": "7718873563"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Abhishek",
    "expectedFees": 3000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "676544371f06b62faf373ec8",
  "type": "BANK",
  "name": "Canara Bank",
  "displayName": "Canara Bank",
  "initial": "CNB"
},
"branch": {
  "_id": "677908cfa5477d50e7dcfbaf",
  "name": "Retail Asset Hub, Vasai",
  "branchCode": "7065",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "cb7065@canarabank.com",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "God's Gift Bunglow, Mary Villa Stuo, Stela, Manickpur, Vasai-401202"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "6765457131b0132fc5831fcc",
  "zoneName": "MUMBAI"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "659ccce98f39506e83489828",
    "role": "DELIVERYPERSON",
    "firstName": "Amit",
    "email": "amitsalvi2909@gmail.com",
```

```
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "67776d60a5477d50e7dbc213",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "AJAY",
"email": "ajayrewale503@gmail.com",
"lastName": "REWALE",
"mobileNo": "9766640171",
"designation": "",
"shortName": "AJAY",
"workWithDocumentMaker": "",
"profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
},
"_id": "60af80072ffdf65bcd658651",
```

```
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.201458057217614",
  "longitude": "72.86626461925292"
},
"geo": {
  "type": "Point",
```

```
"coordinates": [
  72.86626461925292,
  19.201458057217614
],
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "18/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Akurli",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Akurli Sukh Shanti CHSL",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "AD-19",
```

```
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "RSC-1",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "22",
  "label": false
}
```



```
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
```

```
"key": "postalCode",
"value": "400101",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
}
```

```
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```



```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b413b6c594f0b7b656095b",
"ownerName": "MISS AASHITA MAHENDRA SINGH AND MRS SADHANA
MAHENDRA SHENGAR",
"ownerPhoneNo": "6387457876",
"appAddress": "FLAT NO A-22 AKURLI SUKH SHANTI CHS LTD PLOT NO AD-19
ROAD NO RSC -1 KANDIVALI EAST MUMBAI 400101",
"remark": "Contact Mr Dinanath 6387457876",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67b413b6c594f0b7b656095b/
document_1739854727561_1739854724863_Ashita_singh_agreement.pdf",
    "fileName":
"document_1739854727561_1739854724863_Ashita_singh_agreement.pdf",
    "id": "487106",
    "uploadedBy": "659ccce98f39506e83489828",
```

```
    "createdAt": "Tue Feb 18 2025 04:59:34 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014387",
"createdBy": "659cccce98f39506e83489828",
"caseHistory": [
  {
    "id": "779615",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 18 2025 04:59:34 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "MISS AASHITA MAHENDRA SINGH AND MRS SADHANA MAHENDRA SHENGAR",
    "phone": "6387457876",
    "ownershipShare": "",
    "email": "",
    "id": "121784"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe448",
    "name": "externalImg_1739942271382_1739942268334_image_0.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/externalImg_1739942271382_1739942268334_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe449",
    "name": "externalImg_1739942274777_1739942268334_image_1.jpeg",
  }
]
```

```
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942274777_1739942268334_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe44a",
    "name": "externallmg_1739942276610_1739942268334_image_2.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942276610_1739942268334_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe44b",
    "name": "externallmg_1739942276940_1739942268334_image_3.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942276940_1739942268334_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe44c",
    "name": "externallmg_1739942280419_1739942268334_image_4.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942280419_1739942268334_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe44d",
    "name": "externallmg_1739942281995_1739942268334_image_5.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942281995_1739942268334_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe44e",
    "name": "externallmg_1739942283884_1739942268334_image_6.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942283884_1739942268334_image_6.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b569b2dc5b7cb7d2fbe44f",
  "name": "externallmg_1739942286870_1739942268334_image_7.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942286870_1739942268334_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b569b2dc5b7cb7d2fbe450",
  "name": "externallmg_1739942288995_1739942268334_image_8.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942288995_1739942268334_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b569b2dc5b7cb7d2fbe451",
  "name": "externallmg_1739942291660_1739942268334_image_9.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942291660_1739942268334_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b569b2dc5b7cb7d2fbe452",
  "name": "externallmg_1739942299878_1739942268334_image_10.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942299878_1739942268334_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b569b2dc5b7cb7d2fbe453",
  "name": "externallmg_1739942302900_1739942268334_image_11.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942302900_1739942268334_image_11.jpeg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe454",
    "name": "externallmg_1739942303580_1739942268334_image_12.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942303580_1739942268334_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe455",
    "name": "externallmg_1739942306735_1739942268334_image_13.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942306735_1739942268334_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe456",
    "name": "externallmg_1739942310415_1739942268334_image_14.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942310415_1739942268334_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe457",
    "name": "externallmg_1739942312831_1739942268334_image_15.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942312831_1739942268334_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67b569b2dc5b7cb7d2fbe458",
    "name": "externallmg_1739942315276_1739942268334_image_16.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942315276_1739942268334_image_16.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b569b2dc5b7cb7d2fbe459",
  "name": "externallmg_1739942317541_1739942268334_image_17.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942317541_1739942268334_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67b569b2dc5b7cb7d2fbe45a",
  "name": "externallmg_1739942319976_1739942268334_image_18.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942319976_1739942268334_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b56a07e1b0fbb7b7ee5aed",
  "name": "externallmg_1739942369719_1739942329312_image_0.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942369719_1739942329312_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b56a07e1b0fbb7b7ee5aee",
  "name": "externallmg_1739942372251_1739942329312_image_1.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942372251_1739942329312_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b56a07e1b0fbb7b7ee5aef",
  "name": "externallmg_1739942372802_1739942329312_image_2.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942372802_1739942329312_image_2.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5af0",
    "name": "externallmg_1739942373407_1739942329312_image_3.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942373407_1739942329312_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5af1",
    "name": "externallmg_1739942375423_1739942329312_image_4.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942375423_1739942329312_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5af2",
    "name": "externallmg_1739942377703_1739942329312_image_5.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942377703_1739942329312_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5af3",
    "name": "externallmg_1739942379947_1739942329312_image_6.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942379947_1739942329312_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5af4",
    "name": "externallmg_1739942382157_1739942329312_image_7.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942382157_1739942329312_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67b56a07e1b0fbb7b7ee5af5",
  "name": "externallmg_1739942384522_1739942329312_image_8.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942384522_1739942329312_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b56a07e1b0fbb7b7ee5af6",
  "name": "externallmg_1739942386488_1739942329312_image_9.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942386488_1739942329312_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b56a07e1b0fbb7b7ee5af7",
  "name": "externallmg_1739942388602_1739942329312_image_10.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942388602_1739942329312_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b56a07e1b0fbb7b7ee5af8",
  "name": "externallmg_1739942390042_1739942329312_image_11.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942390042_1739942329312_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b56a07e1b0fbb7b7ee5af9",
  "name": "externallmg_1739942391977_1739942329312_image_12.jpeg",
  "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942391977_1739942329312_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "67b56a07e1b0fbb7b7ee5afa",
    "name": "externallmg_1739942393827_1739942329312_image_13.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942393827_1739942329312_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5afb",
    "name": "externallmg_1739942395783_1739942329312_image_14.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942395783_1739942329312_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5afc",
    "name": "externallmg_1739942397943_1739942329312_image_15.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942397943_1739942329312_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5afd",
    "name": "externallmg_1739942400513_1739942329312_image_16.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942400513_1739942329312_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5afe",
    "name": "externallmg_1739942401712_1739942329312_image_17.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externallmg_1739942401712_1739942329312_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5aff",
```

```
    "name": "externalImg_1739942403403_1739942329312_image_18.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externalImg_1739942403403_1739942329312_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b56a07e1b0fbb7b7ee5b00",
    "name": "externalImg_1739942404923_1739942329312_image_19.jpeg",
    "path": "cases/67b413b6c594f0b7b656095b/
externalImg_1739942404923_1739942329312_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-18T04:59:34.517Z",
"updatedAt": "2025-02-19T05:20:07.168Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 22, Ground Floor, Building No Akurli Sukh Shanti
CHSL, Plot No. AD-19, Sector RSC-1, Village - Akurli, Kandivali East, Mumbai, 400101,
State - Maharashtra, India",
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "MISS AASHITA MAHENDRA SINGH AND MRS SADHANA
MAHENDRA SHENGAR",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reId": "",
"siteVisitContactNo": "6387457876"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			