

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a7c4a794dfc26ccf86dc5a"
    },
    "firstName": "Umesh Devchand ",
    "type": "CREDITOFFICER",
    "_id": "64a7c4a794dfc26ccf86dc5d",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar1@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "5900"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a7c4a794dfc26ccf86dc5a",
  "name": "Administrative Office Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "Nashik@sbi.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor, BSNL CTTC, Building no 45-47, D Road MIDC, Satpur
Nashik-422007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "designation": "",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
```

```
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.997129050796474",
  "longitude": "73.81201401313793"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "18/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "9",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3+4+10+11+12+13",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tapovan Link Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp. Maruti Wafers Office, Near Lokesh Plywood,",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "SAI COURT",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "388/1+2A(P)",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422005",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
}
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b45b6dc594f0b7b6565c96",
"ownerName": "SAI COURT",
"ownerPhoneNo": "9604128833",
"fullAddress": "Residential APF No. 9th Floor, SAI COURT, Opp. Maruti Wafers Office,
Near Lokesh Plywood,, Plot No. 3+4+10+11+12+13, New/Current Survey No.
388/1+2A(P), Tapovan Link Road, Village - Nashik, Taluka - Nashik, District - Nashik,
Nashik, 422005",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "15/07/2021",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      }
    }
  }
],
```

```
    "Registration_No": "P51600029904"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739873006573_rera_cert.pdf",
  "path": "cases/67b45b6dc594f0b7b6565c96/
document_1739873006573_rera_cert.pdf",
  "id": "888993",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739873031074_Building_Plan_Revised_1.pdf",
  "path": "cases/67b45b6dc594f0b7b6565c96/
document_1739873031074_Building_Plan_Revised_1.pdf",
  "id": "358901",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739873039404_Building_Plan_Revised_2.pdf",
  "path": "cases/67b45b6dc594f0b7b6565c96/
document_1739873039404_Building_Plan_Revised_2.pdf",
  "id": "165215",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
},
{
```

```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1739873060836_Engineers_Certificate.pdf",
"path": "cases/67b45b6dc594f0b7b6565c96/
document_1739873060836_Engineers_Certificate.pdf",
"id": "677381",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1739873077156_Commencement_Certificates.pdf",
  "path": "cases/67b45b6dc594f0b7b6565c96/
document_1739873077156_Commencement_Certificates.pdf",
  "id": "404634",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1739873085349_Declaration_about_Commencement_Certificate.pdf",
  "path": "cases/67b45b6dc594f0b7b6565c96/
document_1739873085349_Declaration_about_Commencement_Certificate.pdf",
  "id": "324293",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1739873127340_Master_Valuation_Report_SAI_COURT.pdf",
    "path": "cases/67b45b6dc594f0b7b6565c96/
document_1739873127340_Master_Valuation_Report_SAI_COURT.pdf",
    "id": "589441",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014404",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "825852",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 18 2025 10:05:33 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "SAI COURT",
    "phone": "9604128833",
    "ownershipShare": "",
    "email": "",
    "id": "321291"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67b45eebdc5b7cb7d2fba3ea",
  "name":
"externallmg_1739874026104_WhatsApp_Image_20250218_at_111848_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026104_WhatsApp_Image_20250218_at_111848_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3eb",
  "name":
"externallmg_1739874026185_WhatsApp_Image_20250218_at_111848_AM.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026185_WhatsApp_Image_20250218_at_111848_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3ec",
  "name":
"externallmg_1739874026240_WhatsApp_Image_20250218_at_111849_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026240_WhatsApp_Image_20250218_at_111849_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3ed",
  "name":
"externallmg_1739874026290_WhatsApp_Image_20250218_at_111849_AM_2.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026290_WhatsApp_Image_20250218_at_111849_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3ee",
  "name":
"externallmg_1739874026312_WhatsApp_Image_20250218_at_111849_AM.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026312_WhatsApp_Image_20250218_at_111849_AM.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3ef",
  "name":
  "externallmg_1739874026325_WhatsApp_Image_20250218_at_111850_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026325_WhatsApp_Image_20250218_at_111850_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f0",
  "name":
  "externallmg_1739874026362_WhatsApp_Image_20250218_at_111850_AM.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026362_WhatsApp_Image_20250218_at_111850_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f1",
  "name":
  "externallmg_1739874026367_WhatsApp_Image_20250218_at_111851_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026367_WhatsApp_Image_20250218_at_111851_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f2",
  "name":
  "externallmg_1739874026418_WhatsApp_Image_20250218_at_111851_AM.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026418_WhatsApp_Image_20250218_at_111851_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f3",
```

```
"name":
"externallmg_1739874026426_WhatsApp_Image_20250218_at_111852_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026426_WhatsApp_Image_20250218_at_111852_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f4",
  "name":
"externallmg_1739874026453_WhatsApp_Image_20250218_at_111852_AM_2.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026453_WhatsApp_Image_20250218_at_111852_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f5",
  "name":
"externallmg_1739874026460_WhatsApp_Image_20250218_at_111852_AM.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026460_WhatsApp_Image_20250218_at_111852_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f6",
  "name":
"externallmg_1739874026505_WhatsApp_Image_20250218_at_111853_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026505_WhatsApp_Image_20250218_at_111853_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f7",
  "name":
"externallmg_1739874026527_WhatsApp_Image_20250218_at_111853_AM_2.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026527_WhatsApp_Image_20250218_at_111853_AM_2.jpeg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f8",
  "name":
"externallmg_1739874026533_WhatsApp_Image_20250218_at_111853_AM.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026533_WhatsApp_Image_20250218_at_111853_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3f9",
  "name":
"externallmg_1739874026585_WhatsApp_Image_20250218_at_111854_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026585_WhatsApp_Image_20250218_at_111854_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3fa",
  "name":
"externallmg_1739874026590_WhatsApp_Image_20250218_at_111854_AM.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026590_WhatsApp_Image_20250218_at_111854_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3fb",
  "name":
"externallmg_1739874026633_WhatsApp_Image_20250218_at_111855_AM_1.jpeg",
  "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026633_WhatsApp_Image_20250218_at_111855_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67b45eebdc5b7cb7d2fba3fc",
  "name":
"externallmg_1739874026970_WhatsApp_Image_20250218_at_111855_AM.jpeg",
```

```
    "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874026970_WhatsApp_Image_20250218_at_111855_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b45eebdc5b7cb7d2fba3fd",
    "name":
"externallmg_1739874027005_WhatsApp_Image_20250218_at_111856_AM_1.jpeg",
    "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874027005_WhatsApp_Image_20250218_at_111856_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b45ef1dc5b7cb7d2fba420",
    "name":
"externallmg_1739874032836_WhatsApp_Image_20250218_at_111856_AM.jpeg",
    "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874032836_WhatsApp_Image_20250218_at_111856_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67b45ef1dc5b7cb7d2fba421",
    "name":
"externallmg_1739874032851_WhatsApp_Image_20250218_at_111857_AM.jpeg",
    "path": "cases/67b45b6dc594f0b7b6565c96/
externallmg_1739874032851_WhatsApp_Image_20250218_at_111857_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-18T10:05:33.344Z",
"updatedAt": "2025-02-18T10:20:33.016Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
```

"contactPersonName": "SAI COURT",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9604128833"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			