

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a7c4a794dfc26ccf86dc5a"
    },
    "firstName": "Umesh Devchand ",
    "type": "CREDITOFFICER",
    "_id": "64a7c4a794dfc26ccf86dc5d",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar1@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "5900"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a7c4a794dfc26ccf86dc5a",
  "name": "Administrative Office Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "Nashik@sbi.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor, BSNL CTTC, Building no 45-47, D Road MIDC, Satpur
Nashik-422007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
```

```
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.99226216142579",
  "longitude": "73.8073861312953"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "22/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Anandvan Housing Complex",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "443/1/1to3,443/2/1 to 4,443/3/1to3,443/4/5/1",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422001",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
}
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67b96ad525e2779c6344796f",
"ownerName": "Anandvan Housing Complex",
"ownerPhoneNo": "9011076019",
"fullAddress": "Residential APF No. Basement Floor, Anandvan Housing Complex,
New/Current Survey No. 443/1/1to3,443/2/1 to 4,443/3/1to3,443/4/5/1, Village - Nashik,
Taluka - Nashik, District - Nashik, Nashik, 422001, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "28/12/2022",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      },
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      }
    },
    "Registration_No": "P51600023994"
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1740204753911_RC_anandhan_Complex.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
document_1740204753911_RC_anandhan_Complex.pdf",
    "id": "108223",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Feb 22 2025 06:12:36 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1740210043378_Anandvan_brochure_Final_web_file.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
document_1740210043378_Anandvan_brochure_Final_web_file.pdf",
    "id": "246863",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Sat Feb 22 2025 07:40:46 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014511",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "650791",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Feb 22 2025 06:12:37 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Anandvan Housing Complex",
    "phone": "9011076019",
    "ownershipShare": "",
    "email": "",
    "id": "518220"
```

```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a1",
    "name":
"externallmg_1740390230654_WhatsApp_Image_20250222_at_10159_PM_1.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230654_WhatsApp_Image_20250222_at_10159_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a2",
    "name":
"externallmg_1740390230724_WhatsApp_Image_20250222_at_10159_PM_2.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230724_WhatsApp_Image_20250222_at_10159_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a3",
    "name":
"externallmg_1740390230772_WhatsApp_Image_20250222_at_10159_PM_3.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230772_WhatsApp_Image_20250222_at_10159_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a4",
    "name":
"externallmg_1740390230776_WhatsApp_Image_20250222_at_10159_PM_4.jpeg",
```

```
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230776_WhatsApp_Image_20250222_at_10159_PM_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a5",
    "name":
"externallmg_1740390230800_WhatsApp_Image_20250222_at_10159_PM_5.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230800_WhatsApp_Image_20250222_at_10159_PM_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a6",
    "name":
"externallmg_1740390230805_WhatsApp_Image_20250222_at_10159_PM_6.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230805_WhatsApp_Image_20250222_at_10159_PM_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a7",
    "name":
"externallmg_1740390230833_WhatsApp_Image_20250222_at_10159_PM_7.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230833_WhatsApp_Image_20250222_at_10159_PM_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a8",
    "name":
"externallmg_1740390230837_WhatsApp_Image_20250222_at_10159_PM_8.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230837_WhatsApp_Image_20250222_at_10159_PM_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1a9",
    "name":
"externallmg_1740390230868_WhatsApp_Image_20250222_at_10159_PM_9.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230868_WhatsApp_Image_20250222_at_10159_PM_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1aa",
    "name":
"externallmg_1740390230871_WhatsApp_Image_20250222_at_10159_PM_10.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230871_WhatsApp_Image_20250222_at_10159_PM_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1ab",
    "name":
"externallmg_1740390230899_WhatsApp_Image_20250222_at_10159_PM_11.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230899_WhatsApp_Image_20250222_at_10159_PM_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1ac",
    "name":
"externallmg_1740390230903_WhatsApp_Image_20250222_at_10159_PM_12.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230903_WhatsApp_Image_20250222_at_10159_PM_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1ad",
    "name":
"externallmg_1740390230930_WhatsApp_Image_20250222_at_10159_PM_13.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230930_WhatsApp_Image_20250222_at_10159_PM_13.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1ae",
    "name":
"externallmg_1740390230934_WhatsApp_Image_20250222_at_10159_PM.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230934_WhatsApp_Image_20250222_at_10159_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1af",
    "name":
"externallmg_1740390230981_WhatsApp_Image_20250222_at_10200_PM.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390230981_WhatsApp_Image_20250222_at_10200_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1b0",
    "name":
"externallmg_1740390231007_WhatsApp_Image_20250222_at_10234_PM_1.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390231007_WhatsApp_Image_20250222_at_10234_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1b1",
    "name":
"externallmg_1740390231011_WhatsApp_Image_20250222_at_10234_PM.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390231011_WhatsApp_Image_20250222_at_10234_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f579af7e67a8b91f1b2",
```

```
"name":
"externallmg_1740390231035_WhatsApp_Image_20250222_at_10235_PM_1.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390231035_WhatsApp_Image_20250222_at_10235_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f579af7e67a8b91f1b3",
  "name":
"externallmg_1740390231038_WhatsApp_Image_20250222_at_10235_PM_2.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390231038_WhatsApp_Image_20250222_at_10235_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f579af7e67a8b91f1b4",
  "name":
"externallmg_1740390231055_WhatsApp_Image_20250222_at_10235_PM_3.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390231055_WhatsApp_Image_20250222_at_10235_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db468",
  "name":
"externallmg_1740390239182_WhatsApp_Image_20250222_at_10235_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239182_WhatsApp_Image_20250222_at_10235_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db469",
  "name":
"externallmg_1740390239225_WhatsApp_Image_20250222_at_10236_PM_1.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239225_WhatsApp_Image_20250222_at_10236_PM_1.jpeg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db46a",
  "name":
"externallmg_1740390239242_WhatsApp_Image_20250222_at_10236_PM_2.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239242_WhatsApp_Image_20250222_at_10236_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db46b",
  "name":
"externallmg_1740390239260_WhatsApp_Image_20250222_at_10236_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239260_WhatsApp_Image_20250222_at_10236_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db46c",
  "name":
"externallmg_1740390239274_WhatsApp_Image_20250222_at_10309_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239274_WhatsApp_Image_20250222_at_10309_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db46d",
  "name":
"externallmg_1740390239278_WhatsApp_Image_20250222_at_10310_PM_1.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239278_WhatsApp_Image_20250222_at_10310_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db46e",
  "name":
"externallmg_1740390239292_WhatsApp_Image_20250222_at_10310_PM_2.jpeg",
```

```
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239292_WhatsApp_Image_20250222_at_10310_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f5f178be87ad41db46f",
    "name":
"externallmg_1740390239296_WhatsApp_Image_20250222_at_10310_PM.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239296_WhatsApp_Image_20250222_at_10310_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f5f178be87ad41db470",
    "name":
"externallmg_1740390239312_WhatsApp_Image_20250222_at_10311_PM_1.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239312_WhatsApp_Image_20250222_at_10311_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f5f178be87ad41db471",
    "name":
"externallmg_1740390239316_WhatsApp_Image_20250222_at_10311_PM_2.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239316_WhatsApp_Image_20250222_at_10311_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67bc3f5f178be87ad41db472",
    "name":
"externallmg_1740390239333_WhatsApp_Image_20250222_at_10311_PM.jpeg",
    "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239333_WhatsApp_Image_20250222_at_10311_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67bc3f5f178be87ad41db473",
  "name":
"externallmg_1740390239338_WhatsApp_Image_20250222_at_10312_PM_1.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239338_WhatsApp_Image_20250222_at_10312_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db474",
  "name":
"externallmg_1740390239351_WhatsApp_Image_20250222_at_10312_PM_2.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239351_WhatsApp_Image_20250222_at_10312_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db475",
  "name":
"externallmg_1740390239354_WhatsApp_Image_20250222_at_10312_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239354_WhatsApp_Image_20250222_at_10312_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db476",
  "name":
"externallmg_1740390239377_WhatsApp_Image_20250222_at_10313_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239377_WhatsApp_Image_20250222_at_10313_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db477",
  "name":
"externallmg_1740390239378_WhatsApp_Image_20250222_at_10343_PM_1.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239378_WhatsApp_Image_20250222_at_10343_PM_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db478",
  "name":
  "externallmg_1740390239394_WhatsApp_Image_20250222_at_10343_PM_2.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239394_WhatsApp_Image_20250222_at_10343_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db479",
  "name":
  "externallmg_1740390239401_WhatsApp_Image_20250222_at_10343_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239401_WhatsApp_Image_20250222_at_10343_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db47a",
  "name":
  "externallmg_1740390239437_WhatsApp_Image_20250222_at_10344_PM_1.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239437_WhatsApp_Image_20250222_at_10344_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f5f178be87ad41db47b",
  "name":
  "externallmg_1740390239460_WhatsApp_Image_20250222_at_10344_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390239460_WhatsApp_Image_20250222_at_10344_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f66178be87ad41db4be",
```

```
    "name":
"externallmg_1740390246079_WhatsApp_Image_20250222_at_10345_PM_1.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390246079_WhatsApp_Image_20250222_at_10345_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67bc3f66178be87ad41db4bf",
  "name":
"externallmg_1740390246084_WhatsApp_Image_20250222_at_10345_PM.jpeg",
  "path": "cases/67b96ad525e2779c6344796f/
externallmg_1740390246084_WhatsApp_Image_20250222_at_10345_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "1 Building Plan.pdf",
  "filename": "1740204827597_1_Building_Plan.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204827597_1_Building_Plan.pdf",
  "size": "581563",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
  "originalname": "1 Commencement Certificates.pdf",
  "filename": "1740204827709_1_Commencement_Certificates.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204827709_1_Commencement_Certificates.pdf",
  "size": "419261",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
  "originalname": "2 Building Plan.pdf",
  "filename": "1740204827738_2_Building_Plan.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204827738_2_Building_Plan.pdf",
  "size": "240857",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
}
```

```
{
  "originalname": "2 Commencement Certificate.pdf",
  "filename": "1740204827801_2_Commencement_Certificate.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204827801_2_Commencement_Certificate.pdf",
  "size": "438585",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
  "originalname": "4 Building Plan.pdf",
  "filename": "1740204827824_4_Building_Plan.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204827824_4_Building_Plan.pdf",
  "size": "842219",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
  "originalname": "5 Building Plan.pdf",
  "filename": "1740204827866_5_Building_Plan.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204827866_5_Building_Plan.pdf",
  "size": "791302",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
  "originalname": "6 Building Plan.pdf",
  "filename": "1740204828474_6_Building_Plan.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204828474_6_Building_Plan.pdf",
  "size": "516683",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
  "originalname": "7 Building Plan.pdf",
  "filename": "1740204828517_7_Building_Plan.pdf",
  "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204828517_7_Building_Plan.pdf",
  "size": "600606",
  "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "63f9ed37ce84bf289ba991ac"
},
{
```

```
    "originalname": "8 Building Plan.pdf",
    "filename": "1740204828598_8_Building_Plan.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204828598_8_Building_Plan.pdf",
    "size": "203284",
    "createdAt": "Sat Feb 22 2025 06:13:48 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "9 Building Plan.pdf",
    "filename": "1740204841773_9_Building_Plan.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204841773_9_Building_Plan.pdf",
    "size": "1024739",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "10 Building Plan.pdf",
    "filename": "1740204842519_10_Building_Plan.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204842519_10_Building_Plan.pdf",
    "size": "696062",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "11 Building Plan.pdf",
    "filename": "1740204842622_11_Building_Plan.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204842622_11_Building_Plan.pdf",
    "size": "495107",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "12 Building Plan.pdf",
    "filename": "1740204842662_12_Building_Plan.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204842662_12_Building_Plan.pdf",
    "size": "262384",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "13 Building Plan.pdf",
```

```
    "filename": "1740204842732_13_Building_Plan.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204842732_13_Building_Plan.pdf",
    "size": "742281",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "AGREEMENT OF SALE draft.pdf",
    "filename": "1740204842797_AGREEMENT_OF_SALE_draft.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204842797_AGREEMENT_OF_SALE_draft.pdf",
    "size": "445310",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "Architect's Certificate of Percentage of Completion of Wor.pdf",
    "filename":
"1740204842875_Architects_Certificate_of_Percentage_of_Completion_of_Wor.pdf",
    "path": "cases/67b96ad525e2779c6344796f/processingDocuments/1740204842875
_Architects_Certificate_of_Percentage_of_Completion_of_Wor.pdf",
    "size": "689269",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "CC 2.pdf",
    "filename": "1740204843128_CC_2.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204843128_CC_2.pdf",
    "size": "438585",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1740204843314_CC.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204843314_CC.pdf",
    "size": "419261",
    "createdAt": "Sat Feb 22 2025 06:14:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "Declaration about Commencement Certificate.pdf",
```



```
    "filename": "1740204850483_Declaration_about_Commencement_Certificate.pdf",
    "path": "cases/67b96ad525e2779c6344796f/processingDocuments/1740204850483
_Declaration_about_Commencement_Certificate.pdf",
    "size": "604035",
    "createdAt": "Sat Feb 22 2025 06:14:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "Engineers Certificate on Quality Assurance (Form 2A FY
2023-24).pdf",
    "filename": "1740204851062_Engineers_Certificate_on_Quality_Assurance_Form_
2A_FY_202324.pdf",
    "path": "cases/67b96ad525e2779c6344796f/processingDocuments/1740204851062
_Engineers_Certificate_on_Quality_Assurance_Form_2A_FY_202324.pdf",
    "size": "483582",
    "createdAt": "Sat Feb 22 2025 06:14:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "Layout.pdf",
    "filename": "1740204852465_Layout.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204852465_Layout.pdf",
    "size": "298285",
    "createdAt": "Sat Feb 22 2025 06:14:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "RC anandhan Complex.pdf",
    "filename": "1740204852694_RC_anandhan_Complex.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204852694_RC_anandhan_Complex.pdf",
    "size": "153600",
    "createdAt": "Sat Feb 22 2025 06:14:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "tsr.pdf",
    "filename": "1740204852863_tsr.pdf",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740204852863_tsr.pdf",
    "size": "437496",
    "createdAt": "Sat Feb 22 2025 06:14:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
```

```
    "originalname": "Capture.JPG",
    "filename": "1740208879199_Capture.JPG",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740208879199_Capture.JPG",
    "size": "74207",
    "createdAt": "Sat Feb 22 2025 07:21:19 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "igr.JPG",
    "filename": "1740208879236_igr.JPG",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740208879236_igr.JPG",
    "size": "66090",
    "createdAt": "Sat Feb 22 2025 07:21:19 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "listing 2.JPG",
    "filename": "1740208879291_listing_2.JPG",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740208879291_listing_2.JPG",
    "size": "74785",
    "createdAt": "Sat Feb 22 2025 07:21:19 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "listing 3.JPG",
    "filename": "1740208879346_listing_3.JPG",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740208879346_listing_3.JPG",
    "size": "73702",
    "createdAt": "Sat Feb 22 2025 07:21:19 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "listing.JPG",
    "filename": "1740208879386_listing.JPG",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740208879386_listing.JPG",
    "size": "59064",
    "createdAt": "Sat Feb 22 2025 07:21:19 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  },
  {
    "originalname": "Anandvan.xlsx",
```

```
    "filename": "1740390213239_Anandvan.xlsx",
    "path": "cases/67b96ad525e2779c6344796f/
processingDocuments/1740390213239_Anandvan.xlsx",
    "size": "3153684",
    "createdAt": "Mon Feb 24 2025 09:43:33 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f9ed37ce84bf289ba991ac"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "63f9ed37ce84bf289ba991ac",
      "role": "FRONTDESK",
      "firstName": "Rushikesh",
      "lastName": "Pingle",
      "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67bc3f229af7e67a8b91f0b9",
    "note": "EXCEL (Task Reopen)",
    "taskId": "67b96ade9abe929c64fd5022",
    "createdAt": "2025-02-24T09:42:58.424Z"
  }
],
"createdAt": "2025-02-22T06:12:37.128Z",
"updatedAt": "2025-02-24T09:44:06.267Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Anandvan Housing Complex",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9011076019"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			