

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6447c552d11ef125ab25ea51"
    },
    "firstName": "Gajendra",
    "type": "CREDITOFFICER",
    "_id": "6447c552d11ef125ab25ea53",
    "lastName": " Maheta",
    "mobileNo": "",
    "workMobileNo": "9978972670",
    "email": "ubin0550434@unionbank.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "5900"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6447c552d11ef125ab25ea51",
  "name": "Deepali Nagar Branch Nashik",
  "branchCode": "",
  "mobileNo": "2532321326\t",
  "alternateMobileNo": "",
  "email": "ubin0550434@unionbank.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Z P Colony 21 Shrode Complex, Charwak Chowk, indira nagar Nashik
Indira\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9f4adce84bf289ba9956e",
  "role": "FRONTDESK + ENGINEER",
  "firstName": "Swapnnil",
  "email": "waghswapnil309@gmail.com",
  "lastName": "Wagh",
  "mobileNo": "8237116625",
  "designation": "",
  "shortName": "SW",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "designation": "",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
```

```
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62724142afd7d55eddede405",
  "role": "FRONTDESK",
  "firstName": "Sanjay",
  "email": "sanjayrphadol@gmail.com",
  "lastName": "Phadol",
  "mobileNo": "9890380564",
  "designation": "",
  "shortName": "SP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62724142afd7d55eddede405/
profilePhoto_1689235732454_image.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
  "_id": "6084131a13f01f158c6ea1f4",
```

```
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.964783993506824",
  "longitude": "73.75269548538887"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.75269548538887,
    19.964783993506824
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "4/03/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ambad Khurd",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "27",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Manovas",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Ambad Link Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
```

```
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Dakshinmukhi Hanuman Temple",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "304/2/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```



```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422007",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    }
  },
}
```

```
    "privateCars": {
      "title": "Private Cars"
    }
  },
  "apfDetails": {
    "buildings": [],
    "compositions": []
  },
  "igrFinalRate": {
    "floorRatePercentage": "0.00"
  },
  "outgoingDetail": {
    "monthlyRent": ""
  },
  "siteMeasurement": {
    "isSiteVisitAllowed": true
  },
  "finalPlinthArea": {
    "area": "0.00"
  },
  "routeMap": {
    "routeMapDetail": {
      "routeMapImg": "",
      "routeLat": "",
      "routeLng": "",
      "stationName": "",
      "routeDistance": ""
    },
    "finalLatLng": {
      "coordinates": []
    },
    "locationMapImg": []
  },
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    }
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
}
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c5988ba1598804f8d58bcd",
```

```
"ownerName": "Shri. Anant Malhari Shinde",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Row House No. 1, Ground Floor, Manovas, Near
Dakshinmukhi Hanuman Temple, Plot No. 27, New/Current Survey No. 304/2/1, Ambad
Link Road, Village - Ambad Khurd, Taluka - Nashik, District - Nashik, Nashik, 422007",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741002869404_PERMISSION_MORTGAGE.pdf",
    "path": "cases/67c5988ba1598804f8d58bcd/
document_1741002869404_PERMISSION_MORTGAGE.pdf",
    "id": "998446",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Mon Mar 03 2025 11:54:51 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1741002873824_NASAN595832011.pdf",
    "path": "cases/67c5988ba1598804f8d58bcd/
document_1741002873824_NASAN595832011.pdf",
    "id": "313165",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Mon Mar 03 2025 11:54:51 GMT+0000 (Coordinated Universal Time)"
  },
  {

```

```
"documentType": {
  "value": "60ae124aaa6d152c1801b2f7",
  "label": "Any Other Document"
},
"attachConfig": {
  "fromPage": 0,
  "toPage": 0
},
"attachInReport": false,
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1741002881395_NASAN158512007.pdf",
"path": "cases/67c5988ba1598804f8d58bcd/
document_1741002881395_NASAN158512007.pdf",
"id": "137308",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Mon Mar 03 2025 11:54:51 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1741002889364_156586.pdf",
  "path": "cases/67c5988ba1598804f8d58bcd/
document_1741002889364_156586.pdf",
  "id": "913403",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Mon Mar 03 2025 11:54:51 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014648",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
```

```
    "id": "590476",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Mar 03 2025 11:54:51 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Shri. Anant Malhari Shinde",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "328692"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c6ca7a53081d47e3eee7ff",
    "name":
"externalImg_1741081209290_WhatsApp_Image_20250304_at_122149_PM.jpeg",
    "path": "cases/67c5988ba1598804f8d58bcd/
externalImg_1741081209290_WhatsApp_Image_20250304_at_122149_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c6ca7a53081d47e3eee800",
    "name":
"externalImg_1741081209406_WhatsApp_Image_20250304_at_122150_PM_1.jpeg",
    "path": "cases/67c5988ba1598804f8d58bcd/
externalImg_1741081209406_WhatsApp_Image_20250304_at_122150_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67c6ca7a53081d47e3eee801",
  "name":
"externallmg_1741081209508_WhatsApp_Image_20250304_at_122150_PM.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209508_WhatsApp_Image_20250304_at_122150_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee802",
  "name":
"externallmg_1741081209548_WhatsApp_Image_20250304_at_122151_PM_1.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209548_WhatsApp_Image_20250304_at_122151_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee803",
  "name":
"externallmg_1741081209564_WhatsApp_Image_20250304_at_122151_PM_2.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209564_WhatsApp_Image_20250304_at_122151_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee804",
  "name":
"externallmg_1741081209584_WhatsApp_Image_20250304_at_122151_PM_3.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209584_WhatsApp_Image_20250304_at_122151_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee805",
  "name":
"externallmg_1741081209590_WhatsApp_Image_20250304_at_122151_PM_4.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209590_WhatsApp_Image_20250304_at_122151_PM_4.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee806",
  "name":
  "externallmg_1741081209616_WhatsApp_Image_20250304_at_122151_PM_5.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209616_WhatsApp_Image_20250304_at_122151_PM_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee807",
  "name":
  "externallmg_1741081209663_WhatsApp_Image_20250304_at_122151_PM_6.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209663_WhatsApp_Image_20250304_at_122151_PM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee808",
  "name":
  "externallmg_1741081209713_WhatsApp_Image_20250304_at_122151_PM_7.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209713_WhatsApp_Image_20250304_at_122151_PM_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee809",
  "name":
  "externallmg_1741081209726_WhatsApp_Image_20250304_at_122151_PM_8.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209726_WhatsApp_Image_20250304_at_122151_PM_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee80a",
```

```
    "name":
"externallmg_1741081209737_WhatsApp_Image_20250304_at_122151_PM_9.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209737_WhatsApp_Image_20250304_at_122151_PM_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee80b",
  "name":
"externallmg_1741081209743_WhatsApp_Image_20250304_at_122151_PM_10.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209743_WhatsApp_Image_20250304_at_122151_PM_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee80c",
  "name":
"externallmg_1741081209989_WhatsApp_Image_20250304_at_122151_PM_11.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209989_WhatsApp_Image_20250304_at_122151_PM_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee80d",
  "name":
"externallmg_1741081209993_WhatsApp_Image_20250304_at_122151_PM_12.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209993_WhatsApp_Image_20250304_at_122151_PM_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee80e",
  "name":
"externallmg_1741081209995_WhatsApp_Image_20250304_at_122151_PM_13.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081209995_WhatsApp_Image_20250304_at_122151_PM_13.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee80f",
  "name":
"externallmg_1741081210017_WhatsApp_Image_20250304_at_122151_PM_14.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081210017_WhatsApp_Image_20250304_at_122151_PM_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee810",
  "name":
"externallmg_1741081210044_WhatsApp_Image_20250304_at_122151_PM_15.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081210044_WhatsApp_Image_20250304_at_122151_PM_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c6ca7a53081d47e3eee811",
  "name":
"externallmg_1741081210062_WhatsApp_Image_20250304_at_122151_PM.jpeg",
  "path": "cases/67c5988ba1598804f8d58bcd/
externallmg_1741081210062_WhatsApp_Image_20250304_at_122151_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-03-03T11:54:51.923Z",
"updatedAt": "2025-03-04T09:40:10.275Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "62724142afd7d55eddede405",
"contactPersonName": "Shri. Anant Malhari Shinde",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```



"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"rerald": "",  
"siteVisitContactNo": "0000000000"

}

| <b>Name</b> | <b>Length</b> | <b>Width</b> | <b>Total</b> |
|-------------|---------------|--------------|--------------|
|-------------|---------------|--------------|--------------|

---

Composition :

---

Other

Composition :

---