

```
{
  "typeOfReport": {
    "label": "Shop",
    "value": "Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba8e"
    },
    "firstName": "Pratibha BHatia",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942312a9",
    "email": "0_default_pratibha.bhatia@cosmosbank.in",
    "mobileNo": "0_DEFAULT_022-26762671",
    "workMobileNo": "0_DEFAULT_91-9820701094"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3752300",
    "discussWithPerson": "Pratibha BHatia",
    "expectedFees": 1876.15,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba8e",
  "branchCode": "000021",
  "type": "BRANCH",
  "name": "Veera Desai Road Andheri (West) Branch ",
  "email": "pratibha.bhatia@cosmosbank.in",
  "mobileNo": "02226762671",
  "alternateMobileNo": "02226762672",
  "address": "Shop no 7, Dhanashree Heights Building No 42, Off Veera Desai Road
Andheri (West) Mumbai 400053",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "67776d60a5477d50e7dbc213",
    "role": "SITEENGINEER+MAKAR+CHECKER",
    "firstName": "AJAY",
    "email": "ajayrewale503@gmail.com",
    "lastName": "REWALE",
    "mobileNo": "9766640171",
    "designation": "",
    "shortName": "AJAY",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/67776d60a5477d50e7dbc213/
profilePhoto_1739252394344_image.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.130979579963842",
```

```
"longitude": "72.83747819173203"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83747819173203,
    19.130979579963842
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "5/03/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
```

```
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "42",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "DHANA SHREE HEIGHTS",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Azad Nagar Sangam Co-operative Housing Society Limited",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Azad Nagar No.2 Veera Desai Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```

```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```



```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "05",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400053",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri west",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
```



```
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67c836ddd63c0e928fbbb58d",
"ownerName": "MRS.GEETIKA HARKISHIN VASWANI, MR.HARKISHIN HARNAM
VASWANI",
"ownerPhoneNo": "8779386284",
"appAddress": "Dhana Shree Heights Shop No 5 Ground floor Azad Nagar Sangam
Co-op HSG Soc Ltd Bldg no 42 Azad nagar no 2 Veera Desai Road Andheri West
Mumbai 400053",
"remark": "Contact Danish ",
"documents": [
  {
    "documentType": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    }
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  }
}
```

```
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741174476339_1741174474042_Shop_Agreement_Andheri.docx",
    "fileName":
"document_1741174476339_1741174474042_Shop_Agreement_Andheri.docx",
    "id": "605320",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 05 2025 11:34:53 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Index - II (1 Page from agreement)",
      "value": "60ae1256aa6d152c1801b331"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741174935011_202528.pdf",
    "fileName": "document_1741174935011_202528.pdf",
    "id": "624926",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Full Occupation Certificate",
      "value": "60ae1258aa6d152c1801b337"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741174953971_207406.pdf",
    "fileName": "document_1741174953971_207406.pdf",
```

```
"id": "798846",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Maintenance Bill",
    "value": "60ae125eaa6d152c1801b353"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741174974165_80805.pdf",
  "fileName": "document_1741174974165_80805.pdf",
  "id": "174379",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Builder Allotment Lette",
    "value": "60ae1275aa6d152c1801b3c0"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741175167375_1741175165320_DOC062.pdf",
  "fileName": "document_1741175167375_1741175165320_DOC062.pdf",
  "id": "177364",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Agreement for Development",
    "value": "60ae128daa6d152c1801b42d"
```

```
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741175366379_1741175364437_DOC064.pdf",
    "fileName": "document_1741175366379_1741175364437_DOC064.pdf",
    "id": "241548",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Commencement Certificate",
      "value": "60ae1247aa6d152c1801b2ea"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741175512148_1741175510100_DOC056.pdf",
    "fileName": "document_1741175512148_1741175510100_DOC056.pdf",
    "id": "156864",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "attachConfig": {
      "fromPage": 0,
      "toPage": 0
    },
    "attachInReport": false,
    "isHardCopy": false,
    "displayStatus": false,
```



```
"documentType": {
  "label": "Deed of Sale",
  "value": "60ae125baa6d152c1801b345"
},
"attachConfig": {
  "fromPage": 0,
  "toPage": 0
},
"attachInReport": false,
"isHardCopy": false,
"displayStatus": false,
"path": "cases/67c836ddd63c0e928fbbb58d/
document_1741176069089_1741176066712_DOC060.pdf",
"fileName": "document_1741176069089_1741176066712_DOC060.pdf",
"id": "801818",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Lease Deed",
    "value": "60ae1247aa6d152c1801b2eb"
  },
  "attachConfig": {
    "fromPage": 0,
    "toPage": 0
  },
  "attachInReport": false,
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67c836ddd63c0e928fbbb58d/
document_1741176142797_1741176140677_DOC061.pdf",
  "fileName": "document_1741176142797_1741176140677_DOC061.pdf",
  "id": "731770",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Wed Mar 05 2025 12:03:01 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "014706",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "298851",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Mar 05 2025 11:34:53 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "MRS.GEETIKA HARKISHIN VASWANI, MR.HARKISHIN HARNAM
VASWANI",
    "phone": "8779386284",
    "ownershipShare": "",
    "email": "",
    "id": "120512"
  }
],
"proposePurchasers": [
  {
    "name": "MR. SHAHNAWAZ LIYAKAT ALI, MR. DANISH AKHLAQ, SAHIL
AALAM,MO. SHADAN LIYAKAT ALI "
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0678",
    "name": "externalImg_1741284564342_1741284561735_image_0.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externalImg_1741284564342_1741284561735_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0679",
    "name": "externalImg_1741284565070_1741284561735_image_1.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externalImg_1741284565070_1741284561735_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67c9e4ea021414d63cde067a",
  "name": "externallmg_1741284566165_1741284561735_image_2.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284566165_1741284561735_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c9e4ea021414d63cde067b",
  "name": "externallmg_1741284567121_1741284561735_image_3.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284567121_1741284561735_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c9e4ea021414d63cde067c",
  "name": "externallmg_1741284567920_1741284561735_image_4.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284567920_1741284561735_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c9e4ea021414d63cde067d",
  "name": "externallmg_1741284568370_1741284561735_image_5.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284568370_1741284561735_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67c9e4ea021414d63cde067e",
  "name": "externallmg_1741284568998_1741284561735_image_6.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284568998_1741284561735_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```



```
    "_id": "67c9e4ea021414d63cde067f",
    "name": "externallmg_1741284569564_1741284561735_image_7.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284569564_1741284561735_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0680",
    "name": "externallmg_1741284570100_1741284561735_image_8.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284570100_1741284561735_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0681",
    "name": "externallmg_1741284571034_1741284561735_image_9.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284571034_1741284561735_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0682",
    "name": "externallmg_1741284571579_1741284561735_image_10.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284571579_1741284561735_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0683",
    "name": "externallmg_1741284571894_1741284561735_image_11.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284571894_1741284561735_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0684",
```

```
    "name": "externallmg_1741284572870_1741284561735_image_12.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284572870_1741284561735_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0685",
    "name": "externallmg_1741284574074_1741284561735_image_13.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284574074_1741284561735_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0686",
    "name": "externallmg_1741284575120_1741284561735_image_14.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284575120_1741284561735_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0687",
    "name": "externallmg_1741284576019_1741284561735_image_15.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284576019_1741284561735_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0688",
    "name": "externallmg_1741284576825_1741284561735_image_16.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284576825_1741284561735_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde0689",
    "name": "externallmg_1741284578948_1741284561735_image_17.jpeg",
```

```
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284578948_1741284561735_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde068a",
    "name": "externallmg_1741284583355_1741284561735_image_18.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284583355_1741284561735_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67c9e4ea021414d63cde068b",
    "name": "externallmg_1741284585055_1741284561735_image_19.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284585055_1741284561735_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c9e502021414d63cde06b6",
    "name": "externallmg_1741284589950_1741284588769_image_0.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284589950_1741284588769_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c9e502021414d63cde06b7",
    "name": "externallmg_1741284597574_1741284588769_image_1.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284597574_1741284588769_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67c9e502021414d63cde06b8",
    "name": "externallmg_1741284600554_1741284588769_image_2.jpeg",
    "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284600554_1741284588769_image_2.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c9e502021414d63cde06b9",
  "name": "externallmg_1741284600965_1741284588769_image_3.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284600965_1741284588769_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c9e502021414d63cde06ba",
  "name": "externallmg_1741284603805_1741284588769_image_4.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284603805_1741284588769_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c9e502021414d63cde06bb",
  "name": "externallmg_1741284605564_1741284588769_image_5.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741284605564_1741284588769_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c9ec3f021414d63cde07b5",
  "name": "externallmg_1741286429526_1741286424078_image_0.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741286429526_1741286424078_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67c9ec3f021414d63cde07b6",
  "name": "externallmg_1741286442294_1741286424078_image_1.jpeg",
  "path": "cases/67c836ddd63c0e928fbbb58d/
externallmg_1741286442294_1741286424078_image_1.jpeg",
  "orientation": "portrait"
}
```

```

    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2025-03-05T11:34:53.962Z",
  "updatedAt": "2025-03-06T18:41:03.875Z",
  "__v": 0,
  "uniqueNo": "",
  "updatedBy": "67776d60a5477d50e7dbc213",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  },
  "fullAddress": "Residential Shop No. 05, Ground Floor, Building No 42, DHANA SHREE HEIGHTS, Azad Nagar Sangam Co-operative Housing Society Limited, Azad Nagar No.2 Veera Desai Road, Andheri west, Mumbai, 400053, State - Maharashtra, India",
  "addressForMap": "",
  "caseReferredBy": "60af6ae22ffdf65bcd65861d",
  "contactPersonName": "MRS.GEETIKA HARKISHIN VASWANI, MR.HARKISHIN HARNAM VASWANI",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "MR. SHAHNAWAZ LIYAKAT ALI, MR. DANISH AKHLAQ, SAHIL AALAM,MO. SHADAN LIYAKAT ALI ",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "reald": "",
  "siteVisitContactNo": "8779386284"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			