

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7f9"
    },
    "type": "CREDITOFFICER",
    "_id": "640ace424dda382753e5057d",
    "firstName": "Rajeev kumar Ranjan",
    "lastName": "Ranjan",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "Rajeevracpc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "19500000",
    "discussWithPerson": "Rajeev kumar Ranjan",
    "expectedFees": 9750,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,
    }
  }
}
```

```
"duration": "300"
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "641d94b129e5586db05f0dc4",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7f9",
  "branchCode": "000066",
  "type": "BRANCH",
  "name": "RACPC Borivali (West) Branch",
  "email": "racpc.borivali@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "MTNL Building, Devidas Road, Borivali (West), Mumbai, State -
```

```
Maharashtra, Country - India. ",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {
```

```
"type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": ""
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": 19.213942445101164,
  "longitude": 72.8728482089047
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-03-25T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-03-25T09:04:42.188Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-03-25T09:04:42.188Z"
    }
  ]
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Sat Mar 25 2023 11:13:33 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Evershine Crown\t",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Evershine Millenium Paradise, Thakur Village\t",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
```



```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Evershine Crown CHSL",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```

```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "903t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali East",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood",
    "value": "TeakWood"
  },
  "windows": {
    "label": "Aluminium Sliding",
    "value": "Alluminum_Sliding_Windows"
  },
  "fittings": {
```

```
"label": "Concealed plumbing with C.P. fittings. Concealed Electrical wiring",
"value": "Concealed_plumbing_with_C.P._fittings._Concealed_Electrical_wiring"
},
"finishing": {
  "label": "Cement Plastering + POP Finish",
  "value": "Cement_Plastering+_POP_Finish"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "asPerActualAgreement": {
    "north": "Thakur Village Road",
    "west": "120Ft Road",
    "south": "Eversine Millenium ",
    "east": "Evershine Moon"
  },
  "asPerDocumentAgreement": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  }
}
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Medium",
    "value": "Medium"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Owner Occupied",
    "value": "Owner_Occupied"
  }
}
```

```
},
"monthlyRent": "",
},
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "Yes",
    "value": "Yes"
  },
  "carParking": {
    "label": "Basement + Open Parking",
    "value": "Basement+_Open_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2019",
    "fullDate": "1/1/2019"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed Structure",
    "value": "R.C.C._Framed_Structure"
  },
  "qualityOfConstruction": {
    "label": "Good",
    "value": "Good"
  },
}
```

```
"walls": {
  "label": "Yes",
  "value": "1"
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "56",
"ageOfBuilding": "4",
"noOfBasement": "2",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"noOfFloors": "28",
"flatFloorNo": "",
"noOfLifts": "3",
"noOfLiftsInEachWings": "0",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```



```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "641d94b129e5586db05f0dc3",
"ownerName": "Abhishek Pankaj Barot\t",
"ownerPhoneNo": "9028506204",
"appAddress": "Flat no A/903,Evershine Crown Thakur village Kandivali East ",
"remark": "7718949688 (Tekeover cesa)",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/641d94b129e5586db05f0dc3/
document_1679660141931_Abhishek_Borat_SBI_Racpc_Borivali_East.pdf",
    "fileName":
"document_1679660141931_Abhishek_Borat_SBI_Racpc_Borivali_East.pdf",
    "displayStatus": false,
    "id": "335998",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Fri Mar 24 2023 17:46:46 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "000898",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "928409",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 24 2023 17:46:49 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Abhishek Pankaj Barot\t",
    "phone": "9028506204",
    "ownershipShare": "",
    "email": "",
    "id": "178598"
  }
],
"siteInspection": [
  {
```

```
"areaType": {
  "label": "Carpet",
  "value": "Carpet"
},
"providedBy": {
  "label": "Other",
  "value": "Other"
},
"_id": "641eb96051c1d641cf94c34d",
"area": "800.98",
"providedByName": "Site Measurement ",
"providedByContactNo": "0000000000"
},
],
"composition": [
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "910584",
    "name": "Living Room",
    "length": "18.50",
    "length1": "18",
    "length2": "6",
    "width": "10.17",
    "width1": "10",
    "width2": "2",
    "totalArea": "188.08",
    "images": [
      {
        "name": "compositionImg_r_1679734493006_image.jpg",
        "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734493006_image.jpg",
        "orientation": "portrait"
      }
    ],
    "extraAreas": [],
    "finalArea": "188.08"
  },
  {
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
```

```
"name": "Dining",
"length": "12.67",
"length1": "12",
"length2": "8",
"width": "3.83",
"width1": "3",
"width2": "10",
"totalArea": "48.56",
"images": [
  {
    "name": "compositionImg_r_1679734531380_image.jpg",
    "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734531380_image.jpg",
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "48.56"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "9.92",
  "length1": "9",
  "length2": "11",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "77.68",
  "images": [
    {
      "name": "compositionImg_r_1679734567999_image.jpg",
      "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734567999_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "77.68"
},
{
  "measurementType": {
```

```
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "3",
  "name": "Dry Balcony",
  "length": "6.75",
  "length1": "6",
  "length2": "9",
  "width": "4.83",
  "width1": "4",
  "width2": "10",
  "totalArea": "32.62",
  "images": [
    {
      "name": "compositionImg_r_1679734608794_image.jpg",
      "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734608794_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "32.62"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "4",
  "name": "Study Room",
  "length": "10.17",
  "length1": "10",
  "length2": "2",
  "width": "8.42",
  "width1": "8",
  "width2": "5",
  "totalArea": "85.57",
  "images": [
    {
      "name": "compositionImg_r_1679734660628_image.jpg",
      "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734660628_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
```

```
"finalArea": "85.57"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "12.58",
  "length1": "12",
  "length2": "7",
  "width": "9.83",
  "width1": "9",
  "width2": "10",
  "totalArea": "123.74",
  "images": [
    {
      "name": "compositionImg_r_1679734706424_image.jpg",
      "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734706424_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "123.74"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "13.33",
  "length1": "13",
  "length2": "4",
  "width": "10.42",
  "width1": "10",
  "width2": "5",
  "totalArea": "138.89",
  "images": [
    {
      "name": "compositionImg_r_1679734746924_image.jpg",
      "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734746924_image.jpg",
```

```
    "orientation": "portrait"
  }
],
"extraAreas": [],
"finalArea": "138.89"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "7",
  "name": "Toilet",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "32.29",
  "images": [
    {
      "name": "compositionImg_r_1679734875533_image.jpg",
      "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734875533_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "finalArea": "32.29"
},
{
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "29.39",
  "images": [
```

```
{
  "name": "compositionImg_r_1679734920770_image.jpg",
  "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734920770_image.jpg",
  "orientation": "portrait"
}
],
"extraAreas": [],
"finalArea": "29.39"
}
],
"otherComposition": [
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  },
  "measurementType": {
    "label": "Square Feet",
    "value": "Square_Feet"
  },
  "id": "0",
  "length1": "9",
  "length2": "5",
  "length": "9.42",
  "width1": "3",
  "width2": "10",
  "width": "3.83",
  "totalArea": "36.10",
  "percentageBeforeTotal": "36.10",
  "images": [
    {
      "name": "compositionImg_r_1679734998332_image.jpg",
      "path": "cases/641d94b129e5586db05f0dc3/
compositionImg_r_1679734998332_image.jpg",
      "orientation": "portrait"
    }
  ],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "36.1"
},
{
  "name": {
    "label": "Passage",
    "value": "Passage"
  }
}
```



```
    },
    "measurementType": {
      "label": "Square Feet",
      "value": "Square_Feet"
    },
    "id": "1",
    "length1": "3",
    "length2": "10",
    "length": "3.83",
    "width1": "2",
    "width2": "11",
    "width": "2.92",
    "totalArea": "11.18",
    "percentageBeforeTotal": "11.18",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "11.18"
  }
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "status": false,
    "_id": "641eb55b51c1d641cf94bed7",
    "path": "cases/641d94b129e5586db05f0dc3/
externallmg_r_1679734088397_1679733936158_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "641eb55b51c1d641cf94bed8",
    "path": "cases/641d94b129e5586db05f0dc3/
externallmg_r_1679734090363_1679733936158_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "641eb55b51c1d641cf94bed9",
    "path": "cases/641d94b129e5586db05f0dc3/
externallmg_r_1679734091689_1679733936158_image_2.jpg",
    "orientation": "portrait"
  },
]
```

```
{
  "status": false,
  "_id": "641eb55b51c1d641cf94beda",
  "path": "cases/641d94b129e5586db05f0dc3/
externallmg_r_1679734092870_1679733936158_image_3.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "641eb55b51c1d641cf94bedb",
  "path": "cases/641d94b129e5586db05f0dc3/
externallmg_r_1679734097018_1679733936158_image_6.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "641eb55b51c1d641cf94bedc",
  "path": "cases/641d94b129e5586db05f0dc3/
externallmg_r_1679734095364_1679733936158_image_5.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "641eb55b51c1d641cf94bedd",
  "path": "cases/641d94b129e5586db05f0dc3/
externallmg_r_1679734094214_1679733936158_image_4.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-03-24T12:16:49.638Z",
"updatedAt": "2023-03-25T09:07:40.945Z",
"__v": 0,
"updatedBy": "627208c1afd7d55eddedc372",
"fullAddress": "Residential Flat No. 903\t, 9th Floor, Wing - A, Evershine Crown\t,
Evershine Crown CHSL, Evershine Millenium Paradise, Thakur Village\t, Kandivali
East, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Abhishek Pankaj Barot\t",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9028506204",
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + Dry Balcony + Study Room + 2 Toilet",
 "carpetTotal": "756.8199999999999",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "47.28",
 "siteVisitDate": "2023-03-25"

}

Name	Length	Width	Total
Composition :			
Living Room	18'6"	10'2"	188.08
Dining	12'8"	3'10"	48.56
Kitchen	9'11"	7'10"	77.68
Dry Balcony	6'9"	4'10"	32.62
Study Room	10'2"	8'5"	85.57
Bedroom	12'7"	9'10"	123.74
Bedroom	13'4"	10'5"	138.89
Toilet	7'9"	4'2"	32.29
Toilet	7'8"	3'10"	29.39
Other Composition :			
Passage	9'5"	3'10"	36.10
Passage	3'10"	2'11"	11.18