

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7d6"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b942311e3",
    "firstName": "Kedar Pujari",
    "email": "0_DEFAULT_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9423154330"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "NITIN",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
  "organization": {
    "package": {
      "_id": "5fc0d7e47d6c8d39dc34a294",
      "title": "basic",
      "price": 5.1,
      "case": 20,
      "duration": "300"
    }
  }
}
```

```
},
"status": true,
"isdelete": false,
"_id": "5f2bdee67813470eb443deb4",
"name": "Vastukala Consultants India Pvt. Ltd.",
"gstNo": "18AABCT3518Q1ZZ",
"panNo": "ABCDE1234A",
"freeCases": "10",
"email": "vastukalamumbai@vastukala.com",
"phone": "9819670183",
"address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai -
400 093",
"remark": "",
"theme": "DEFAULT",
"profilePhoto": "public\\images\\
\\1606738172464_51041525c82381638d4d202735b1f05d.png",
"shortName": "VCIPL",
"waterMarkImage": [
  {
    "_id": "642e492c91d7c62df11e110a",
    "path": "public\\Vastukala Letter head H 2019.jpg",
    "pageNo": "2"
  }
],
"city": "Mumbai",
"stampImage": []
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7d6",
  "branchCode": "000030",
  "type": "BRANCH",
  "name": "SMECCC Bandra (East)",
  "email": "secc.mum@sbi.co.in",
  "mobileNo": "022-26591641 / 46",
  "alternateMobileNo": "",
  "address": "Small & Medium Enterprises City Credit Centre, Jasmin Co. Op. Hsg.
Society, Madhusudan Kalekar Marg, Kalanagar, Bandra (East), Mumbai - 400 051,
```

```

State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA-JASMIN",
  "fax": "022-26591648 / 50",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "DELIVERYPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
    "shortName": "RP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627208c1afd7d55eddedc372",
    "role": "FRONTDESK",
    "firstName": "Aniket",
    "email": "Aniket@vastukala.org",
    "lastName": "Navale",
    "mobileNo": "9892222307",
    "designation": "",
    "shortName": "AN",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627208c1afd7d55eddedc372/
profilePhoto_1667995077581_WhatsApp_Image_20221109_at_52453_PM.jpeg"
  },
  "rateVerifier": {

```

```
"type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "642bad2b91d7c62df117fef2",
  "role": "MAKER",
  "firstName": "Abhishek",
  "email": "abhishekharijan@gmail.com",
  "lastName": "Harijan",
  "mobileNo": "8369839430",
  "designation": "",
  "shortName": "AH",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "CAT-I-A-812",
        "label": "The Indian Institution of Valuers (India)"
      }
    ]
  }
]
```

```
],
  "type": "EMPLOYEE",
  "_id": "60b49ad42ffdf65bcd658828",
  "PANNo": "AHFPC0271K",
  "role": "VALUER",
  "firstName": "Shashikant",
  "fatherName": "Baburao",
  "email": "shashikant@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9167204062",
  "designation": "Valuer",
  "registrationNo": [
    {
      "title": {
        "value": "The_Indian_Institution_of_Valuers_(India)",
        "label": "The Indian Institution of Valuers (India)"
      },
      "_id": "60b49ad42ffdf65bcd658829",
      "number": "CAT-I-A-812"
    }
  ],
  "shortName": "shashi",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b49ad42ffdf65bcd658828\\
\\profilePhoto_1623044018456_Shashilant Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.19989197539997",
  "longitude": "72.87460671349402"
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-04-06T03:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-04-06T03:30:00.000Z",
      "remark": "Vikas arora\t 9769579090\n"
    }
  ]
}
```

```
    }
  ],
  "visitedDate": [],
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu Apr 06 2023 10:23:49 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "12\t",
    "label": true
  },
  "district": {
```

```
"status": false,
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Lokhandwala Township\t",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Ackurli ROad",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "Senate Building NO 12 CHSL\t",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "404t",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandlivali (East)t",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
}
```

```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"createCase": "false",
"type": "CASE",
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"_id": "642e492c91d7c62df11e1109",
"ownerName": "Rinku Batra",
"ownerPhoneNo": "9769579090",
"appAddress": "flat no - 404, 4th floor, A wing, bldg no - 12, senate Co. Op .hsg. soc. ltd, plot no - C, , sect - 2, lokhandwala township, kandivali east ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ee",
      "label": "Previous Valuation Report"
    },
    "inputs": {
      "documentDate": "30/09/2020"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1680756817055_Valuation_Report_Rinku__1_doc.pdf",
    "path": "cases/642e492c91d7c62df11e1109/document_1680756817055_Valuation_Report_Rinku__1_doc.pdf",
    "id": "759319",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Thu Apr 06 2023 10:23:44 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "001025",
```

```
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "677360",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Apr 06 2023 09:53:08 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rinku Batra",
    "phone": "9769579090",
    "ownershipShare": "",
    "email": "",
    "id": "280741"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [],
"externalDocuments": [],
"createdAt": "2023-04-06T04:23:08.877Z",
"updatedAt": "2023-04-06T05:51:31.652Z",
"__v": 0,
"fullAddress": "Residential Flat No. 404\t, 4th Floor, Building No 12\t, Wing - Senate
Building NO 12 CHSL\t, Lokhandwala Township\t, Ackurli ROad, Kandlivali (East)\t,
State - Maharashtra, India",
"updatedBy": "627208c1afd7d55eddedc372",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Rinku Batra",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9769579090"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			