

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba8e"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418fd",
    "email": "rajendra.warekar@cosmosbank.in",
    "firstName": "Shruti Rao",
    "mobileNo": "9930040275",
    "workMobileNo": "9930040275",
    "lastName": "Rao"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "1189000",
    "discussWithPerson": "Shruti Rao",
    "expectedFees": 594.5,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  }
}
```

```
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba8e",
  "branchCode": "000021",
  "type": "BRANCH",
  "name": "Veera Desai Road Andheri (West) Branch ",
  "email": "pratibha.bhatia@cosmosbank.in",
  "mobileNo": "02226762671",
  "alternateMobileNo": "02226762672",
  "address": "Shop no 7, Dhanashree Heights Building No 42, Off Veera Desai Road
Andheri (West) Mumbai 400053",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
```

```
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
```

```
"_id": "60f915d3f3dd69653a592199",
"role": "CHECKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    }
  ],
  {
    "title": {
```

```
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.437587319688912",
  "longitude": "72.81809463240191"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81809463240191,
    19.437587319688912
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-05-11T05:30:00.000Z",
      "remark": ""
    }
  ]
},
```

```
{
  "dateTime": "2023-05-11T05:30:00.000Z",
  "remark": ""
}
],
"visitedDate": [
  {
    "remark": "MANUAL",
    "status": "COMPLETED",
    "dateTime": "2023-05-13T10:00:00.000Z"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Thu May 11 2023 11:51:06 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "More",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
}
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ostwal Nagari Bldg No 19-20-21 CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```



```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
```

```
"status": false,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
```

```
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nalasopara East",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```



```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "645c86ba7f94762ec7881fef",
"ownerName": "Satej SUryakant Kasale",
"ownerPhoneNo": "9768665557",
"appAddress": "Flat no.103, Ostwal Nagari Bldg no . 19/20/21,CHSL, Village - More,
Nalasopara East -401209",
"remark": "visit time Engg ko bolo jagdish sir Approved Plan copy ka photo leneko ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/645c86ba7f94762ec7881fef/
document_1683784912465_Setej_Kalase_.pdf",
    "fileName": "document_1683784912465_Setej_Kalase_.pdf",
    "displayStatus": false,
    "id": "415059",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Thu May 11 2023 11:39:54 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Conveyance Deed",
      "value": "60ae1252aa6d152c1801b31f"
    },
    "isHardCopy": false,
    "path": "cases/645c86ba7f94762ec7881fef/
document_1683785015282_conveyance_deed_bldg_Setej_Kalase.pdf",
    "fileName":
"document_1683785015282_conveyance_deed_bldg_Setej_Kalase.pdf",
```

```
"displayStatus": false,
"id": "985793",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Thu May 11 2023 11:39:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "path": "cases/645c86ba7f94762ec7881fef/
document_1683785384233_Setej_Kasale_documents.pdf",
  "fileName": "document_1683785384233_Setej_Kasale_documents.pdf",
  "displayStatus": false,
  "id": "170527",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Thu May 11 2023 11:39:54 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001524",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "555445",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu May 11 2023 11:40:02 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Satej SUryakant Kasale",
    "phone": "9768665557",
    "ownershipShare": "",
    "email": "",
    "id": "610854"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734c3",
    "name":
"externalImg_1684121965083_WhatsApp_Image_20230513_at_92538_PM_1.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externalImg_1684121965083_WhatsApp_Image_20230513_at_92538_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734c4",
    "name":
"externalImg_1684121965085_WhatsApp_Image_20230513_at_92538_PM.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externalImg_1684121965085_WhatsApp_Image_20230513_at_92538_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734c5",
    "name":
"externalImg_1684121965096_WhatsApp_Image_20230513_at_92539_PM_1.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externalImg_1684121965096_WhatsApp_Image_20230513_at_92539_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734c6",
    "name":
"externalImg_1684121965110_WhatsApp_Image_20230513_at_92539_PM.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externalImg_1684121965110_WhatsApp_Image_20230513_at_92539_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734c7",
    "name":
"externalImg_1684121965129_WhatsApp_Image_20230513_at_92540_PM_1.jpeg",
```

```
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121965129_WhatsApp_Image_20230513_at_92540_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734c8",
    "name":
"externallmg_1684121965146_WhatsApp_Image_20230513_at_92540_PM_2.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121965146_WhatsApp_Image_20230513_at_92540_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734c9",
    "name":
"externallmg_1684121965162_WhatsApp_Image_20230513_at_92540_PM.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121965162_WhatsApp_Image_20230513_at_92540_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734ca",
    "name":
"externallmg_1684121965176_WhatsApp_Image_20230513_at_92541_PM_1.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121965176_WhatsApp_Image_20230513_at_92541_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a96dee6a9735bf7734cb",
    "name":
"externallmg_1684121965184_WhatsApp_Image_20230513_at_92541_PM.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121965184_WhatsApp_Image_20230513_at_92541_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6461a96dee6a9735bf7734cc",
  "name":
"externallmg_1684121965201_WhatsApp_Image_20230513_at_92542_PM_1.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121965201_WhatsApp_Image_20230513_at_92542_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773504",
  "name":
"externallmg_1684121986423_WhatsApp_Image_20230513_at_92542_PM.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986423_WhatsApp_Image_20230513_at_92542_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773505",
  "name":
"externallmg_1684121986427_WhatsApp_Image_20230513_at_92543_PM_1.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986427_WhatsApp_Image_20230513_at_92543_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773506",
  "name":
"externallmg_1684121986439_WhatsApp_Image_20230513_at_92543_PM_2.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986439_WhatsApp_Image_20230513_at_92543_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773507",
  "name":
"externallmg_1684121986450_WhatsApp_Image_20230513_at_92543_PM.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986450_WhatsApp_Image_20230513_at_92543_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a983ee6a9735bf773508",
    "name":
"externallmg_1684121986456_WhatsApp_Image_20230513_at_92544_PM_1.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986456_WhatsApp_Image_20230513_at_92544_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a983ee6a9735bf773509",
    "name":
"externallmg_1684121986464_WhatsApp_Image_20230513_at_92544_PM.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986464_WhatsApp_Image_20230513_at_92544_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a983ee6a9735bf77350a",
    "name":
"externallmg_1684121986479_WhatsApp_Image_20230513_at_92545_PM_1.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986479_WhatsApp_Image_20230513_at_92545_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a983ee6a9735bf77350b",
    "name":
"externallmg_1684121986488_WhatsApp_Image_20230513_at_92545_PM_2.jpeg",
    "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986488_WhatsApp_Image_20230513_at_92545_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6461a983ee6a9735bf77350c",
```

```
"name":
"externallmg_1684121986499_WhatsApp_Image_20230513_at_92545_PM.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986499_WhatsApp_Image_20230513_at_92545_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf77350d",
  "name":
"externallmg_1684121986508_WhatsApp_Image_20230513_at_92546_PM_1.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986508_WhatsApp_Image_20230513_at_92546_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf77350e",
  "name":
"externallmg_1684121986517_WhatsApp_Image_20230513_at_92546_PM.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986517_WhatsApp_Image_20230513_at_92546_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf77350f",
  "name":
"externallmg_1684121986526_WhatsApp_Image_20230513_at_92547_PM_1.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986526_WhatsApp_Image_20230513_at_92547_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773510",
  "name":
"externallmg_1684121986537_WhatsApp_Image_20230513_at_92547_PM_2.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986537_WhatsApp_Image_20230513_at_92547_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773511",
  "name":
"externallmg_1684121986548_WhatsApp_Image_20230513_at_92547_PM.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986548_WhatsApp_Image_20230513_at_92547_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773512",
  "name":
"externallmg_1684121986555_WhatsApp_Image_20230513_at_92642_PM.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986555_WhatsApp_Image_20230513_at_92642_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6461a983ee6a9735bf773513",
  "name":
"externallmg_1684121986566_WhatsApp_Image_20230513_at_92810_PM.jpeg",
  "path": "cases/645c86ba7f94762ec7881fef/
externallmg_1684121986566_WhatsApp_Image_20230513_at_92810_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-05-11T06:10:02.769Z",
"updatedAt": "2023-05-15T03:39:55.734Z",
"__v": 0,
"fullAddress": "Residential Flat No. 103, 1st Floor, Ostwal Nagari Bldg No 19-20-21
CHSL, Village - More, Nalasopara East, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Satej SURyakant Kasale",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": ""
```


"relationWithOwner": "self",
"siteVisitContactNo": "9768665557",
"reason": ""

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			