

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb60"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b9423133d",
    "firstName": "Jagruti Raut",
    "email": "0_default_jagruti.raut@janasevabank.in\t",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9702043605"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2200000",
    "discussWithPerson": "Jagruti Raut",
    "expectedFees": 1100,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "email": "info@vastukala.org",
    "address": "121, 1st Floor, Ackruti Star, Central Road, MIDC, Andheri (E), Mumbai",
    "city": "Mumbai"
  },
}
```

```
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb60",
  "branchCode": "0000010",
  "type": "BRANCH",
  "name": "Bhaynder (East) Brtanch",
  "email": "jagruti.raut@janasevabank.in",
  "mobileNo": "02228171617",
  "alternateMobileNo": "02228171618",
  "address": "Janki Avanie 1st floor, phatak road, Bhaynder East Thane-401105",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
    "role": "PICKUPPERSON",
    "firstName": "Mangesh ",
    "email": "mangeshpalande17@gmail.com",
    "lastName": "Palande",
    "mobileNo": "9833030550",
    "shortName": "MP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
```

```
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
  "shortName": "SB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER+CHECKER",
  "firstName": "Shobha",
```

```
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
    },
  ],
}
```

```
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.415732",
  "longitude": "72.821530"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82153,
    19.415732
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "2023-06-14T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-06-14T10:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    },
    {
      "dateTime": "2023-06-14T10:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": [
    {
      "remark": "MANUAL",
      "status": "COMPLETED",
      "dateTime": "2023-06-15T07:00:00.000Z"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"verifiedDocument": {
  "value": true,
  "remark": "",
  "dateTime": "Wed Jun 14 2023 16:45:14 GMT+0530 (India Standard Time)"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Achole",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nallasopara (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Tania Empire (Freny Glory)",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shiv Sahyadri Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "139",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "105",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "401 209",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "CeramicTileFlooring",
    "label": "Ceramic Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring",
    "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring"
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  }
}
```

```
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "CIDCO",
  "label": "CIDCO"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road & Sahara Apartment",
  "west": "Sunshine Heights",
  "south": "Garden ",
  "east": "Internal Road & Laxman Paradise Building"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"extraDetailOfProperty": ""
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "34.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "5637.5",
  "depreciatedBuildingRate": "1637.5"
},
"igrRate": {
  "propertyName": "Achole Village",
  "rate": "60400",
  "landRate": "20000",
  "igrImage": "cases/648967ea171a1a25b984a7c6/igr_1686890469140_Image.png",
  "squareMeterGuideLineRate": "57380.00",
  "squareFeetGuideLineRate": "5331.00"
```

```
},
"igrFinalRate": {
  "rate": "4532.00",
  "squareFeetGuideLineRate": "4532.00",
  "squareMeterGuideLineRate": "48783.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "5,500.00",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per CIDCO norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\\_Thk._Brick_Masonry",
    "label": "6\\ Thk. Brick Masonery"
  }
}
```

```
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": {
  "value": "Open_Car_Parking",
  "label": "Open Car Parking"
},
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2000",
  "fullDate": "1/1/2000"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"groundStilt": {
```

```
    "value": "ground",
    "label": "Ground"
  },
  "yearOfConstructionAsPer": {
    "value": "as_per_occupancy_certificate",
    "label": "As per occupancy certificate"
  },
  "isSiteVisitAllowed": true,
  "ageOfBuilding": "23",
  "totalLifeBuilding": "60",
  "estimatedAge": "37",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "4",
  "flatFloorNo": "1",
  "noOfLifts": "",
  "noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "460.00",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/648967ea171a1a25b984a7c6/
routeMap_1686829930280_Image.png",
    "routeLat": "19.415732",
    "routeLng": "72.821530",
    "stationName": "Nallasopara",
    "routeDistance": "500 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
```



```
"finalatlng": true
},
"locationMapImg": [
  {
    "id": "1s8zag",
    "name": "1s8zag",
    "image": "cases/648967ea171a1a25b984a7c6/
routeMap_1686829839330_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "2593480.00",
  "bookValue": "0",
  "finalValue": "2593480.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEM_GENERATED",
```

```
"date": "Thu Jun 15 2023 17:27:19 GMT+0530 (India Standard Time)",
"number": "046931",
"dayCount": "12",
"monthCount": "108",
"generatedBy": "60eebe33f3dd69653a5837ae"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2084720.00",
  "selectedBuildUpValue": "460.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "648afb8c719c32253ddd19c5",
    "name":
"externallmg_1686829963367_WhatsApp_Image_20230615_at_41823_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963367_WhatsApp_Image_20230615_at_41823_PM_1.jpeg",
    "orientation": "landscape"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "648afb96719c32253ddd1a67",
    "name":
"externallmg_1686829973810_WhatsApp_Image_20230615_at_41828_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973810_WhatsApp_Image_20230615_at_41828_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "648afb96719c32253ddd1a62",
    "name":
"externallmg_1686829973687_WhatsApp_Image_20230615_at_41826_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973687_WhatsApp_Image_20230615_at_41826_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648afb8c719c32253ddd19c9",
    "name":
"externallmg_1686829963488_WhatsApp_Image_20230615_at_41824_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963488_WhatsApp_Image_20230615_at_41824_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "648afb8c719c32253ddd19c4",
    "name":
"externallmg_1686829963342_WhatsApp_Image_20230615_at_41822_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963342_WhatsApp_Image_20230615_at_41822_PM.jpeg",
```

```
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "648afb96719c32253ddd1a61",
    "name":
"externallmg_1686829973656_WhatsApp_Image_20230615_at_41825_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973656_WhatsApp_Image_20230615_at_41825_PM.jpeg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "648afb96719c32253ddd1a65",
    "name": "Living Room",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973760_WhatsApp_Image_20230615_at_41827_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648afb96719c32253ddd1a66",
    "name": "Living Room",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973774_WhatsApp_Image_20230615_at_41828_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648afbb2719c32253ddd1aa8",
    "name": "Bedroom",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002266_WhatsApp_Image_20230615_at_41832_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648afbb2719c32253ddd1aa7",
    "name": "Kitchen",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002247_WhatsApp_Image_20230615_at_41831_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "648afb96719c32253ddd1a6a",
    "name": "Passage",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973863_WhatsApp_Image_20230615_at_41830_PM_1.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": true,
"CHECKER": true,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
finalValuationArea": "460.00",
empanelmentNo": [
"36/ LOAN H.O./2016-17/232"
],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "REPORTGENERATED",
"_id": "648967ea171a1a25b984a7c6",
"ownerName": "Mr. Deepak Chandrakant Kadu & Mrs. Sangeeta Deepak Kadu",
"ownerPhoneNo": "9029398430",
"appAddress": "A/105 Taniya Empire freny glory shiv sahyadri chs achole Rd
nalasopara east",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "10/11/2022",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Santosh Atmaram Bhojane",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Deepak Chandrakant Kadu & Mrs. Sangeeta Deepak Kadu"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "path": "cases/648967ea171a1a25b984a7c6/
document_1686828676477_137737.pdf",
    "id": "292005",
    "uploadedBy": "60eebe33f3dd69653a5837ae",
    "createdAt": "Thu Jun 15 2023 17:03:08 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "20/12/2000",
      "nameOfApprovingAuthority": {
        "value": "CIDCO",
        "label": "CIDCO"
      }
    }
  }
]
```

```
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CIDCO / VVSR / BP-1002 / E / 1928"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/648967ea171a1a25b984a7c6/
document_1686828767429_148195.pdf",
  "id": "940466",
  "uploadedBy": "60eebe33f3dd69653a5837ae",
  "createdAt": "Thu Jun 15 2023 17:03:08 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "001939",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "528183",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jun 14 2023 12:40:34 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Deepak Chandrakant Kadu & Mrs. Sangeeta Deepak Kadu",
    "phone": "9029398430",
    "ownershipShare": "",
    "email": "",
    "id": "660235"
  }
],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "369431",
    "name": "Living Room",
    "length": "15.00",
    "length1": "15",
    "length2": "0",
```

```
"width": "9.25",
"width1": "9",
"width2": "3",
"totalArea": "138.75",
"images": [],
"extraAreas": [],
"finalArea": "138.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "3.00",
  "length1": "3",
  "length2": "0",
  "width": "4.17",
  "width1": "4",
  "width2": "2",
  "totalArea": "12.50",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.50"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "WC",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "12.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.00"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Bathroom",
  "length": "",
  "length1": "5",
  "length2": "0",
  "width": "",
  "width1": "4",
  "width2": "0",
  "totalArea": "20.00",
  "images": [],
  "finalArea": "20.00",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "9.00",
  "length1": "9",
  "length2": "00",
  "width": "6.33",
  "width1": "6",
  "width2": "4",
  "totalArea": "57.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "57.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "9.17",
  "length1": "9",
  "length2": "2",
  "width": "8.75",
  "width1": "8",
```

```
"width2": "9",
"totalArea": "80.21",
"images": [],
"extraAreas": [],
"finalArea": "80.21"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "565770",
  "selectAreaTypeDocument": "Built_Up",
  "totalAreaDocument": "460",
  "squareMeterArea": "42.74",
  "docFinalBuiltUp": "0.00",
  "docFinalBuiltUpSquareMeter": "0.00",
  "docBuiltpPercentage": "",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "648be618719c32253ddd4d8e",
  "id": "1",
  "property": "Achole Road, Nallasopara East",
  "area": "400",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "Middle",
  "source": "Nobroker.com",
  "expectedPrice": "2600000",
```

```
    "expectedRate": "6500.00",
    "builtUpExpectedRate": "2600000",
    "image": "cases/648967ea171a1a25b984a7c6/
indicator_1686890008092_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "648be65d719c32253ddd4e0f",
    "id": "2",
    "property": "Achole Road, Nallasopara East",
    "area": "525",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "1",
    "source": "magic_bricks",
    "expectedPrice": "3500000",
    "expectedRate": "6666.67",
    "builtUpExpectedRate": "3500000",
    "image": "cases/648967ea171a1a25b984a7c6/
indicator_1686890077342_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "648be693719c32253ddd4e70",
    "id": "3",
    "property": "Sayut Nagar, Nallasopara East",
    "area": "505",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "1",
    "source": "magic_bricks",
    "expectedPrice": "3250000",
    "expectedRate": "6435.64",
    "builtUpExpectedRate": "3250000",
    "image": "cases/648967ea171a1a25b984a7c6/
indicator_1686890131790_Image.png"
  },
  {
    "printlnReport": true,
    "_id": "648be781719c32253ddd5557",
    "id": "4",
    "property": "Sai Crystal Empire, Nallsopara East",
```

```
    "area": "660",
    "builtUpPercentage": "10",
    "saleablePercentage": "20",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "floor": "10",
    "source": "https://www.99acres.com/",
    "expectedPrice": "3600000",
    "expectedRate": "5454.55",
    "builtUpExpectedRate": "3600000",
    "image": "cases/648967ea171a1a25b984a7c6/
indicator_1686890369047_Image.png"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19be",
    "name":
"externallmg_1686829963156_WhatsApp_Image_20230615_at_41816_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963156_WhatsApp_Image_20230615_at_41816_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19bf",
    "name":
"externallmg_1686829963172_WhatsApp_Image_20230615_at_41816_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963172_WhatsApp_Image_20230615_at_41816_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19c0",
    "name":
"externallmg_1686829963198_WhatsApp_Image_20230615_at_41817_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963198_WhatsApp_Image_20230615_at_41817_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19c1",
    "name":
"externallmg_1686829963223_WhatsApp_Image_20230615_at_41817_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963223_WhatsApp_Image_20230615_at_41817_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19c2",
    "name":
"externallmg_1686829963266_WhatsApp_Image_20230615_at_41819_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963266_WhatsApp_Image_20230615_at_41819_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19c3",
    "name":
"externallmg_1686829963300_WhatsApp_Image_20230615_at_41822_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963300_WhatsApp_Image_20230615_at_41822_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19c4",
    "name":
"externallmg_1686829963342_WhatsApp_Image_20230615_at_41822_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963342_WhatsApp_Image_20230615_at_41822_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb8c719c32253ddd19c5",
    "name":
"externallmg_1686829963367_WhatsApp_Image_20230615_at_41823_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963367_WhatsApp_Image_20230615_at_41823_PM_1.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb8c719c32253ddd19c6",
  "name":
  "externallmg_1686829963405_WhatsApp_Image_20230615_at_41823_PM_2.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963405_WhatsApp_Image_20230615_at_41823_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb8c719c32253ddd19c7",
  "name":
  "externallmg_1686829963433_WhatsApp_Image_20230615_at_41823_PM.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963433_WhatsApp_Image_20230615_at_41823_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb8c719c32253ddd19c8",
  "name":
  "externallmg_1686829963460_WhatsApp_Image_20230615_at_41824_PM_1.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963460_WhatsApp_Image_20230615_at_41824_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb8c719c32253ddd19c9",
  "name":
  "externallmg_1686829963488_WhatsApp_Image_20230615_at_41824_PM.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829963488_WhatsApp_Image_20230615_at_41824_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb96719c32253ddd1a5f",
```

```
    "name":
"externallmg_1686829973635_WhatsApp_Image_20230615_at_41825_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973635_WhatsApp_Image_20230615_at_41825_PM_1.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb96719c32253ddd1a60",
    "name":
"externallmg_1686829973642_WhatsApp_Image_20230615_at_41825_PM_2.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973642_WhatsApp_Image_20230615_at_41825_PM_2.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb96719c32253ddd1a61",
    "name":
"externallmg_1686829973656_WhatsApp_Image_20230615_at_41825_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973656_WhatsApp_Image_20230615_at_41825_PM.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb96719c32253ddd1a62",
    "name":
"externallmg_1686829973687_WhatsApp_Image_20230615_at_41826_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973687_WhatsApp_Image_20230615_at_41826_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb96719c32253ddd1a63",
    "name":
"externallmg_1686829973710_WhatsApp_Image_20230615_at_41826_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973710_WhatsApp_Image_20230615_at_41826_PM.jpeg",
    "orientation": "landscape"
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb96719c32253ddd1a64",
  "name":
"externallmg_1686829973730_WhatsApp_Image_20230615_at_41827_PM_1.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973730_WhatsApp_Image_20230615_at_41827_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb96719c32253ddd1a65",
  "name":
"externallmg_1686829973760_WhatsApp_Image_20230615_at_41827_PM.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973760_WhatsApp_Image_20230615_at_41827_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb96719c32253ddd1a66",
  "name":
"externallmg_1686829973774_WhatsApp_Image_20230615_at_41828_PM_1.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973774_WhatsApp_Image_20230615_at_41828_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb96719c32253ddd1a67",
  "name":
"externallmg_1686829973810_WhatsApp_Image_20230615_at_41828_PM.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973810_WhatsApp_Image_20230615_at_41828_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afb96719c32253ddd1a68",
  "name":
"externallmg_1686829973830_WhatsApp_Image_20230615_at_41829_PM_1.jpeg",
```

```
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973830_WhatsApp_Image_20230615_at_41829_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb96719c32253ddd1a69",
    "name":
"externallmg_1686829973844_WhatsApp_Image_20230615_at_41829_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973844_WhatsApp_Image_20230615_at_41829_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afb96719c32253ddd1a6a",
    "name":
"externallmg_1686829973863_WhatsApp_Image_20230615_at_41830_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686829973863_WhatsApp_Image_20230615_at_41830_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afbb2719c32253ddd1aa4",
    "name":
"externallmg_1686830002168_WhatsApp_Image_20230615_at_41830_PM.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002168_WhatsApp_Image_20230615_at_41830_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "648afbb2719c32253ddd1aa5",
    "name":
"externallmg_1686830002192_WhatsApp_Image_20230615_at_41831_PM_1.jpeg",
    "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002192_WhatsApp_Image_20230615_at_41831_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "648afbb2719c32253ddd1aa6",
  "name":
"externallmg_1686830002225_WhatsApp_Image_20230615_at_41831_PM_2.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002225_WhatsApp_Image_20230615_at_41831_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afbb2719c32253ddd1aa7",
  "name":
"externallmg_1686830002247_WhatsApp_Image_20230615_at_41831_PM.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002247_WhatsApp_Image_20230615_at_41831_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afbb2719c32253ddd1aa8",
  "name":
"externallmg_1686830002266_WhatsApp_Image_20230615_at_41832_PM_1.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002266_WhatsApp_Image_20230615_at_41832_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afbb2719c32253ddd1aa9",
  "name":
"externallmg_1686830002295_WhatsApp_Image_20230615_at_41832_PM.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002295_WhatsApp_Image_20230615_at_41832_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "648afbb2719c32253ddd1aaa",
  "name":
"externallmg_1686830002313_WhatsApp_Image_20230615_at_41855_PM.jpeg",
  "path": "cases/648967ea171a1a25b984a7c6/
externallmg_1686830002313_WhatsApp_Image_20230615_at_41855_PM.jpeg",
```

```
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-06-14T07:10:34.866Z",
"updatedAt": "2023-06-16T06:53:49.620Z",
"__v": 0,
"fullAddress": "Residential Flat No. 105, 1st Floor, Wing - A, Tania Empire (Freny Glory), Shiv Sahyadri Co-op. Hsg. Soc. Ltd., Village - Achole, Taluka - Vasai, District - Palghar, Nallasopara (East), 401 209, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Mrs. Sangeeta Deepak Kadu",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Self",
"siteVisitContactNo": "9029398430",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + WC + Bathroom",
"carpetTotal": "320.46",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "352.51",
"finalCarpetArea": "320.46",
"finalSalableArea": "387.76",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 460.00",
"reason": "",
"buildingServicesRate": "2500",
"flatRate": "6500",
"landOtherRate": "4000",
"siteVisitDate": "2023-06-15",
"otherCompositionBuiltUpTotal": "0.00",
```

"otherCompositionCarpetTotal": "0.00",  
"otherCompositionSaleableTotal": "0.00"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	15'0"	9'3"	138.75
Passage	3'0"	4'2"	12.50
WC	4'00"	3'00"	12.00
Bathroom	5'0"	4'0"	20.00
Kitchen	9'00"	6'4"	57.00
Bedroom	9'2"	8'9"	80.21
Other Composition :			