### PROFORMA INVOICE

Vastukala Consultants (I) Pvt Ltd Invoice No. Dated B1-001, U/B FLOOR, PG-1425/23-24 6-Jul-23 BOOMERANG, CHANDIVALI FARM ROAD. **Delivery Note** Mode/Terms of Payment ANDHERI-EAST 400072 AGAINST REPORT GSTIN/UIN: 27AADCV4303R1ZX Reference No. & Date. Other References State Name: Maharashtra, Code: 27 E-Mail: accounts@vastukala.org Buyer's Order No. Buyer (Bill to) Dated STATE BANK OF INDIA - RACPC GHATKOPAR RACPC GHATKOPAR BRANCH, OPP. DAMODAR PARK, Dispatch Doc No. Delivery Note Date ASHOK SILK MILLS COMPOUND, L.B.S. MARG, 002334 / 2301433 GHATKOPAR (W), MUMBAI-400086 Dispatched through Destination GSTIN/UIN : 27AAACS8577K2ZO State Name : Maharashtra, Code: 27 Terms of Delivery SI Particulars HSN/SAC **GST** Amount No. Rate 1 STRUCTURAL REPORT FEE 997224 18 % 2,500.00 (Technical Inspection and Certification Services) **CGST** 225.00 **SGST** 225.00 Total ₹ 2.950.00 Amount Chargeable (in words) E. & O.E Indian Rupee Two Thousand Nine Hundred Fifty Only HSN/SAC Taxable Central Tax State Tax Total Value Rate Amount Rate Amount Tax Amount 997224 2,500.00 9% 225.00 9% 225.00 450.00 Total 2,500.00 225.00 225.00 450.00 Tax Amount (in words): Indian Rupee Four Hundred Fifty Only Company's Bank Details Bank Name : State Bank of India A/c No. 32632562114 Branch & IFS Code: MIDC Andheri (E) & SBIN0007074 Santosh Trimbak Mane - Residential Flat No. 701, 7th Floor, Wing - D, Building No. 1, "Sai Aasha Daya Co -Op. Hsg. Soc. Ltd.", Gavanpada Road, Next to Neelam Nagar Phase II, Mulund (East), Mumbai - 400 081, State - Maharashtra, Country - India Company's PAN : AADCV4303R Declaration UPI Virtual ID : vastukala@icici NOTE - AS PER MSME RULES INVOICE NEED TO for Vastukala Consultants (I) Pvt Ltd BE CLEARED WITHIN 45 DAYS OR INTEREST

sed Signatory

CHARGES APPLICABLE AS PER THE RULE. MSME Registration No. - 27222201137

	GHATKOPAR RW), MUMBAL-400086 GSTIMIUIN 27AAACSBS77RQZQ Siete Name Maharashira Code 27

CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company

Consultants (I) Pvt. Ltd.



Valuation Report Prepared For: SBI / RACPC Ghatkopar (West)/ Shri. Santosh Trimbak Mane (2334/2301433)

Page 1 of 3

Vastu/Mumbai/07/2023/2334/2301433 06/04-58-PRSH

Date: 06.07.2023

## Structural Stability Report

Structural Observation Report of Residential Flat No. 701, 7th Floor, Wing - D, Building No. 1, "Sai Aasha Daya Co-Op. Hsg. Soc. Ltd.", Gavanpada Road, Next to Neelam Nagar Phase II, Mulund (East), Mumbai - 400 081, State - Maharashtra, Country - India.

Name of Owners: Shri. Santosh Trimbak Mane

This is to certify that on visual inspection, it appears that the structure at "Sai Aasha Daya Co-Op. Hsg. Soc. Ltd." is in good condition and the future life can be reasonably takes under good condition and with proper periodic repairs & maintenance is about 43 years.

General Information:

A.		Introduction
1	Name of Building	"Sai Aasha Daya Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 701, 7th Floor, Wing – D, Building No. 1, "Sai Aasha Daya Co-Op. Hsg. Soc. Ltd.", Gavanpada
		Road, Next to Neelam Nagar Phase II, Mulund (East) Mumbai – 400 081, State – Maharashtra, Country – India.
3	Type of Building	Residential Residential
4	No. of Floors	Part Ground + Part Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking provided	Stilt Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2006 (As per Occupancy Certificate)
11	Present age of building	17 years
12	Residual age of the building hink. In	43 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	4 Flats on 7th Floor
14	Methodology adopted	As per visual site inspection





Our Pan India Presence at :

Mumbai 💡 Aurangabad Pune Thane

 Nanded 💡 Delhi NCR 💡 Nashik

Indore Ahmedabad 💡 Jaipur

Rajkot 🗣 Raipur 🖁 Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24 

B.	External Observation of the Building			
1	Plaster	Good Condition		
2	Chajjas	Good Condition		
3	Plumbing	Good Condition		
4	Cracks on the external walls	Not found		
5	Filling cracks on the external walls	Not found		
6	Cracks on columns & beams	Not found		
7	Vegetation	Not found		
8	Leakages of water in the drainage pipes or water pipes	Not found		
9	Dampness external in the wall due to leakages	Not found		
10	Any other observation about the	The external condition of the building is good.		
С	Internal Observation of the common areas of the building and captioned premises			
1	Beams (Cracks & Leakages)	Not Found		
2	Columns (Cracks & Leakages)	Not Found		
3	Ceiling (Cracks & Leakages)	Not Found		
4	Leakages inside the property	Not Found		
5	Painting inside the property	Good		
6	Maintenance of staircase & cracks	Good		
D	Common Observation			
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws		
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit		
	(Co-Operative Societies Act / Rules)	of the building of the society as follows		
2	Remark			

#### E Conclusion

The captioned building is having Part Ground + Part Stilt + 7 Upper Floors Upper Floors which are constructed in year 2006 (As per Occupancy Certificate). Estimated future life under present circumstances is about 43 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 23.06.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT.

Sharadkumar B. Chalikwar

Director

Dightally signed by Sharadkumar B.
Challkwar
DN: cn=Sharadkumar B. Challkwar,
o=Vastukala Consultants (I) Pvt. Ltd.,
ou=CMD, emaile-cmd@vastukala.org, c=IN
Date: 2023.07.06 12:30:50 +05'30'

Auth. Sign.

### Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India) Reg. No. IBBI/RV/07/2019/11744 Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





# Actual site photographs

















