

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "635f7d78e363ef22db2f2888",
    "firstName": "Amita ",
    "lastName": "Patel",
    "mobileNo": "",
    "email": "me2@me.com",
    "workMobileNo": "8691048841"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "20000000",
    "discussWithPerson": "Amita ",
    "expectedFees": 10000,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "VCIPL Mumbai",
    "shortName": "VCIPLM",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land & Building / _Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
```

```
"mobileNo": "9167204055",
"shortName": "RBK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60b7189d2ffdf65bcd65882b\
\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.040507977827932",
  "longitude": "73.01517917387706"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.01517917387706,
    19.040507977827932
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nerul",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi MUmbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3A",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gahlot Avauue",
  "label": false
},
}
```

```
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "46A",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```

```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```



```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
```

```
    "label": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
```

```
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64b2b7e15e3c942514e8e114",
"ownerName": "Tejas Dashrath Auti",
"ownerPhoneNo": "9930004106",
"appAddress": "flat no 1204 12th floor sector no 46 A Bldg A wing pam Brich Road
Gahlot Avenue Nerul ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64b2b7e15e3c942514e8e114/
document_1689434034327_New_Doc_07152023_1753.pdf",
    "fileName": "document_1689434034327_New_Doc_07152023_1753.pdf",
    "displayStatus": false,
    "id": "472043",
    "uploadedBy": "60b7189d2ffdf65bcd65882b",
    "createdAt": "Sat Jul 15 2023 20:44:20 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002607",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "171505",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jul 15 2023 20:44:41 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Tejas Dashrath Auti",
    "phone": "9930004106",
    "ownershipShare": ""
  }
]
```



```
"email": "",
"id": "723147"
}
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64bb5229a87c525d5c045f72",
"name": "externallmg_r_1689997863088_00669__20230721Fri_121532PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
"path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997863088_00669
__20230721Fri_121532PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64bb5229a87c525d5c045f73",
"name": "externallmg_r_1689997863068_00668__20230721Fri_121527PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
"path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997863068_00668
__20230721Fri_121527PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64bb5229a87c525d5c045f74",
"name": "externallmg_r_1689997863108_00670__20230721Fri_121553PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
"path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997863108_00670
__20230721Fri_121553PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64bb5229a87c525d5c045f75",
```

```
  "name": "externallmg_r_1689997864711_00672___20230721Fri_122009PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997864711_00672
___20230721Fri_122009PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5229a87c525d5c045f76",
  "name": "externallmg_r_1689997864728_00674___20230721Fri_122107PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997864728_00674
___20230721Fri_122107PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5229a87c525d5c045f77",
  "name": "externallmg_r_1689997864753_00675___20230721Fri_122740PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997864753_00675
___20230721Fri_122740PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5229a87c525d5c045f78",
  "name": "externallmg_r_1689997864774_00676___20230721Fri_122742PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997864774_00676
___20230721Fri_122742PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5229a87c525d5c045f79",
  "name": "externallmg_r_1689997864794_00677___20230721Fri_122745PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997864794_00677
___20230721Fri_122745PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5229a87c525d5c045f7a",
  "name": "externallmg_r_1689997863136_00671__20230721Fri_121910PM__xrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997863136_00671__20230721Fri_121910PM__xrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5237a87c525d5c045f8f",
  "name": "externallmg_1689997879450_00671__20230721Fri_121910PM__xrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_1689997879450_00671__20230721Fri_121910PM__xrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5237a87c525d5c045f90",
  "name": "externallmg_r_1689997879607_00675__20230721Fri_122740PM__xrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997879607_00675__20230721Fri_122740PM__xrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045faf",
  "name": "externallmg_1689997891683_IMG_20230722_082113.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_1689997891683_IMG_20230722_082113.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb0",
  "name": "externallmg_1689997891722_IMG_20230722_082120.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_1689997891722_IMG_20230722_082120.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb1",
  "name": "externallmg_1689997891744_IMG_20230722_083115.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/
externallmg_1689997891744_IMG_20230722_083115.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb2",
  "name": "externallmg_1689997891791_IMG_20230722_083142.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/
externallmg_1689997891791_IMG_20230722_083142.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb3",
  "name": "externallmg_1689997891818_Screenshot_20230722_082524.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/
externallmg_1689997891818_Screenshot_20230722_082524.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb4",
  "name": "externallmg_r_1689997891365_00676__20230721Fri_122742PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997891365_00676
__20230721Fri_122742PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb5",
  "name": "externallmg_r_1689997891444_00679__20230721Fri_122751PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997891444_00679
```

```
____20230721Fri_122751PM____xrrddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb6",
  "name": "externallmg_r_1689997891429_00678____20230721Fri_122746PM____xrr
ddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997891429_00678
____20230721Fri_122746PM____xrrddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb7",
  "name": "externallmg_r_1689997891405_00677____20230721Fri_122745PM____xrr
ddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997891405_00677
____20230721Fri_122745PM____xrrddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb8",
  "name": "externallmg_r_1689997891537_00683____20230721Fri_122917PM____xrr
ddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997891537_00683
____20230721Fri_122917PM____xrrddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fb9",
  "name": "externallmg_r_1689997891501_00681____20230721Fri_122803PM____xrr
ddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externallmg_r_1689997891501_00681
____20230721Fri_122803PM____xrrddrrxz2223murism_____hnbm_lmjn____org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
  "_id": "64bb5244a87c525d5c045fba",
  "name": "externalimg_r_1689997891472_00680___20230721Fri_122756PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalimg_r_1689997891472_00680
___20230721Fri_122756PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fbb",
  "name": "externalimg_r_1689997891524_00682___20230721Fri_122805PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalimg_r_1689997891524_00682
___20230721Fri_122805PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fbc",
  "name": "externalimg_r_1689997891561_00684___20230721Fri_122919PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalimg_r_1689997891561_00684
___20230721Fri_122919PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fbd",
  "name": "externalimg_r_1689997891578_00685___20230721Fri_122929PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalimg_r_1689997891578_00685
___20230721Fri_122929PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fbe",
  "name": "externalimg_r_1689997891595_00686___20230721Fri_122932PM___xrr
ddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalimg_r_1689997891595_00686
___20230721Fri_122932PM___xrrddrrxz2223murism_____hnbm_lmjn___org.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fbf",
  "name": "externalImg_r_1689997891617_00687__20230721Fri_122947PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalImg_r_1689997891617_00687
__20230721Fri_122947PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fc0",
  "name": "externalImg_r_1689997891637_00688__20230721Fri_122949PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalImg_r_1689997891637_00688
__20230721Fri_122949PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64bb5244a87c525d5c045fc1",
  "name": "externalImg_r_1689997891660_00689__20230721Fri_123218PM__xrr
ddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "path": "cases/64b2b7e15e3c942514e8e114/externalImg_r_1689997891660_00689
__20230721Fri_123218PM__xrrddrrxz2223murism_____hnbm_lmjn__org.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-07-15T15:14:41.077Z",
"updatedAt": "2023-07-22T03:51:32.060Z",
"__v": 0,
"invoiceId": "64b2b7e15e3c942514e8e11a",
"fullAddress": " Flat No. 1204, Basement Floor, Wing - A, Gahlot Avanie, Plot No. 3A,
Sector 46A, Village - Nerul, Navi MUmbai, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Tejas Dashrath Auti",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9930004106"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			