

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8d5"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230ce9",
    "firstName": "Atul Thombre ",
    "email": "atul.thombre@cosmosbank.in",
    "mobileNo": "21640621",
    "workMobileNo": "8975758534"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  }
}
```

```
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8d5",
  "branchCode": "000007",
  "type": "BRANCH",
  "name": "Mulund (West) Branch",
  "email": "cosmos@mulundwestgmail.com",
  "mobileNo": "022-21640621",
  "alternateMobileNo": "022-21646370",
  "address": "Apurva Co-Op. Housing Society, Govardhan Nagar, L.B.S. Road, Mulund
(West), Mumbai - 400 080, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "PICKUPPERSON",
    "firstName": "Harshad",
    "email": "harshad@vastukala.org",
    "lastName": "Panchal",
    "mobileNo": "9029575553",
```

```
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": "",
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.18719425636324",
  "longitude": "72.94042053558213"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
0,
0
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-07-20",
      "remark": "1 bhk converted into 2 bhk "
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Mulund",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "4",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Kurla",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Mulund",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lok Nisarg Co-op Hsg. Soc. Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Ghati Pada Road, Near Vaishali Nagar",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
```

```
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "001",
  "label": false
},
}
```

```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```



```
"value": "400 080",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
```

```
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORMAKER",
"_id": "64b8d73538df6b2b30c5a1ec",
"ownerName": "Mr. Girish Jamnadas Thakkar & Mrs. Kalpana Girish Thakkar",
"ownerPhoneNo": "9022334499",
"fullAddress": "Residential Flat No. 001, 1st Floor, Building No 4, Wing - B, Lok Nisarg
Co-op Hsg. Soc. Ltd, Ghati Pada Road, Near Vaishali Nagar, Village - Mulund, Taluka -
Mulund, District - Kurla, Mumbai, 400 080, State - Maharashtra, India",
"remark": "1 bhk converted into 2 bhk ",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "25/02/2015",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Bhagwan Vishnu Satpute & Mrs. Snehlata Bhagwan Satpute",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mr. Girish Jamnadas Thakkar & Mrs. Kalpana Girish Thakkar"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/64b8d73538df6b2b30c5a1ec/document_undefined",
```

```
"id": "575967",
"uploadedBy": "6430f74691d7c62df11f3f15",
"createdAt": "Thu Jul 20 2023 12:11:36 GMT+0530 (India Standard Time)",
"fileName": "document_undefined"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "30/11/2002",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CE / 4239 / BPES / AT"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1690973678129_135242.pdf",
"path": "cases/64b8d73538df6b2b30c5a1ec/
document_1690973678129_135242.pdf",
"id": "655894",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Wed Aug 02 2023 16:26:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1252aa6d152c1801b31d",
    "label": "Society Letter"
  },
  "inputs": {
    "documentDate": "28/02/2015",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    }
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  }
},
```



```
    "Document_No": "NA"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1690973747199_107703.pdf",
  "path": "cases/64b8d73538df6b2b30c5a1ec/
document_1690973747199_107703.pdf",
  "id": "427375",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Aug 02 2023 16:26:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1264aa6d152c1801b371",
    "label": "Share Certificate "
  },
  "inputs": {
    "documentDate": "07/02/2016",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "119"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1690973789428_116657.pdf",
  "path": "cases/64b8d73538df6b2b30c5a1ec/
document_1690973789428_116657.pdf",
  "id": "933059",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Aug 02 2023 16:26:29 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002676",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "589220",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jul 20 2023 12:11:57 GMT+0530 (India Standard Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Mr. Girish Jamnadas Thakkar & Mrs. Kalpana Girish Thakkar",
    "phone": "9022334499",
    "ownershipShare": "",
    "email": "",
    "id": "488830"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b8fd0138df6b2b30c62475",
    "name": "externallmg_1689844979467_1689844762098_image_0.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979467_1689844762098_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b8fd0138df6b2b30c62476",
    "name": "externallmg_1689844979531_1689844762098_image_1.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979531_1689844762098_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b8fd0138df6b2b30c62477",
    "name": "externallmg_1689844979555_1689844762098_image_2.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979555_1689844762098_image_2.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8fd0138df6b2b30c62478",
  "name": "externallmg_1689844979598_1689844762098_image_3.jpeg",
  "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979598_1689844762098_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8fd0138df6b2b30c62479",
  "name": "externallmg_1689844979631_1689844762098_image_4.jpeg",
  "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979631_1689844762098_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8fd0138df6b2b30c6247a",
  "name": "externallmg_1689844979648_1689844762098_image_5.jpeg",
  "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979648_1689844762098_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8fd0138df6b2b30c6247b",
  "name": "externallmg_1689844979682_1689844762098_image_6.jpeg",
  "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979682_1689844762098_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64b8fd0138df6b2b30c6247c",
  "name": "externallmg_1689844979701_1689844762098_image_7.jpeg",
  "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979701_1689844762098_image_7.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b8fd0138df6b2b30c6247d",
    "name": "externallmg_1689844979720_1689844762098_image_8.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979720_1689844762098_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b8fd0138df6b2b30c6247e",
    "name": "externallmg_1689844979733_1689844762098_image_9.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979733_1689844762098_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64b8fd0138df6b2b30c6247f",
    "name": "externallmg_1689844979751_1689844762098_image_10.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844979751_1689844762098_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b8fd0138df6b2b30c62480",
    "name": "externallmg_1689844944178_1689844673492_image_0.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844944178_1689844673492_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "64b8fd0138df6b2b30c62481",
    "name": "externallmg_1689844944208_1689844723267_image_0.jpeg",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externallmg_1689844944208_1689844723267_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```

    "status": false,
    "_id": "64b8fd0138df6b2b30c62482",
    "name": "externalImg_1689844944220_1689844728647_image_0.png",
    "path": "cases/64b8d73538df6b2b30c5a1ec/
externalImg_1689844944220_1689844728647_image_0.png",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-07-20T06:41:57.802Z",
"updatedAt": "2023-08-02T10:56:29.522Z",
"__v": 0,
"invoiceId": "64b8d73538df6b2b30c5a1f9",
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mr. Girish Jamnadas Thakkar & Mrs. Kalpana Girish Thakkar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9022334499",
"reason": "Oc Required",
"siteVisitDate": "2023-07-20"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			