

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6454ca2514bbf555ec469814"
    },
    "type": "CREDITOFFICER",
    "_id": "6454ca2514bbf555ec469819",
    "firstName": "Deepak Kumar",
    "lastName": "Aarya",
    "mobileNo": "",
    "workMobileNo": "7350000012",
    "email": "ubin0561380@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2262000",
    "discussWithPerson": "Deepak Kumar",
    "expectedFees": 1131,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6454ca2514bbf555ec469814",
  "name": "Gokhivire Vasai Branch\t",
  "branchCode": "",
  "mobileNo": "2502464808\t",
  "alternateMobileNo": "",
  "email": "ubin0561380@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Surucha Muldapat Residency, Ground Floor, Pinto Travelles Campus,
Gokhivire, Vasai East\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
    "role": "PICKUPPERSON",
    "firstName": "Mangesh ",
    "email": "mangeshpalande17@gmail.com",
    "lastName": "Palande",
    "mobileNo": "9833030550",
```

```
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.398494234146867",
  "longitude": "72.84674092024167"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84674092024167,
    19.398494234146867
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
```

```
"value": "3",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "vasai east",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Deep Darshan ",
  "label": false
},
"selectArea": {
```

```
"status": false,
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "gokhivare ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
```

```
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "C-501",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
```



```
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
```

```
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64be32a8109daa2dd5ba8456",
"ownerName": "vinod vishwakarma ",
"ownerPhoneNo": "9821622446",
"appAddress": "c-501 deep darshan bldg bldg no 3 gokhivare vasai east",
"remark": "rera certificate rec'd pls check oc including ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64be32a8109daa2dd5ba8456/
document_1690186249319_vinod_vishwakarma.pdf",
    "fileName": "document_1690186249319_vinod_vishwakarma.pdf",
    "displayStatus": false,
    "id": "442471",
    "uploadedBy": "627219d6afd7d55eddedd283",
    "createdAt": "Mon Jul 24 2023 13:43:04 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002750",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "808737",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jul 24 2023 13:43:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "vinod vishwakarma ",
    "phone": "9821622446",
    "ownershipShare": "",
    "email": "",
    "id": "815688"
```



```
}
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d656",
    "name":
"externallmg_1690433885948_WhatsApp_Image_20230726_at_103826_PM_1.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885948_WhatsApp_Image_20230726_at_103826_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d657",
    "name":
"externallmg_1690433885951_WhatsApp_Image_20230726_at_103826_PM_2.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885951_WhatsApp_Image_20230726_at_103826_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d658",
    "name":
"externallmg_1690433885952_WhatsApp_Image_20230726_at_103826_PM_3.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885952_WhatsApp_Image_20230726_at_103826_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d659",
    "name":
"externallmg_1690433885953_WhatsApp_Image_20230726_at_103826_PM.jpeg",
```

```
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885953_WhatsApp_Image_20230726_at_103826_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d65a",
    "name":
"externallmg_1690433885956_WhatsApp_Image_20230726_at_103827_PM_1.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885956_WhatsApp_Image_20230726_at_103827_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d65b",
    "name":
"externallmg_1690433885958_WhatsApp_Image_20230726_at_103827_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885958_WhatsApp_Image_20230726_at_103827_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d65c",
    "name":
"externallmg_1690433885963_WhatsApp_Image_20230726_at_103828_PM_1.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885963_WhatsApp_Image_20230726_at_103828_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d65d",
    "name":
"externallmg_1690433885967_WhatsApp_Image_20230726_at_103828_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885967_WhatsApp_Image_20230726_at_103828_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d65e",
    "name":
"externallmg_1690433885972_WhatsApp_Image_20230726_at_103902_PM_1.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885972_WhatsApp_Image_20230726_at_103902_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d65f",
    "name":
"externallmg_1690433885975_WhatsApp_Image_20230726_at_103902_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885975_WhatsApp_Image_20230726_at_103902_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d660",
    "name":
"externallmg_1690433885977_WhatsApp_Image_20230726_at_103903_PM_1.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885977_WhatsApp_Image_20230726_at_103903_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d661",
    "name":
"externallmg_1690433885979_WhatsApp_Image_20230726_at_103903_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885979_WhatsApp_Image_20230726_at_103903_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d662",
    "name":
"externallmg_1690433885983_WhatsApp_Image_20230726_at_104011_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885983_WhatsApp_Image_20230726_at_104011_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d663",
    "name":
"externallmg_1690433885986_WhatsApp_Image_20230726_at_103809_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885986_WhatsApp_Image_20230726_at_103809_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d664",
    "name":
"externallmg_1690433885990_WhatsApp_Image_20230726_at_103810_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885990_WhatsApp_Image_20230726_at_103810_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d665",
    "name":
"externallmg_1690433885992_WhatsApp_Image_20230726_at_103811_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885992_WhatsApp_Image_20230726_at_103811_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d666",
    "name":
"externallmg_1690433885997_WhatsApp_Image_20230726_at_103815_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433885997_WhatsApp_Image_20230726_at_103815_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f95e9d3a3e4ed9d1d667",
```

```
"name":
"externalimg_1690433886000_WhatsApp_Image_20230726_at_103817_PM.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalimg_1690433886000_WhatsApp_Image_20230726_at_103817_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f95e9d3a3e4ed9d1d668",
  "name":
"externalimg_1690433886003_WhatsApp_Image_20230726_at_103820_PM.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalimg_1690433886003_WhatsApp_Image_20230726_at_103820_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daa8",
  "name":
"externalimg_1690433930278_WhatsApp_Image_20230726_at_103821_PM_1.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalimg_1690433930278_WhatsApp_Image_20230726_at_103821_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daa9",
  "name":
"externalimg_1690433930301_WhatsApp_Image_20230726_at_103821_PM_2.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalimg_1690433930301_WhatsApp_Image_20230726_at_103821_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daaa",
  "name":
"externalimg_1690433930309_WhatsApp_Image_20230726_at_103821_PM.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalimg_1690433930309_WhatsApp_Image_20230726_at_103821_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daab",
  "name":
"externallmg_1690433930312_WhatsApp_Image_20230726_at_103822_PM_1.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930312_WhatsApp_Image_20230726_at_103822_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daac",
  "name":
"externallmg_1690433930317_WhatsApp_Image_20230726_at_103822_PM_2.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930317_WhatsApp_Image_20230726_at_103822_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daad",
  "name":
"externallmg_1690433930320_WhatsApp_Image_20230726_at_103822_PM.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930320_WhatsApp_Image_20230726_at_103822_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daae",
  "name":
"externallmg_1690433930325_WhatsApp_Image_20230726_at_103823_PM_1.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930325_WhatsApp_Image_20230726_at_103823_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1daaf",
  "name":
"externallmg_1690433930328_WhatsApp_Image_20230726_at_103823_PM_2.jpeg",
```

```
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930328_WhatsApp_Image_20230726_at_103823_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f98a9d3a3e4ed9d1dab0",
    "name":
"externallmg_1690433930330_WhatsApp_Image_20230726_at_103823_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930330_WhatsApp_Image_20230726_at_103823_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f98a9d3a3e4ed9d1dab1",
    "name":
"externallmg_1690433930333_WhatsApp_Image_20230726_at_103824_PM_1.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930333_WhatsApp_Image_20230726_at_103824_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f98a9d3a3e4ed9d1dab2",
    "name":
"externallmg_1690433930336_WhatsApp_Image_20230726_at_103824_PM_2.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930336_WhatsApp_Image_20230726_at_103824_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c1f98a9d3a3e4ed9d1dab3",
    "name":
"externallmg_1690433930338_WhatsApp_Image_20230726_at_103824_PM.jpeg",
    "path": "cases/64be32a8109daa2dd5ba8456/
externallmg_1690433930338_WhatsApp_Image_20230726_at_103824_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64c1f98a9d3a3e4ed9d1dab4",
  "name":
"externalImg_1690433930340_WhatsApp_Image_20230726_at_103825_PM_1.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalImg_1690433930340_WhatsApp_Image_20230726_at_103825_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1dab5",
  "name":
"externalImg_1690433930342_WhatsApp_Image_20230726_at_103825_PM_2.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalImg_1690433930342_WhatsApp_Image_20230726_at_103825_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c1f98a9d3a3e4ed9d1dab6",
  "name":
"externalImg_1690433930343_WhatsApp_Image_20230726_at_103825_PM.jpeg",
  "path": "cases/64be32a8109daa2dd5ba8456/
externalImg_1690433930343_WhatsApp_Image_20230726_at_103825_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"createdAt": "2023-07-24T08:13:28.682Z",
"updatedAt": "2023-07-27T04:58:50.414Z",
"__v": 0,
"invoiceId": "64be32a8109daa2dd5ba845d",
"fullAddress": " Flat No. C-501, Basement Floor, Building No 3, Deep Darshan ,
gokhivare , vasai east, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "vinod vishwakarma ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```


"siteVisitContactNo": "9821622446"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
