

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "type": "CREDITOFFICER",
    "_id": "646dc536b05e530fb6c47b3d",
    "firstName": "r. Mohanty",
    "lastName": " Sir",
    "mobileNo": "",
    "workMobileNo": "8411020137",
    "email": "rlf.nasik@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2950"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",
    "name": "Nashik Branch",
    "shortName": "NSK",
    "email": "nashik@vastukala.org",
    "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, "
```

```
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
    "email": "sachinraundal9021@gmail.com",
    "lastName": "Raundal",
    "mobileNo": "9021337843",
    "shortName": "Sachin",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
```

```
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "636a29b64d42487767af43ea",
  "role": "NASHIK (LEAD + VISIT + RATE)",
  "firstName": "Sachin",
  "email": "sachinraundal9021@gmail.com",
  "lastName": "Raundal",
  "mobileNo": "9021337843",
  "designation": "Site Engg",
  "shortName": "Sachin",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.980818226518945",
  "longitude": "73.83902288856152"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
```

```
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dasak",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "01",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shiv Orchid Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": " Near Mahadubaba Mandir",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "58/ 7/ 8",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "101",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```

```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
```



```
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
```

```
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64c24acf0950be569fe6f576",
"ownerName": "Sonali Lokesh Kamde.",
```

```
"ownerPhoneNo": "9552992185",
"fullAddress": " Flat No. 101, Basement Floor, Shiv Orchid Apartment, Near
Mahadubaba Mandir, Plot No. 01, Village - Dasak, Taluka - Nashik, District - Nashik,
Nashik, 422101, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "LND/ BP / C4/ 477/ 2022"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1690454507084_New_CaseDeepak_Pardeshi_BankBOB_Branch.pdf",
    "path": "cases/64c24acf0950be569fe6f576/
document_1690454507084_New_CaseDeepak_Pardeshi_BankBOB_Branch.pdf",
    "id": "121560",
    "uploadedBy": "636a29b64d42487767af43ea",
    "createdAt": "Thu Jul 27 2023 16:15:10 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "LND/ BP / C4/ 477/ 2022"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1690454536796_CC.pdf",
    "path": "cases/64c24acf0950be569fe6f576/document_1690454536796_CC.pdf",
    "id": "577877",
    "uploadedBy": "636a29b64d42487767af43ea",
```

```
"createdAt": "Thu Jul 27 2023 16:15:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "BP/ C4/ 477/ 2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690454565512_Deepak_Pardeshi__Plan.pdf",
"path": "cases/64c24acf0950be569fe6f576/
document_1690454565512_Deepak_Pardeshi__Plan.pdf",
"id": "260424",
"uploadedBy": "636a29b64d42487767af43ea",
"createdAt": "Thu Jul 27 2023 16:15:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "BP/ C4/ 477/ 2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690454591123_Plan.pdf",
"path": "cases/64c24acf0950be569fe6f576/document_1690454591123_Plan.pdf",
"id": "979823",
"uploadedBy": "636a29b64d42487767af43ea",
"createdAt": "Thu Jul 27 2023 16:15:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
```



```
"label": "RERA Certificate"
},
"inputs": {
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "P51600049498"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1690454608421_rera_cert.pdf",
"path": "cases/64c24acf0950be569fe6f576/
document_1690454608421_rera_cert.pdf",
"id": "937974",
"uploadedBy": "636a29b64d42487767af43ea",
"createdAt": "Thu Jul 27 2023 16:15:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae126caa6d152c1801b395",
    "label": "Correction Deed"
  },
  "inputs": {
    "from": {
      "value": "Developers",
      "label": "Developers"
    },
    "Developers": "M/s Landmark Infra",
    "to": {
      "value": "buyer",
      "label": "buyer"
    },
    "buyer": "Sonali Lokesh Kamde",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1690454688149_Shiv_ORCHID_correction_Deed.pdf",
  "path": "cases/64c24acf0950be569fe6f576/
document_1690454688149_Shiv_ORCHID_correction_Deed.pdf",
  "id": "996663",
```

```
"uploadedBy": "636a29b64d42487767af43ea",
"createdAt": "Thu Jul 27 2023 16:15:10 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "002826",
"createdBy": "636a29b64d42487767af43ea",
"caseHistory": [
  {
    "id": "501977",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jul 27 2023 16:15:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sonali Lokesh Kamde.",
    "phone": "9552992185",
    "ownershipShare": "",
    "email": "",
    "id": "532277"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b3e0950be569fe73ba1",
    "name":
"externallmg_1690454845592_WhatsApp_Image_20230721_at_120854_PM.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454845592_WhatsApp_Image_20230721_at_120854_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b3e0950be569fe73ba2",
    "name":
"externallmg_1690454845652_WhatsApp_Image_20230721_at_120859_PM_1.jpeg",
```

```
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454845652_WhatsApp_Image_20230721_at_120859_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b3e0950be569fe73ba3",
    "name":
"externallmg_1690454845749_WhatsApp_Image_20230721_at_120900_PM_1.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454845749_WhatsApp_Image_20230721_at_120900_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b3e0950be569fe73ba4",
    "name":
"externallmg_1690454845832_WhatsApp_Image_20230721_at_120901_PM.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454845832_WhatsApp_Image_20230721_at_120901_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b520950be569fe73f18",
    "name":
"externallmg_1690454865801_WhatsApp_Image_20230721_at_120853_PM_1.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454865801_WhatsApp_Image_20230721_at_120853_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b520950be569fe73f19",
    "name":
"externallmg_1690454865856_WhatsApp_Image_20230721_at_120854_PM_2.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454865856_WhatsApp_Image_20230721_at_120854_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64c24b520950be569fe73f1a",
  "name":
"externallmg_1690454865912_WhatsApp_Image_20230721_at_120855_PM_1.jpeg",
  "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454865912_WhatsApp_Image_20230721_at_120855_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c24b520950be569fe73f1b",
  "name":
"externallmg_1690454865955_WhatsApp_Image_20230721_at_120855_PM_2.jpeg",
  "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454865955_WhatsApp_Image_20230721_at_120855_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c24b520950be569fe73f1c",
  "name":
"externallmg_1690454866023_WhatsApp_Image_20230721_at_120855_PM.jpeg",
  "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454866023_WhatsApp_Image_20230721_at_120855_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c24b520950be569fe73f1d",
  "name":
"externallmg_1690454866080_WhatsApp_Image_20230721_at_120856_PM_1.jpeg",
  "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454866080_WhatsApp_Image_20230721_at_120856_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64c24b520950be569fe73f1e",
  "name":
"externallmg_1690454866127_WhatsApp_Image_20230721_at_120857_PM.jpeg",
  "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454866127_WhatsApp_Image_20230721_at_120857_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b520950be569fe73f1f",
    "name":
"externallmg_1690454866164_WhatsApp_Image_20230721_at_120858_PM_1.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/"
externallmg_1690454866164_WhatsApp_Image_20230721_at_120858_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b520950be569fe73f20",
    "name":
"externallmg_1690454866194_WhatsApp_Image_20230721_at_120858_PM_2.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/"
externallmg_1690454866194_WhatsApp_Image_20230721_at_120858_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b520950be569fe73f21",
    "name":
"externallmg_1690454866266_WhatsApp_Image_20230721_at_120858_PM.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/"
externallmg_1690454866266_WhatsApp_Image_20230721_at_120858_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b520950be569fe73f22",
    "name":
"externallmg_1690454866318_WhatsApp_Image_20230721_at_120859_PM.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/"
externallmg_1690454866318_WhatsApp_Image_20230721_at_120859_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b5f0950be569fe74282",
```

```

    "name":
"externallmg_1690454878965_WhatsApp_Image_20230721_at_120851_PM.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_1690454878965_WhatsApp_Image_20230721_at_120851_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64c24b5f0950be569fe74283",
    "name":
"externallmg_r_1690454879062_WhatsApp_Image_20230721_at_120852_PM.jpeg",
    "path": "cases/64c24acf0950be569fe6f576/
externallmg_r_1690454879062_WhatsApp_Image_20230721_at_120852_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-07-27T10:45:35.310Z",
"updatedAt": "2023-07-27T10:47:59.477Z",
"__v": 0,
"invoiceId": "64c24acf0950be569fe6f582",
"updatedBy": "636a29b64d42487767af43ea",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Sonali Lokesh Kamde.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9552992185"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			