

```
{
  "typeOfReport": {
    "label": "Commercial Shop",
    "value": "Commercial_Shop"
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64019061ce84bf289bac0837"
    },
    "type": "CREDITOFFICER",
    "_id": "6417edd296b58848585ec24a",
    "firstName": "Varkha Gupta",
    "lastName": "Gupta",
    "mobileNo": "",
    "workMobileNo": "9699720444",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4500000",
    "discussWithPerson": "Varkha Gupta",
    "expectedFees": 2250,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
```

```
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64019061ce84bf289bac0837",
  "name": "PLP BKC",
  "branchCode": "",
  "mobileNo": "8699542403",
  "alternateMobileNo": "",
  "email": "plp6605@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "PNB Pragati Tower C 9, G Block, 3rd floor, Bandra Kurla Complex,
Bandra(E), Mumbai - 400051, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62723addafd7d55eddeddfe4",
    "role": "PICKUPPERSON",
    "firstName": "Ramkrishna ",
    "email": "rampatakar1991@gmail.com",
    "lastName": "Patkar",
    "mobileNo": "7045746060",
```

```
"shortName": "RP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
```

```
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.06027768565161",
  "longitude": "73.01055517035942"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.01055517035942,
    19.06027768565161
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-03T06:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": []
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Sanpada",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
```

```
"name": "District",
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shiv Triveni Complex CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "7",
  "label": true
}
```

```
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
```

```
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Shop no 22",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
}
```



```
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
```

```
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64ca37273bd5b90592723de6",
"ownerName": "Mrunal Sanjay Babar",
"ownerPhoneNo": "9819192908",
"appAddress": "shop no 21, shiv Triveni complex Co opt hsg soc, Sanpada, navi
Mumbai ,sect 7",
"remark": "Tommarow soft copy.. evening ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64ca37273bd5b90592723de6/
document_1690974055853_plp__21_mrunal.pdf",
    "fileName": "document_1690974055853_plp__21_mrunal.pdf",
    "displayStatus": false,
    "id": "114356",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Wed Aug 02 2023 16:31:32 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "002892",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "579156",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 02 2023 16:29:51 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrunal Sanjay Babar",
    "phone": "9819192908",
    "ownershipShare": "",
    "email": "",
    "id": "892383"
  }
],
"siteInspection": [],
"composition": [],
```



```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb52430faf29427aca521f",
    "name":
"externallmg_1691046466960_WhatsApp_Image_20230803_at_111512_AM_1.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046466960_WhatsApp_Image_20230803_at_111512_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb52430faf29427aca5220",
    "name":
"externallmg_1691046466962_WhatsApp_Image_20230803_at_111512_AM.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046466962_WhatsApp_Image_20230803_at_111512_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb52430faf29427aca5221",
    "name":
"externallmg_1691046466968_WhatsApp_Image_20230803_at_111513_AM_1.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046466968_WhatsApp_Image_20230803_at_111513_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb52430faf29427aca5222",
    "name":
"externallmg_1691046466971_WhatsApp_Image_20230803_at_111513_AM.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046466971_WhatsApp_Image_20230803_at_111513_AM.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb526b0faf29427aca527c",
  "name":
"externallmg_1691046507008_WhatsApp_Image_20230803_at_111514_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046507008_WhatsApp_Image_20230803_at_111514_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb526b0faf29427aca527d",
  "name":
"externallmg_1691046507013_WhatsApp_Image_20230803_at_111515_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046507013_WhatsApp_Image_20230803_at_111515_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb526b0faf29427aca527e",
  "name":
"externallmg_1691046507019_WhatsApp_Image_20230803_at_111516_AM_1.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046507019_WhatsApp_Image_20230803_at_111516_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb526b0faf29427aca527f",
  "name":
"externallmg_1691046507022_WhatsApp_Image_20230803_at_111516_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046507022_WhatsApp_Image_20230803_at_111516_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb526b0faf29427aca5280",
  "name":
"externallmg_1691046507028_WhatsApp_Image_20230803_at_111518_AM.jpeg",
```

```
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046507028_WhatsApp_Image_20230803_at_111518_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52bb",
    "name":
"externallmg_1691046523108_WhatsApp_Image_20230803_at_111518_AM.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523108_WhatsApp_Image_20230803_at_111518_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52bc",
    "name":
"externallmg_1691046523111_WhatsApp_Image_20230803_at_111519_AM.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523111_WhatsApp_Image_20230803_at_111519_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52bd",
    "name":
"externallmg_1691046523114_WhatsApp_Image_20230803_at_111520_AM.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523114_WhatsApp_Image_20230803_at_111520_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52be",
    "name":
"externallmg_1691046523117_WhatsApp_Image_20230803_at_111521_AM_1.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523117_WhatsApp_Image_20230803_at_111521_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64cb527b0faf29427aca52bf",
  "name":
"externallmg_1691046523119_WhatsApp_Image_20230803_at_111521_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523119_WhatsApp_Image_20230803_at_111521_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52c0",
  "name":
"externallmg_1691046523122_WhatsApp_Image_20230803_at_111522_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523122_WhatsApp_Image_20230803_at_111522_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52c1",
  "name":
"externallmg_1691046523125_WhatsApp_Image_20230803_at_111523_AM_1.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523125_WhatsApp_Image_20230803_at_111523_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52c2",
  "name":
"externallmg_1691046523127_WhatsApp_Image_20230803_at_111523_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523127_WhatsApp_Image_20230803_at_111523_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52c3",
  "name":
"externallmg_1691046523130_WhatsApp_Image_20230803_at_111524_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523130_WhatsApp_Image_20230803_at_111524_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52c4",
    "name":
"externallmg_1691046523132_WhatsApp_Image_20230803_at_111525_AM_1.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523132_WhatsApp_Image_20230803_at_111525_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52c5",
    "name":
"externallmg_1691046523134_WhatsApp_Image_20230803_at_111525_AM.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523134_WhatsApp_Image_20230803_at_111525_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52c6",
    "name":
"externallmg_1691046523137_WhatsApp_Image_20230803_at_111526_AM_1.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523137_WhatsApp_Image_20230803_at_111526_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52c7",
    "name":
"externallmg_1691046523139_WhatsApp_Image_20230803_at_111526_AM.jpeg",
    "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523139_WhatsApp_Image_20230803_at_111526_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cb527b0faf29427aca52c8",
```

```
    "name":
"externallmg_1691046523142_WhatsApp_Image_20230803_at_111527_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523142_WhatsApp_Image_20230803_at_111527_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52c9",
  "name":
"externallmg_1691046523143_WhatsApp_Image_20230803_at_111528_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523143_WhatsApp_Image_20230803_at_111528_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52ca",
  "name":
"externallmg_1691046523146_WhatsApp_Image_20230803_at_111529_AM_1.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523146_WhatsApp_Image_20230803_at_111529_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52cb",
  "name":
"externallmg_1691046523150_WhatsApp_Image_20230803_at_111529_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523150_WhatsApp_Image_20230803_at_111529_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52cc",
  "name":
"externallmg_1691046523154_WhatsApp_Image_20230803_at_111530_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523154_WhatsApp_Image_20230803_at_111530_AM.jpeg",
  "orientation": "portrait"
},
}
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52cd",
  "name":
"externallmg_1691046523156_WhatsApp_Image_20230803_at_111531_AM_1.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523156_WhatsApp_Image_20230803_at_111531_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cb527b0faf29427aca52ce",
  "name":
"externallmg_1691046523162_WhatsApp_Image_20230803_at_111531_AM.jpeg",
  "path": "cases/64ca37273bd5b90592723de6/
externallmg_1691046523162_WhatsApp_Image_20230803_at_111531_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"createdAt": "2023-08-02T10:59:51.953Z",
"updatedAt": "2023-08-03T07:08:43.273Z",
"__v": 0,
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"fullAddress": " Commercial Shop No. Shop no 22, Ground Floor, Shiv Triveni
Complex CHSL, Sector 7, Village - Sanpada, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Mrunal Sanjay Babar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819192908"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---