

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "640f306e63e4271bcefdbb9e"
    },
    "type": "CREDITOFFICER",
    "_id": "640f306e63e4271bcefdbba0",
    "firstName": "Prachi",
    "lastName": "Desai",
    "mobileNo": "",
    "workMobileNo": "9702602797",
    "email": "prachi.desai@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "6418456a96b58848585f8cb2",
    "name": "Thane",
    "email": "thane@vastukala.com",
    "phone": "1234567890",
    "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
```

```
400 601",
  "city": "Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "640f306e63e4271bcefd9bb9e",
  "name": "Kalyan Khadakpada Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "kalyan@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground floor, Shiv Villa Apt. Opp. gagangiri Soc. Sai Chowk, Khadakpada
Kalyan West 421301\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62720e52afd7d55eddedc887",
    "role": "PICKUPPERSON",
    "firstName": "Harshad",
    "email": "harshad@vastukala.org",
    "lastName": "Panchal",
    "mobileNo": "9029575553",
```

```
"shortName": "HP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "designation": "",
  "shortName": "PS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
```

```
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      },
      {
        "title": {
          "value": "Chartered_Engineer",
          "label": "Chartered Engineer"
        },
        "_id": "60af80072ffdf65bcd658653",
        "number": "AM161706-3"
      },
      {
        "title": {
          "value": "Registered_Valuer",
          "label": "Registered Valuer"
        },
        "_id": "60af80072ffdf65bcd658654",
```

```
    "number": "IBBI/RV/07/2018/10366"
  }
],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.261850816115988",
  "longitude": " 73.13828266441774"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-03T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-03T08:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-03T08:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft."
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "gandhare",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "3",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kalyan",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vasant Valley",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": false,
"name": "Street 1",
"key": "street1",
"value": "",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "501",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kalyan West",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "true",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
status": true,
```



```
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64cb74f70faf29427acab9cf",
"ownerName": "Vedprakash Gupta",
"ownerPhoneNo": "9769114377",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9769114377",
"contactPersonName": "Vedprakash Gupta",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Vedprakash Gupta",
    "phone": "9769114377",
    "ownershipShare": "",
    "email": "",
    "id": "809147"
  }
],
"caseReferredBy": "62720e52afd7d55eddedc887",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 501, 5th Floor, Building No 3, Vasant Valley, Village
- gandhare, Kalyan West, Kalyan, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1691055205228_PD4.pdf",
    "path": "cases/64cb74f70faf29427acab9cf/document_1691055205228_PD4.pdf",
    "id": "464888",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Aug 03 2023 15:05:26 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1691055221182_PD3.pdf",
    "path": "cases/64cb74f70faf29427acab9cf/document_1691055221182_PD3.pdf",
```

```
"id": "474304",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Thu Aug 03 2023 15:05:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691055257782_PD2.pdf",
  "path": "cases/64cb74f70faf29427acab9cf/document_1691055257782_PD2.pdf",
  "id": "358609",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Thu Aug 03 2023 15:05:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691055275549_PD1.pdf",
  "path": "cases/64cb74f70faf29427acab9cf/document_1691055275549_PD1.pdf",
  "id": "848167",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Thu Aug 03 2023 15:05:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1691055319712_118008.pdf",
  "path": "cases/64cb74f70faf29427acab9cf/document_1691055319712_118008.pdf",
  "id": "970533",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Thu Aug 03 2023 15:05:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
```

```
"label": "Agreement for sale"
},
"inputs": {
  "from": {
    "value": "Promoter",
    "label": "Promoter"
  },
  "Promoter": "M/s. Vikas Builders and Developers ",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Vedprakash Gupta & Mrs. Sarita Gupta "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1691401009828_document_1691055275549_PD11.pdf",
"path": "cases/64cb74f70faf29427acab9cf/
document_1691401009828_document_1691055275549_PD11.pdf",
"id": "144109",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Aug 07 2023 15:09:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "21/03/2012",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "KDMC / NRV / CC / KV / 526"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1691401095100_142166.pdf",
  "path": "cases/64cb74f70faf29427acab9cf/document_1691401095100_142166.pdf",
  "id": "239507",
  "uploadedBy": "627222afafd7d55eddeddd82",
```

```
"createdAt": "Mon Aug 07 2023 15:09:31 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "19/12/2008",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KDMC / NRV / BP / KV / 422 -198 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1691401170998_202130.pdf",
"path": "cases/64cb74f70faf29427acab9cf/document_1691401170998_202130.pdf",
"id": "664550",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Mon Aug 07 2023 15:09:31 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "002912",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "723526",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Thu Aug 03 2023 15:05:51 GMT+0530 (India Standard Time)"
  }
],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
```

```
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd475dc9f3034f3feb960",
    "name":
"externallmg_1691210869168_WhatsApp_Image_20230805_at_94417_AM_1.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210869168_WhatsApp_Image_20230805_at_94417_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd475dc9f3034f3feb961",
    "name":
"externallmg_1691210869173_WhatsApp_Image_20230805_at_94417_AM_2.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210869173_WhatsApp_Image_20230805_at_94417_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd475dc9f3034f3feb962",
    "name":
"externallmg_1691210869179_WhatsApp_Image_20230805_at_94417_AM_3.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210869179_WhatsApp_Image_20230805_at_94417_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9a8",
    "name":
"externallmg_1691210883884_WhatsApp_Image_20230805_at_94417_AM_4.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883884_WhatsApp_Image_20230805_at_94417_AM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "64cdd484dc9f3034f3feb9a9",
    "name":
"externallmg_1691210883888_WhatsApp_Image_20230805_at_94417_AM_5.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883888_WhatsApp_Image_20230805_at_94417_AM_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9aa",
    "name":
"externallmg_1691210883892_WhatsApp_Image_20230805_at_94417_AM_6.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883892_WhatsApp_Image_20230805_at_94417_AM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9ab",
    "name":
"externallmg_1691210883897_WhatsApp_Image_20230805_at_94417_AM_7.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883897_WhatsApp_Image_20230805_at_94417_AM_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9ac",
    "name":
"externallmg_1691210883902_WhatsApp_Image_20230805_at_94417_AM_8.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883902_WhatsApp_Image_20230805_at_94417_AM_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9ad",
    "name":
"externallmg_1691210883906_WhatsApp_Image_20230805_at_94417_AM_9.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883906_WhatsApp_Image_20230805_at_94417_AM_9.jpeg",
    "orientation": "landscape"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cdd484dc9f3034f3feb9ae",
  "name":
"externallmg_1691210883909_WhatsApp_Image_20230805_at_94417_AM_10.jpeg",
  "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883909_WhatsApp_Image_20230805_at_94417_AM_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cdd484dc9f3034f3feb9af",
  "name":
"externallmg_1691210883913_WhatsApp_Image_20230805_at_94417_AM_11.jpeg",
  "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883913_WhatsApp_Image_20230805_at_94417_AM_11.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cdd484dc9f3034f3feb9b0",
  "name":
"externallmg_1691210883915_WhatsApp_Image_20230805_at_94417_AM_12.jpeg",
  "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883915_WhatsApp_Image_20230805_at_94417_AM_12.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cdd484dc9f3034f3feb9b1",
  "name":
"externallmg_1691210883918_WhatsApp_Image_20230805_at_94417_AM_13.jpeg",
  "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883918_WhatsApp_Image_20230805_at_94417_AM_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64cdd484dc9f3034f3feb9b2",
  "name":
"externallmg_1691210883928_WhatsApp_Image_20230805_at_94417_AM_14.jpeg",
```

```
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883928_WhatsApp_Image_20230805_at_94417_AM_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9b3",
    "name":
"externallmg_1691210883933_WhatsApp_Image_20230805_at_94417_AM_15.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883933_WhatsApp_Image_20230805_at_94417_AM_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9b4",
    "name":
"externallmg_1691210883938_WhatsApp_Image_20230805_at_94417_AM_16.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883938_WhatsApp_Image_20230805_at_94417_AM_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9b5",
    "name":
"externallmg_1691210883939_WhatsApp_Image_20230805_at_94417_AM_17.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883939_WhatsApp_Image_20230805_at_94417_AM_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9b6",
    "name":
"externallmg_1691210883945_WhatsApp_Image_20230805_at_94417_AM_18.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externallmg_1691210883945_WhatsApp_Image_20230805_at_94417_AM_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9b7",
    "name":
"externalImg_1691210883948_WhatsApp_Image_20230805_at_94417_AM_19.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externalImg_1691210883948_WhatsApp_Image_20230805_at_94417_AM_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9b8",
    "name":
"externalImg_1691210883951_WhatsApp_Image_20230805_at_94417_AM_20.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externalImg_1691210883951_WhatsApp_Image_20230805_at_94417_AM_20.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9b9",
    "name":
"externalImg_1691210883953_WhatsApp_Image_20230805_at_94417_AM.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externalImg_1691210883953_WhatsApp_Image_20230805_at_94417_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64cdd484dc9f3034f3feb9ba",
    "name":
"externalImg_1691210883962_WhatsApp_Image_20230805_at_94800_AM.jpeg",
    "path": "cases/64cb74f70faf29427acab9cf/
externalImg_1691210883962_WhatsApp_Image_20230805_at_94800_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"createdAt": "2023-08-03T09:35:51.522Z",
"updatedAt": "2023-08-07T09:39:31.097Z",
"__v": 0,
"invoiceId": "64cb74f70faf29427acab9d5",
"addressForMap": "",
"updatedBy": "627222afafd7d55eddedd82"
```

}

**Name**

**Length**

**Width**

**Total**

---

Composition :

---

Other

Composition :

---