

```
{
  "typeOfReport": {
    "label": "APF",
    "value": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64a7c4a794dfc26ccf86dc61"
    },
    "type": "CREDITOFFICER",
    "_id": "64a7c4a794dfc26ccf86dc64",
    "firstName": "Umesh Devchand ",
    "lastName": "Pagar",
    "mobileNo": "",
    "workMobileNo": "7020235315",
    "email": "umesh.pagar1@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Umesh Devchand ",
    "expectedFees": 2500,
    "quotedAmount": "5900"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64a7c4a794dfc26ccf86dc61",
  "name": "Administrative Office Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "Nashik@sbi.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "1st Floor, BSNL CTTC, Building no 45-47, D Road MIDC, Satpur
Nashik-422007"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
    "email": "sachinraundal9021@gmail.com",
    "lastName": "Raundal",
    "mobileNo": "9021337843",
    "shortName": "Sachin",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
```

```
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "designation": "",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"valuers": [],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
},
"location": {
  "latitude": "20°05'12.2\"N",
  "longitude": "73°54'55.9\"E"
},
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Ozar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Nashik",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
```

```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Dynamic Health Club",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Kalpataru Baug Phase-2",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
```

```
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": false
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
```

```
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "2658/1",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422006",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```



```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "NEW",
"_id": "64d719233cb8cf13cb847cdb",
"ownerName": "Kalpataru Baug - Phase 2",
"ownerPhoneNo": "9527382171",
"appAddress": "Kalpataru Baug - Phase 2 shivaji Nagar ozar ",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "label": "RERA Certificate",
    "value": "60ae129faa6d152c1801b47d"
  },
  "isHardCopy": false,
  "path": "cases/64d719233cb8cf13cb847cdb/
document_1691818164497_Rera_Cert.pdf",
  "fileName": "document_1691818164497_Rera_Cert.pdf",
  "displayStatus": false,
  "id": "510691",
  "uploadedBy": "636a29b64d42487767af43ea",
  "createdAt": "Sat Aug 12 2023 11:00:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Building Plan",
    "value": "60ae124eaa6d152c1801b308"
  },
  "isHardCopy": false,
  "path": "cases/64d719233cb8cf13cb847cdb/
document_1691818179228_Plan_21.pdf",
  "fileName": "document_1691818179228_Plan_21.pdf",
  "displayStatus": false,
  "id": "256513",
  "uploadedBy": "636a29b64d42487767af43ea",
  "createdAt": "Sat Aug 12 2023 11:00:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Commencement Certificate",
    "value": "60ae1247aa6d152c1801b2ea"
  },
  "isHardCopy": false,
  "path": "cases/64d719233cb8cf13cb847cdb/document_1691818195995_CC.pdf",
  "fileName": "document_1691818195995_CC.pdf",
  "displayStatus": false,
  "id": "387331",
  "uploadedBy": "636a29b64d42487767af43ea",
  "createdAt": "Sat Aug 12 2023 11:00:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Title Certificate",
    "value": "60ae125aaa6d152c1801b343"
  },
}
```

```
"isHardCopy": false,
"path": "cases/64d719233cb8cf13cb847cdb/document_1691818219826_TSR.pdf",
"fileName": "document_1691818219826_TSR.pdf",
"displayStatus": false,
"id": "375368",
"uploadedBy": "636a29b64d42487767af43ea",
"createdAt": "Sat Aug 12 2023 11:00:49 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003107",
"createdBy": "636a29b64d42487767af43ea",
"caseHistory": [
{
  "id": "409598",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Sat Aug 12 2023 11:01:15 GMT+0530 (India Standard Time)"
}
],
"owners": [],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487cc",
  "name":
"externallmg_1691818816455_WhatsApp_Image_20230812_at_103733_AM.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818816455_WhatsApp_Image_20230812_at_103733_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487cd",
  "name":
"externallmg_1691818816556_WhatsApp_Image_20230812_at_103734_AM.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818816556_WhatsApp_Image_20230812_at_103734_AM.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487ce",
    "name":
    "externallmg_1691818816624_WhatsApp_Image_20230812_at_103748_AM.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818816624_WhatsApp_Image_20230812_at_103748_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487cf",
    "name":
    "externallmg_1691818816692_WhatsApp_Image_20230812_at_103749_AM_1.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818816692_WhatsApp_Image_20230812_at_103749_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487d0",
    "name":
    "externallmg_1691818816858_WhatsApp_Image_20230812_at_103749_AM.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818816858_WhatsApp_Image_20230812_at_103749_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487d1",
    "name":
    "externallmg_1691818816994_WhatsApp_Image_20230812_at_103757_AM.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818816994_WhatsApp_Image_20230812_at_103757_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487d2",
```

```
"name":
"externallmg_1691818817098_WhatsApp_Image_20230812_at_103758_AM_1.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817098_WhatsApp_Image_20230812_at_103758_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487d3",
  "name":
"externallmg_1691818817230_WhatsApp_Image_20230812_at_103758_AM_2.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817230_WhatsApp_Image_20230812_at_103758_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487d4",
  "name":
"externallmg_1691818817373_WhatsApp_Image_20230812_at_103758_AM.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817373_WhatsApp_Image_20230812_at_103758_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487d5",
  "name":
"externallmg_1691818817494_WhatsApp_Image_20230812_at_103759_AM_1.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817494_WhatsApp_Image_20230812_at_103759_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487d6",
  "name":
"externallmg_1691818817637_WhatsApp_Image_20230812_at_103759_AM_2.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817637_WhatsApp_Image_20230812_at_103759_AM_2.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487d7",
  "name":
"externallmg_1691818817762_WhatsApp_Image_20230812_at_103759_AM.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817762_WhatsApp_Image_20230812_at_103759_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487d8",
  "name":
"externallmg_1691818817900_WhatsApp_Image_20230812_at_103800_AM_1.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817900_WhatsApp_Image_20230812_at_103800_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487d9",
  "name":
"externallmg_1691818817983_WhatsApp_Image_20230812_at_103800_AM_2.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818817983_WhatsApp_Image_20230812_at_103800_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487da",
  "name":
"externallmg_1691818818091_WhatsApp_Image_20230812_at_103800_AM.jpeg",
  "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818818091_WhatsApp_Image_20230812_at_103800_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64d71b433cb8cf13cb8487db",
  "name":
"externallmg_1691818818237_WhatsApp_Image_20230812_at_103801_AM_1.jpeg",
```

```
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818818237_WhatsApp_Image_20230812_at_103801_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487dc",
    "name":
"externallmg_1691818818340_WhatsApp_Image_20230812_at_103801_AM_2.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818818340_WhatsApp_Image_20230812_at_103801_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487dd",
    "name":
"externallmg_1691818818494_WhatsApp_Image_20230812_at_103801_AM.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818818494_WhatsApp_Image_20230812_at_103801_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487de",
    "name":
"externallmg_1691818818618_WhatsApp_Image_20230812_at_103802_AM_1.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818818618_WhatsApp_Image_20230812_at_103802_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64d71b433cb8cf13cb8487df",
    "name":
"externallmg_1691818818762_WhatsApp_Image_20230812_at_103802_AM.jpeg",
    "path": "cases/64d719233cb8cf13cb847cdb/
externallmg_1691818818762_WhatsApp_Image_20230812_at_103802_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

"processingDocuments": [],
"createdAt": "2023-08-12T05:31:15.462Z",
"updatedAt": "2023-08-12T05:40:19.002Z",
"__v": 0,
"invoiceId": "64d719233cb8cf13cb847ce7",
"fullAddress": "APF No. Basement Floor, Kalpataru Baug Phase-2, Near Dynamic Health Club, Village - Ozar, Gut No. 2658/1, Taluka - Nashik, District - Nashik, Nashik, 422006, State - Maharashtra, India",
"updatedBy": "63f9ed37ce84bf289ba991ac"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			