

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Vetting_Of_Estimates",
    "label": "Vetting Of Estimates"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "632ee4c4e2561b46f656d584"
    },
    "type": "CREDITOFFICER",
    "_id": "635f7a01e363ef22db2f2417",
    "firstName": "testadgaon",
    "lastName": "adgaon",
    "mobileNo": "",
    "email": "adgaon@vastukala.org",
    "workMobileNo": "0000000000"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4589000",
    "discussWithPerson": "Bank",
    "expectedFees": 2294.5,
    "quotedAmount": "1180"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "632ee4c4e2561b46f656d584",
  "name": "RACPC Adgaon,",
  "branchCode": "14",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "me@me.sbi",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "RACPC Adgaon, Nashik Branch,Nshik, Maharashtra State –
Maharashtra, Country – India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9f4adce84bf289ba9956e",
    "role": "FRONTDESK + ENGINEER",
```

```
"firstName": "Swapnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": "",
"maker": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
```

```
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.95660956522125",
  "longitude": "73.77139126686583"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "30,31 & 40,41",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Morya Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dnyaneshwar Nagar, Wasan Nagar Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Pathardi Phata",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "Near Police Headquater Ground",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Jaap Builders",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "897/ 1/ B",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
}
```

```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "03",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```



```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422 009",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64e2efeeae896715ef7eec88",
"ownerName": "Mukesh Gupta",
"ownerPhoneNo": "7903048057",
"fullAddress": " Cost Vetting No. 03, 1st Floor, Wing - A, Morya Heights, Jaap Builders,
Near Police Headquater Ground, Plot No. 30,31 & 40,41, New/Current Survey No. 897/
1/ B, Dnyaneshwar Nagar, Wasan Nagar Road, Pathardi Phata, Village - Nashik, Taluka
- Nashik, District - Nashik, Nashik, 422 009",
"remark": "",
"documents": [
{
"documentType": {
"value": "60ae129faa6d152c1801b47d",
"label": "RERA Certificate"
}
},
"inputs": {
```

```
"nameOfApprovingAuthority": {
  "value": "Nashik_Municipal_Corporation",
  "label": "Nashik Municipal Corporation"
},
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "P51600028961"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1692593762496_Rera.pdf",
"path": "cases/64e2efeeae896715ef7eec88/document_1692593762496_Rera.pdf",
"id": "830732",
"uploadedBy": "63f9f4adce84bf289ba9956e",
"createdAt": "Mon Aug 21 2023 10:32:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "documentDate": "31/03/2021",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "897/1/B"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692593849161_Plan.pdf",
  "path": "cases/64e2efeeae896715ef7eec88/document_1692593849161_Plan.pdf",
  "id": "109175",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Mon Aug 21 2023 10:32:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
```



```
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692593863725_OC.pdf",
  "path": "cases/64e2efeeae896715ef7eec88/document_1692593863725_OC.pdf",
  "id": "321861",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Mon Aug 21 2023 10:32:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692593895092_Mukesh_Gupta_TSR.pdf",
  "path": "cases/64e2efeeae896715ef7eec88/
document_1692593895092_Mukesh_Gupta_TSR.pdf",
  "id": "479755",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Mon Aug 21 2023 10:32:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692593910640_Mukesh_Gupta_Plan.pdf",
  "path": "cases/64e2efeeae896715ef7eec88/
document_1692593910640_Mukesh_Gupta_Plan.pdf",
  "id": "155367",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Mon Aug 21 2023 10:32:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12adaa6d152c1801b4bf",
    "label": "Notarized Agreement for Sale"
  },
  "inputs": {
    "from": {
      "value": "Developers",
```

```
    "label": "Developers"
  },
  "Developers": "Mr.Atul Anil Ncrpagsr",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mukesh Gupta"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1692593998837_Mukesh_Gupta_NotaryCC.pdf",
"path": "cases/64e2efeeae896715ef7eec88/
document_1692593998837_Mukesh_Gupta_NotaryCC.pdf",
"id": "295785",
"uploadedBy": "63f9f4adce84bf289ba9956e",
"createdAt": "Mon Aug 21 2023 10:32:10 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae127eaa6d152c1801b3ed",
    "label": "Vetting Estimate"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692606508448_113982.pdf",
  "path": "cases/64e2efeeae896715ef7eec88/
document_1692606508448_113982.pdf",
  "id": "713674",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Mon Aug 21 2023 13:58:28 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003242",
"createdBy": "63f9f4adce84bf289ba9956e",
"caseHistory": [
  {
    "id": "609718",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 21 2023 10:32:38 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mukesh Gupta",
```

```
    "phone": "7903048057",
    "ownershipShare": "",
    "email": "",
    "id": "586262"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabb9",
    "name":
"externallmg_1692606460617_WhatsApp_Image_20230818_at_12502_PM_1.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606460617_WhatsApp_Image_20230818_at_12502_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabba",
    "name":
"externallmg_1692606460713_WhatsApp_Image_20230818_at_12502_PM.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606460713_WhatsApp_Image_20230818_at_12502_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabbb",
    "name":
"externallmg_1692606460769_WhatsApp_Image_20230818_at_12503_PM_1.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606460769_WhatsApp_Image_20230818_at_12503_PM_1.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabbc",
    "name":
"externallmg_1692606460827_WhatsApp_Image_20230818_at_12503_PM.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606460827_WhatsApp_Image_20230818_at_12503_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabbd",
    "name":
"externallmg_1692606460886_WhatsApp_Image_20230818_at_12504_PM_1.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606460886_WhatsApp_Image_20230818_at_12504_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabbe",
    "name":
"externallmg_1692606460930_WhatsApp_Image_20230818_at_12504_PM.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606460930_WhatsApp_Image_20230818_at_12504_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabbf",
    "name":
"externallmg_1692606460974_WhatsApp_Image_20230818_at_12505_PM_1.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606460974_WhatsApp_Image_20230818_at_12505_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fabcb",
    "name":
"externallmg_1692606461087_WhatsApp_Image_20230818_at_12505_PM_2.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461087_WhatsApp_Image_20230818_at_12505_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fab1",
    "name":
    "externallmg_1692606461104_WhatsApp_Image_20230818_at_12505_PM.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461104_WhatsApp_Image_20230818_at_12505_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fab2",
    "name":
    "externallmg_1692606461161_WhatsApp_Image_20230818_at_12506_PM_1.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461161_WhatsApp_Image_20230818_at_12506_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fab3",
    "name":
    "externallmg_1692606461218_WhatsApp_Image_20230818_at_12506_PM_2.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461218_WhatsApp_Image_20230818_at_12506_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fab4",
    "name":
    "externallmg_1692606461261_WhatsApp_Image_20230818_at_12506_PM.jpeg",
    "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461261_WhatsApp_Image_20230818_at_12506_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e31ffdae896715ef7fab5",
```

```
    "name":
"externallmg_1692606461303_WhatsApp_Image_20230818_at_12507_PM_1.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461303_WhatsApp_Image_20230818_at_12507_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e31ffdae896715ef7fab6",
  "name":
"externallmg_1692606461373_WhatsApp_Image_20230818_at_12507_PM.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461373_WhatsApp_Image_20230818_at_12507_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e31ffdae896715ef7fab7",
  "name":
"externallmg_1692606461417_WhatsApp_Image_20230818_at_12508_PM_1.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461417_WhatsApp_Image_20230818_at_12508_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e31ffdae896715ef7fab8",
  "name":
"externallmg_1692606461434_WhatsApp_Image_20230818_at_12508_PM.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461434_WhatsApp_Image_20230818_at_12508_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e31ffdae896715ef7fab9",
  "name":
"externallmg_1692606461477_WhatsApp_Image_20230818_at_12730_PM.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461477_WhatsApp_Image_20230818_at_12730_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e31ffdae896715ef7fabca",
  "name":
"externallmg_1692606461506_WhatsApp_Image_20230818_at_12743_PM_1.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461506_WhatsApp_Image_20230818_at_12743_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e31ffdae896715ef7fabcb",
  "name":
"externallmg_1692606461580_WhatsApp_Image_20230818_at_12743_PM.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461580_WhatsApp_Image_20230818_at_12743_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e31ffdae896715ef7fabcc",
  "name":
"externallmg_1692606461635_WhatsApp_Image_20230818_at_12744_PM.jpeg",
  "path": "cases/64e2efeeae896715ef7eec88/
externallmg_1692606461635_WhatsApp_Image_20230818_at_12744_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-21T05:02:38.931Z",
"updatedAt": "2023-08-21T08:28:28.581Z",
"__v": 0,
"invoiceId": "64e2efefae896715ef7eeca8",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mukesh Gupta",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": ""
```

"relationWithOwner": "self",
"siteVisitContactNo": "7903048057"

}

Name

Length

Width

Total

Composition :

Other

Composition :
