

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb59"
    },
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94231331",
    "firstName": "Namrata Ghone",
    "email": "0_default_",
    "mobileNo": "0_DEFAULT_-",
    "workMobileNo": "0_DEFAULT_91-9769152981"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "1770"
  },
  "organization": {
    "_id": "643a5bee108b68389ed736e5",

```

```
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb59",
  "branchCode": "000352",
  "type": "BRANCH",
  "name": "RACPC Nashik ",
  "email": "sbi.10518@sbi.co.in",
  "mobileNo": "02532501640",
  "alternateMobileNo": "",
  "address": "1st Floor,Patel Plaza ,N.D.Patel Road,Opp BSNL,Landmark Seawoods
Navratna Hotel Nashik-422001",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fdaf22ce84bf289baae42d",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"designation": "",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": ""
```

```
"shortName": "RV",
"workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.998141346773885",
  "longitude": "73.70832797173966"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pimpalgaon Bahula",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Nashik",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "01",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "\\ Nirman Vrundavan Garden - A - 2 Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Gangapur - Satpur Link Road",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Hotel Parth Palace, Near Smt Vitthal Rukmini & Sant Savta",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```

```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "501",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```



```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "195/ F",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422007",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64e43bf0ae896715ef80e04e",
"ownerName": "Sima Sagar Bhati ",
"ownerPhoneNo": "9657836579",
"fullAddress": " Flat No. 501, 5th Floor, \" Nirman Vrundavan Garden - A - 2
```

Apartment, Behind Hotel Parth Palace, Near Smt Vitthal Rukmini & Sant Savta, Plot No. 01, Gangapur - Satpur Link Road, Village - Pimpalgaon Bahula, Gut No. 195/ F, Taluka - Nashik, District - Nashik, Nashik, 422007",

"remark": "",

"documents": [

{

"documentType": {

"value": "60ae124aaa6d152c1801b2f7",

"label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document\_1692679003247\_New\_Doc\_08102023\_1619.pdf",

"path": "cases/64e43bf0ae896715ef80e04e/

document\_1692679003247\_New\_Doc\_08102023\_1619.pdf",

"id": "802556",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Tue Aug 22 2023 10:08:43 GMT+0530 (India Standard Time)"

},

{

"documentType": {

"value": "60ae124aaa6d152c1801b2f7",

"label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document\_1692679054490\_New\_Doc\_08102023\_1621.pdf",

"path": "cases/64e43bf0ae896715ef80e04e/

document\_1692679054490\_New\_Doc\_08102023\_1621.pdf",

"id": "899504",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Tue Aug 22 2023 10:08:43 GMT+0530 (India Standard Time)"

},

{

"documentType": {

"value": "60ae1277aa6d152c1801b3cc",

"label": "Approved Building Plan"

},

"inputs": {

"number": {

"value": "Document\_No",

"label": "Document No"

},

"Document\_No": "B2/ 403/ 4464 "

},

"isHardCopy": false,



```
    "displayStatus": false,
    "fileName": "document_1692679092723_New_Doc_08102023_1622.pdf",
    "path": "cases/64e43bf0ae896715ef80e04e/
document_1692679092723_New_Doc_08102023_1622.pdf",
    "id": "433414",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Aug 22 2023 10:08:43 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003275",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "971829",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Aug 22 2023 10:09:12 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sima Sagar Bhati ",
    "phone": "9657836579",
    "ownershipShare": "",
    "email": "",
    "id": "197356"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4da",
    "name":
"externallmg_1692679260134_WhatsApp_Image_20230819_at_34531_PM_1.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679260134_WhatsApp_Image_20230819_at_34531_PM_1.jpeg",
    "orientation": "landscape"
  }
]
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4db",
    "name":
"externallmg_1692679260362_WhatsApp_Image_20230819_at_34531_PM.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679260362_WhatsApp_Image_20230819_at_34531_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4dc",
    "name":
"externallmg_1692679260544_WhatsApp_Image_20230819_at_34532_PM_1.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679260544_WhatsApp_Image_20230819_at_34532_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4dd",
    "name":
"externallmg_1692679260754_WhatsApp_Image_20230819_at_34532_PM.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679260754_WhatsApp_Image_20230819_at_34532_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4de",
    "name":
"externallmg_1692679260939_WhatsApp_Image_20230819_at_34533_PM_1.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679260939_WhatsApp_Image_20230819_at_34533_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4df",
    "name":
"externallmg_1692679261203_WhatsApp_Image_20230819_at_34533_PM_2.jpeg",
```

```
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679261203_WhatsApp_Image_20230819_at_34533_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4e0",
    "name":
"externallmg_1692679261433_WhatsApp_Image_20230819_at_34533_PM.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679261433_WhatsApp_Image_20230819_at_34533_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4e1",
    "name":
"externallmg_1692679261659_WhatsApp_Image_20230819_at_34534_PM_1.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679261659_WhatsApp_Image_20230819_at_34534_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4e2",
    "name":
"externallmg_1692679261790_WhatsApp_Image_20230819_at_34534_PM_2.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679261790_WhatsApp_Image_20230819_at_34534_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4e3",
    "name":
"externallmg_1692679262067_WhatsApp_Image_20230819_at_34534_PM.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679262067_WhatsApp_Image_20230819_at_34534_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64e43c62ae896715ef80e4e4",
  "name":
"externallmg_1692679262299_WhatsApp_Image_20230819_at_34535_PM.jpeg",
  "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679262299_WhatsApp_Image_20230819_at_34535_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e43c62ae896715ef80e4e5",
  "name":
"externallmg_1692679262399_WhatsApp_Image_20230819_at_34539_PM_1.jpeg",
  "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679262399_WhatsApp_Image_20230819_at_34539_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e43c62ae896715ef80e4e6",
  "name":
"externallmg_1692679262538_WhatsApp_Image_20230819_at_34540_PM_1.jpeg",
  "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679262538_WhatsApp_Image_20230819_at_34540_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e43c62ae896715ef80e4e7",
  "name":
"externallmg_1692679263876_WhatsApp_Image_20230819_at_34540_PM_2.jpeg",
  "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679263876_WhatsApp_Image_20230819_at_34540_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e43c62ae896715ef80e4e8",
  "name":
"externallmg_1692679265604_WhatsApp_Image_20230819_at_34540_PM.jpeg",
  "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679265604_WhatsApp_Image_20230819_at_34540_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4e9",
    "name":
"externallmg_1692679266090_WhatsApp_Image_20230819_at_34541_PM_1.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679266090_WhatsApp_Image_20230819_at_34541_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4ea",
    "name":
"externallmg_1692679266147_WhatsApp_Image_20230819_at_34541_PM.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679266147_WhatsApp_Image_20230819_at_34541_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4eb",
    "name":
"externallmg_1692679266177_WhatsApp_Image_20230819_at_34542_PM_1.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679266177_WhatsApp_Image_20230819_at_34542_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4ec",
    "name":
"externallmg_1692679266179_WhatsApp_Image_20230819_at_34542_PM_2.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externallmg_1692679266179_WhatsApp_Image_20230819_at_34542_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e43c62ae896715ef80e4ed",
```

```

    "name":
    "externalImg_1692679266202_WhatsApp_Image_20230819_at_34542_PM.jpeg",
    "path": "cases/64e43bf0ae896715ef80e04e/
externalImg_1692679266202_WhatsApp_Image_20230819_at_34542_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-22T04:39:12.630Z",
"updatedAt": "2023-08-22T04:41:06.411Z",
"__v": 0,
"invoiceId": "64e43bf0ae896715ef80e05e",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Sima Sagar Bhati ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9657836579"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			