

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64130b50e6a52007fbaa7d90"
    },
    "type": "CREDITOFFICER",
    "_id": "64130b50e6a52007fbaa7d92",
    "firstName": "testgangapur",
    "lastName": "testgangapur",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "3540"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64130b50e6a52007fbaa7d90",
  "name": "Gangapur Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "GangapurBranch@me.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SHree Ganesh Avanie, Gangapur road, Nashik 422013, State
Maharashtra"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "designation": "",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "designation": "",
  "shortName": "Chintamani",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "647ed1960ab64c23c9fcf71d",
  "role": "FRONTDESK",
  "firstName": "Rishidatt",
```

```
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": "",
"shortName": "RV",
"workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.020820942344027",
  "longitude": "73.78587694003284"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Prabhat Empire Apartment ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```

```
"name": "Street 1",
"key": "street1",
"value": "Makhmalabad Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Vitthal Rukhmani Hall & Maharudra Hanuman Mandir",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "13/ 1/ 3",
  "label": true
}
```

```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "602",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```



```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
}
```

```
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
```

```
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
```

```
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
```

```
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
"isAdvanceInvoice": false,
status": true,
caseStatus": "RATEVERIFICATIONCOMPLETED",
```

```
"_id": "64e58c70daae6a1c980f8cd9",
"ownerName": "Vibhavari Sangale ",
"ownerPhoneNo": "9226807155",
"fullAddress": " Flat No. 602, 6th Floor, Prabhat Empire Apartment , Near Vitthal
Rukhmani Hall & Maharudra Hanuman Mandir, Plot No. 3, Makhmalabad Road, Village
- Nashik, Taluka - Nashik, District - Nashik, Nashik, 422003",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1692765082298_sangale.pdf",
    "path": "cases/64e58c70daae6a1c980f8cd9/
document_1692765082298_sangale.pdf",
    "id": "426322",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Wed Aug 23 2023 10:04:27 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "P51600030812"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1692765115295_Rera.pdf",
    "path": "cases/64e58c70daae6a1c980f8cd9/document_1692765115295_Rera.pdf",
    "id": "521351",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Wed Aug 23 2023 10:04:27 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2ea",
      "label": "Commencement Certificate"
    }
  }
]
```



```
},
"inputs": {
  "nameOfApprovingAuthority": {
    "value": "Nashik_Municipal_Corporation",
    "label": "Nashik Municipal Corporation"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "LND/ BP/ C-2/ 224/ 2021"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1692765149978_CC.pdf",
"path": "cases/64e58c70daae6a1c980f8cd9/document_1692765149978_CC.pdf",
"id": "588277",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Aug 23 2023 10:04:27 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "NNRV/ C1/ 31225/ 2023"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692765184235_OC.pdf",
  "path": "cases/64e58c70daae6a1c980f8cd9/document_1692765184235_OC.pdf",
  "id": "366694",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Aug 23 2023 10:04:27 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
"value": "60ae1277aa6d152c1801b3cc",
"label": "Approved Building Plan"
},
"inputs": {
  "nameOfApprovingAuthority": {
    "value": "Nashik_Municipal_Corporation",
    "label": "Nashik Municipal Corporation"
  },
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "C-2/ 224/ 2021"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1692765207641_Plan_1.pdf",
"path": "cases/64e58c70daae6a1c980f8cd9/
document_1692765207641_Plan_1.pdf",
"id": "463745",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Aug 23 2023 10:04:27 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "C-2/ 224/ 2021"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1692765244537_Plan_2.pdf",
  "path": "cases/64e58c70daae6a1c980f8cd9/
document_1692765244537_Plan_2.pdf",
  "id": "984217",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
```

```
    "createdAt": "Wed Aug 23 2023 10:04:27 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003309",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "252397",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Aug 23 2023 10:04:56 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Vibhavari Sangale ",
    "phone": "9226807155",
    "ownershipShare": "",
    "email": "",
    "id": "241279"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92b2",
    "name":
"externallmg_1692765438718_WhatsApp_Image_20230821_at_41519_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438718_WhatsApp_Image_20230821_at_41519_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92b3",
    "name":
"externallmg_1692765438744_WhatsApp_Image_20230821_at_41519_PM.jpeg",
```

```
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438744_WhatsApp_Image_20230821_at_41519_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92b4",
    "name":
"externallmg_1692765438782_WhatsApp_Image_20230821_at_41520_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438782_WhatsApp_Image_20230821_at_41520_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92b5",
    "name":
"externallmg_1692765438809_WhatsApp_Image_20230821_at_41520_PM_2.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438809_WhatsApp_Image_20230821_at_41520_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92b6",
    "name":
"externallmg_1692765438848_WhatsApp_Image_20230821_at_41520_PM.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438848_WhatsApp_Image_20230821_at_41520_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92b7",
    "name":
"externallmg_1692765438887_WhatsApp_Image_20230821_at_41521_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438887_WhatsApp_Image_20230821_at_41521_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64e58cffdaae6a1c980f92b8",
  "name":
"externallmg_1692765438939_WhatsApp_Image_20230821_at_41521_PM_2.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438939_WhatsApp_Image_20230821_at_41521_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cffdaae6a1c980f92b9",
  "name":
"externallmg_1692765438979_WhatsApp_Image_20230821_at_41521_PM.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765438979_WhatsApp_Image_20230821_at_41521_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cffdaae6a1c980f92ba",
  "name":
"externallmg_1692765439005_WhatsApp_Image_20230821_at_41522_PM_1.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439005_WhatsApp_Image_20230821_at_41522_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cffdaae6a1c980f92bb",
  "name":
"externallmg_1692765439063_WhatsApp_Image_20230821_at_41522_PM_2.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439063_WhatsApp_Image_20230821_at_41522_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58cffdaae6a1c980f92bc",
  "name":
"externallmg_1692765439128_WhatsApp_Image_20230821_at_41522_PM.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439128_WhatsApp_Image_20230821_at_41522_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92bd",
    "name":
"externallmg_1692765439172_WhatsApp_Image_20230821_at_41523_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439172_WhatsApp_Image_20230821_at_41523_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92be",
    "name":
"externallmg_1692765439216_WhatsApp_Image_20230821_at_41523_PM.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439216_WhatsApp_Image_20230821_at_41523_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92bf",
    "name":
"externallmg_1692765439254_WhatsApp_Image_20230821_at_41524_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439254_WhatsApp_Image_20230821_at_41524_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92c0",
    "name":
"externallmg_1692765439306_WhatsApp_Image_20230821_at_41524_PM_2.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439306_WhatsApp_Image_20230821_at_41524_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58cffdaae6a1c980f92c1",
```

```
    "name":
"externallmg_1692765439333_WhatsApp_Image_20230821_at_41524_PM.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765439333_WhatsApp_Image_20230821_at_41524_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f9386",
    "name":
"externallmg_1692765449219_WhatsApp_Image_20230821_at_41525_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449219_WhatsApp_Image_20230821_at_41525_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f9387",
    "name":
"externallmg_1692765449263_WhatsApp_Image_20230821_at_41525_PM_2.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449263_WhatsApp_Image_20230821_at_41525_PM_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f9388",
    "name":
"externallmg_1692765449278_WhatsApp_Image_20230821_at_41525_PM.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449278_WhatsApp_Image_20230821_at_41525_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f9389",
    "name":
"externallmg_1692765449325_WhatsApp_Image_20230821_at_41526_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449325_WhatsApp_Image_20230821_at_41526_PM_1.jpeg",
    "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d0adaae6a1c980f938a",
  "name":
"externallmg_1692765449401_WhatsApp_Image_20230821_at_41526_PM_2.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449401_WhatsApp_Image_20230821_at_41526_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d0adaae6a1c980f938b",
  "name":
"externallmg_1692765449461_WhatsApp_Image_20230821_at_41526_PM.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449461_WhatsApp_Image_20230821_at_41526_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d0adaae6a1c980f938c",
  "name":
"externallmg_1692765449493_WhatsApp_Image_20230821_at_41527_PM_1.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449493_WhatsApp_Image_20230821_at_41527_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d0adaae6a1c980f938d",
  "name":
"externallmg_1692765449523_WhatsApp_Image_20230821_at_41527_PM_2.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449523_WhatsApp_Image_20230821_at_41527_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d0adaae6a1c980f938e",
  "name":
"externallmg_1692765449541_WhatsApp_Image_20230821_at_41527_PM.jpeg",
```



```
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449541_WhatsApp_Image_20230821_at_41527_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f938f",
    "name":
"externallmg_1692765449572_WhatsApp_Image_20230821_at_41528_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449572_WhatsApp_Image_20230821_at_41528_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f9390",
    "name":
"externallmg_1692765449616_WhatsApp_Image_20230821_at_41528_PM_2.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449616_WhatsApp_Image_20230821_at_41528_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f9391",
    "name":
"externallmg_1692765449694_WhatsApp_Image_20230821_at_41528_PM.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449694_WhatsApp_Image_20230821_at_41528_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e58d0adaae6a1c980f9392",
    "name":
"externallmg_1692765449723_WhatsApp_Image_20230821_at_41529_PM_1.jpeg",
    "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449723_WhatsApp_Image_20230821_at_41529_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64e58d0adaae6a1c980f9393",
  "name":
"externallmg_1692765449798_WhatsApp_Image_20230821_at_41529_PM_2.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449798_WhatsApp_Image_20230821_at_41529_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d0adaae6a1c980f9394",
  "name":
"externallmg_1692765449874_WhatsApp_Image_20230821_at_41529_PM.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449874_WhatsApp_Image_20230821_at_41529_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d0adaae6a1c980f9395",
  "name":
"externallmg_1692765449961_WhatsApp_Image_20230821_at_41530_PM_1.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765449961_WhatsApp_Image_20230821_at_41530_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d15daae6a1c980f93d5",
  "name":
"externallmg_1692765460492_WhatsApp_Image_20230821_at_41530_PM_2.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765460492_WhatsApp_Image_20230821_at_41530_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d15daae6a1c980f93d6",
  "name":
"externallmg_1692765460583_WhatsApp_Image_20230821_at_41530_PM.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765460583_WhatsApp_Image_20230821_at_41530_PM.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d15daae6a1c980f93d7",
  "name":
  "externallmg_1692765460896_WhatsApp_Image_20230822_at_32456_PM_1.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765460896_WhatsApp_Image_20230822_at_32456_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d15daae6a1c980f93d8",
  "name":
  "externallmg_1692765460899_WhatsApp_Image_20230822_at_32456_PM_2.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765460899_WhatsApp_Image_20230822_at_32456_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e58d15daae6a1c980f93d9",
  "name":
  "externallmg_1692765460930_WhatsApp_Image_20230822_at_32456_PM.jpeg",
  "path": "cases/64e58c70daae6a1c980f8cd9/
externallmg_1692765460930_WhatsApp_Image_20230822_at_32456_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-23T04:34:56.316Z",
"updatedAt": "2023-08-23T04:37:41.091Z",
"__v": 0,
"invoiceId": "64e58c70daae6a1c980f8cec",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Vibhavari Sangale ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```

"ownershipShare": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9226807155"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			