

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7c3"
    },
    "type": "CREDITOFFICER",
    "_id": "64e727581452884516b694f4",
    "firstName": "Rajpal",
    "lastName": "Varma",
    "mobileNo": "",
    "workMobileNo": "7276503838",
    "email": "sbi.01821@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2300000",
    "discussWithPerson": "Mangesh A. Gaware",
    "expectedFees": 1150,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7c3",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Churchgate (Mumbai) Branch",
  "email": "sbi.01821@sbi.co.in",
  "mobileNo": "022-22030017",
  "alternateMobileNo": "",
  "address": "\\The International \\, 17 Maharshi Karve Road, Churchgate, Mumbai -
400 020, State - Maharashtra, Country - India. \\r\\n",
  "ledgerName": "STATE BANK OF INDIA - CHURCHGATE",
  "fax": "022-22002752",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6401b61f0e28255fb44e636a",
  "role": "SITEENGINEER",
  "firstName": "Sanket",
  "email": "ksanket7414@yahoo.com",
  "lastName": "Karalkar",
  "mobileNo": "8080582858",
  "designation": "",
  "shortName": "SAK",
  "workWithDocumentMaker": ""
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.405818746173846",
  "longitude": "72.82398495646935"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    72.82398495646935,
    19.405818746173846
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-24T11:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Achole",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Durvas",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Yashwant Viva Township",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "M",
  "label": true
},
}
```

```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```



```
"value": "502",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": false,
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nalasopara East",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```

```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64e72af01452884516b69f7a",
"ownerName": "Rajesh Anant bharati ",
"ownerPhoneNo": "8779645900",
"appAddress": "502 Durvesh co operative\society \nsector no 4 \nVasai 401209",
"remark": "Sbi\nRajpal Varma\n16 maharshi Karve road\nchachget\n7276503838",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64e72af01452884516b69f7a/document_1692871299856_22950.pdf",
    "fileName": "document_1692871299856_22950.pdf",
    "displayStatus": false,
    "id": "489616",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Thu Aug 24 2023 15:33:00 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003354",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "233489",
    "title": "Create Lead",
```



```
"description": "Create Lead",
"datetime": "Thu Aug 24 2023 15:33:28 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Rajesh Anant bharati ",
"phone": "8779645900",
"ownershipShare": "",
"email": "",
"id": "373039"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64ec1dd3eb1f822256d73619",
"name":
"externallmg_1693195731792_WhatsApp_Image_20230826_at_93452_PM_2.jpeg",
"path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731792_WhatsApp_Image_20230826_at_93452_PM_2.jpeg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64ec1dd3eb1f822256d7361a",
"name":
"externallmg_1693195731795_WhatsApp_Image_20230826_at_93453_PM_1.jpeg",
"path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731795_WhatsApp_Image_20230826_at_93453_PM_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "64ec1dd3eb1f822256d7361b",
```

```
"name":
"externallmg_1693195731800_WhatsApp_Image_20230826_at_93453_PM_2.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731800_WhatsApp_Image_20230826_at_93453_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d7361c",
  "name":
"externallmg_1693195731806_WhatsApp_Image_20230826_at_93453_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731806_WhatsApp_Image_20230826_at_93453_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d7361d",
  "name":
"externallmg_1693195731810_WhatsApp_Image_20230826_at_93454_PM_1.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731810_WhatsApp_Image_20230826_at_93454_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d7361e",
  "name":
"externallmg_1693195731813_WhatsApp_Image_20230826_at_93454_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731813_WhatsApp_Image_20230826_at_93454_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d7361f",
  "name":
"externallmg_1693195731816_WhatsApp_Image_20230826_at_93457_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731816_WhatsApp_Image_20230826_at_93457_PM.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d73620",
  "name":
"externallmg_1693195731819_WhatsApp_Image_20230826_at_93459_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731819_WhatsApp_Image_20230826_at_93459_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d73621",
  "name":
"externallmg_1693195731821_WhatsApp_Image_20230826_at_93500_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731821_WhatsApp_Image_20230826_at_93500_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d73622",
  "name":
"externallmg_1693195731823_WhatsApp_Image_20230826_at_93501_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731823_WhatsApp_Image_20230826_at_93501_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d73623",
  "name":
"externallmg_1693195731825_WhatsApp_Image_20230826_at_93646_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731825_WhatsApp_Image_20230826_at_93646_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1dd3eb1f822256d73624",
  "name":
"externallmg_1693195731827_WhatsApp_Image_20230826_at_93650_PM_1.jpeg",
```

```
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731827_WhatsApp_Image_20230826_at_93650_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1dd3eb1f822256d73625",
    "name":
"externallmg_1693195731829_WhatsApp_Image_20230826_at_93650_PM.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731829_WhatsApp_Image_20230826_at_93650_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1dd3eb1f822256d73626",
    "name":
"externallmg_1693195731835_WhatsApp_Image_20230826_at_93651_PM_1.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731835_WhatsApp_Image_20230826_at_93651_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1dd3eb1f822256d73627",
    "name":
"externallmg_1693195731837_WhatsApp_Image_20230826_at_93651_PM.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195731837_WhatsApp_Image_20230826_at_93651_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1de8eb1f822256d73696",
    "name":
"externallmg_1693195752779_WhatsApp_Image_20230826_at_93652_PM_1.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752779_WhatsApp_Image_20230826_at_93652_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64ec1de8eb1f822256d73697",
  "name":
"externallmg_1693195752782_WhatsApp_Image_20230826_at_93652_PM_2.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752782_WhatsApp_Image_20230826_at_93652_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d73698",
  "name":
"externallmg_1693195752785_WhatsApp_Image_20230826_at_93652_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752785_WhatsApp_Image_20230826_at_93652_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d73699",
  "name":
"externallmg_1693195752788_WhatsApp_Image_20230826_at_93653_PM_1.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752788_WhatsApp_Image_20230826_at_93653_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d7369a",
  "name":
"externallmg_1693195752792_WhatsApp_Image_20230826_at_93653_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752792_WhatsApp_Image_20230826_at_93653_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d7369b",
  "name":
"externallmg_1693195752796_WhatsApp_Image_20230826_at_93732_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752796_WhatsApp_Image_20230826_at_93732_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1de8eb1f822256d7369c",
    "name":
"externallmg_1693195752801_WhatsApp_Image_20230826_at_93448_PM_1.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752801_WhatsApp_Image_20230826_at_93448_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1de8eb1f822256d7369d",
    "name":
"externallmg_1693195752806_WhatsApp_Image_20230826_at_93448_PM.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752806_WhatsApp_Image_20230826_at_93448_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1de8eb1f822256d7369e",
    "name":
"externallmg_1693195752811_WhatsApp_Image_20230826_at_93449_PM_1.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752811_WhatsApp_Image_20230826_at_93449_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1de8eb1f822256d7369f",
    "name":
"externallmg_1693195752818_WhatsApp_Image_20230826_at_93449_PM.jpeg",
    "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752818_WhatsApp_Image_20230826_at_93449_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ec1de8eb1f822256d736a0",
```

```
    "name":
"externallmg_1693195752823_WhatsApp_Image_20230826_at_93450_PM_1.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752823_WhatsApp_Image_20230826_at_93450_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a1",
  "name":
"externallmg_1693195752827_WhatsApp_Image_20230826_at_93450_PM_2.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752827_WhatsApp_Image_20230826_at_93450_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a2",
  "name":
"externallmg_1693195752832_WhatsApp_Image_20230826_at_93450_PM_3.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752832_WhatsApp_Image_20230826_at_93450_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a3",
  "name":
"externallmg_1693195752835_WhatsApp_Image_20230826_at_93450_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752835_WhatsApp_Image_20230826_at_93450_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a4",
  "name":
"externallmg_1693195752839_WhatsApp_Image_20230826_at_93451_PM_1.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752839_WhatsApp_Image_20230826_at_93451_PM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a5",
  "name":
"externallmg_1693195752842_WhatsApp_Image_20230826_at_93451_PM_2.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752842_WhatsApp_Image_20230826_at_93451_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a6",
  "name":
"externallmg_1693195752846_WhatsApp_Image_20230826_at_93451_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752846_WhatsApp_Image_20230826_at_93451_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a7",
  "name":
"externallmg_1693195752852_WhatsApp_Image_20230826_at_93452_PM_1.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752852_WhatsApp_Image_20230826_at_93452_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ec1de8eb1f822256d736a8",
  "name":
"externallmg_1693195752855_WhatsApp_Image_20230826_at_93452_PM.jpeg",
  "path": "cases/64e72af01452884516b69f7a/
externallmg_1693195752855_WhatsApp_Image_20230826_at_93452_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-24T10:03:28.363Z",
"updatedAt": "2023-08-28T04:09:12.950Z",
"__v": 0,
```


"invoiceId": "64e72af01452884516b69f84",
"fullAddress": " Flat No. 502, 5th Floor, Wing - M, Durvas, Yashwant Viva Township,
Village - Achole, Nalasopara East, Vasai",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Rajesh Anant bharati ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8779645900",
"remarks": []

}

Name	Length	Width	Total
Composition :			
Other Composition :			