

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "firstName": "Manish",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60b7177d2ffdf65bcd65882a",
"role": "PICKUPPERSON",
"firstName": "Saurabh",
"email": "saurabhvelonde143@gmail.com",
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
```

```
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  {

```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.44696252657104",
  "longitude": "72.81436897976087"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Virar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Radiant Hospital",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Land & Building",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
```

```
    "value": "",
    "label": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```



```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64e9e12b1452884516bbeaf9",
"ownerName": "Messarse United Forever LLP",
"ownerPhoneNo": "7977861026",
"fullAddress": " Land and Building No. Land & Building, Ground Floor, Radiant
Hospital, Village - Virar",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1693047284230_Radiant_Hospital.pdf",
    "path": "cases/64e9e12b1452884516bbeaf9/
document_1693047284230_Radiant_Hospital.pdf",
    "id": "713666",
    "uploadedBy": "62691c48afd7d55eddecfda3",
    "createdAt": "Sat Aug 26 2023 16:55:00 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003417",
"createdBy": "62691c48afd7d55eddecfda3",
"caseHistory": [
  {
    "id": "953208",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 26 2023 16:55:31 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Messarse United Forever LLP",
    "phone": "7977861026",
```

```
    "ownershipShare": "",
    "email": "",
    "id": "557421"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4059",
    "name":
"externalImg_1693051126261_WhatsApp_Image_20230817_at_32416_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externalImg_1693051126261_WhatsApp_Image_20230817_at_32416_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc405a",
    "name":
"externalImg_1693051126263_WhatsApp_Image_20230817_at_32416_PM_2.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externalImg_1693051126263_WhatsApp_Image_20230817_at_32416_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc405b",
    "name":
"externalImg_1693051126266_WhatsApp_Image_20230817_at_32416_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externalImg_1693051126266_WhatsApp_Image_20230817_at_32416_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64e9e8f61452884516bc405c",
    "name":
"externallmg_1693051126269_WhatsApp_Image_20230817_at_32417_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126269_WhatsApp_Image_20230817_at_32417_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc405d",
    "name":
"externallmg_1693051126272_WhatsApp_Image_20230817_at_32417_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126272_WhatsApp_Image_20230817_at_32417_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc405e",
    "name":
"externallmg_1693051126275_WhatsApp_Image_20230817_at_32418_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126275_WhatsApp_Image_20230817_at_32418_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc405f",
    "name":
"externallmg_1693051126278_WhatsApp_Image_20230817_at_32418_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126278_WhatsApp_Image_20230817_at_32418_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4060",
    "name":
"externallmg_1693051126282_WhatsApp_Image_20230817_at_32419_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126282_WhatsApp_Image_20230817_at_32419_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4061",
    "name":
"externallmg_1693051126285_WhatsApp_Image_20230817_at_32419_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126285_WhatsApp_Image_20230817_at_32419_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4062",
    "name":
"externallmg_1693051126289_WhatsApp_Image_20230817_at_32420_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126289_WhatsApp_Image_20230817_at_32420_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4063",
    "name":
"externallmg_1693051126292_WhatsApp_Image_20230817_at_32420_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126292_WhatsApp_Image_20230817_at_32420_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4064",
    "name":
"externallmg_1693051126296_WhatsApp_Image_20230817_at_32421_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126296_WhatsApp_Image_20230817_at_32421_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4065",
```

```
    "name":
"externallmg_1693051126301_WhatsApp_Image_20230817_at_32421_PM_2.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126301_WhatsApp_Image_20230817_at_32421_PM_2.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4066",
    "name":
"externallmg_1693051126304_WhatsApp_Image_20230817_at_32421_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126304_WhatsApp_Image_20230817_at_32421_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4067",
    "name":
"externallmg_1693051126307_WhatsApp_Image_20230817_at_32422_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126307_WhatsApp_Image_20230817_at_32422_PM_1.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4068",
    "name":
"externallmg_1693051126311_WhatsApp_Image_20230817_at_32422_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126311_WhatsApp_Image_20230817_at_32422_PM.jpeg",
    "orientation": "portrait"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e8f61452884516bc4069",
    "name":
"externallmg_1693051126314_WhatsApp_Image_20230817_at_32423_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126314_WhatsApp_Image_20230817_at_32423_PM_1.jpeg",
    "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e8f61452884516bc406a",
  "name":
"externallmg_1693051126315_WhatsApp_Image_20230817_at_32423_PM.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126315_WhatsApp_Image_20230817_at_32423_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e8f61452884516bc406b",
  "name":
"externallmg_1693051126318_WhatsApp_Image_20230817_at_32424_PM_1.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126318_WhatsApp_Image_20230817_at_32424_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e8f61452884516bc406c",
  "name":
"externallmg_1693051126320_WhatsApp_Image_20230817_at_32424_PM.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051126320_WhatsApp_Image_20230817_at_32424_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e9041452884516bc40d6",
  "name":
"externallmg_1693051140389_WhatsApp_Image_20230817_at_32425_PM_1.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140389_WhatsApp_Image_20230817_at_32425_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e9041452884516bc40d7",
  "name":
"externallmg_1693051140393_WhatsApp_Image_20230817_at_32425_PM_2.jpeg",
```

```
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140393_WhatsApp_Image_20230817_at_32425_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40d8",
    "name":
"externallmg_1693051140398_WhatsApp_Image_20230817_at_32425_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140398_WhatsApp_Image_20230817_at_32425_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40d9",
    "name":
"externallmg_1693051140401_WhatsApp_Image_20230817_at_32426_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140401_WhatsApp_Image_20230817_at_32426_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40da",
    "name":
"externallmg_1693051140404_WhatsApp_Image_20230817_at_32426_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140404_WhatsApp_Image_20230817_at_32426_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40db",
    "name":
"externallmg_1693051140408_WhatsApp_Image_20230817_at_32427_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140408_WhatsApp_Image_20230817_at_32427_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64e9e9041452884516bc40dc",
  "name":
"externallmg_1693051140411_WhatsApp_Image_20230817_at_32427_PM.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140411_WhatsApp_Image_20230817_at_32427_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e9041452884516bc40dd",
  "name":
"externallmg_1693051140413_WhatsApp_Image_20230817_at_32428_PM_1.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140413_WhatsApp_Image_20230817_at_32428_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e9041452884516bc40de",
  "name":
"externallmg_1693051140415_WhatsApp_Image_20230817_at_32428_PM_2.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140415_WhatsApp_Image_20230817_at_32428_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e9041452884516bc40df",
  "name":
"externallmg_1693051140417_WhatsApp_Image_20230817_at_32428_PM.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140417_WhatsApp_Image_20230817_at_32428_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64e9e9041452884516bc40e0",
  "name":
"externallmg_1693051140419_WhatsApp_Image_20230817_at_32429_PM_1.jpeg",
  "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140419_WhatsApp_Image_20230817_at_32429_PM_1.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40e1",
    "name":
"externallmg_1693051140421_WhatsApp_Image_20230817_at_32429_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140421_WhatsApp_Image_20230817_at_32429_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40e2",
    "name":
"externallmg_1693051140423_WhatsApp_Image_20230817_at_32430_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140423_WhatsApp_Image_20230817_at_32430_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40e3",
    "name":
"externallmg_1693051140426_WhatsApp_Image_20230817_at_32430_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140426_WhatsApp_Image_20230817_at_32430_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40e4",
    "name":
"externallmg_1693051140428_WhatsApp_Image_20230817_at_32431_PM_1.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140428_WhatsApp_Image_20230817_at_32431_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40e5",
```

```

    "name":
    "externallmg_1693051140430_WhatsApp_Image_20230817_at_32431_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140430_WhatsApp_Image_20230817_at_32431_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64e9e9041452884516bc40e6",
    "name":
    "externallmg_1693051140432_WhatsApp_Image_20230817_at_32432_PM.jpeg",
    "path": "cases/64e9e12b1452884516bbeaf9/
externallmg_1693051140432_WhatsApp_Image_20230817_at_32432_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"createdAt": "2023-08-26T11:25:31.582Z",
"updatedAt": "2023-08-26T11:59:00.520Z",
"__v": 0,
"invoiceId": "64e9e12b1452884516bbeb05",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "5ff3ead28cda966090eacbbe",
"contactPersonName": "Messarse United Forever LLP",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7977861026"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			