

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64ec3372eb1f822256d7a6c0"
    },
    "type": "CREDITOFFICER",
    "_id": "64ec3372eb1f822256d7a6c2",
    "firstName": "Abhimanyu",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8763993948",
    "email": "bmmsro2197@centralbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "18200000",
    "discussWithPerson": "Abhimanyu",
    "expectedFees": 9100,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64ec3372eb1f822256d7a6c0",
  "name": "Goregaon West Branch",
  "branchCode": "",
  "mobileNo": "022 28720068",
  "alternateMobileNo": "",
  "email": "bmmsro2197@centralbank.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Nirala House. Pt. Dayal Upadhyay Chowk, 36. Jawahar Nahar, Goregaon
West, Mumbai - 400 1004"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
```

```
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.146661568533496",
  "longitude": "72.83058987791128"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83058987791128,
    19.146661568533496
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-08-28T10:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-08-28T10:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
```

```
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Oshiwara",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
}
```

```
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "66",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Oshiwara Avalon CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Oshiwara Mhada",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
```

```
"key": "street2",
"value": "New Link Road",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
}
```



```
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "502",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
```

```
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri West\t",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
},
"locationMapImg": []
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
}
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64ec3aeaeb1f822256d7d2d9",
"ownerName": "Soham Sanjay Mhatre",
"ownerPhoneNo": "8291235544",
"appAddress": "flat no 502 bldg no no 7 mhada oshiora adarsh nagar opp oshiora
police station oshiora Andheri w",
"remark": "old agreement new agreement will receive today ",
"documents": [
  {
```



```
"documentType": {
  "label": "Agreement for sale",
  "value": "60af48bf2ffdf65bcd6585fa"
},
"isHardCopy": false,
"path": "cases/64ec3aeaeb1f822256d7d2d9/
document_1693202962870_DOC20230826WA0008.pdf",
"fileName": "document_1693202962870_DOC20230826WA0008.pdf",
"displayStatus": false,
"id": "115992",
"uploadedBy": "627219d6afd7d55eddedd283",
"createdAt": "Mon Aug 28 2023 11:42:29 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693225587353_119735.pdf",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
document_1693225587353_119735.pdf",
  "id": "194922",
  "uploadedBy": "6006d4ce5080a310ac1fd2c2",
  "createdAt": "Mon Aug 28 2023 17:56:40 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003422",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "331357",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 28 2023 11:42:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Soham Sanjay Mhatre",
    "phone": "8291235544",
    "ownershipShare": "",
    "email": "",
    "id": "313551"
  }
]
```

```
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b16",
    "name":
"externallmg_1693298957514_WhatsApp_Image_20230829_at_21230_PM_1.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957514_WhatsApp_Image_20230829_at_21230_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b17",
    "name":
"externallmg_1693298957518_WhatsApp_Image_20230829_at_21230_PM_2.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957518_WhatsApp_Image_20230829_at_21230_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b18",
    "name":
"externallmg_1693298957528_WhatsApp_Image_20230829_at_21231_PM_1.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957528_WhatsApp_Image_20230829_at_21231_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b19",
    "name":
"externallmg_1693298957534_WhatsApp_Image_20230829_at_21231_PM.jpeg",
```

```
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957534_WhatsApp_Image_20230829_at_21231_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b1a",
    "name":
"externallmg_1693298957539_WhatsApp_Image_20230829_at_21232_PM_1.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957539_WhatsApp_Image_20230829_at_21232_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b1b",
    "name":
"externallmg_1693298957545_WhatsApp_Image_20230829_at_21232_PM_2.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957545_WhatsApp_Image_20230829_at_21232_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b1c",
    "name":
"externallmg_1693298957551_WhatsApp_Image_20230829_at_21232_PM.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957551_WhatsApp_Image_20230829_at_21232_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb10deb1f822256da8b1d",
    "name":
"externallmg_1693298957556_WhatsApp_Image_20230829_at_21233_PM_1.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957556_WhatsApp_Image_20230829_at_21233_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64edb10deb1f822256da8b1e",
  "name":
"externallmg_1693298957558_WhatsApp_Image_20230829_at_21233_PM_2.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298957558_WhatsApp_Image_20230829_at_21233_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b59",
  "name":
"externallmg_1693298973797_WhatsApp_Image_20230829_at_21233_PM.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973797_WhatsApp_Image_20230829_at_21233_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b5a",
  "name":
"externallmg_1693298973798_WhatsApp_Image_20230829_at_21234_PM_1.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973798_WhatsApp_Image_20230829_at_21234_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b5b",
  "name":
"externallmg_1693298973802_WhatsApp_Image_20230829_at_21234_PM_2.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973802_WhatsApp_Image_20230829_at_21234_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b5c",
  "name":
"externallmg_1693298973805_WhatsApp_Image_20230829_at_21234_PM.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973805_WhatsApp_Image_20230829_at_21234_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb11deb1f822256da8b5d",
    "name":
"externallmg_1693298973807_WhatsApp_Image_20230829_at_21235_PM_1.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973807_WhatsApp_Image_20230829_at_21235_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb11deb1f822256da8b5e",
    "name":
"externallmg_1693298973811_WhatsApp_Image_20230829_at_21235_PM_2.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973811_WhatsApp_Image_20230829_at_21235_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb11deb1f822256da8b5f",
    "name":
"externallmg_1693298973813_WhatsApp_Image_20230829_at_21235_PM.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973813_WhatsApp_Image_20230829_at_21235_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb11deb1f822256da8b60",
    "name":
"externallmg_1693298973816_WhatsApp_Image_20230829_at_21236_PM_1.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973816_WhatsApp_Image_20230829_at_21236_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb11deb1f822256da8b61",
```

```
    "name":
"externallmg_1693298973818_WhatsApp_Image_20230829_at_21236_PM_2.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973818_WhatsApp_Image_20230829_at_21236_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b62",
  "name":
"externallmg_1693298973820_WhatsApp_Image_20230829_at_21236_PM.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973820_WhatsApp_Image_20230829_at_21236_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b63",
  "name":
"externallmg_1693298973822_WhatsApp_Image_20230829_at_21237_PM_1.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973822_WhatsApp_Image_20230829_at_21237_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b64",
  "name":
"externallmg_1693298973825_WhatsApp_Image_20230829_at_21237_PM.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973825_WhatsApp_Image_20230829_at_21237_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b65",
  "name":
"externallmg_1693298973827_WhatsApp_Image_20230829_at_21238_PM_1.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973827_WhatsApp_Image_20230829_at_21238_PM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b66",
  "name":
"externallmg_1693298973829_WhatsApp_Image_20230829_at_21238_PM_2.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973829_WhatsApp_Image_20230829_at_21238_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b67",
  "name":
"externallmg_1693298973832_WhatsApp_Image_20230829_at_21238_PM.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973832_WhatsApp_Image_20230829_at_21238_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b68",
  "name":
"externallmg_1693298973839_WhatsApp_Image_20230829_at_21239_PM_1.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973839_WhatsApp_Image_20230829_at_21239_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b69",
  "name":
"externallmg_1693298973845_WhatsApp_Image_20230829_at_21239_PM_2.jpeg",
  "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973845_WhatsApp_Image_20230829_at_21239_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64edb11deb1f822256da8b6a",
  "name":
"externallmg_1693298973850_WhatsApp_Image_20230829_at_21239_PM.jpeg",
```

```

    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973850_WhatsApp_Image_20230829_at_21239_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64edb11deb1f822256da8b6b",
    "name":
"externallmg_1693298973856_WhatsApp_Image_20230829_at_21230_PM.jpeg",
    "path": "cases/64ec3aeaeb1f822256d7d2d9/
externallmg_1693298973856_WhatsApp_Image_20230829_at_21230_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-08-28T06:12:59.016Z",
"updatedAt": "2023-08-29T08:49:33.939Z",
"__v": 0,
"invoiceId": "64ec3aebeb1f822256d7d2ef",
"fullAddress": "Residential Flat No. 502, 5th Floor, Oshiwara Avalon CHSL, Plot No.
66, Oshiwara Mhada, New Link Road, Village - Oshiwara, Andheri West\t, Mumbai,
State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fd2c2",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Soham Sanjay Mhatre",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8291235544"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			