

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "647ebb3f0ab64c23c9fcb8b2"
    },
    "type": "CREDITOFFICER",
    "_id": "64eecf64eb1f822256dbd63a",
    "firstName": "Sidhartha ",
    "lastName": "Mhade",
    "mobileNo": "",
    "workMobileNo": "8980518779",
    "email": "Sidhartha@unionbankofindia.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Sidhartha ",
  }
}
```

```
"expectedFees": 2500,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "647ebb3f0ab64c23c9fcb8b2",
  "name": "SAMB Fort Branch",
  "branchCode": "",
  "mobileNo": "02222615205",
  "alternateMobileNo": "",
  "email": "bm3077@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bharat House, Ground floor, 104, M. S. Marg, Fort, Mumbai - 400001,
State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
}
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f9462345132d6a6bddb9d5",
    "role": "SITEENGINEER",
    "firstName": "Dashrath ",
    "email": "dasrat.jaiswar1234@gmail.com",
    "lastName": "Jaiswar",
    "mobileNo": "9987305468",
    "designation": "",
    "shortName": "DFJ",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
  },
  "maker": "",
  "checker": "",
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
```

```
    "value": "[N]C.C.I.T/I -14/52/2008-09",
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.051695211527722",
  "longitude": "72.86802997791128"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86802997791128,
    19.051695211527722
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-01T06:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chunabhatti",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "Shree Hind CHSL ( Vrindavan Complex)",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```

```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "05",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```



```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
```

```
"status": true,
"name": "Suburb",
"key": "suburb",
"value": "Sion west ",
"label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64f17ff7eb1f822256defb6a",
"ownerName": "Tejal Shah",
"ownerPhoneNo": "9820013017",
"appAddress": "Flat no 05,Building No 7,Kriti Prakash Shree Hind CHS ,N.S.Mankikar
Marg,Chunabhatti Mumbai",
"remark": "visit on 2.09.2023 \n+919820013017",
"documents": [
  {
    "documentType": {
      "label": "Gift Deed",
      "value": "60ae1251aa6d152c1801b317"
    },
    "isHardCopy": false,
    "path": "cases/64f17ff7eb1f822256defb6a/
document_1693548383738_Tejal_ShahUBI_SAMB_Fort.pdf",
    "fileName": "document_1693548383738_Tejal_ShahUBI_SAMB_Fort.pdf",
    "displayStatus": false,
    "id": "920065",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Fri Sep 01 2023 11:38:24 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003510",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "393489",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 01 2023 11:38:55 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```



```
{
  "name": "Tejal Shah",
  "phone": "9820013017",
  "ownershipShare": "",
  "email": "",
  "id": "275251"
},
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010a5a8e9b70221dfad97",
    "name":
"externalImg_1694503076900_WhatsApp_Image_20230912_at_122659_PM.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externalImg_1694503076900_WhatsApp_Image_20230912_at_122659_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010a5a8e9b70221dfad98",
    "name":
"externalImg_1694503076902_WhatsApp_Image_20230912_at_122700_PM.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externalImg_1694503076902_WhatsApp_Image_20230912_at_122700_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010a5a8e9b70221dfad99",
    "name":
"externalImg_1694503076905_WhatsApp_Image_20230912_at_122702_PM.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externalImg_1694503076905_WhatsApp_Image_20230912_at_122702_PM.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010a5a8e9b70221dfad9a",
  "name":
"externallmg_1694503076908_WhatsApp_Image_20230912_at_122704_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076908_WhatsApp_Image_20230912_at_122704_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010a5a8e9b70221dfad9b",
  "name":
"externallmg_1694503076911_WhatsApp_Image_20230912_at_122705_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076911_WhatsApp_Image_20230912_at_122705_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010a5a8e9b70221dfad9c",
  "name":
"externallmg_1694503076913_WhatsApp_Image_20230912_at_122707_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076913_WhatsApp_Image_20230912_at_122707_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010a5a8e9b70221dfad9d",
  "name":
"externallmg_1694503076917_WhatsApp_Image_20230912_at_122708_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076917_WhatsApp_Image_20230912_at_122708_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010a5a8e9b70221dfad9e",
  "name":
"externallmg_1694503076919_WhatsApp_Image_20230912_at_122709_PM.jpeg",
```

```
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076919_WhatsApp_Image_20230912_at_122709_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010a5a8e9b70221dfad9f",
    "name":
"externallmg_1694503076920_WhatsApp_Image_20230912_at_122711_PM.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076920_WhatsApp_Image_20230912_at_122711_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010a5a8e9b70221dfada0",
    "name":
"externallmg_1694503076923_WhatsApp_Image_20230912_at_122712_PM_1.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076923_WhatsApp_Image_20230912_at_122712_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010a5a8e9b70221dfada1",
    "name":
"externallmg_1694503076925_WhatsApp_Image_20230912_at_122712_PM.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076925_WhatsApp_Image_20230912_at_122712_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010a5a8e9b70221dfada2",
    "name":
"externallmg_1694503076927_WhatsApp_Image_20230912_at_122713_PM_1.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076927_WhatsApp_Image_20230912_at_122713_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "650010a5a8e9b70221dfada3",
  "name":
"externallmg_1694503076929_WhatsApp_Image_20230912_at_122713_PM_2.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076929_WhatsApp_Image_20230912_at_122713_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010a5a8e9b70221dfada4",
  "name":
"externallmg_1694503076931_WhatsApp_Image_20230912_at_122713_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076931_WhatsApp_Image_20230912_at_122713_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010a5a8e9b70221dfada5",
  "name":
"externallmg_1694503076933_WhatsApp_Image_20230912_at_122714_PM_1.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503076933_WhatsApp_Image_20230912_at_122714_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae00",
  "name":
"externallmg_1694503094699_WhatsApp_Image_20230912_at_122714_PM_2.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094699_WhatsApp_Image_20230912_at_122714_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae01",
  "name":
"externallmg_1694503094700_WhatsApp_Image_20230912_at_122714_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094700_WhatsApp_Image_20230912_at_122714_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010b6a8e9b70221dfae02",
    "name":
"externallmg_1694503094704_WhatsApp_Image_20230912_at_122715_PM_1.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094704_WhatsApp_Image_20230912_at_122715_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010b6a8e9b70221dfae03",
    "name":
"externallmg_1694503094708_WhatsApp_Image_20230912_at_122715_PM.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094708_WhatsApp_Image_20230912_at_122715_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010b6a8e9b70221dfae04",
    "name":
"externallmg_1694503094712_WhatsApp_Image_20230912_at_122716_PM_1.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094712_WhatsApp_Image_20230912_at_122716_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010b6a8e9b70221dfae05",
    "name":
"externallmg_1694503094716_WhatsApp_Image_20230912_at_122716_PM_2.jpeg",
    "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094716_WhatsApp_Image_20230912_at_122716_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650010b6a8e9b70221dfae06",
```

```
    "name":
"externallmg_1694503094720_WhatsApp_Image_20230912_at_122716_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094720_WhatsApp_Image_20230912_at_122716_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae07",
  "name":
"externallmg_1694503094724_WhatsApp_Image_20230912_at_122717_PM_1.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094724_WhatsApp_Image_20230912_at_122717_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae08",
  "name":
"externallmg_1694503094727_WhatsApp_Image_20230912_at_122717_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094727_WhatsApp_Image_20230912_at_122717_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae09",
  "name":
"externallmg_1694503094731_WhatsApp_Image_20230912_at_122718_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094731_WhatsApp_Image_20230912_at_122718_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae0a",
  "name":
"externallmg_1694503094734_WhatsApp_Image_20230912_at_122654_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094734_WhatsApp_Image_20230912_at_122654_PM.jpeg",
  "orientation": "portrait"
},
}
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae0b",
  "name":
"externallmg_1694503094736_WhatsApp_Image_20230912_at_122658_PM_1.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094736_WhatsApp_Image_20230912_at_122658_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650010b6a8e9b70221dfae0c",
  "name":
"externallmg_1694503094737_WhatsApp_Image_20230912_at_122658_PM.jpeg",
  "path": "cases/64f17ff7eb1f822256defb6a/
externallmg_1694503094737_WhatsApp_Image_20230912_at_122658_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-01T06:08:55.432Z",
"updatedAt": "2023-09-12T07:18:14.830Z",
"__v": 0,
"invoiceId": "64f17ff7eb1f822256defb77",
"fullAddress": " Flat No. 05, 2nd Floor, Shree Hind CHSL ( Vrindavan Complex),
Village - Chunabhatti, Sion west , Mumbai",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Tejal Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820013017"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---