

```

{
  "typeOfReport": {
    "value": "NPA_Case(With_Depreciation)",
    "label": "NPA Case(With Depreciation)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64425b2d629ac20845e9f4bf"
    },
    "type": "CREDITOFFICER",
    "_id": "64425b2d629ac20845e9f4c1",
    "firstName": "shell",
    "lastName": "shell",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "12me@me.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2360"
  },
  "organization": {

```

```

    "_id": "643a5bee108b68389ed736e5",
    "name": "Nashik Branch",
    "shortName": "NSK",
    "email": "nashik@vastukala.org",
    "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
    "city": "Nashik"
  },
  "client": {
    "_id": "5fc6a0d8da3c631ed41d17f4",
    "type": "BANK",
    "name": "State Bank of India",
    "displayName": "State Bank of India",
    "initial": "SBI",
    "remark": "Temp",
    "status": true
  },
  "branch": {
    "_id": "64425b2d629ac20845e9f4bf",
    "name": "RACC Nashik Branch",
    "branchCode": "",
    "mobileNo": "02225923555",
    "alternateMobileNo": "",
    "email": "testjagdish.bhatt@vastukala.org",
    "fax": "",
    "ledgerName": "",
    "sendStructuralCertificate": "0",
    "address": "RBO.2, The Wave Building Opposite Shell Petrol Pump, First Floor, Pathardi Road Nashik.422010,\n\nState – Maharashtra, Country – India."
  },
  "assetsClass": {
    "value": "Land_&_Building_/_Immovable_Property",
    "label": "Land & Building / Immovable Property"
  },
  "propertyType": {
    "value": "Residential",
    "label": "Residential"
  },
  "zone": {
    "_id": "63fdaf22ce84bf289baae42d",
    "zoneName": "Nashik Zone"
  },
  "staff": {
    "pickupPerson": {
      "type": "EMPLOYEE",
      "_id": "63f9ed37ce84bf289ba991ac",
      "role": "FRONTDESK",

```

```

    "firstName": "Rushikesh",
    "email": "rushingle2201@gmail.com",
    "lastName": "Pingle",
    "mobileNo": "8788210361",
    "shortName": "RUP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
    "email": "sachinraundal9021@gmail.com",
    "lastName": "Raundal",
    "mobileNo": "9021337843",
    "designation": "Site Engg",
    "shortName": "Sachin",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
    "role": "MAKER + RATE VERFIER",
    "firstName": "Chintamani",
    "email": "chintamanichaudhari099@gmail.com",
    "lastName": "Chaudhari",
    "mobileNo": "8007230780",
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "636a1ad14d42487767af3f91",
    "role": "MAKER + RATE VERFIER",
    "firstName": "Chintamani",
    "email": "chintamanichaudhari099@gmail.com",
    "lastName": "Chaudhari",
    "mobileNo": "8007230780",
    "designation": "",

```

```
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chauthari_Photo_2.jpg"
  },
  "checker": {
    "_id": "60f915d3f3dd69653a592199",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg",
    "firstName": "Shobha",
    "lastName": "Kuperkar",
    "shortName": "SH",
    "email": "shobha@vastukala.org",
    "designation": "",
    "mobileNo": "9004134140",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "type": "EMPLOYEE",
    "workWithDocumentMaker": ""
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.95294499882926",
  "longitude": "73.77139142528964"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Pathardi ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "63",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Sai Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```

"value": "Samarth Nagar",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Dnyaneshwar Nagar",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Jagannath Mandir, Opp Datta Mandir",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "330/1 to 7/2/1A/63, ",
  "label": true
},
"hissaNo": {

```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "11",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422010",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
```

```
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
},
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
```

```
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
```

```
"title": "Kitchen arrangements",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
    },
    "others": {
      "title": "Others / Car Parking",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "totalValues": {
      "title": "Total",
      "quantity": "",
      "ratePerUnit": "",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    }
  },
  "taskStatus": {
    "SITE_INSPECTION": false,
    "RATE_VERIFY": false,
    "MAKER": false,
    "CHECKER": false,
    "PREPARE_INVOICE": false,
    "PRINT": false,
    "SIGN": false,
    "SIGNED_REPORT_UPLOAD": false,
    "DELIVERY": false,
    "PAYMENT_COLLECT": false,
    "COMPLETED": false
  },
  "createCase": "false",
  "type": "CASE",
  "leadType": {
    "label": "Lead",
    "value": "LEAD"
  },
  "siteVisitType": "FULL",
  "isSiteMeasurementAllowed": true,
  "finalValuationArea": "0",
  "empanelmentNo": [],
  "isAdvanceInvoice": false,
  "status": true,
  "caseStatus": "READYFORCHECKER",
  "_id": "64f2d633eb1f822256e09150",
  "ownerName": "Rohit Jadhav",
```

```
"ownerPhoneNo": "8007244449",
"fullAddress": "Residential NPA Case(With Depreciation) No. 11, 2nd Floor, Shree Sai
Apartment, Near Jagannath Mandir, Opp Datta Mandir, Plot No. 63, New/Current
Survey No. 330/1 to 7/2/1A/63, , Samarth Nagar, Dnyaneshwar Nagar, Village -
Pathardi , Taluka - Nashik, District - Nashik, Nashik, 422010, State - Maharashtra,
India",
"remark": "",
"documents": [
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693636092478_rohit_jadhav.pdf",
  "path": "cases/64f2d633eb1f822256e09150/
document_1693636092478_rohit_jadhav.pdf",
  "id": "535395",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Sep 02 2023 11:58:36 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1278aa6d152c1801b3ce",
    "label": "Bank Letter for Re-Valuation of the Property"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1693636287922_75129.pdf",
  "path": "cases/64f2d633eb1f822256e09150/document_1693636287922_75129.pdf",
  "id": "725827",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Sat Sep 02 2023 12:01:28 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003528",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
{
  "id": "266175",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Sat Sep 02 2023 11:59:07 GMT+0530 (India Standard Time)"
}
],
```



```
"owners": [
  {
    "name": "Rohit Jadhav",
    "phone": "8007244449",
    "ownershipShare": "",
    "email": "",
    "id": "358299"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095c8",
    "name":
"externallmg_1693636253846_WhatsApp_Image_20230831_at_54303_PM_1.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636253846_WhatsApp_Image_20230831_at_54303_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095c9",
    "name":
"externallmg_1693636253925_WhatsApp_Image_20230831_at_54303_PM.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636253925_WhatsApp_Image_20230831_at_54303_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095ca",
    "name":
"externallmg_1693636254002_WhatsApp_Image_20230831_at_54305_PM_1.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254002_WhatsApp_Image_20230831_at_54305_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095cb",
    "name":
"externallmg_1693636254070_WhatsApp_Image_20230831_at_54305_PM_2.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254070_WhatsApp_Image_20230831_at_54305_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095cc",
    "name":
"externallmg_1693636254135_WhatsApp_Image_20230831_at_54305_PM.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254135_WhatsApp_Image_20230831_at_54305_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095cd",
    "name":
"externallmg_1693636254391_WhatsApp_Image_20230831_at_54306_PM_1.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254391_WhatsApp_Image_20230831_at_54306_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095ce",
    "name":
"externallmg_1693636254432_WhatsApp_Image_20230831_at_54306_PM.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254432_WhatsApp_Image_20230831_at_54306_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095cf",
```

```
    "name":
"externallmg_1693636254537_WhatsApp_Image_20230831_at_54307_PM_1.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254537_WhatsApp_Image_20230831_at_54307_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095d0",
    "name":
"externallmg_1693636254703_WhatsApp_Image_20230831_at_54307_PM.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254703_WhatsApp_Image_20230831_at_54307_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095d1",
    "name":
"externallmg_1693636254773_WhatsApp_Image_20230831_at_54308_PM_1.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254773_WhatsApp_Image_20230831_at_54308_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095d2",
    "name":
"externallmg_1693636254861_WhatsApp_Image_20230831_at_54308_PM.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254861_WhatsApp_Image_20230831_at_54308_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095d3",
    "name":
"externallmg_1693636254936_WhatsApp_Image_20230831_at_54309_PM_1.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254936_WhatsApp_Image_20230831_at_54309_PM_1.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f2d69feb1f822256e095d4",
  "name":
"externallmg_1693636254999_WhatsApp_Image_20230831_at_54309_PM_2.jpeg",
  "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636254999_WhatsApp_Image_20230831_at_54309_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f2d69feb1f822256e095d5",
  "name":
"externallmg_1693636255026_WhatsApp_Image_20230831_at_54309_PM_3.jpeg",
  "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636255026_WhatsApp_Image_20230831_at_54309_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f2d69feb1f822256e095d6",
  "name":
"externallmg_1693636255067_WhatsApp_Image_20230831_at_54309_PM.jpeg",
  "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636255067_WhatsApp_Image_20230831_at_54309_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f2d69feb1f822256e095d7",
  "name":
"externallmg_1693636255106_WhatsApp_Image_20230831_at_54310_PM_1.jpeg",
  "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636255106_WhatsApp_Image_20230831_at_54310_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f2d69feb1f822256e095d8",
  "name":
"externallmg_1693636255157_WhatsApp_Image_20230831_at_54310_PM_2.jpeg",
```

```
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636255157_WhatsApp_Image_20230831_at_54310_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095d9",
    "name":
"externallmg_1693636255209_WhatsApp_Image_20230831_at_54310_PM.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636255209_WhatsApp_Image_20230831_at_54310_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095da",
    "name":
"externallmg_1693636255248_WhatsApp_Image_20230831_at_54311_PM_1.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636255248_WhatsApp_Image_20230831_at_54311_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f2d69feb1f822256e095db",
    "name":
"externallmg_1693636255298_WhatsApp_Image_20230831_at_54311_PM.jpeg",
    "path": "cases/64f2d633eb1f822256e09150/
externallmg_1693636255298_WhatsApp_Image_20230831_at_54311_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [
  {
    "originalname": "Rohit Jadhav.doc",
    "filename": "1693636241165_Rohit_Jadhav.doc",
    "path": "cases/64f2d633eb1f822256e09150/
externalDocuments/1693636241165_Rohit_Jadhav.doc",
    "size": "5132288",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    }
  },

```

```

    "createdAt": "Sat Sep 02 2023 12:00:42 GMT+0530 (India Standard Time)",
    "uploadedBy": "636a1ad14d42487767af3f91"
  }
],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-02T06:29:07.574Z",
"updatedAt": "2023-09-02T06:31:28.035Z",
"__v": 0,
"invoiceId": "64f2d633eb1f822256e09156",
"updatedAt": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Rohit Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8007244449"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			