

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6417f07e96b58848585ed4db",
    "firstName": "Jeetendra Vaity",
    "lastName": "Vaity",
    "mobileNo": "",
    "workMobileNo": "9987835248",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6300000",
    "discussWithPerson": "Jeetendra Vaity",
    "expectedFees": 3150,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyam_Photo.jpg"
},
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
```

```
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
```

```
\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.229270642800472",
  "longitude": "73.11080810859515"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.11080810859515,
    19.229270642800472
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-04T10:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
}
```

```
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kanchangaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Dombivali",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
```

```
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sarvodaya Leela",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
}
```

```
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
```



```
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
```

```
"status": false,
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivali East",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
```

```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```

```
    "title": "Total",
    "quantity": "",
    "ratePerUnit": "",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64f5a9a7eb1f822256e27416",
"ownerName": "Akshay Avinash Jawlgaikar",
"ownerPhoneNo": "8097375749",
"appAddress": "Flat no 601,6floor,Building No 8,Sarvodaya Leela CHS,Kanchangaon
Village,Thakurli East",
"remark": "Cont Archita kulkarni Mob no 8097375749",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },

```



```
    "isHardCopy": false,
    "path": "cases/64f5a9a7eb1f822256e27416/
document_1693821193849_Sale_Agreement_Sarvoday_Leela_chain_1_.pdf",
    "fileName":
"document_1693821193849_Sale_Agreement_Sarvoday_Leela_chain_1_.pdf",
    "displayStatus": false,
    "id": "609715",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Sep 04 2023 15:25:19 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64f5a9a7eb1f822256e27416/
document_1693821218922_Sale_agreement_sarvoday_Leela_chain_2.pdf",
    "fileName":
"document_1693821218922_Sale_agreement_sarvoday_Leela_chain_2.pdf",
    "displayStatus": false,
    "id": "137354",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Sep 04 2023 15:25:19 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64f5a9a7eb1f822256e27416/
document_1693821241750_correction_deed_AkshayArchita.pdf",
    "fileName": "document_1693821241750_correction_deed_AkshayArchita.pdf",
    "displayStatus": false,
    "id": "123978",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Sep 04 2023 15:25:19 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003552",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "441017",
    "title": "Create Lead",
```

```
    "description": "Create Lead",
    "datetime": "Mon Sep 04 2023 15:25:51 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Akshay Avinash Jawlgaikar",
    "phone": "8097375749",
    "ownershipShare": "",
    "email": "",
    "id": "916990"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0cdeb1f822256e3834e",
    "name":
"externallmg_1693888717595_WhatsApp_Image_20230905_at_100145_AM_20.jpeg",
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888717595_WhatsApp_Image_20230905_at_100145_AM_20.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0cdeb1f822256e3834f",
    "name":
"externallmg_1693888717599_WhatsApp_Image_20230905_at_100145_AM_21.jpeg",
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888717599_WhatsApp_Image_20230905_at_100145_AM_21.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0cdeb1f822256e38350",
```

```
    "name":
"externallmg_1693888717603_WhatsApp_Image_20230905_at_100145_AM_1.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888717603_WhatsApp_Image_20230905_at_100145_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a2",
  "name":
"externallmg_1693888731848_WhatsApp_Image_20230905_at_100145_AM_2.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731848_WhatsApp_Image_20230905_at_100145_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a3",
  "name":
"externallmg_1693888731851_WhatsApp_Image_20230905_at_100145_AM_3.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731851_WhatsApp_Image_20230905_at_100145_AM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a4",
  "name":
"externallmg_1693888731857_WhatsApp_Image_20230905_at_100145_AM_4.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731857_WhatsApp_Image_20230905_at_100145_AM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a5",
  "name":
"externallmg_1693888731861_WhatsApp_Image_20230905_at_100145_AM_5.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731861_WhatsApp_Image_20230905_at_100145_AM_5.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a6",
  "name":
"externallmg_1693888731864_WhatsApp_Image_20230905_at_100145_AM_6.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731864_WhatsApp_Image_20230905_at_100145_AM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a7",
  "name":
"externallmg_1693888731866_WhatsApp_Image_20230905_at_100145_AM_7.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731866_WhatsApp_Image_20230905_at_100145_AM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a8",
  "name":
"externallmg_1693888731868_WhatsApp_Image_20230905_at_100145_AM_8.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731868_WhatsApp_Image_20230905_at_100145_AM_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383a9",
  "name":
"externallmg_1693888731870_WhatsApp_Image_20230905_at_100145_AM_9.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731870_WhatsApp_Image_20230905_at_100145_AM_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383aa",
  "name":
"externallmg_1693888731872_WhatsApp_Image_20230905_at_100145_AM_10.jpeg",
```

```
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731872_WhatsApp_Image_20230905_at_100145_AM_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0dbeb1f822256e383ab",
    "name":
"externallmg_1693888731875_WhatsApp_Image_20230905_at_100145_AM_11.jpeg",
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731875_WhatsApp_Image_20230905_at_100145_AM_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0dbeb1f822256e383ac",
    "name":
"externallmg_1693888731877_WhatsApp_Image_20230905_at_100145_AM_12.jpeg",
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731877_WhatsApp_Image_20230905_at_100145_AM_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0dbeb1f822256e383ad",
    "name":
"externallmg_1693888731879_WhatsApp_Image_20230905_at_100145_AM_13.jpeg",
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731879_WhatsApp_Image_20230905_at_100145_AM_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0dbeb1f822256e383ae",
    "name":
"externallmg_1693888731881_WhatsApp_Image_20230905_at_100145_AM_14.jpeg",
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731881_WhatsApp_Image_20230905_at_100145_AM_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64f6b0dbeb1f822256e383af",
  "name":
"externallmg_1693888731883_WhatsApp_Image_20230905_at_100145_AM_15.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731883_WhatsApp_Image_20230905_at_100145_AM_15.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383b0",
  "name":
"externallmg_1693888731885_WhatsApp_Image_20230905_at_100145_AM_16.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731885_WhatsApp_Image_20230905_at_100145_AM_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383b1",
  "name":
"externallmg_1693888731887_WhatsApp_Image_20230905_at_100145_AM_17.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731887_WhatsApp_Image_20230905_at_100145_AM_17.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383b2",
  "name":
"externallmg_1693888731890_WhatsApp_Image_20230905_at_100145_AM_18.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731890_WhatsApp_Image_20230905_at_100145_AM_18.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f6b0dbeb1f822256e383b3",
  "name":
"externallmg_1693888731892_WhatsApp_Image_20230905_at_100145_AM_19.jpeg",
  "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731892_WhatsApp_Image_20230905_at_100145_AM_19.jpeg",
```

```

    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f6b0dbeb1f822256e383b4",
    "name":
"externallmg_1693888731895_WhatsApp_Image_20230905_at_100145_AM.jpeg",
    "path": "cases/64f5a9a7eb1f822256e27416/
externallmg_1693888731895_WhatsApp_Image_20230905_at_100145_AM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-04T09:55:51.456Z",
"updatedAt": "2023-09-05T04:38:51.972Z",
"__v": 0,
"invoiceId": "64f5a9a8eb1f822256e27434",
"fullAddress": "Residential Flat No. 601, 6th Floor, Sarvodaya Leela, Village -
Kanchangaon, Dombivali East, Dombivali, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Akshay Avinash Jawlgaikar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8097375749"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			