

```
{
  "typeOfReport": {
    "value": "Commercial_Shop",
    "label": "Commercial Shop"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Market Value",
    "value": "Market_Value"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "000",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "64f5c8d5eb1f822256e32640",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Patthan Chhina subhash Shah",
"displayname": "Patthan Chhina subhash Shah",
"initial": "P"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Commercial",
  "label": "Commercial"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "ADMIN",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60092304a16fab0f2af9b0c2",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
```

```
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": "",
"checker": "",
"valuers": [
{
  "valuersRegistrationNumber": [
    {
      "value": "IBBI/RV/07/2018/10366",
      "label": "Registered Valuer"
    }
  ],
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
      "title": {
        "label": "IBBI"
      },
      "_id": "60af80072ffdf65bcd658651",
      "number": "IBBI/RV/07/2018/10366"
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
```

```
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Private Clients",
  "value": "PRIVATE_CLIENT"
},
"location": {
  "latitude": "19.139907240027078",
  "longitude": "72.84358837791129"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84358837791129,
    19.139907240027078
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-05T03:00:00.000Z",
      "remark": ""
    }
  ]
}
```

```
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
"status": true,
"name": "Village",
"key": "village",
"value": "Bandivali",
"label": true
},
"floorNo": {
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "1",
"label": false
},
"buildingNo": {
"status": false,
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
}
```

```
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Markaz View CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
```

```
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "S V Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
}
```

```
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "110",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
```



```
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
```

```
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "64f5c8f5eb1f822256e32649",
"ownerName": "Patthan Chhina subhan Shah",
"ownerPhoneNo": "0000000000",
"appAddress": "Office no 110 ,Markaj View SV Road Jogeshwari west ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/64f5c8f5eb1f822256e32649/document_1693829270396_FLAT_NO_110_MR_CHINNA_SUBHAN_SHAH_PATTAN_001.pdf",
    "fileName": "document_1693829270396_FLAT_NO_110_MR_CHINNA_SUBHAN_S
HAH_PATTAN_001.pdf",
    "displayStatus": false,
    "id": "757791",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Mon Sep 04 2023 17:38:53 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003561",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "829135",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 04 2023 17:39:25 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Patthan Chhina subhan Shah",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "633632"
  }
]
```



```
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab1",
    "name":
"externallmg_1693984186009_WhatsApp_Image_20230906_at_123549_PM.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186009_WhatsApp_Image_20230906_at_123549_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab2",
    "name":
"externallmg_1693984186011_WhatsApp_Image_20230906_at_123520_PM_1.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186011_WhatsApp_Image_20230906_at_123520_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab3",
    "name":
"externallmg_1693984186014_WhatsApp_Image_20230906_at_123520_PM_2.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186014_WhatsApp_Image_20230906_at_123520_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab4",
    "name":
"externallmg_1693984186016_WhatsApp_Image_20230906_at_123520_PM.jpeg",
```

```
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186016_WhatsApp_Image_20230906_at_123520_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab5",
    "name":
"externallmg_1693984186025_WhatsApp_Image_20230906_at_123521_PM_1.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186025_WhatsApp_Image_20230906_at_123521_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab6",
    "name":
"externallmg_1693984186029_WhatsApp_Image_20230906_at_123521_PM_2.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186029_WhatsApp_Image_20230906_at_123521_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab7",
    "name":
"externallmg_1693984186034_WhatsApp_Image_20230906_at_123521_PM.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186034_WhatsApp_Image_20230906_at_123521_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eab8",
    "name":
"externallmg_1693984186040_WhatsApp_Image_20230906_at_123522_PM_1.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186040_WhatsApp_Image_20230906_at_123522_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64f825baeb1f822256e5eab9",
    "name":
"externallmg_1693984186043_WhatsApp_Image_20230906_at_123522_PM.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186043_WhatsApp_Image_20230906_at_123522_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eaba",
    "name":
"externallmg_1693984186046_WhatsApp_Image_20230906_at_123523_PM_1.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186046_WhatsApp_Image_20230906_at_123523_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eabb",
    "name":
"externallmg_1693984186049_WhatsApp_Image_20230906_at_123523_PM.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186049_WhatsApp_Image_20230906_at_123523_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eabc",
    "name":
"externallmg_1693984186052_WhatsApp_Image_20230906_at_123524_PM_1.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186052_WhatsApp_Image_20230906_at_123524_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eabd",
    "name":
"externallmg_1693984186056_WhatsApp_Image_20230906_at_123524_PM_2.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186056_WhatsApp_Image_20230906_at_123524_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eabe",
    "name":
"externallmg_1693984186060_WhatsApp_Image_20230906_at_123524_PM.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186060_WhatsApp_Image_20230906_at_123524_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eabf",
    "name":
"externallmg_1693984186063_WhatsApp_Image_20230906_at_123525_PM_1.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186063_WhatsApp_Image_20230906_at_123525_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eac0",
    "name":
"externallmg_1693984186065_WhatsApp_Image_20230906_at_123525_PM_2.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186065_WhatsApp_Image_20230906_at_123525_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825baeb1f822256e5eac1",
    "name":
"externallmg_1693984186068_WhatsApp_Image_20230906_at_123525_PM.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984186068_WhatsApp_Image_20230906_at_123525_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825c7eb1f822256e5eaf4",
```

```
    "name":  
    "externallmg_1693984199533_WhatsApp_Image_20230906_at_123526_PM_1.jpeg",  
    "path": "cases/64f5c8f5eb1f822256e32649/  
externallmg_1693984199533_WhatsApp_Image_20230906_at_123526_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64f825c7eb1f822256e5eaf5",  
    "name":  
    "externallmg_1693984199537_WhatsApp_Image_20230906_at_123526_PM.jpeg",  
    "path": "cases/64f5c8f5eb1f822256e32649/  
externallmg_1693984199537_WhatsApp_Image_20230906_at_123526_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64f825c7eb1f822256e5eaf6",  
    "name":  
    "externallmg_1693984199541_WhatsApp_Image_20230906_at_123527_PM.jpeg",  
    "path": "cases/64f5c8f5eb1f822256e32649/  
externallmg_1693984199541_WhatsApp_Image_20230906_at_123527_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64f825c7eb1f822256e5eaf7",  
    "name":  
    "externallmg_1693984199547_WhatsApp_Image_20230906_at_123528_PM_1.jpeg",  
    "path": "cases/64f5c8f5eb1f822256e32649/  
externallmg_1693984199547_WhatsApp_Image_20230906_at_123528_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64f825c7eb1f822256e5eaf8",  
    "name":  
    "externallmg_1693984199549_WhatsApp_Image_20230906_at_123528_PM.jpeg",  
    "path": "cases/64f5c8f5eb1f822256e32649/  
externallmg_1693984199549_WhatsApp_Image_20230906_at_123528_PM.jpeg",  
    "orientation": "portrait"  
  },  
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f825c7eb1f822256e5eaf9",
  "name":
"externallmg_1693984199556_WhatsApp_Image_20230906_at_123541_PM.jpeg",
  "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984199556_WhatsApp_Image_20230906_at_123541_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f825c7eb1f822256e5eafa",
  "name":
"externallmg_1693984199560_WhatsApp_Image_20230906_at_123455_PM.jpeg",
  "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984199560_WhatsApp_Image_20230906_at_123455_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f825c7eb1f822256e5eafb",
  "name":
"externallmg_1693984199566_WhatsApp_Image_20230906_at_123458_PM.jpeg",
  "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984199566_WhatsApp_Image_20230906_at_123458_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f825c7eb1f822256e5eafc",
  "name":
"externallmg_1693984199568_WhatsApp_Image_20230906_at_123513_PM.jpeg",
  "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984199568_WhatsApp_Image_20230906_at_123513_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f825c7eb1f822256e5eafd",
  "name":
"externallmg_1693984199574_WhatsApp_Image_20230906_at_123518_PM.jpeg",
```

```

    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984199574_WhatsApp_Image_20230906_at_123518_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f825c7eb1f822256e5eafe",
    "name":
"externallmg_1693984199578_WhatsApp_Image_20230906_at_123519_PM.jpeg",
    "path": "cases/64f5c8f5eb1f822256e32649/
externallmg_1693984199578_WhatsApp_Image_20230906_at_123519_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-04T12:09:25.465Z",
"updatedAt": "2023-09-06T07:09:59.643Z",
"__v": 0,
"invoiceId": "64f5c8f5eb1f822256e32663",
"fullAddress": " Flat No. 110, 1st Floor, Markaz View CHSL, S V Road, Village -
Bandivali, Mumbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Patthan Chhina subhan Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			