

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64f966f863830d2aa3b47dcc"
    },
    "type": "CREDITOFFICER",
    "_id": "64f966f863830d2aa3b47dce",
    "firstName": "Kamalshil",
    "lastName": "Sir",
    "mobileNo": "9175130760",
    "workMobileNo": "9175130760",
    "email": "ubin0563293@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "5900"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64f966f863830d2aa3b47dcc",
  "name": "Pune Branch",
  "branchCode": "",
  "mobileNo": "1800222244",
  "alternateMobileNo": "02164-227228",
  "email": "ubin0563293@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Survey No 207/2C, Patil Heritage, Shaniwar Peth, Karad - 415110 (Dutta
Chowk)"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushipingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "636a29b64d42487767af43ea",
  "role": "NASHIK (LEAD + VISIT + RATE)",
  "firstName": "Sachin",
  "email": "sachinraundal9021@gmail.com",
  "lastName": "Raundal",
  "mobileNo": "9021337843",
  "designation": "Site Engg",
  "shortName": "Sachin",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
  "email": "chintamanichaudhari099@gmail.com",
  "lastName": "Chaudhari",
  "mobileNo": "8007230780",
  "designation": "",
  "shortName": "Chintamani",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "636a1ad14d42487767af3f91",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Chintamani",
```

```
    "email": "chintamanichaudhari099@gmail.com",
    "lastName": "Chaudhari",
    "mobileNo": "8007230780",
    "designation": "",
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.995976520515885",
  "longitude": "73.82709199999992"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Aurangabad Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Panchavati",
  "label": false
}
```

```
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Lohakare Mala, Chari No.4",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "356/2/2",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "2/2",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
}
```



```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422003",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
```

```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
}
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"_id": "64f96e3863830d2aa3b47fae",
"ownerName": "Bhaskar Lohakare",
"ownerPhoneNo": "7620939741",
"fullAddress": " Land and Building No. Ground Floor, Lohakare Mala, Chari No.4,
New/Current Survey No. 356/2/2, Hissa No. 2/2, Aurangabad Road, Panchavati, Village
- Nashik, Taluka - Nashik, District - Nashik, Nashik, 422003",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
```

```
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066617216_Microsoft_Word__BHASKAR_LOHAKARE
_FARM_HOUSE_TITLE_signed.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/document_1694066617216_Microsoft
_Word__BHASKAR_LOHAKARE_FARM_HOUSE_TITLE_signed.pdf",
  "id": "734494",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066632416_712.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/document_1694066632416_712.pdf",
  "id": "879458",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066640962_Area_statement__certificate.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694066640962_Area_statement__certificate.pdf",
  "id": "985407",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
```



```
"fileName": "document_1694066651548_Bhaskar_Lohakare_DOcs.pdf",
"path": "cases/64f96e3863830d2aa3b47fae/
document_1694066651548_Bhaskar_Lohakare_DOcs.pdf",
"id": "877872",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1694066662704_Building_plan_Architect__Owner_sign.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694066662704_Building_plan_Architect__Owner_sign.pdf",
  "id": "431603",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066672973_Building_plan_NMC_stamps.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694066672973_Building_plan_NMC_stamps.pdf",
  "id": "283044",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  }
}
```

```
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066709752_DOcs.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/document_1694066709752_DOcs.pdf",
  "id": "238419",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1694066726038_DocScanner_Aug_23_2023_1239_PM_1.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694066726038_DocScanner_Aug_23_2023_1239_PM_1.pdf",
  "id": "316623",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1694066737362_DocScanner_Aug_23_2023_1239_PM.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694066737362_DocScanner_Aug_23_2023_1239_PM.pdf",
  "id": "960395",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
"fileName":
"document_1694066745194_DocScanner_Aug_23_2023_1245_PM.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694066745194_DocScanner_Aug_23_2023_1245_PM.pdf",
  "id": "843449",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066752227_House_Layout_.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694066752227_House_Layout_.pdf",
  "id": "869067",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066797501_Microsoft_Word__BHASKAR_LOHAKARE
_FARM_HOUSE_TITLE_signed.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/document_1694066797501_Microsoft_
Word__BHASKAR_LOHAKARE_FARM_HOUSE_TITLE_signed.pdf",
  "id": "278188",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694066804001_Plan.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/document_1694066804001_Plan.pdf",
```

```
"id": "106731",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Thu Sep 07 2023 12:00:47 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694068572131_143094.pdf",
  "path": "cases/64f96e3863830d2aa3b47fae/
document_1694068572131_143094.pdf",
  "id": "211224",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Thu Sep 07 2023 12:06:12 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003608",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "737231",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 07 2023 12:01:20 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Bhaskar Lohakare",
    "phone": "7620939741",
    "ownershipShare": "",
    "email": "",
    "id": "151698"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b4825e",
    "name":
"externalImg_1694068523903_WhatsApp_Image_20230823_at_121709_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externalImg_1694068523903_WhatsApp_Image_20230823_at_121709_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b4825f",
    "name":
"externalImg_1694068524048_WhatsApp_Image_20230823_at_121710_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externalImg_1694068524048_WhatsApp_Image_20230823_at_121710_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48260",
    "name":
"externalImg_1694068524180_WhatsApp_Image_20230823_at_121710_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externalImg_1694068524180_WhatsApp_Image_20230823_at_121710_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48261",
    "name":
"externalImg_1694068524314_WhatsApp_Image_20230823_at_121711_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externalImg_1694068524314_WhatsApp_Image_20230823_at_121711_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48262",
    "name":
"externalImg_1694068524456_WhatsApp_Image_20230823_at_121711_PM_2.jpeg",
```

```
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068524456_WhatsApp_Image_20230823_at_121711_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48263",
    "name":
"externallmg_1694068524541_WhatsApp_Image_20230823_at_121711_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068524541_WhatsApp_Image_20230823_at_121711_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48264",
    "name":
"externallmg_1694068524704_WhatsApp_Image_20230823_at_121712_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068524704_WhatsApp_Image_20230823_at_121712_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48265",
    "name":
"externallmg_1694068524759_WhatsApp_Image_20230823_at_121712_PM_2.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068524759_WhatsApp_Image_20230823_at_121712_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48266",
    "name":
"externallmg_1694068524827_WhatsApp_Image_20230823_at_121712_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068524827_WhatsApp_Image_20230823_at_121712_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64f96f2d63830d2aa3b48267",
  "name":
"externallmg_1694068524907_WhatsApp_Image_20230823_at_121718_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068524907_WhatsApp_Image_20230823_at_121718_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f2d63830d2aa3b48268",
  "name":
"externallmg_1694068524960_WhatsApp_Image_20230823_at_121718_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068524960_WhatsApp_Image_20230823_at_121718_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f2d63830d2aa3b48269",
  "name":
"externallmg_1694068525000_WhatsApp_Image_20230823_at_121719_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525000_WhatsApp_Image_20230823_at_121719_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f2d63830d2aa3b4826a",
  "name":
"externallmg_1694068525067_WhatsApp_Image_20230823_at_121719_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525067_WhatsApp_Image_20230823_at_121719_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f2d63830d2aa3b4826b",
  "name":
"externallmg_1694068525130_WhatsApp_Image_20230823_at_121720_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525130_WhatsApp_Image_20230823_at_121720_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b4826c",
    "name":
"externallmg_1694068525208_WhatsApp_Image_20230823_at_121720_PM_2.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525208_WhatsApp_Image_20230823_at_121720_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b4826d",
    "name":
"externallmg_1694068525274_WhatsApp_Image_20230823_at_121720_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525274_WhatsApp_Image_20230823_at_121720_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b4826e",
    "name":
"externallmg_1694068525340_WhatsApp_Image_20230823_at_121721_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525340_WhatsApp_Image_20230823_at_121721_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b4826f",
    "name":
"externallmg_1694068525404_WhatsApp_Image_20230823_at_121721_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525404_WhatsApp_Image_20230823_at_121721_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f2d63830d2aa3b48270",
```



```
    "name":
"externallmg_1694068525472_WhatsApp_Image_20230823_at_121722_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525472_WhatsApp_Image_20230823_at_121722_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f2d63830d2aa3b48271",
  "name":
"externallmg_1694068525538_WhatsApp_Image_20230823_at_121722_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068525538_WhatsApp_Image_20230823_at_121722_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482b9",
  "name":
"externallmg_1694068534816_WhatsApp_Image_20230823_at_121723_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068534816_WhatsApp_Image_20230823_at_121723_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482ba",
  "name":
"externallmg_1694068534950_WhatsApp_Image_20230823_at_121724_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068534950_WhatsApp_Image_20230823_at_121724_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482bb",
  "name":
"externallmg_1694068535052_WhatsApp_Image_20230823_at_121724_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535052_WhatsApp_Image_20230823_at_121724_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482bc",
  "name":
"externallmg_1694068535144_WhatsApp_Image_20230823_at_121725_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535144_WhatsApp_Image_20230823_at_121725_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482bd",
  "name":
"externallmg_1694068535227_WhatsApp_Image_20230823_at_121726_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535227_WhatsApp_Image_20230823_at_121726_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482be",
  "name":
"externallmg_1694068535318_WhatsApp_Image_20230823_at_121728_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535318_WhatsApp_Image_20230823_at_121728_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482bf",
  "name":
"externallmg_1694068535358_WhatsApp_Image_20230823_at_121728_PM_2.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535358_WhatsApp_Image_20230823_at_121728_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482c0",
  "name":
"externallmg_1694068535440_WhatsApp_Image_20230823_at_121728_PM.jpeg",
```

```
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535440_WhatsApp_Image_20230823_at_121728_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f3863830d2aa3b482c1",
    "name":
"externallmg_1694068535466_WhatsApp_Image_20230823_at_121729_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535466_WhatsApp_Image_20230823_at_121729_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f3863830d2aa3b482c2",
    "name":
"externallmg_1694068535523_WhatsApp_Image_20230823_at_121729_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535523_WhatsApp_Image_20230823_at_121729_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f3863830d2aa3b482c3",
    "name":
"externallmg_1694068535563_WhatsApp_Image_20230823_at_121730_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535563_WhatsApp_Image_20230823_at_121730_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f3863830d2aa3b482c4",
    "name":
"externallmg_1694068535613_WhatsApp_Image_20230823_at_121730_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535613_WhatsApp_Image_20230823_at_121730_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64f96f3863830d2aa3b482c5",
  "name":
"externallmg_1694068535652_WhatsApp_Image_20230823_at_121731_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535652_WhatsApp_Image_20230823_at_121731_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482c6",
  "name":
"externallmg_1694068535730_WhatsApp_Image_20230823_at_121731_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535730_WhatsApp_Image_20230823_at_121731_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482c7",
  "name":
"externallmg_1694068535758_WhatsApp_Image_20230823_at_121732_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535758_WhatsApp_Image_20230823_at_121732_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482c8",
  "name":
"externallmg_1694068535831_WhatsApp_Image_20230823_at_121733_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535831_WhatsApp_Image_20230823_at_121733_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f3863830d2aa3b482c9",
  "name":
"externallmg_1694068535957_WhatsApp_Image_20230823_at_121738_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535957_WhatsApp_Image_20230823_at_121738_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f3863830d2aa3b482ca",
    "name":
"externallmg_1694068535984_WhatsApp_Image_20230823_at_121738_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068535984_WhatsApp_Image_20230823_at_121738_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f3863830d2aa3b482cb",
    "name":
"externallmg_1694068536113_WhatsApp_Image_20230823_at_121739_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068536113_WhatsApp_Image_20230823_at_121739_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f3863830d2aa3b482cc",
    "name":
"externallmg_1694068536167_WhatsApp_Image_20230823_at_121739_PM.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068536167_WhatsApp_Image_20230823_at_121739_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f4463830d2aa3b48312",
    "name":
"externallmg_1694068548182_WhatsApp_Image_20230823_at_121740_PM_1.jpeg",
    "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548182_WhatsApp_Image_20230823_at_121740_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64f96f4463830d2aa3b48313",
```

```
    "name":
"externallmg_1694068548251_WhatsApp_Image_20230823_at_121740_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548251_WhatsApp_Image_20230823_at_121740_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f4463830d2aa3b48314",
  "name":
"externallmg_1694068548307_WhatsApp_Image_20230823_at_121741_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548307_WhatsApp_Image_20230823_at_121741_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f4463830d2aa3b48315",
  "name":
"externallmg_1694068548361_WhatsApp_Image_20230823_at_121741_PM_2.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548361_WhatsApp_Image_20230823_at_121741_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f4463830d2aa3b48316",
  "name":
"externallmg_1694068548431_WhatsApp_Image_20230823_at_121741_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548431_WhatsApp_Image_20230823_at_121741_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f4463830d2aa3b48317",
  "name":
"externallmg_1694068548487_WhatsApp_Image_20230823_at_121742_PM_1.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548487_WhatsApp_Image_20230823_at_121742_PM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f4463830d2aa3b48318",
  "name":
"externallmg_1694068548547_WhatsApp_Image_20230823_at_121742_PM_2.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548547_WhatsApp_Image_20230823_at_121742_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f4463830d2aa3b48319",
  "name":
"externallmg_1694068548616_WhatsApp_Image_20230823_at_121742_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548616_WhatsApp_Image_20230823_at_121742_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64f96f4463830d2aa3b4831a",
  "name":
"externallmg_1694068548684_WhatsApp_Image_20230823_at_121743_PM.jpeg",
  "path": "cases/64f96e3863830d2aa3b47fae/
externallmg_1694068548684_WhatsApp_Image_20230823_at_121743_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-07T06:31:20.244Z",
"updatedAt": "2023-09-07T06:36:12.259Z",
"__v": 0,
"invoiceId": "64f96e3863830d2aa3b47fb7",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Bhaskar Lohakare",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7620939741"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			