

```
{
  "typeOfReport": {
    "value": "NPA_Case(With_Depreciation)",
    "label": "NPA Case(With Depreciation)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "641ef58a695fbc66ee1a2c39"
    },
    "type": "CREDITOFFICER",
    "_id": "641ef58a695fbc66ee1a2c3b",
    "firstName": "Manish ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7506921112",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "3540"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "641ef58a695fbc66ee1a2c39",
  "name": "RLP Nashik\t",
  "branchCode": "",
  "mobileNo": "02532571977\t",
  "alternateMobileNo": "",
  "email": "ulpnasik@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Union Loanpoint Nashiik,\nNawandar Sankul Racca Colony, Near Soni
Paithani, Sharanpur road Nashik-02"
},
"assetsClass": {
  "value": "Land_ &_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "636a29b64d42487767af43ea",
  "role": "NASHIK (LEAD + VISIT + RATE)",
  "firstName": "Sachin",
  "email": "sachinraundal9021@gmail.com",
  "lastName": "Raundal",
  "mobileNo": "9021337843",
  "designation": "Site Engg",
  "shortName": "Sachin",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Prajakta",
```

```
    "email": "prajakta@vastukala.org",
    "lastName": "Patil",
    "mobileNo": "9769797568",
    "designation": "",
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "20.001391070809206",
  "longitude": "73.79272452775643"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Madhali Holi",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Tiwandha Chowk, Old Nashik",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
```

```
"key": "CTSNo",
"value": "3122",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2300",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```



```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422001",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
```

```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
}
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64fad44563830d2aa3b54337",
"ownerName": "Atul Kulkarni",
"ownerPhoneNo": "9922183353",
"fullAddress": " NPA Case(With Depreciation) No. 2300, Basement Floor, Near
Tiwandha Chowk, Old Nashik, CTS No. 3122, Madhali Holi, Village - Nashik, Taluka -
Nashik, District - Nashik, Nashik, 422001",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
```

```
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694159846070_Kulkarni_.pdf",
  "path": "cases/64fad44563830d2aa3b54337/
document_1694159846070_Kulkarni_.pdf",
  "id": "625321",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Fri Sep 08 2023 13:28:26 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003625",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "159694",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 08 2023 13:29:01 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Atul Kulkarni",
    "phone": "9922183353",
    "ownershipShare": "",
    "email": "",
    "id": "490165"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b5474b",
    "name":
"externallmg_1694160281860_WhatsApp_Image_20230906_at_50115_PM.jpeg",
```



```
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160281860_WhatsApp_Image_20230906_at_50115_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b5474c",
    "name":
"externallmg_1694160282374_WhatsApp_Image_20230906_at_50142_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160282374_WhatsApp_Image_20230906_at_50142_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b5474d",
    "name":
"externallmg_1694160282657_WhatsApp_Image_20230906_at_50145_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160282657_WhatsApp_Image_20230906_at_50145_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b5474e",
    "name":
"externallmg_1694160282800_WhatsApp_Image_20230906_at_50146_PM_1.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160282800_WhatsApp_Image_20230906_at_50146_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b5474f",
    "name":
"externallmg_1694160283062_WhatsApp_Image_20230906_at_50146_PM_2.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160283062_WhatsApp_Image_20230906_at_50146_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "64fad59d63830d2aa3b54750",
    "name":
"externallmg_1694160283237_WhatsApp_Image_20230906_at_50146_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160283237_WhatsApp_Image_20230906_at_50146_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54751",
    "name":
"externallmg_1694160283387_WhatsApp_Image_20230906_at_50147_PM_1.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160283387_WhatsApp_Image_20230906_at_50147_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54752",
    "name":
"externallmg_1694160283592_WhatsApp_Image_20230906_at_50147_PM_2.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160283592_WhatsApp_Image_20230906_at_50147_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54753",
    "name":
"externallmg_1694160283815_WhatsApp_Image_20230906_at_50147_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160283815_WhatsApp_Image_20230906_at_50147_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54754",
    "name":
"externallmg_1694160283965_WhatsApp_Image_20230906_at_50148_PM_1.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160283965_WhatsApp_Image_20230906_at_50148_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54755",
    "name":
"externallmg_1694160284312_WhatsApp_Image_20230906_at_50148_PM_2.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160284312_WhatsApp_Image_20230906_at_50148_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54756",
    "name":
"externallmg_1694160284625_WhatsApp_Image_20230906_at_50148_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160284625_WhatsApp_Image_20230906_at_50148_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54757",
    "name":
"externallmg_1694160284881_WhatsApp_Image_20230906_at_50149_PM_1.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160284881_WhatsApp_Image_20230906_at_50149_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54758",
    "name":
"externallmg_1694160284995_WhatsApp_Image_20230906_at_50149_PM_2.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160284995_WhatsApp_Image_20230906_at_50149_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad59d63830d2aa3b54759",
```

```
"name":
"externallmg_1694160285152_WhatsApp_Image_20230906_at_50149_PM.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160285152_WhatsApp_Image_20230906_at_50149_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad59d63830d2aa3b5475a",
  "name":
"externallmg_r_1694160282020_WhatsApp_Image_20230906_at_50117_PM.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_r_1694160282020_WhatsApp_Image_20230906_at_50117_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b54907",
  "name":
"externallmg_1694160327243_WhatsApp_Image_20230906_at_50150_PM_1.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160327243_WhatsApp_Image_20230906_at_50150_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b54908",
  "name":
"externallmg_1694160327427_WhatsApp_Image_20230906_at_50150_PM_2.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160327427_WhatsApp_Image_20230906_at_50150_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b54909",
  "name":
"externallmg_1694160327486_WhatsApp_Image_20230906_at_50150_PM.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160327486_WhatsApp_Image_20230906_at_50150_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b5490a",
  "name":
"externallmg_1694160327538_WhatsApp_Image_20230906_at_50151_PM_1.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160327538_WhatsApp_Image_20230906_at_50151_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b5490b",
  "name":
"externallmg_1694160327608_WhatsApp_Image_20230906_at_50151_PM_2.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160327608_WhatsApp_Image_20230906_at_50151_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b5490c",
  "name":
"externallmg_1694160327962_WhatsApp_Image_20230906_at_50151_PM.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160327962_WhatsApp_Image_20230906_at_50151_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b5490d",
  "name":
"externallmg_1694160327979_WhatsApp_Image_20230906_at_50152_PM_1.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160327979_WhatsApp_Image_20230906_at_50152_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b5490e",
  "name":
"externallmg_1694160328035_WhatsApp_Image_20230906_at_50152_PM_2.jpeg",
```

```
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160328035_WhatsApp_Image_20230906_at_50152_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad5cd63830d2aa3b5490f",
    "name":
"externallmg_1694160328145_WhatsApp_Image_20230906_at_50152_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160328145_WhatsApp_Image_20230906_at_50152_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad5cd63830d2aa3b54910",
    "name":
"externallmg_1694160328191_WhatsApp_Image_20230906_at_50153_PM_1.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160328191_WhatsApp_Image_20230906_at_50153_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad5cd63830d2aa3b54911",
    "name":
"externallmg_1694160328262_WhatsApp_Image_20230906_at_50153_PM_2.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160328262_WhatsApp_Image_20230906_at_50153_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad5cd63830d2aa3b54912",
    "name":
"externallmg_1694160328301_WhatsApp_Image_20230906_at_50153_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160328301_WhatsApp_Image_20230906_at_50153_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "64fad5cd63830d2aa3b54913",
  "name":
"externallmg_1694160328437_WhatsApp_Image_20230906_at_50154_PM_1.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160328437_WhatsApp_Image_20230906_at_50154_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b54914",
  "name":
"externallmg_1694160328523_WhatsApp_Image_20230906_at_50154_PM_2.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160328523_WhatsApp_Image_20230906_at_50154_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b54915",
  "name":
"externallmg_1694160329210_WhatsApp_Image_20230906_at_50154_PM.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160329210_WhatsApp_Image_20230906_at_50154_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b54916",
  "name":
"externallmg_1694160331828_WhatsApp_Image_20230906_at_50155_PM_1.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160331828_WhatsApp_Image_20230906_at_50155_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64fad5cd63830d2aa3b54917",
  "name":
"externallmg_1694160333449_WhatsApp_Image_20230906_at_50155_PM_2.jpeg",
  "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160333449_WhatsApp_Image_20230906_at_50155_PM_2.jpeg",
```

```

    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64fad5cd63830d2aa3b54918",
    "name":
"externallmg_1694160333637_WhatsApp_Image_20230906_at_50155_PM.jpeg",
    "path": "cases/64fad44563830d2aa3b54337/
externallmg_1694160333637_WhatsApp_Image_20230906_at_50155_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-08T07:59:01.537Z",
"updatedAt": "2023-09-08T08:05:33.786Z",
"__v": 0,
"invoiceId": "64fad44563830d2aa3b54346",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Atul Kulkarni",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9922183353"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			