

```
{
  "typeOfReport": {
    "label": "Residential",
    "value": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6413f770e6a52007fbaadc8"
    },
    "type": "CREDITOFFICER",
    "_id": "6413f770e6a52007fbaadcba",
    "firstName": "Vishakha ",
    "lastName": "Mane",
    "mobileNo": "",
    "workMobileNo": "9833242472",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Vishakha ",
    "expectedFees": 2500,
    "quotedAmount": "5000"
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6413f770e6a52007fbaadcb8",
  "name": "Ambarnath Branch",
  "branchCode": "",
  "mobileNo": "02512990632\t",
  "alternateMobileNo": "",
  "email": "vishakha.mane@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Panvelkar Pride, Shop no 1 to 4, Plot no 63-64, C T S NO 4740, Near
Hutatma Chawk Ambarnath (East)\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "6410199a140f140ffc59b58c",
"role": "PICKUPPERSON",
"firstName": "Prakash ",
"email": "prakashnvetkoli@gmail.com",
"lastName": "Vetkoli",
"mobileNo": "9076237689",
"shortName": "PV",
"workWithDocumentMaker": "",
"profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "MAKER",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvantha",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.22921999151663",
  "longitude": " 73.11081347301261"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.11081347301261,
    19.22921999151663
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-11T06:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kanchangaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "7",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "3",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Thane",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sarvodaya Leela",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```



```
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "704",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
```



```
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "64fec1e7a8e9b70221ddf8dd",
"ownerName": "Rajendra mane",
"ownerPhoneNo": "9022174883",
"appAddress": "704, 7th flr., Building no. 03, Sarvoday Leela, Kanchangaon,
Dombivali",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Approved Building Plan",
      "value": "60ae1277aa6d152c1801b3cc"
    },
    "inputs": {
      "documentDate": "03/01/2017",
      "nameOfApprovingAuthority": {
        "value": "Kalyan_Dombivli_Municipal_Corporation",
        "label": "Kalyan Dombivli Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "KDMC / NRV / CC / DOM / 328 "
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "426069",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
document_1694417201569_Plan_Copy_mane.pdf",
    "fileName": "document_1694417201569_Plan_Copy_mane.pdf"
  },
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "12/10/2012",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Swastik Realtors ",
      "to": {
```

```
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Rajendra Tukaram Mane & Mrs. Vaishali Rajendra Mane"
},
"isHardCopy": false,
"displayStatus": true,
"id": "251438",
"path": "cases/64fec1e7a8e9b70221ddf8dd/
document_1694417220261_Rajendra_mane_cos_A_704.pdf",
"fileName": "document_1694417220261_Rajendra_mane_cos_A_704.pdf"
},
{
  "documentType": {
    "label": "Share Certificate ",
    "value": "60ae1264aa6d152c1801b371"
  },
  "inputs": {
    "documentDate": "30/11/2017",
    "nameOfApprovingAuthority": {
      "value": "SOCIETY",
      "label": "SOCIETY"
    },
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Rajendra Tukaram Mane & Mrs. Vaishali Rajendra Mane",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "76"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "793753",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
document_1694417278401_289559.pdf",
  "fileName": "document_1694417278401_289559.pdf"
},
{
  "documentType": {
    "label": "Tax Receipt",
    "value": "60ae12afaa6d152c1801b4c8"
  },
}
```

```
"inputs": {
  "documentDate": "18/07/2023",
  "nameOfApprovingAuthority": {
    "value": "Kalyan_Dombivli_Municipal_Corporation",
    "label": "Kalyan Dombivli Municipal Corporation"
  }
},
"isHardCopy": false,
"displayStatus": true,
"id": "750818",
"path": "cases/64fec1e7a8e9b70221ddf8dd/
document_1694417304638_690023.pdf",
"fileName": "document_1694417304638_690023.pdf"
},
{
  "documentType": {
    "value": "60ae12a8aa6d152c1801b4a8",
    "label": "Part Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "19/06/2015",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    }
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1694500260185_165613.pdf",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
document_1694500260185_165613.pdf",
  "id": "570896",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Tue Sep 12 2023 12:02:50 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12a8aa6d152c1801b4a8",
    "label": "Part Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "03/01/2017",
    "nameOfApprovingAuthority": {
      "value": "Kalyan_Dombivli_Municipal_Corporation",
      "label": "Kalyan Dombivli Municipal Corporation"
    }
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1694500299226_106239.pdf",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
document_1694500299226_106239.pdf",
    "id": "203653",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Tue Sep 12 2023 12:02:50 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003669",
"createdBy": "6410199a140f140ffc59b58c",
"caseHistory": [
  {
    "id": "654426",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 11 2023 12:59:43 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rajendra mane",
    "phone": "9022174883",
    "ownershipShare": "",
    "email": "",
    "id": "306455"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeea6",
    "name":
"externalImg_1694437653987_WhatsApp_Image_20230911_at_42729_PM_2.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externalImg_1694437653987_WhatsApp_Image_20230911_at_42729_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeea7",
    "name":
"externallmg_1694437653989_WhatsApp_Image_20230911_at_42451_PM_1.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437653989_WhatsApp_Image_20230911_at_42451_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeea8",
    "name":
"externallmg_1694437653996_WhatsApp_Image_20230911_at_42451_PM_2.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437653996_WhatsApp_Image_20230911_at_42451_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeea9",
    "name":
"externallmg_1694437654002_WhatsApp_Image_20230911_at_42451_PM_3.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654002_WhatsApp_Image_20230911_at_42451_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeeaa",
    "name":
"externallmg_1694437654007_WhatsApp_Image_20230911_at_42451_PM_4.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654007_WhatsApp_Image_20230911_at_42451_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeeab",
```

```
    "name":
"externallmg_1694437654010_WhatsApp_Image_20230911_at_42451_PM.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654010_WhatsApp_Image_20230911_at_42451_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeac",
  "name":
"externallmg_1694437654013_WhatsApp_Image_20230911_at_42452_PM_1.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654013_WhatsApp_Image_20230911_at_42452_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeead",
  "name":
"externallmg_1694437654016_WhatsApp_Image_20230911_at_42452_PM_2.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654016_WhatsApp_Image_20230911_at_42452_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeae",
  "name":
"externallmg_1694437654018_WhatsApp_Image_20230911_at_42452_PM_3.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654018_WhatsApp_Image_20230911_at_42452_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeaf",
  "name":
"externallmg_1694437654021_WhatsApp_Image_20230911_at_42452_PM_4.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654021_WhatsApp_Image_20230911_at_42452_PM_4.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeb0",
  "name":
"externallmg_1694437654023_WhatsApp_Image_20230911_at_42452_PM_5.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654023_WhatsApp_Image_20230911_at_42452_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeb1",
  "name":
"externallmg_1694437654025_WhatsApp_Image_20230911_at_42452_PM_6.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654025_WhatsApp_Image_20230911_at_42452_PM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeb2",
  "name":
"externallmg_1694437654028_WhatsApp_Image_20230911_at_42452_PM.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654028_WhatsApp_Image_20230911_at_42452_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeb3",
  "name":
"externallmg_1694437654030_WhatsApp_Image_20230911_at_42453_PM_1.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654030_WhatsApp_Image_20230911_at_42453_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1116a8e9b70221deeeb4",
  "name":
"externallmg_1694437654033_WhatsApp_Image_20230911_at_42453_PM_2.jpeg",
```

```
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654033_WhatsApp_Image_20230911_at_42453_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeeb5",
    "name":
"externallmg_1694437654036_WhatsApp_Image_20230911_at_42453_PM.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654036_WhatsApp_Image_20230911_at_42453_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeeb6",
    "name":
"externallmg_1694437654037_WhatsApp_Image_20230911_at_42454_PM_1.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654037_WhatsApp_Image_20230911_at_42454_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeeb7",
    "name":
"externallmg_1694437654039_WhatsApp_Image_20230911_at_42454_PM.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654039_WhatsApp_Image_20230911_at_42454_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1116a8e9b70221deeeb8",
    "name":
"externallmg_1694437654041_WhatsApp_Image_20230911_at_42726_PM_1.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654041_WhatsApp_Image_20230911_at_42726_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "64ff1116a8e9b70221deeeb9",
  "name":
"externallmg_1694437654043_WhatsApp_Image_20230911_at_42726_PM_2.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437654043_WhatsApp_Image_20230911_at_42726_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1129a8e9b70221deef26",
  "name":
"externallmg_1694437673523_WhatsApp_Image_20230911_at_42726_PM_4.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673523_WhatsApp_Image_20230911_at_42726_PM_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1129a8e9b70221deef27",
  "name":
"externallmg_1694437673526_WhatsApp_Image_20230911_at_42726_PM_5.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673526_WhatsApp_Image_20230911_at_42726_PM_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1129a8e9b70221deef28",
  "name":
"externallmg_1694437673529_WhatsApp_Image_20230911_at_42726_PM_6.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673529_WhatsApp_Image_20230911_at_42726_PM_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1129a8e9b70221deef29",
  "name":
"externallmg_1694437673531_WhatsApp_Image_20230911_at_42726_PM_7.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673531_WhatsApp_Image_20230911_at_42726_PM_7.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1129a8e9b70221deef2a",
    "name":
"externallmg_1694437673534_WhatsApp_Image_20230911_at_42726_PM_8.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673534_WhatsApp_Image_20230911_at_42726_PM_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1129a8e9b70221deef2b",
    "name":
"externallmg_1694437673536_WhatsApp_Image_20230911_at_42726_PM.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673536_WhatsApp_Image_20230911_at_42726_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1129a8e9b70221deef2c",
    "name":
"externallmg_1694437673540_WhatsApp_Image_20230911_at_42727_PM_1.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673540_WhatsApp_Image_20230911_at_42727_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1129a8e9b70221deef2d",
    "name":
"externallmg_1694437673542_WhatsApp_Image_20230911_at_42727_PM_2.jpeg",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673542_WhatsApp_Image_20230911_at_42727_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "64ff1129a8e9b70221deef2e",
```

```
    "name":  
    "externallmg_1694437673545_WhatsApp_Image_20230911_at_42727_PM_3.jpeg",  
    "path": "cases/64fec1e7a8e9b70221ddf8dd/  
externallmg_1694437673545_WhatsApp_Image_20230911_at_42727_PM_3.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64ff1129a8e9b70221deef2f",  
    "name":  
    "externallmg_1694437673548_WhatsApp_Image_20230911_at_42727_PM_4.jpeg",  
    "path": "cases/64fec1e7a8e9b70221ddf8dd/  
externallmg_1694437673548_WhatsApp_Image_20230911_at_42727_PM_4.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64ff1129a8e9b70221deef30",  
    "name":  
    "externallmg_1694437673550_WhatsApp_Image_20230911_at_42727_PM_5.jpeg",  
    "path": "cases/64fec1e7a8e9b70221ddf8dd/  
externallmg_1694437673550_WhatsApp_Image_20230911_at_42727_PM_5.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64ff1129a8e9b70221deef31",  
    "name":  
    "externallmg_1694437673552_WhatsApp_Image_20230911_at_42727_PM_6.jpeg",  
    "path": "cases/64fec1e7a8e9b70221ddf8dd/  
externallmg_1694437673552_WhatsApp_Image_20230911_at_42727_PM_6.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "64ff1129a8e9b70221deef32",  
    "name":  
    "externallmg_1694437673555_WhatsApp_Image_20230911_at_42727_PM_7.jpeg",  
    "path": "cases/64fec1e7a8e9b70221ddf8dd/  
externallmg_1694437673555_WhatsApp_Image_20230911_at_42727_PM_7.jpeg",  
    "orientation": "portrait"  
  },  
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1129a8e9b70221deef33",
  "name":
"externallmg_1694437673558_WhatsApp_Image_20230911_at_42727_PM.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673558_WhatsApp_Image_20230911_at_42727_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1129a8e9b70221deef34",
  "name":
"externallmg_1694437673560_WhatsApp_Image_20230911_at_42729_PM_1.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673560_WhatsApp_Image_20230911_at_42729_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "64ff1129a8e9b70221deef35",
  "name":
"externallmg_1694437673563_WhatsApp_Image_20230911_at_42729_PM.jpeg",
  "path": "cases/64fec1e7a8e9b70221ddf8dd/
externallmg_1694437673563_WhatsApp_Image_20230911_at_42729_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "IGR-01.pdf",
    "filename": "1694435154036_IGR01.pdf",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154036_IGR01.pdf",
    "size": "98992",
    "createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1694435154041_IGR02.pdf",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154041_IGR02.pdf",
```

```
"size": "99117",
"createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-03.pdf",
"filename": "1694435154045_IGR03.pdf",
"path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154045_IGR03.pdf",
"size": "99759",
"createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-04.pdf",
"filename": "1694435154049_IGR04.pdf",
"path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154049_IGR04.pdf",
"size": "99678",
"createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-05.pdf",
"filename": "1694435154054_IGR05.pdf",
"path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154054_IGR05.pdf",
"size": "100068",
"createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-06.pdf",
"filename": "1694435154057_IGR06.pdf",
"path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154057_IGR06.pdf",
"size": "99042",
"createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "IGR-07.pdf",
"filename": "1694435154059_IGR07.pdf",
"path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154059_IGR07.pdf",
"size": "99832",
```

```

    "createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "Summary New=Rajendra.xlsx",
    "filename": "1694435154062_Summary_NewRajendra.xlsx",
    "path": "cases/64fec1e7a8e9b70221ddf8dd/
processingDocuments/1694435154062_Summary_NewRajendra.xlsx",
    "size": "4913072",
    "createdAt": "Mon Sep 11 2023 17:55:54 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
],
"remarks": [],
"createdAt": "2023-09-11T07:29:44.020Z",
"updatedAt": "2023-09-12T06:32:50.610Z",
"__v": 0,
"invoiceId": "64fec1e8a8e9b70221ddf8f7",
"fullAddress": " Flat No. 704, 7th Floor, Building No 3, Sarvodaya Leela, Village -
Kanchangaon, Taluka - Kalyan, District - Thane",
"updatedAt": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Rajendra mane",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9022174883"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			