

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "641ef58a695fbc66ee1a2c39"
    },
    "type": "CREDITOFFICER",
    "_id": "641ef58a695fbc66ee1a2c3b",
    "firstName": "Manish ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7506921112",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "5900"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "641ef58a695fbc66ee1a2c39",
  "name": "RLP Nashik\t",
  "branchCode": "",
  "mobileNo": "02532571977\t",
  "alternateMobileNo": "",
  "email": "ulpnasik@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Union Loanpoint Nashiik,\nNawandar Sankul Racca Colony, Near Soni
Paithani, Sharanpur road Nashik-02"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential_cum_commercial",
  "label": "Residential cum Commercial"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f9147bf3dd69653a591e8c",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
```

```
    "shortName": "V",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.983888246117438",
  "longitude": "73.77523302812963"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-12T09:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tahasil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Old Canel Link Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Bussiness Center Roognta",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "THREE LEAVES PHASE ONE",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "789/3",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```



```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422009",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"_id": "650037c2a8e9b70221e0403a",
"ownerName": "Three Leaves",
"ownerPhoneNo": "9823339180",
"fullAddress": " APF No. Basement Floor, THREE LEAVES PHASE ONE, Near
Bussiness Center Roognta, New/Current Survey No. 789/3, Old Canel Link Road,
Village - Nashik, District - Nashik, Nashik, 422009",
"remark": "",
"documents": [
  {
    "documentType": {
```

```
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694512790681_agreement.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/
document_1694512790681_agreement.pdf",
  "id": "899801",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/10/2022",
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "LND/BP/B2/253/2022"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694512834416_CC.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/document_1694512834416_CC.pdf",
  "id": "204290",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  }
}
```



```
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694512847864_DCC.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/document_1694512847864_DCC.pdf",
  "id": "979999",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694512858705_doc.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/document_1694512858705_doc.pdf",
  "id": "923353",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694512868622_docs.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/document_1694512868622_docs.pdf",
  "id": "594410",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2e8",
    "label": "Layout Plan"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694512882538_Layout.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/
document_1694512882538_Layout.pdf",
```

```
"id": "272362",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "LND/BP/B2/253/2022"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1694512913260_plan_1.pdf",
"path": "cases/650037c2a8e9b70221e0403a/
document_1694512913260_plan_1.pdf",
"id": "627922",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": ""
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1694512922562_plan_2.pdf",
"path": "cases/650037c2a8e9b70221e0403a/
document_1694512922562_plan_2.pdf",
```

```
"id": "331174",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694512975155_plan_3.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/
document_1694512975155_plan_3.pdf",
  "id": "798771",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    }
  },
  "Document_No": "P51600047728"
},
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694513010604_RERA.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/
document_1694513010604_RERA.pdf",
  "id": "950246",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12a8aa6d152c1801b4a7",
```

```
    "label": "Title Search Report"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": ""
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1694513024327_Three_Leaves_Phase_One___Title_Search_Report.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/
document_1694513024327_Three_Leaves_Phase_One___Title_Search_Report.pdf",
  "id": "198984",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae125aaa6d152c1801b343",
    "label": "Title Certificate"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1694513038510_TSR.pdf",
  "path": "cases/650037c2a8e9b70221e0403a/document_1694513038510_TSR.pdf",
  "id": "969007",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Sep 12 2023 15:34:13 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "003732",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "104571",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Sep 12 2023 15:34:50 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Three Leaves",
```

```
    "phone": "9823339180",
    "ownershipShare": "",
    "email": "",
    "id": "901222"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046ef",
    "name":
"externallmg_1694513216542_WhatsApp_Image_20230912_at_22149_PM.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216542_WhatsApp_Image_20230912_at_22149_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f0",
    "name":
"externallmg_1694513216608_WhatsApp_Image_20230912_at_22151_PM_1.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216608_WhatsApp_Image_20230912_at_22151_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f1",
    "name":
"externallmg_1694513216646_WhatsApp_Image_20230912_at_22151_PM.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216646_WhatsApp_Image_20230912_at_22151_PM.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f2",
    "name":
"externallmg_1694513216690_WhatsApp_Image_20230912_at_22152_PM_1.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216690_WhatsApp_Image_20230912_at_22152_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f3",
    "name":
"externallmg_1694513216741_WhatsApp_Image_20230912_at_22152_PM.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216741_WhatsApp_Image_20230912_at_22152_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f4",
    "name":
"externallmg_1694513216822_WhatsApp_Image_20230912_at_22153_PM_1.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216822_WhatsApp_Image_20230912_at_22153_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f5",
    "name":
"externallmg_1694513216852_WhatsApp_Image_20230912_at_22153_PM_2.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216852_WhatsApp_Image_20230912_at_22153_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f6",
    "name":
"externallmg_1694513216929_WhatsApp_Image_20230912_at_22153_PM.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513216929_WhatsApp_Image_20230912_at_22153_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f7",
    "name":
"externallmg_1694513217015_WhatsApp_Image_20230912_at_22154_PM_1.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513217015_WhatsApp_Image_20230912_at_22154_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f8",
    "name":
"externallmg_1694513217093_WhatsApp_Image_20230912_at_22154_PM.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513217093_WhatsApp_Image_20230912_at_22154_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046f9",
    "name":
"externallmg_1694513217213_WhatsApp_Image_20230912_at_22155_PM_1.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513217213_WhatsApp_Image_20230912_at_22155_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046fa",
    "name":
"externallmg_1694513217268_WhatsApp_Image_20230912_at_22155_PM_2.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513217268_WhatsApp_Image_20230912_at_22155_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046fb",
```

```

    "name":
    "externallmg_1694513217348_WhatsApp_Image_20230912_at_22155_PM.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513217348_WhatsApp_Image_20230912_at_22155_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65003841a8e9b70221e046fc",
    "name":
    "externallmg_1694513217415_WhatsApp_Image_20230912_at_22156_PM.jpeg",
    "path": "cases/650037c2a8e9b70221e0403a/
externallmg_1694513217415_WhatsApp_Image_20230912_at_22156_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-12T10:04:50.438Z",
"updatedAt": "2023-09-12T10:06:57.619Z",
"__v": 0,
"invoiceId": "650037c2a8e9b70221e04056",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a29b64d42487767af43ea",
"contactPersonName": "Three Leaves",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9823339180"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			