

```
{
  "typeOfReport": {
    "label": "Capital Gain",
    "value": "Capital_Gain"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Capital Gain",
    "value": "Capital_Gain"
  },
  "masterTypeOfPurpose": {
    "label": "Capital Gain",
    "value": "Capital_Gain"
  },
  "toAssess": {
    "label": "Capital Gain 2001",
    "value": "Capital_Gain_2001"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "1700000",
    "discussWithPerson": "",
    "expectedFees": 850,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "6507dff2a8e9b70221e95341",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "PravinchandraShah & Vinodchandra Shah",
"displayname": "PravinchandraShah & Vinodchandra Shah",
"initial": "P"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Industrial",
  "label": "Industrial"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "64d09914dc9f3034f3008833",
    "role": "SITEENGINEER+MAKAR",
    "firstName": "Meetal",
    "email": "meetalirasal@gmail.com",
    "lastName": "Rasal",
    "mobileNo": "7397882283",
    "designation": "Junior Architect",
    "shortName": "MR",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
```

```
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
```

```
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Private Clients",
  "value": "PRIVATE_CLIENT"
},
"location": {
  "latitude": "19.172457712241545",
  "longitude": "72.8558111699629"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8558111699629,
    19.172457712241545
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-09-18T06:30:00.000Z",
      "remark": ""
    }
  ]
}
```

```
    }
  ],
  "visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dindoshi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
  }
}
```

```
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Synthofine Estate",
  "label": false
},
"selectArea": {
  "status": false,
```

```
"name": "Sector",
"key": "selectArea",
"value": "",
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Off Aarey Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Unit No 11",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
```



```
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon East",
  "label": false
}
```

```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
```

```
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
},
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"_id": "6507e015a8e9b70221e95347",
"ownerName": "PravinchandraShah & Vinodchandra Shah",
"ownerPhoneNo": "9833916037",
"appAddress": "Unit no.B-011, Ground floor,Bldg- B, Synthofine Estate Goregoan East
- 400063",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    },
    "isHardCopy": false,
    "path": "cases/6507e015a8e9b70221e95347/
document_1695014732988_Document_page_49.pdf",
    "fileName": "document_1695014732988_Document_page_49.pdf",
    "displayStatus": false,
    "id": "314632",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Sep 18 2023 10:58:18 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Draft Agreement for sale",
      "value": "60ae1256aa6d152c1801b330"
    },
    "isHardCopy": false,
    "path": "cases/6507e015a8e9b70221e95347/
document_1695018905690_Document_Pvt_case.pdf",
    "fileName": "document_1695018905690_Document_Pvt_case.pdf",
    "displayStatus": false,
    "id": "758165",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Sep 18 2023 12:07:13 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae12a0aa6d152c1801b483",
      "label": "site Details"
    }
  }
]
```



```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1695024233319_Site_details.pdf",
    "path": "cases/6507e015a8e9b70221e95347/
document_1695024233319_Site_details.pdf",
    "id": "922740",
    "uploadedBy": "64d09914dc9f3034f3008833",
    "createdAt": "Mon Sep 18 2023 13:33:53 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "003889",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "386506",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 18 2023 10:58:53 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "PravinchandraShah & Vinodchandra Shah",
    "phone": "9833916037",
    "ownershipShare": "",
    "email": "",
    "id": "909749"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11d8",
    "name":
"externalImg_1695031992396_WhatsApp_Image_20230918_at_12651_PM_1.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externalImg_1695031992396_WhatsApp_Image_20230918_at_12651_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11d9",
    "name":
"externallmg_1695031992401_WhatsApp_Image_20230918_at_12651_PM_2.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992401_WhatsApp_Image_20230918_at_12651_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11da",
    "name":
"externallmg_1695031992407_WhatsApp_Image_20230918_at_12651_PM_3.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992407_WhatsApp_Image_20230918_at_12651_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11db",
    "name":
"externallmg_1695031992417_WhatsApp_Image_20230918_at_12651_PM.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992417_WhatsApp_Image_20230918_at_12651_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11dc",
    "name":
"externallmg_1695031992422_WhatsApp_Image_20230918_at_12652_PM_1.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992422_WhatsApp_Image_20230918_at_12652_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11dd",
```

```
    "name":
"externallmg_1695031992427_WhatsApp_Image_20230918_at_12652_PM_2.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992427_WhatsApp_Image_20230918_at_12652_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11de",
    "name":
"externallmg_1695031992431_WhatsApp_Image_20230918_at_12652_PM.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992431_WhatsApp_Image_20230918_at_12652_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11df",
    "name":
"externallmg_1695031992436_WhatsApp_Image_20230918_at_12653_PM_1.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992436_WhatsApp_Image_20230918_at_12653_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11e0",
    "name":
"externallmg_1695031992448_WhatsApp_Image_20230918_at_12653_PM_2.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992448_WhatsApp_Image_20230918_at_12653_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822b8a8e9b70221ea11e1",
    "name":
"externallmg_1695031992453_WhatsApp_Image_20230918_at_12653_PM.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992453_WhatsApp_Image_20230918_at_12653_PM.jpeg",
    "orientation": "portrait"
  },
  }
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822b8a8e9b70221ea11e2",
  "name":
"externallmg_1695031992456_WhatsApp_Image_20230918_at_12654_PM_1.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992456_WhatsApp_Image_20230918_at_12654_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822b8a8e9b70221ea11e3",
  "name":
"externallmg_1695031992459_WhatsApp_Image_20230918_at_12654_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695031992459_WhatsApp_Image_20230918_at_12654_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822c9a8e9b70221ea1246",
  "name":
"externallmg_1695032009378_WhatsApp_Image_20230918_at_12641_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009378_WhatsApp_Image_20230918_at_12641_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822c9a8e9b70221ea1247",
  "name":
"externallmg_1695032009381_WhatsApp_Image_20230918_at_12645_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009381_WhatsApp_Image_20230918_at_12645_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822c9a8e9b70221ea1248",
  "name":
"externallmg_1695032009384_WhatsApp_Image_20230918_at_12646_PM.jpeg",
```

```
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009384_WhatsApp_Image_20230918_at_12646_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea1249",
    "name":
"externallmg_1695032009388_WhatsApp_Image_20230918_at_12647_PM_1.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009388_WhatsApp_Image_20230918_at_12647_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea124a",
    "name":
"externallmg_1695032009391_WhatsApp_Image_20230918_at_12647_PM_2.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009391_WhatsApp_Image_20230918_at_12647_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea124b",
    "name":
"externallmg_1695032009394_WhatsApp_Image_20230918_at_12647_PM.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009394_WhatsApp_Image_20230918_at_12647_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea124c",
    "name":
"externallmg_1695032009397_WhatsApp_Image_20230918_at_12648_PM_1.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009397_WhatsApp_Image_20230918_at_12648_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "650822c9a8e9b70221ea124d",
  "name":
"externallmg_1695032009399_WhatsApp_Image_20230918_at_12648_PM_2.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009399_WhatsApp_Image_20230918_at_12648_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822c9a8e9b70221ea124e",
  "name":
"externallmg_1695032009404_WhatsApp_Image_20230918_at_12648_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009404_WhatsApp_Image_20230918_at_12648_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822c9a8e9b70221ea124f",
  "name":
"externallmg_1695032009407_WhatsApp_Image_20230918_at_12649_PM_1.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009407_WhatsApp_Image_20230918_at_12649_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822c9a8e9b70221ea1250",
  "name":
"externallmg_1695032009409_WhatsApp_Image_20230918_at_12649_PM_2.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009409_WhatsApp_Image_20230918_at_12649_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822c9a8e9b70221ea1251",
  "name":
"externallmg_1695032009411_WhatsApp_Image_20230918_at_12649_PM_3.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009411_WhatsApp_Image_20230918_at_12649_PM_3.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea1252",
    "name":
"externallmg_1695032009412_WhatsApp_Image_20230918_at_12649_PM.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009412_WhatsApp_Image_20230918_at_12649_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea1253",
    "name":
"externallmg_1695032009414_WhatsApp_Image_20230918_at_12650_PM_1.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009414_WhatsApp_Image_20230918_at_12650_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea1254",
    "name":
"externallmg_1695032009416_WhatsApp_Image_20230918_at_12650_PM_2.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009416_WhatsApp_Image_20230918_at_12650_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822c9a8e9b70221ea1255",
    "name":
"externallmg_1695032009419_WhatsApp_Image_20230918_at_12650_PM.jpeg",
    "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032009419_WhatsApp_Image_20230918_at_12650_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "650822d1a8e9b70221ea133b",
```

```
    "name":
"externallmg_1695032016994_WhatsApp_Image_20230918_at_12616_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032016994_WhatsApp_Image_20230918_at_12616_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822d1a8e9b70221ea133c",
  "name":
"externallmg_1695032016997_WhatsApp_Image_20230918_at_12618_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032016997_WhatsApp_Image_20230918_at_12618_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822d1a8e9b70221ea133d",
  "name":
"externallmg_1695032017000_WhatsApp_Image_20230918_at_12620_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032017000_WhatsApp_Image_20230918_at_12620_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822d1a8e9b70221ea133e",
  "name":
"externallmg_1695032017002_WhatsApp_Image_20230918_at_12628_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032017002_WhatsApp_Image_20230918_at_12628_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822d1a8e9b70221ea133f",
  "name":
"externallmg_1695032017004_WhatsApp_Image_20230918_at_12631_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032017004_WhatsApp_Image_20230918_at_12631_PM.jpeg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822d1a8e9b70221ea1340",
  "name":
"externallmg_1695032017006_WhatsApp_Image_20230918_at_12632_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032017006_WhatsApp_Image_20230918_at_12632_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822d1a8e9b70221ea1341",
  "name":
"externallmg_1695032017009_WhatsApp_Image_20230918_at_12634_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032017009_WhatsApp_Image_20230918_at_12634_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "650822d1a8e9b70221ea1342",
  "name":
"externallmg_1695032017011_WhatsApp_Image_20230918_at_12638_PM.jpeg",
  "path": "cases/6507e015a8e9b70221e95347/
externallmg_1695032017011_WhatsApp_Image_20230918_at_12638_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-09-18T05:28:53.974Z",
"updatedAt": "2023-09-18T10:13:37.069Z",
"__v": 0,
"invoiceId": "6507e016a8e9b70221e95358",
"updatedBy": "64d09914dc9f3034f3008833",
"fullAddress": " Capital Gain No. Unit No 11, Ground Floor, Wing - B, Synthofine
Estate, Off Aarey Road, Village - Dindoshi, Goregaon East, Mumbai",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "PravinchandraShah & Vinodchandra Shah",
"email": "",
"isExternal": "false",
```

"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9833916037"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			