

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "62789cf4b0d7f32a7ac19e1c",
    "firstName": "Naman Agarwal",
    "lastName": "Agarwal",
    "mobileNo": "",
    "email": "naman.agarwal@sbi.co.in",
    "workMobileNo": "9160388615"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Naman Agarwal",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordinatiion",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
```

```
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      }
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.16631026873656",
  "longitude": "72.8777148973992"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8777148973992,
    19.16631026873656
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [
  {
    "dateTime": "2023-09-29T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-29T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-29T12:00:00.000Z",
    "remark": ""
  },
  {
    "dateTime": "2023-09-29T12:00:00.000Z",
    "remark": ""
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
```

```
"name": "Village",
"key": "village",
"value": "Pahadi Goregaon",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Goregaon (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
}
```

```
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Navnath Jayas ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Jayprakash Nagar, Road No. 5",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
```



```
"key": "wing",
"value": "A",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "440, 440/1, 440/2, 440/3, 440/3",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
}
```

```
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
```

```
"value": "",
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 063",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
```

```
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Pahadi Road",
    "west": "Internal Road & Amey CHSL",
    "south": "Wing - B",
    "east": "Under Construction Building "
  },
  "asPerDocumentAgreement": {
    "north": "Pahadi School Road No. 2",
    "west": "BMC Colony",
    "south": "Open Ground",
    "east": "Julius Wadi Redevelopment Project"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Details is not available",
      "east": "Details is not available",
      "south": "Details is not available",
      "west": "Details is not available"
    },
    "asPerDocument": {
      "north": "Details is not available",
      "east": "Details is not available",
      "south": "Details is not available",
      "west": "Details is not available"
    }
  },
}
```

```
    "isDisplay": false,
    "title": "Boundaries of The Flat"
  },
  "extraDetailOfProperty": "As Per Approved Plan, the composition of flat will be 1
Bedrooms + Living Room + Kitchen + 2 Toilets + Passage (i.e. 1BHK with 2 Toilets)",
  "dateOfIssusApprovePlan": "",
  "approvePlanVerified": "",
  "empanelledOfApprovePlan": ""
},
"compositeRate": {
  "remark": "At the time of site inspection, internal visit not allowed at site. The details
about the work progress status have been provided by site supervisor Mr. Prathamesh
Pawar (Contact No. 7038074232).",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "142760",
  "landRate": "63420",
  "igrImage": "cases/651653f2e393a05c2411b065/igr_1696075844220_Image.png",
  "squareMeterGuideLineRate": "142760.00",
  "squareFeetGuideLineRate": "13263.00"
},
"igrFinalRate": {
  "depreciationPercentage": "0",
  "rate": "142760",
  "squareMeterGuideLineRate": "142760.00",
  "squareFeetGuideLineRate": "13263.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
},
```

```
"monthlyRent": "17,500",
"assessmentNo": "Details is not available",
"taxPaidHolderName": "Details is not available",
"taxAmount": "Details is not available",
"electricityServiceConnectionNo": "Details is not available",
"meterCardHolderName": "Details is not available",
"undividedAreaOfLandAsPerSaleDeed": "Details is not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Building is under construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Along with one car parking space",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
```

```
"date": "",
"month": "1",
"year": "2027",
"fullDate": "1/1/2027"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
```

```
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
"value": "Building_is_under_construction_",
"label": "Building is under construction "
},
"maintenancelssues": {
"value": "Information_not_available",
"label": "Information not available"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "17",
"flatFloorNo": "",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"area": "445.50",
"measurementType": "Sq. Ft.",
```



```
"areaAsPer": "Area As per Agreement for sale"
},
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/651653f2e393a05c2411b065/
routeMap_1696311541494_Image.png",
    "routeLat": "19.164147",
    "routeLng": "72.855275",
    "stationName": "Goregaon",
    "routeDistance": "700 Mtr."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "xtj337s",
      "name": "xtj337s",
      "image": "cases/651653f2e393a05c2411b065/
routeMap_1696311451313_Image.png"
    }
  ],
  "valuation": {
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
    "showcasesRate": "0",
    "totalshowcasesRate": "0",
    "kitchenArrangementsQty": "0",
    "kitchenArrangementsRate": "0",
    "totalkitchenArrangementsRate": "0",
    "superfineFinishQty": "0",
```

```
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8505000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8505000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "10.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5908667.00",
  "selectedBuildUpValue": "445.50",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "651813b62c6c0778ddf14aa1",
      "name": "externallmg_1696076726273_IMG20230930WA0103.jpg",
      "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726273_IMG20230930WA0103.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "651813b62c6c0778ddf14a9c",
      "name": "externallmg_1696076726245_IMG20230930WA0098.jpg",
      "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726245_IMG20230930WA0098.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "651813b62c6c0778ddf14a9d",
      "name": "externallmg_1696076726248_IMG20230930WA0099.jpg",
      "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726248_IMG20230930WA0099.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "651813b62c6c0778ddf14aa2",
      "name": "externallmg_1696076726280_IMG20230930WA0104.jpg",
      "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726280_IMG20230930WA0104.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "651813b62c6c0778ddf14aa6",
      "name": "externallmg_1696076726298_IMG20230930WA0108.jpg",
      "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726298_IMG20230930WA0108.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "651813b62c6c0778ddf14aa5",
      "name": "externallmg_1696076726295_IMG20230930WA0107.jpg",
      "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726295_IMG20230930WA0107.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "651813b62c6c0778ddf14aa7",
      "name": "externallmg_1696076726317_IMG20230930WA0109.jpg",
      "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726317_IMG20230930WA0109.jpg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20296",
    "max": "26914"
  },
  "builtUpRateRange": {
    "min": "16914",
    "max": "22428"
  }
}
```

```
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
```



```
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "405.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "651653f2e393a05c2411b065",
"ownerName": "Mrs. Sneha Samir Korgaonkar & Mr. Samir Shashikant Korgaonkar",
"ownerPhoneNo": "8879632653",
"appAddress": "Flat no 202,2floor,A-wing,Navnath Jayas,Jay prakash Nagar.Road no
5,Goregaon East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "11/09/2023",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      }
    }
  }
]
```

```
    },
    "Promoter": "M/s. Navnath Infrastructure Pvt. Ltd.",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Mrs. Sneha Samir Korgaokar & Mr. Samir Shashikant Korgaonkar"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "972222",
  "path": "cases/651653f2e393a05c2411b065/
document_document_1695961822866_DocScanner_28Sep2023_1604.pdf",
  "fileName":
"document_document_1695961822866_DocScanner_28Sep2023_1604.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "23/06/2023",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51800051536"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696310381116_852120.pdf",
  "path": "cases/651653f2e393a05c2411b065/
document_1696310381116_852120.pdf",
  "id": "697895",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Tue Oct 03 2023 10:49:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "27/04/2022",
    "nameOfApprovingAuthority": {
```

```
    "value": "Municipal_Corporation_Of_Greater_Mumbai",
    "label": "Municipal Corporation Of Greater Mumbai"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P - 10999 / 2022 / (440 And Other) / P / S / Ward / PAHADI GOREGAON -
E / CC / 1 / New"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1696310512479_785054.pdf",
"path": "cases/651653f2e393a05c2411b065/
document_1696310512479_785054.pdf",
"id": "136814",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Oct 03 2023 10:51:52 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "21/01/2023",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_Of_Greater_Mumbai",
      "label": "Municipal Corporation Of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P - 10999 / 2022 / (440 And Other) / P / S / Ward / PAHADI GOREGAON -
E"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "448441",
  "path": "cases/651653f2e393a05c2411b065/document_1696310686783_6_2.pdf",
  "fileName": "document_1696310686783_6_2.pdf"
}
],
"caseNumber": "004093",
"createdBy": "60af3d172ffdf65bcd6585cd",
```

```
"caseHistory": [
  {
    "id": "673361",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 29 2023 10:04:58 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Sneha Samir Korgaokar & Mr. Samir Shashikant Korgaonkar",
    "phone": "8879632653",
    "ownershipShare": "",
    "email": "",
    "id": "686653"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "207990",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "405",
    "squareMeterArea": "37.63",
    "docFinalBuiltUp": "445.5",
    "docFinalBuiltUpSquareMeter": "41.393",
    "docBultupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
```

```
{
  "printlnReport": true,
  "_id": "6518109b2c6c0778ddf135bc",
  "property": "Residential Flat",
  "area": "405",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "10100000",
  "expectedRate": "24938.27",
  "builtUpExpectedRate": "20781.89",
  "image": "cases/651653f2e393a05c2411b065/
indicator_1696075531785_Image.png",
  "squareMeter": "37.63",
  "id": "424044"
},
{
  "printlnReport": true,
  "_id": "6518109b2c6c0778ddf135bd",
  "property": "Residential Flat",
  "area": "405",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "10900000",
  "expectedRate": "26913.58",
  "builtUpExpectedRate": "22427.98",
  "image": "cases/651653f2e393a05c2411b065/
indicator_1696075569104_Image.png",
  "squareMeter": "37.63",
  "id": "650183"
},
{
  "printlnReport": true,
  "_id": "6518109b2c6c0778ddf135be",
  "property": "Residential Flat",
  "area": "405",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
```

```
    "expectedPrice": "8220000",
    "expectedRate": "20296.30",
    "builtUpExpectedRate": "16913.58",
    "image": "cases/651653f2e393a05c2411b065/
indicator_1696075627924_Image.png",
    "squareMeter": "37.63",
    "id": "789439"
  },
  {
    "printlnReport": true,
    "_id": "6518109b2c6c0778ddf135bf",
    "property": "Residential Flat",
    "area": "608",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Carpet",
    "source": "Index_no.2",
    "expectedPrice": "12950400",
    "expectedRate": "21300.00",
    "builtUpExpectedRate": "17750.00",
    "image": "cases/651653f2e393a05c2411b065/
indicator_1696075678604_Image.png",
    "squareMeter": "56.49",
    "id": "844140"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651813b62c6c0778ddf14a9c",
    "name": "externalImg_1696076726245_IMG20230930WA0098.jpg",
    "path": "cases/651653f2e393a05c2411b065/
externalImg_1696076726245_IMG20230930WA0098.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651813b62c6c0778ddf14a9d",
    "name": "externalImg_1696076726248_IMG20230930WA0099.jpg",
    "path": "cases/651653f2e393a05c2411b065/
externalImg_1696076726248_IMG20230930WA0099.jpg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651813b62c6c0778ddf14a9e",
  "name": "externallmg_1696076726254_IMG20230930WA0100.jpg",
  "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726254_IMG20230930WA0100.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651813b62c6c0778ddf14a9f",
  "name": "externallmg_1696076726262_IMG20230930WA0101.jpg",
  "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726262_IMG20230930WA0101.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651813b62c6c0778ddf14aa0",
  "name": "externallmg_1696076726268_IMG20230930WA0102.jpg",
  "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726268_IMG20230930WA0102.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651813b62c6c0778ddf14aa1",
  "name": "externallmg_1696076726273_IMG20230930WA0103.jpg",
  "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726273_IMG20230930WA0103.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "651813b62c6c0778ddf14aa2",
  "name": "externallmg_1696076726280_IMG20230930WA0104.jpg",
  "path": "cases/651653f2e393a05c2411b065/
externallmg_1696076726280_IMG20230930WA0104.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651813b62c6c0778ddf14aa3",
    "name": "externalImg_1696076726284_IMG20230930WA0105.jpg",
    "path": "cases/651653f2e393a05c2411b065/
externalImg_1696076726284_IMG20230930WA0105.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651813b62c6c0778ddf14aa4",
    "name": "externalImg_1696076726288_IMG20230930WA0106.jpg",
    "path": "cases/651653f2e393a05c2411b065/
externalImg_1696076726288_IMG20230930WA0106.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651813b62c6c0778ddf14aa5",
    "name": "externalImg_1696076726295_IMG20230930WA0107.jpg",
    "path": "cases/651653f2e393a05c2411b065/
externalImg_1696076726295_IMG20230930WA0107.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651813b62c6c0778ddf14aa6",
    "name": "externalImg_1696076726298_IMG20230930WA0108.jpg",
    "path": "cases/651653f2e393a05c2411b065/
externalImg_1696076726298_IMG20230930WA0108.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "651813b62c6c0778ddf14aa7",
    "name": "externalImg_1696076726317_IMG20230930WA0109.jpg",
    "path": "cases/651653f2e393a05c2411b065/
externalImg_1696076726317_IMG20230930WA0109.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```



```
"processingDocuments": [
  {
    "originalname": "6 (2).pdf",
    "filename": "1696312550212_6_2.pdf",
    "path": "cases/651653f2e393a05c2411b065/
processingDocuments/1696312550212_6_2.pdf",
    "size": "2085238",
    "createdAt": "Tue Oct 03 2023 11:25:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1696313148465_Calculation_Sheet.xlsx",
    "path": "cases/651653f2e393a05c2411b065/
processingDocuments/1696313148465_Calculation_Sheet.xlsx",
    "size": "16272",
    "createdAt": "Tue Oct 03 2023 11:35:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "Summary Sheet (1).xlsx",
    "filename": "1696313148466_Summary_Sheet_1.xlsx",
    "path": "cases/651653f2e393a05c2411b065/
processingDocuments/1696313148466_Summary_Sheet_1.xlsx",
    "size": "1872119",
    "createdAt": "Tue Oct 03 2023 11:35:48 GMT+0530 (India Standard Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  }
],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "6517c7252c6c0778ddf00493",
    "note": "Value Confirmed - Pending For Site Visit ",
    "taskId": "6516b6b02c6c0778ddef0b05",
    "createdAt": "2023-09-30T06:58:45.294Z"
  }
]
```

```

    }
  ],
  "createdAt": "2023-09-29T04:34:58.396Z",
  "updatedAt": "2023-10-03T07:08:45.723Z",
  "__v": 0,
  "invoiceId": "651653f2e393a05c2411b084",
  "fullAddress": "Residential Flat No. 202, 2nd Floor, Wing - A, Navnath Jayas ,
Jayprakash Nagar, Road No. 5, Village - Pahadi Goregaon, Taluka - Borivali, District -
Mumbai Suburban, Goregaon (East), PIN - 400 063, State - Maharashtra, India",
  "updatedBy": "64dc7184ccaf1e7b7f637f47",
  "addressForMap": "",
  "caseReferredBy": "",
  "contactPersonName": "Mr. Prathamesh Pawar",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Site Supervisor",
  "siteVisitContactNo": "7038074232",
  "buildingServicesRate": "2500",
  "finalAreaType": "Carpet Area",
  "finalAsPerArea": "Agreement For Sale",
  "finalBuiltUpPercentage": "10",
  "finalCarpetConvertToBuiltUpPer": "10",
  "finalMeasurementType": "Sq. Ft.",
  "finalValuationAreaString": "Carpet Area in Sq. Ft. = 405.00",
  "flatRate": "21000",
  "landOtherRate": "18500",
  "builtupPercentage": "10",
  "carpetTotal": "0",
  "extendOfSiteRemark": "",
  "finalBuiltupArea": "0.00",
  "finalCarpetArea": "0.00",
  "finalSalableArea": "0.00",
  "otherCarpetTotal": "0",
  "salablePercentage": "10",
  "siteMeasurementRemark": "",
  "toBeAdded": "",
  "finalSaleablePercentage": "0"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
