

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Capital Gain",
    "value": "Capital_Gain"
  },
  "masterTypeOfPurpose": {
    "label": "Capital Gain",
    "value": "Capital_Gain"
  },
  "toAssess": {
    "label": "Capital Gain 2001",
    "value": "Capital_Gain_2001"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "651fe470119cca234ddbc78d",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Aryacorp Pvt Ltd ",
"displayName": "Aryacorp Pvt Ltd ",
"initial": "A"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "6401b61f0e28255fb44e636a",
    "role": "SITEENGINEER",
    "firstName": "Sanket",
    "email": "ksanket7414@yahoo.com",
    "lastName": "Karalkar",
    "mobileNo": "8080582858",
    "designation": "",
    "shortName": "SAK",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
```

```
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
]
},
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
```

```
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Private Clients",
  "value": "PRIVATE_CLIENT"
},
"location": {
  "latitude": "19.419795161680472",
  "longitude": "72.81223802565201"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81223802565201,
    19.419795161680472
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nile More",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
```

```
"key": "district",
"value": "",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Prashtha Building no 51 CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Third Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sri Prashtha Complex",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```

```
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```



```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nalasopara West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
}
```

```
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
}
```

```
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
```

```
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "651fe49a119cca234ddbc793",
"ownerName": "Aryacorp Pvt Ltd ",
"ownerPhoneNo": "9821230309",
"appAddress": "Flat no 202.2floor,B-wing,Building No-51,Sri Prastha Building No 51
CHS,Plot no 51,Nilemore ,3rd Road,Sri Prastha Complex, Nallasopara West",
"remark": "Prithviraj Arya\r\n+919821230309\r\nhttps://truecaller.com/search/in/
+919821230309\r\n\r\nsent using Truecaller",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/651fe49a119cca234ddbc793/
document_1696588852804_Aryacorp_Pvt_LtdCapital_2001.pdf",
    "fileName": "document_1696588852804_Aryacorp_Pvt_LtdCapital_2001.pdf",
    "displayStatus": false,
    "id": "229142",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Fri Oct 06 2023 16:11:52 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004240",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "426550",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 06 2023 16:12:34 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Aryacorp Pvt Ltd ",
    "phone": "9821230309",
```



```
    "ownershipShare": "",
    "email": "",
    "id": "960052"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b7e",
    "name":
"externalImg_1697601313380_WhatsApp_Image_20231017_at_111844_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externalImg_1697601313380_WhatsApp_Image_20231017_at_111844_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b7f",
    "name":
"externalImg_1697601313386_WhatsApp_Image_20231017_at_111844_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externalImg_1697601313386_WhatsApp_Image_20231017_at_111844_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b80",
    "name":
"externalImg_1697601313393_WhatsApp_Image_20231017_at_111845_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externalImg_1697601313393_WhatsApp_Image_20231017_at_111845_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "652f57217e32132d40930b81",
  "name":
"externallmg_1697601313399_WhatsApp_Image_20231017_at_111845_PM_2.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313399_WhatsApp_Image_20231017_at_111845_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b82",
  "name":
"externallmg_1697601313406_WhatsApp_Image_20231017_at_111845_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313406_WhatsApp_Image_20231017_at_111845_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b83",
  "name":
"externallmg_1697601313410_WhatsApp_Image_20231017_at_111846_PM_1.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313410_WhatsApp_Image_20231017_at_111846_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b84",
  "name":
"externallmg_1697601313414_WhatsApp_Image_20231017_at_111846_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313414_WhatsApp_Image_20231017_at_111846_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b85",
  "name":
"externallmg_1697601313419_WhatsApp_Image_20231017_at_111907_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313419_WhatsApp_Image_20231017_at_111907_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b86",
    "name":
"externallmg_1697601313421_WhatsApp_Image_20231017_at_111811_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313421_WhatsApp_Image_20231017_at_111811_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b87",
    "name":
"externallmg_1697601313423_WhatsApp_Image_20231017_at_111813_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313423_WhatsApp_Image_20231017_at_111813_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b88",
    "name":
"externallmg_1697601313426_WhatsApp_Image_20231017_at_111813_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313426_WhatsApp_Image_20231017_at_111813_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b89",
    "name":
"externallmg_1697601313430_WhatsApp_Image_20231017_at_111814_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313430_WhatsApp_Image_20231017_at_111814_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57217e32132d40930b8a",
```

```
    "name":
"externallmg_1697601313432_WhatsApp_Image_20231017_at_111814_PM_2.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313432_WhatsApp_Image_20231017_at_111814_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b8b",
  "name":
"externallmg_1697601313434_WhatsApp_Image_20231017_at_111814_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313434_WhatsApp_Image_20231017_at_111814_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b8c",
  "name":
"externallmg_1697601313436_WhatsApp_Image_20231017_at_111815_PM_1.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313436_WhatsApp_Image_20231017_at_111815_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b8d",
  "name":
"externallmg_1697601313438_WhatsApp_Image_20231017_at_111815_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313438_WhatsApp_Image_20231017_at_111815_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b8e",
  "name":
"externallmg_1697601313440_WhatsApp_Image_20231017_at_111819_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313440_WhatsApp_Image_20231017_at_111819_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b8f",
  "name":
"externallmg_1697601313442_WhatsApp_Image_20231017_at_111820_PM_1.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313442_WhatsApp_Image_20231017_at_111820_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b90",
  "name":
"externallmg_1697601313444_WhatsApp_Image_20231017_at_111820_PM_2.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313444_WhatsApp_Image_20231017_at_111820_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57217e32132d40930b91",
  "name":
"externallmg_1697601313446_WhatsApp_Image_20231017_at_111820_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601313446_WhatsApp_Image_20231017_at_111820_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57357e32132d40930bf7",
  "name":
"externallmg_1697601333483_WhatsApp_Image_20231017_at_111821_PM_1.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333483_WhatsApp_Image_20231017_at_111821_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57357e32132d40930bf8",
  "name":
"externallmg_1697601333485_WhatsApp_Image_20231017_at_111821_PM_2.jpeg",
```

```
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333485_WhatsApp_Image_20231017_at_111821_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930bf9",
    "name":
"externallmg_1697601333489_WhatsApp_Image_20231017_at_111821_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333489_WhatsApp_Image_20231017_at_111821_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930bfa",
    "name":
"externallmg_1697601333491_WhatsApp_Image_20231017_at_111822_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333491_WhatsApp_Image_20231017_at_111822_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930bfb",
    "name":
"externallmg_1697601333498_WhatsApp_Image_20231017_at_111822_PM_2.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333498_WhatsApp_Image_20231017_at_111822_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930bfc",
    "name":
"externallmg_1697601333502_WhatsApp_Image_20231017_at_111822_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333502_WhatsApp_Image_20231017_at_111822_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "652f57357e32132d40930bfd",
    "name":
"externallmg_1697601333505_WhatsApp_Image_20231017_at_111823_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333505_WhatsApp_Image_20231017_at_111823_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930bfe",
    "name":
"externallmg_1697601333508_WhatsApp_Image_20231017_at_111823_PM_2.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333508_WhatsApp_Image_20231017_at_111823_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930bff",
    "name":
"externallmg_1697601333511_WhatsApp_Image_20231017_at_111823_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333511_WhatsApp_Image_20231017_at_111823_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930c00",
    "name":
"externallmg_1697601333514_WhatsApp_Image_20231017_at_111824_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333514_WhatsApp_Image_20231017_at_111824_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930c01",
    "name":
"externallmg_1697601333517_WhatsApp_Image_20231017_at_111824_PM_2.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333517_WhatsApp_Image_20231017_at_111824_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930c02",
    "name":
"externallmg_1697601333519_WhatsApp_Image_20231017_at_111824_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333519_WhatsApp_Image_20231017_at_111824_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930c03",
    "name":
"externallmg_1697601333522_WhatsApp_Image_20231017_at_111825_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333522_WhatsApp_Image_20231017_at_111825_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930c04",
    "name":
"externallmg_1697601333526_WhatsApp_Image_20231017_at_111825_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333526_WhatsApp_Image_20231017_at_111825_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930c05",
    "name":
"externallmg_1697601333529_WhatsApp_Image_20231017_at_111826_PM_1.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333529_WhatsApp_Image_20231017_at_111826_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57357e32132d40930c06",
```



```
    "name":
"externallmg_1697601333533_WhatsApp_Image_20231017_at_111826_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333533_WhatsApp_Image_20231017_at_111826_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57357e32132d40930c07",
  "name":
"externallmg_1697601333538_WhatsApp_Image_20231017_at_111827_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333538_WhatsApp_Image_20231017_at_111827_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57357e32132d40930c08",
  "name":
"externallmg_1697601333542_WhatsApp_Image_20231017_at_111828_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333542_WhatsApp_Image_20231017_at_111828_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57357e32132d40930c09",
  "name":
"externallmg_1697601333544_WhatsApp_Image_20231017_at_111838_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333544_WhatsApp_Image_20231017_at_111838_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57357e32132d40930c0a",
  "name":
"externallmg_1697601333548_WhatsApp_Image_20231017_at_111839_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601333548_WhatsApp_Image_20231017_at_111839_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57407e32132d40930c66",
  "name":
"externallmg_1697601344709_WhatsApp_Image_20231017_at_111839_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601344709_WhatsApp_Image_20231017_at_111839_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57407e32132d40930c67",
  "name":
"externallmg_1697601344713_WhatsApp_Image_20231017_at_111841_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601344713_WhatsApp_Image_20231017_at_111841_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57407e32132d40930c68",
  "name":
"externallmg_1697601344717_WhatsApp_Image_20231017_at_111842_PM_1.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601344717_WhatsApp_Image_20231017_at_111842_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57407e32132d40930c69",
  "name":
"externallmg_1697601344723_WhatsApp_Image_20231017_at_111842_PM.jpeg",
  "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601344723_WhatsApp_Image_20231017_at_111842_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652f57407e32132d40930c6a",
  "name":
"externallmg_1697601344726_WhatsApp_Image_20231017_at_111843_PM_1.jpeg",
```

```
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601344726_WhatsApp_Image_20231017_at_111843_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57407e32132d40930c6b",
    "name":
"externallmg_1697601344730_WhatsApp_Image_20231017_at_111843_PM_2.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601344730_WhatsApp_Image_20231017_at_111843_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652f57407e32132d40930c6c",
    "name":
"externallmg_1697601344733_WhatsApp_Image_20231017_at_111843_PM.jpeg",
    "path": "cases/651fe49a119cca234ddbc793/
externallmg_1697601344733_WhatsApp_Image_20231017_at_111843_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-06T10:42:34.727Z",
"updatedAt": "2023-10-18T03:55:44.798Z",
"__v": 0,
"invoiceId": "651fe49b119cca234ddbc7b2",
"fullAddress": "Residential Flat No. 202, 2nd Floor, Wing - B, Sai Prashtha Building no
51 CHSL, Third Road, Sri Prashtha Complex, Village - Nile More, Nalasopara West,
State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Aryacorp Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9821230309"
```

}

**Name**

**Length**

**Width**

**Total**

---

Composition :

---

Other

Composition :

---