

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64b0d939c3fce965da5a2285"
    },
    "type": "CREDITOFFICER",
    "_id": "64b0d939c3fce965da5a2287",
    "firstName": "S K ",
    "lastName": "S K Satam",
    "mobileNo": "",
    "workMobileNo": "9920909040",
    "email": "dahisar@abhyudayabank.net"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4200000",
    "discussWithPerson": "S K ",
    "expectedFees": 2100,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1802",
  "type": "BANK",
  "name": "Abhyudaya",
  "displayName": "Abhyudaya",
  "initial": "Abhyudaya",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64b0d939c3fce965da5a2285",
  "name": "Dahisar Branch (East)",
  "branchCode": "",
  "mobileNo": " 9920909040",
  "alternateMobileNo": "",
  "email": "dahisar@abhyudayabank.net",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Madhuram, Ground floor, Harishankar Joshi Road, Dahisar-East,
Mumbai-400 068"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f8fe68f3dd69653a5909b3",
  "zoneName": "Mumbai, Navi Mumbai, Pune, Aurangabad & Nanded Region"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
```

```
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
}
],

```

```
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.262142559346717",
  "longitude": " 72.86106659325321"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  72.86106659325321,
  19.262142559346717
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-10-12T05:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dahisar",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "New Ashish ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "C S Complex Road No 4",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```

```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
```



```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dahisar East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "652641bd703d7c40db99f715",
"ownerName": "Prashant Dhanani Shirke ",
"ownerPhoneNo": "9082349551",
"appAddress": "flat no b201 new Ashish chs c s Rd no 4 dahisar East ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Index - II",
      "value": "60ae1287aa6d152c1801b415"
    },
    "isHardCopy": false,
    "path": "cases/652641bd703d7c40db99f715/
document_1697005943315_36880.pdf",
    "fileName": "document_1697005943315_36880.pdf",
    "displayStatus": false,
    "id": "270514",
    "uploadedBy": "627219d6afd7d55eddedd283",
    "createdAt": "Wed Oct 11 2023 12:02:48 GMT+0530 (India Standard Time)"
  },
  {
```



```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1697087392696_Prashant_shirke_abhudya_bank.pdf",
"path": "cases/652641bd703d7c40db99f715/
document_1697087392696_Prashant_shirke_abhudya_bank.pdf",
"id": "316102",
"uploadedBy": "62691c48afd7d55eddecfda3",
"createdAt": "Thu Oct 12 2023 10:39:52 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004343",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "141125",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 11 2023 12:03:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Prashant Dhanani Shirke ",
    "phone": "9082349551",
    "ownershipShare": "",
    "email": "",
    "id": "183144"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ee5f29c604408189f58",
```

```
    "name":
"externallmg_1697087204901_IMG_20231011_164646_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087204901_IMG_20231011_164646_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ee5f29c604408189f59",
  "name":
"externallmg_1697087204912_IMG_20231011_164650_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087204912_IMG_20231011_164650_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ee5f29c604408189f5a",
  "name":
"externallmg_1697087204921_IMG_20231011_164654_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087204921_IMG_20231011_164654_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ee5f29c604408189f5b",
  "name":
"externallmg_1697087204972_IMG_20231011_164657_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087204972_IMG_20231011_164657_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ee5f29c604408189f5c",
  "name":
"externallmg_1697087204980_IMG_20231011_164659_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087204980_IMG_20231011_164659_copy_1600x1200.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ee5f29c604408189f5d",
  "name":
"externallmg_1697087204985_IMG_20231011_164703_copy_900x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087204985_IMG_20231011_164703_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ee5f29c604408189f5e",
  "name":
"externallmg_1697087204998_IMG_20231011_164704_copy_900x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087204998_IMG_20231011_164704_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fd9",
  "name":
"externallmg_1697087222759_IMG_20231011_164707_copy_900x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222759_IMG_20231011_164707_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fda",
  "name":
"externallmg_1697087222772_IMG_20231011_164724_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222772_IMG_20231011_164724_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fdb",
  "name":
"externallmg_1697087222778_IMG_20231011_164726_copy_1600x1200.jpg",
```

```
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222778_IMG_20231011_164726_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fdc",
    "name":
"externallmg_1697087222785_IMG_20231011_164732_copy_1600x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222785_IMG_20231011_164732_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fdd",
    "name":
"externallmg_1697087222791_IMG_20231011_164734_copy_1600x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222791_IMG_20231011_164734_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fde",
    "name":
"externallmg_1697087222800_IMG_20231011_165020_copy_900x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222800_IMG_20231011_165020_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fdf",
    "name":
"externallmg_1697087222812_IMG_20231011_165022_copy_900x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222812_IMG_20231011_165022_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65277ef7f29c604408189fe0",
  "name":
"externallmg_1697087222823_IMG_20231011_165111_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222823_IMG_20231011_165111_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fe1",
  "name":
"externallmg_1697087222827_IMG_20231011_165112_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222827_IMG_20231011_165112_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fe2",
  "name":
"externallmg_1697087222832_IMG_20231011_165116_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222832_IMG_20231011_165116_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fe3",
  "name":
"externallmg_1697087222837_IMG_20231011_165134_copy_901x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222837_IMG_20231011_165134_copy_901x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fe4",
  "name":
"externallmg_1697087222850_IMG_20231011_165140_copy_900x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222850_IMG_20231011_165140_copy_900x1200.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fe5",
    "name":
"externallmg_1697087222863_IMG_20231011_165157_copy_900x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222863_IMG_20231011_165157_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fe6",
    "name":
"externallmg_1697087222876_IMG_20231011_165158_copy_900x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222876_IMG_20231011_165158_copy_900x1200.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fe7",
    "name":
"externallmg_1697087222889_IMG_20231011_165201_copy_1600x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222889_IMG_20231011_165201_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fe8",
    "name":
"externallmg_1697087222899_IMG_20231011_165203_copy_1600x1200.jpg",
    "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222899_IMG_20231011_165203_copy_1600x1200.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65277ef7f29c604408189fe9",
```

```
"name":
"externallmg_1697087222908_IMG_20231011_224555_copy_900x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222908_IMG_20231011_224555_copy_900x1200.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189fea",
  "name":
"externallmg_1697087222923_IMG_20231011_224606_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222923_IMG_20231011_224606_copy_1600x1200.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65277ef7f29c604408189feb",
  "name":
"externallmg_1697087222928_IMG_20231011_224608_copy_1600x1200.jpg",
  "path": "cases/652641bd703d7c40db99f715/
externallmg_1697087222928_IMG_20231011_224608_copy_1600x1200.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-11T06:33:33.629Z",
"updatedAt": "2023-10-12T05:09:52.905Z",
"__v": 0,
"invoiceId": "652641be703d7c40db99f73c",
"fullAddress": " Flat No. 201, 2nd Floor, New Ashish , C S Complex Road No 4, Village
- Dahisar, Dahisar East, Mumbai",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Prashant Dhanani Shirke ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9082349551"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
