

```
{
  "typeOfReport": {
    "value": "Residential",
    "label": "Residential"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9e6"
    },
    "type": "CREDITOFFICER",
    "_id": "64c8b0a2a5c3051014f5f888",
    "firstName": "Priti",
    "lastName": "Madam",
    "mobileNo": "",
    "workMobileNo": "9773028294",
    "email": "preeti.shinde@comsosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3000000",
    "discussWithPerson": "Priti",
    "expectedFees": 1500,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9e6",
  "branchCode": "000014",
  "type": "BRANCH",
  "name": "Dombivali (East) Branch",
  "email": "dombivali@cosmosbank.in",
  "mobileNo": "02512435618",
  "alternateMobileNo": "",
  "address": "Sindhurg C.H.S., Ground Floor, Tilak Chowk, Tilak Nagar, Dombivali
(East), Taluka Kalyan, District Thane - 400605, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "6410199a140f140ffc59b58c",
  "role": "PICKUPPERSON",
  "firstName": "Prakash ",
  "email": "prakashnvetkoli@gmail.com",
  "lastName": "Vetkoli",
  "mobileNo": "9076237689",
  "shortName": "PV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/6410199a140f140ffc59b58c/
profilePhoto_1689054480133_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "MAKER",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
    "designation": "",
    "shortName": "PS",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60f915d3f3dd69653a592199",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shobha",
    "email": "shobha@vastukala.org",
    "lastName": "Kuperkar",
    "mobileNo": "9004134140",
    "designation": "",
    "shortName": "SH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
  },
  "valuers": [],
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.151130",
  "longitude": "73.236450"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.23645,
    19.15113
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-12",
      "remark": ""
    }
  ],
},
```

```
{
  "status": "COMPLETED",
  "dateTime": "2023-10-12",
  "remark": ""
}
],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "459.00",
  "rate": "6359.00",
  "yearOfConstruction": "2018",
  "compositionOfBuilding": "(Part) Ground + (Part) Stilt + 7 Upper Floors"
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Shirgaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
```

```
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "Vasant Springwoods",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Astor",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Shirgaon, Badlapur",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "502, ",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Oct 13 2023 16:23:20 GMT+0530 (India Standard Time)",
  "number": "2302992",
  "dayCount": "13",
  "monthCount": "189",
  "generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
```

```
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
```

```
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORDELIVERY",
"paymentId": [],
"_id": "65265149703d7c40db9a4781",
"ownerName": "Mr. Mularam Dhalaramji Kumavat",
"ownerPhoneNo": "9082683808",
"appAddress": "502, 5th flr., B aster building, Vasant springwoods, Shirgaon, Badlapur
east",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1257aa6d152c1801b334",
      "label": "Rectification Deed"
    }
  },
  "inputs": {
    "documentDate": "20/10/2018",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    }
  },
  "Promoter": "M/s. Shree Construction",
  "to": {
```



```
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Ankush Kondiba Pawar & Mrs. Sunita Ankush Pawar"
},
"isHardCopy": false,
"displayStatus": true,
"id": "563715",
"path": "cases/65265149703d7c40db9a4781/
document_1697009779308_Ankush_pawar_Cos_D.pdf",
"fileName": "document_1697009779308_Ankush_pawar_Cos_D.pdf"
},
{
  "documentType": {
    "label": "Agreement Attached Sale Plan",
    "value": "60ae125aaa6d152c1801b344"
  },
  "isHardCopy": false,
  "path": "cases/65265149703d7c40db9a4781/
document_1697009892076_44291.pdf",
  "fileName": "document_1697009892076_44291.pdf",
  "displayStatus": false,
  "id": "249572",
  "uploadedBy": "6410199a140f140ffc59b58c",
  "createdAt": "Wed Oct 11 2023 13:09:07 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "21/09/2018",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "M/s. Shree Construction",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Ankush Kondiba Pawar & Mrs. Sunita Ankush Pawar",
    "number": {
      "value": "No",
      "label": "No"
    }
  }
}
```

```
    },
    "No": "12302 / 2018"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "274876",
  "path": "cases/65265149703d7c40db9a4781/
document_1697014935899_117459.pdf",
  "fileName": "document_1697014935899_117459.pdf"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
    "label": "Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "28/12/2018",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KBNP / NRV / 9721 / 2018 - 2019 "
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1697172612173_OC.pdf",
  "path": "cases/65265149703d7c40db9a4781/document_1697172612173_OC.pdf",
  "id": "393794",
  "uploadedBy": "627222afafd7d55eddedd82",
  "createdAt": "Fri Oct 13 2023 10:32:51 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "31/01/2017",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    }
  },
}
```

```
"number": {
  "value": "No",
  "label": "No"
},
"No": "KBNP / NRV / BP / 942 / 2016 – 2017 / Unik No. 150"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1697173161776_1_Commencement_Certificates___NA_Order_for_plotted_development__20231012T170429071.pdf",
"path": "cases/65265149703d7c40db9a4781/document_1697173161776_1_Commencement_Certificates___NA_Order_for_plotted_development__20231012T170429071.pdf",
"id": "807135",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Oct 13 2023 10:32:51 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "19/08/2017",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51700020335"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1697173294228_P51700008622.pdf",
  "path": "cases/65265149703d7c40db9a4781/document_1697173294228_P51700008622.pdf",
  "id": "266510",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Oct 13 2023 10:32:51 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
```

```
"label": "Approved Building Plan"
},
"inputs": {
  "documentDate": "31/01/2017",
  "nameOfApprovingAuthority": {
    "value": "Kulgaon_Badlapur_Municipal_Council",
    "label": "Kulgaon Badlapur Municipal Council"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "KBNP / NRV / BP / 942 – 150"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1697173371478_1_Copy_of_Layout_Approval_in_case_of_Layout__20231012T174901373.pdf",
"path": "cases/65265149703d7c40db9a4781/document_1697173371478_1_Copy_of_Layout_Approval_in_case_of_layout__20231012T174901373.pdf",
"id": "566334",
"uploadedBy": "627222afafd7d55eddedd82",
"createdAt": "Fri Oct 13 2023 10:32:51 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "05/10/2023",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Mr. Ankush Kondiba Pawar & Mrs. Sunita Ankush Pawar",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mr. Mularam Dhalaramji Kumavat & Mrs. Soni Mularam Kumavat",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "13473/2023"
  }
}
```

```
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName":
"document_1697459741668_New_Document__Kumavat_Agreement__16102023.pdf",
    "path": "cases/65265149703d7c40db9a4781/
document_1697459741668_New_Document__Kumavat_Agreement__16102023.pdf",
    "id": "324864",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Mon Oct 16 2023 18:05:42 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004347",
"createdBy": "6410199a140f140ffc59b58c",
"caseHistory": [
  {
    "id": "800445",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 11 2023 13:09:53 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Mularam Dhalaramji Kumavat",
    "phone": "9082683808",
    "ownershipShare": "",
    "email": "",
    "id": "574567"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65279be382e2722e3be57735",
    "name": "externallmg_1697094221948_1697094139898_image_0.jpeg",
    "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094221948_1697094139898_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57736",
  "name": "externallmg_1697094225873_1697094139898_image_1.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094225873_1697094139898_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57737",
  "name": "externallmg_1697094226402_1697094139898_image_2.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094226402_1697094139898_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57738",
  "name": "externallmg_1697094227183_1697094139898_image_3.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094227183_1697094139898_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57739",
  "name": "externallmg_1697094228498_1697094139898_image_5.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094228498_1697094139898_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be5773a",
  "name": "externallmg_1697094229243_1697094139898_image_6.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094229243_1697094139898_image_6.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65279be382e2722e3be5773b",
      "name": "externallmg_1697094233201_1697094139898_image_8.jpeg",
      "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094233201_1697094139898_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65279be382e2722e3be5773c",
      "name": "externallmg_1697094234353_1697094139898_image_9.jpeg",
      "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094234353_1697094139898_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65279be382e2722e3be5773d",
      "name": "externallmg_1697094234717_1697094139898_image_10.jpeg",
      "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094234717_1697094139898_image_10.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65279be382e2722e3be5773e",
      "name": "externallmg_1697094235023_1697094139898_image_11.jpeg",
      "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094235023_1697094139898_image_11.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "65279be382e2722e3be5773f",
      "name": "externallmg_1697094235192_1697094139898_image_12.jpeg",
      "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094235192_1697094139898_image_12.jpeg",
      "orientation": "landscape"
    },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57740",
  "name": "externallmg_1697094235317_1697094139898_image_13.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094235317_1697094139898_image_13.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57741",
  "name": "externallmg_1697094496434_1697094418985_image_0.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094496434_1697094418985_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57742",
  "name": "externallmg_1697094519810_1697094443482_image_0.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094519810_1697094443482_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65279be382e2722e3be57743",
  "name": "externallmg_1697094547354_1697094467279_image_0.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094547354_1697094467279_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65279be382e2722e3be57744",
  "name": "externallmg_1697094194027_1697094118014_image_0.jpeg",
  "path": "cases/65265149703d7c40db9a4781/
externallmg_1697094194027_1697094118014_image_0.jpeg",
  "orientation": "portrait"
},
{
```



```
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "65279be382e2722e3be57745",
"name": "externalimg_1697094198229_1697094118014_image_1.jpeg",
"path": "cases/65265149703d7c40db9a4781/
externalimg_1697094198229_1697094118014_image_1.jpeg",
"orientation": "portrait"
}
],
"externalDocuments": [
{
"originalname": "Ankush Kondiba Pawar.doc",
"filename": "1697173708955_Ankush_Kondiba_Pawar.doc",
"path": "cases/65265149703d7c40db9a4781/
externalDocuments/1697173708955_Ankush_Kondiba_Pawar.doc",
"size": "22691840",
"documentType": {
"value": "649998c6cab24d3d1a2cc577",
"label": "Draft Word Report"
},
"createdAt": "Fri Oct 13 2023 10:38:35 GMT+0530 (India Standard Time)",
"uploadedBy": "627222afafd7d55eddeddd82"
},
{
"originalname": "1697173708955_Ankush_Kondiba_Pawar.doc",
"filename": "1697195315897_1697173708955_Ankush_Kondiba_Pawar.doc",
"path": "cases/65265149703d7c40db9a4781/
externalDocuments/1697195315897_1697173708955_Ankush_Kondiba_Pawar.doc",
"size": "22693376",
"documentType": {
"value": "64058cdff10de22571d01b37",
"label": "Final Word Report"
},
"createdAt": "Fri Oct 13 2023 16:38:36 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "Valuation_Reportr_Ankush_Kondiba_Pawar.pdf",
"filename": "1697198956970_Valuation_Reportr_Ankush_Kondiba_Pawar.pdf",
"path": "cases/65265149703d7c40db9a4781/
externalDocuments/1697198956970_Valuation_Reportr_Ankush_Kondiba_Pawar.pdf",
"size": "985389",
"documentType": {
"value": "640ece6024088f0f94ee4ea8",
"label": "Final PDF Report"
}
},
}
```

```
"createdAt": "Fri Oct 13 2023 17:39:17 GMT+0530 (India Standard Time)",
"uploadedBy": "63f31d626f9c2254a9b39144"
}
],
"processingDocuments": [
{
"originalname": "Calculation (1).xlsx",
"filename": "1697104445596_Calculation_1.xlsx",
"path": "cases/65265149703d7c40db9a4781/
processingDocuments/1697104445596_Calculation_1.xlsx",
"size": "3455173",
"createdAt": "Thu Oct 12 2023 15:24:07 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
"originalname": "Dep.xlsx",
"filename": "1697173849740_Dep.xlsx",
"path": "cases/65265149703d7c40db9a4781/
processingDocuments/1697173849740_Dep.xlsx",
"size": "255860",
"createdAt": "Fri Oct 13 2023 10:40:50 GMT+0530 (India Standard Time)",
"uploadedBy": "627222afafd7d55eddeddd82"
},
{
"originalname": "P51700008622 (2).pdf",
"filename": "1697173849818_P51700008622_2.pdf",
"path": "cases/65265149703d7c40db9a4781/
processingDocuments/1697173849818_P51700008622_2.pdf",
"size": "158091",
"createdAt": "Fri Oct 13 2023 10:40:50 GMT+0530 (India Standard Time)",
"uploadedBy": "627222afafd7d55eddeddd82"
},
{
"originalname": "1 Copy of Layout Approval (in case of layout) -
2023-10-12T174901.373.pdf",
"filename": "1697173849874_1_Copy_of_Layout_Approval_in_case_of_layout__202
31012T174901373.pdf",
"path": "cases/65265149703d7c40db9a4781/processingDocuments/169717384987
4_1_Copy_of_Layout_Approval_in_case_of_layout__20231012T174901373.pdf",
"size": "446086",
"createdAt": "Fri Oct 13 2023 10:40:50 GMT+0530 (India Standard Time)",
"uploadedBy": "627222afafd7d55eddeddd82"
},
{
"originalname": "1 Commencement Certificates _ NA Order for plotted development
- 2023-10-12T170429.071.pdf",
```

```
"filename": "1697173849999_1_Commencement_Certificates___NA_Order_for_plot
ted_development__20231012T170429071.pdf",
  "path": "cases/65265149703d7c40db9a4781/processingDocuments/169717384999
9_1_Commencement_Certificates___NA_Order_for_plotted_development__20231012T
170429071.pdf",
  "size": "742746",
  "createdAt": "Fri Oct 13 2023 10:40:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "Loc.jpg",
  "filename": "1697173850231_Loc.jpg",
  "path": "cases/65265149703d7c40db9a4781/
processingDocuments/1697173850231_Loc.jpg",
  "size": "215203",
  "createdAt": "Fri Oct 13 2023 10:40:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
},
{
  "originalname": "Sat.jpg",
  "filename": "1697173850314_Sat.jpg",
  "path": "cases/65265149703d7c40db9a4781/
processingDocuments/1697173850314_Sat.jpg",
  "size": "360097",
  "createdAt": "Fri Oct 13 2023 10:40:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "627222afafd7d55eddeddd82"
}
],
"remarks": [],
"createdAt": "2023-10-11T07:39:53.312Z",
"updatedAt": "2023-10-16T12:35:42.692Z",
"__v": 0,
"invoiceld": "6526514a703d7c40db9a47c1",
"fullAddress": "Residential Flat No. 502, , 5th Floor, Building No Vasant Springwoods,
Wing - B, Astor, Shirgaon, Badlapur, Village - Shirgaon, Taluka - Ambernath, District -
Thane, State - Maharashtra, India",
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Mularam Dhalaramji Kumavat",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9082683808",  
"siteVisitDate": "2023-10-12"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---