

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65292f27758ee2361b40ff16"
    },
    "type": "CREDITOFFICER",
    "_id": "65292f27758ee2361b40ff18",
    "firstName": "Shailesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7905451493",
    "email": "cbsmalharganj@unionbankofindia.com"
  },
  "fees": {
    "type": "quoted",
    "propertyValue": "6800000",
    "discussWithPerson": "Shailesh ",
    "expectedFees": 3400,
    "quotedAmount": "3000"
  },
  "organization": {
```

```
"_id": "6450f43cba18c8062aad0215",
"name": "Indore",
"shortName": "Indore",
"email": "indore@vastukala.org",
"address": "106, 1st Floor, Gold Star Tower, ,576, M G Road, Opp T1 Mall,
Indore-452001, Madhya Pradesh India",
"city": "Indore"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "65292f27758ee2361b40ff16",
  "name": "Malhar Ganj branch",
  "branchCode": "536261",
  "mobileNo": "07312459154",
  "alternateMobileNo": "",
  "email": "cbsmalharganj@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Union Bank Of India\nMalharganj , Indore\nPincode -452007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "6437ee3a8989760c1fb68468",
  "zoneName": "Indore Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6421248a695fbc66ee1a7ce3",
    "role": "ADMIN",
```

```
"firstName": "Niti",
"email": "niti@vastukala.org",
"lastName": "Kuril",
"mobileNo": "9926411111",
"shortName": "NSK",
"workWithDocumentMaker": "",
"profilePhoto": "users/6421248a695fbc66ee1a7ce3/
profilePhoto_1679893769249_WhatsApp_Image_20230324_at_20338_PM_1.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "644d108bd4903a28b8e52967",
"role": "SITEENGINEER+MAKAR+ RATE VERIFIER + CHECKER",
"firstName": "Somesh",
"email": "somesnaha111@gmail.com",
"lastName": "Nahar",
"mobileNo": "7354486085",
"designation": "",
"shortName": "Somesh",
"workWithDocumentMaker": "60016f965256c07aec8e6dd6",
"profilePhoto": "users/644d108bd4903a28b8e52967/
profilePhoto_1688544438161_WhatsApp_Image_20230705_at_13245_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "644d108bd4903a28b8e52967",
"role": "SITEENGINEER+MAKAR+ RATE VERIFIER + CHECKER",
"firstName": "Somesh",
"email": "somesnaha111@gmail.com",
"lastName": "Nahar",
"mobileNo": "7354486085",
"designation": "",
"shortName": "Somesh",
"workWithDocumentMaker": "60016f965256c07aec8e6dd6",
"profilePhoto": "users/644d108bd4903a28b8e52967/
profilePhoto_1688544438161_WhatsApp_Image_20230705_at_13245_PM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "644d067cd4903a28b8e51b30",
"role": "SITEENGINEER+MAKAR",
"firstName": "Akshay Kumar ",
"email": "atrivedi321@gmail.com",
"lastName": "Trivedi",
"mobileNo": "8871809210",
"designation": ""
```

```
    "shortName": "Akshay",
    "workWithDocumentMaker": "60016f965256c07aec8e6dd6",
    "profilePhoto": "users/644d067cd4903a28b8e51b30/
profilePhoto_1688545747727_image.jpeg"
  },
  "checker": {
    "_id": "60016f965256c07aec8e6dd6",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "firstName": "Akhilesh",
    "lastName": "Yadav",
    "shortName": "AY",
    "email": "akhilesh.yadav@vastukala.org",
    "designation": "Processing Officer",
    "mobileNo": "9545753921",
    "role": "MAKER + RATE VERIFIER + CHEAKER",
    "type": "EMPLOYEE",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ]
    }
  ]
}
```

```
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "22.716634772480855",
  "longitude": "75.86268815767129"
},
"geo": {
  "type": "Point",
  "coordinates": [
    75.86268815767129,
    22.716634772480855
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-10-13T11:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Indore",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Indore",
  "label": false
},
"tahasilNo": {
```

```
"status": true,
"name": "Tahasil",
"key": "tahasilNo",
"value": "Indore",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "36",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Rani Pura, Daulat Ganj, Jawahar Marg, Indore Bhopal Road, ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Behind Jhanda Chowk",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "452007",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Oct 19 2023 17:22:59 GMT+0530 (India Standard Time)",
  "number": "2303103",
  "dayCount": "25",
  "monthCount": "300",
  "generatedBy": "60016f965256c07aec8e6dd6"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": true,
status": true,
```



```
"caseStatus": "REPORTGENERATED",
"paymentId": [],
"_id": "65293be1758ee2361b41379d",
"ownerName": "Nasir Husan S/o Abdul Sattar",
"ownerPhoneNo": "8605149765",
"appAddress": "Residential House on Plot No. 36, Rani Pura, Daulat Ganj, Jawahar
Marg, \nIndore Bhopal Road, Behind Jhanda Chowk, Tehsil & District Indore, PIN – 452
007, \nState – Madhya Pradesh, Country – India.\n\n\n",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Approved Building Plan",
      "value": "60ae1277aa6d152c1801b3cc"
    },
    "isHardCopy": false,
    "path": "cases/65293be1758ee2361b41379d/
document_1697201072012_1279334.pdf",
    "fileName": "document_1697201072012_1279334.pdf",
    "displayStatus": false,
    "id": "242254",
    "uploadedBy": "6421248a695fbc66ee1a7ce3",
    "createdAt": "Fri Oct 13 2023 18:14:35 GMT+0530 (India Standard Time)"
  }
],
"gstNo": "",
"caseNumber": "004404",
"createdBy": "6421248a695fbc66ee1a7ce3",
"caseHistory": [
  {
    "id": "286933",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 13 2023 18:15:21 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Nasir Husan S/o Abdul Sattar",
    "phone": "8605149765",
    "ownershipShare": "",
    "email": "",
    "id": "275527"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65311984619c14402da5fe3b",
    "name": "externalImg_1697716612462_Outside_1.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externalImg_1697716612462_Outside_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65311984619c14402da5fe3c",
    "name": "externalImg_1697716612465_Outside_2.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externalImg_1697716612465_Outside_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65311984619c14402da5fe3d",
    "name": "externalImg_1697716612468_Outside_3.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externalImg_1697716612468_Outside_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65311984619c14402da5fe3e",
    "name": "externalImg_1697716612471_Outside_4.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externalImg_1697716612471_Outside_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65311984619c14402da5fe3f",
  "name": "externallmg_1697716612473_Outside_5.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716612473_Outside_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65311984619c14402da5fe40",
  "name": "externallmg_1697716612477_Outside_6.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716612477_Outside_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65311984619c14402da5fe41",
  "name": "externallmg_1697716612480_Outside_7.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716612480_Outside_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531199e619c14402da5ff2e",
  "name": "externallmg_1697716637994_Outside_8.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716637994_Outside_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531199e619c14402da5ff2f",
  "name": "externallmg_1697716637998_Outside_9.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716637998_Outside_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6531199e619c14402da5ff30",
    "name":
"externallmg_1697716638002_WhatsApp_Image_20231013_at_31228_PM_1.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638002_WhatsApp_Image_20231013_at_31228_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff31",
    "name":
"externallmg_1697716638004_WhatsApp_Image_20231013_at_31229_PM.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638004_WhatsApp_Image_20231013_at_31229_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff32",
    "name":
"externallmg_1697716638007_WhatsApp_Image_20231013_at_31230_PM_1.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638007_WhatsApp_Image_20231013_at_31230_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff33",
    "name":
"externallmg_1697716638010_WhatsApp_Image_20231013_at_31231_PM_1.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638010_WhatsApp_Image_20231013_at_31231_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff34",
    "name":
"externallmg_1697716638017_WhatsApp_Image_20231013_at_31231_PM_2.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638017_WhatsApp_Image_20231013_at_31231_PM_2.jpeg",
    "orientation": "portrait"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531199e619c14402da5ff35",
  "name":
  "externallmg_1697716638018_WhatsApp_Image_20231013_at_31231_PM.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638018_WhatsApp_Image_20231013_at_31231_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531199e619c14402da5ff36",
  "name":
  "externallmg_1697716638022_WhatsApp_Image_20231013_at_31232_PM_1.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638022_WhatsApp_Image_20231013_at_31232_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531199e619c14402da5ff37",
  "name":
  "externallmg_1697716638023_WhatsApp_Image_20231013_at_31232_PM_2.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638023_WhatsApp_Image_20231013_at_31232_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531199e619c14402da5ff38",
  "name":
  "externallmg_1697716638024_WhatsApp_Image_20231013_at_31232_PM.jpeg",
  "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638024_WhatsApp_Image_20231013_at_31232_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6531199e619c14402da5ff39",
  "name":
  "externallmg_1697716638028_WhatsApp_Image_20231013_at_31233_PM_1.jpeg",
```

```
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638028_WhatsApp_Image_20231013_at_31233_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff3a",
    "name":
"externallmg_1697716638029_WhatsApp_Image_20231013_at_31233_PM.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638029_WhatsApp_Image_20231013_at_31233_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff3b",
    "name":
"externallmg_1697716638031_WhatsApp_Image_20231013_at_31234_PM_1.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638031_WhatsApp_Image_20231013_at_31234_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff3c",
    "name":
"externallmg_1697716638032_WhatsApp_Image_20231013_at_31234_PM_2.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638032_WhatsApp_Image_20231013_at_31234_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff3d",
    "name":
"externallmg_1697716638035_WhatsApp_Image_20231013_at_31234_PM.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externallmg_1697716638035_WhatsApp_Image_20231013_at_31234_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6531199e619c14402da5ff3e",
    "name":
"externalImg_1697716638039_WhatsApp_Image_20231013_at_31235_PM_1.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externalImg_1697716638039_WhatsApp_Image_20231013_at_31235_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6531199e619c14402da5ff3f",
    "name":
"externalImg_1697716638041_WhatsApp_Image_20231013_at_31235_PM.jpeg",
    "path": "cases/65293be1758ee2361b41379d/
externalImg_1697716638041_WhatsApp_Image_20231013_at_31235_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalName": "Nasir Husain-Rani Pura.docx",
    "filename": "1697716535437_Nasir_HusainRani_Pura.docx",
    "path": "cases/65293be1758ee2361b41379d/
externalDocuments/1697716535437_Nasir_HusainRani_Pura.docx",
    "size": "2930990",
    "documentType": {
      "value": "64058cdf10de22571d01b37",
      "label": "Final Word Report"
    },
    "createdAt": "Thu Oct 19 2023 17:25:35 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  }
],
"processingDocuments": [
  {
    "originalName": "Nasir Husain.docx",
    "filename": "1697609463087_Nasir_Husain.docx",
    "path": "cases/65293be1758ee2361b41379d/
processingDocuments/1697609463087_Nasir_Husain.docx",
    "size": "2929806",
    "createdAt": "Wed Oct 18 2023 11:41:04 GMT+0530 (India Standard Time)",
    "uploadedBy": "644d067cd4903a28b8e51b30"
  },
  {
    "originalName": "Map (2).pdf",
```

```
    "filename": "1697716550747_Map_2.pdf",
    "path": "cases/65293be1758ee2361b41379d/
processingDocuments/1697716550747_Map_2.pdf",
    "size": "1555430",
    "createdAt": "Thu Oct 19 2023 17:25:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Sale Deed.pdf",
    "filename": "1697716550772_Sale_Deed.pdf",
    "path": "cases/65293be1758ee2361b41379d/
processingDocuments/1697716550772_Sale_Deed.pdf",
    "size": "4995545",
    "createdAt": "Thu Oct 19 2023 17:25:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Valuation Report.pdf",
    "filename": "1697716550862_Valuation_Report.pdf",
    "path": "cases/65293be1758ee2361b41379d/
processingDocuments/1697716550862_Valuation_Report.pdf",
    "size": "7724055",
    "createdAt": "Thu Oct 19 2023 17:25:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Visit Format.pdf",
    "filename": "1697716550981_Visit_Format.pdf",
    "path": "cases/65293be1758ee2361b41379d/
processingDocuments/1697716550981_Visit_Format.pdf",
    "size": "251713",
    "createdAt": "Thu Oct 19 2023 17:25:51 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Nasir Husen-Rani Pura.xlsx",
    "filename": "1697716566868_Nasir_HusenRani_Pura.xlsx",
    "path": "cases/65293be1758ee2361b41379d/
processingDocuments/1697716566868_Nasir_HusenRani_Pura.xlsx",
    "size": "16021",
    "createdAt": "Thu Oct 19 2023 17:26:06 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  }
],
"remarks": [
  {
```



```

    "createdBy": {
      "_id": "60016f965256c07aec8e6dd6",
      "role": "MAKER + RATE VERFIER + CHEAKER",
      "firstName": "Akhilesh",
      "lastName": "Yadav",
      "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg"
    },
    "workType": "CHECKER",
    "display": true,
    "status": true,
    "_id": "652f7d687e32132d4093969c",
    "note": "Draft Report sent, Pending for confirmation",
    "taskId": "652f76fd7e32132d40937eea",
    "createdAt": "2023-10-18T06:38:32.470Z"
  }
],
"createdAt": "2023-10-13T12:45:21.074Z",
"updatedAt": "2023-10-19T11:57:18.114Z",
"__v": 0,
"invoiceId": "65293be2758ee2361b4137da",
"fullAddress": " Land and Building No. Ground Floor, Plot No. 36, Rani Pura, Daulat
Ganj, Jawahar Marg, Indore Bhopal Road, , Behind Jhanda Chowk, Tahasil Indore,
District - Indore, Indore, 452007, State - Madhya Pradesh",
"updatedBy": "60016f965256c07aec8e6dd6",
"addressForMap": "",
"caseReferredBy": "6421248a695fbc66ee1a7ce3",
"contactPersonName": "Nasir Husan S/o Abdul Sattar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8605149765"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			