

```
{
  "typeOfReport": {
    "value": "NPA_Case(With_Depreciation)",
    "label": "NPA Case(With Depreciation)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6415b3cc96b58848585e4e4e"
    },
    "type": "CREDITOFFICER",
    "_id": "6415b3cc96b58848585e4e50",
    "firstName": "testnashik",
    "lastName": "testnashik",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": ""
  }
}
```

```
"expectedFees": null,
"quotedAmount": "3540"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6415b3cc96b58848585e4e4e",
  "name": "Nashik City Branch",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "jagdish.bhatt@vastukala.org",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Navondar Sankul, 1366, M-1 Racca Colony, Sharanpur Road\nNashik –
422 002, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_ &_ Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63f9ed37ce84bf289ba991ac",
  "role": "FRONTDESK",
  "firstName": "Rushikesh",
  "email": "rushipingle2201@gmail.com",
  "lastName": "Pingle",
  "mobileNo": "8788210361",
  "shortName": "RUP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "636a29b64d42487767af43ea",
  "role": "NASHIK (LEAD + VISIT + RATE)",
  "firstName": "Sachin",
  "email": "sachinraundal9021@gmail.com",
  "lastName": "Raundal",
  "mobileNo": "9021337843",
  "designation": "Site Engg",
  "shortName": "Sachin",
  "workWithDocumentMaker": "62724142afd7d55eddede405",
  "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.988904125584554",
  "longitude": "73.72370858100838"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Satpur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
```

```
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "05",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
}
```

```
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Satpur Colony Bhaji Market",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": " Satpur Colony, OfiTrimbak Road",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Rohit Hospital",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
```

```
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "487/B/1/Prt",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
```

```
"status": false,
"name": "Khata No",
"key": "khataNo",
"value": "",
"label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422007",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
```



```
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
```

```
    "label": "External Development & Final Finishing",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": false
  },
  "workCompleted": {
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
```

```
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
```

```
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "652e1a19316e1359cebe378a",
"ownerName": "Milind Jadhav",
"ownerPhoneNo": "9021337843",
"fullAddress": " NPA Case(With Depreciation) No. Basement Floor, Near Rohit
Hospital, Plot No. 05, New/Current Survey No. 487/B/1/Prt, Satpur Colony Bhaji
Market, Satpur Colony, OfiTrimbak Road, Village - Satpur, Taluka - Nashik, District -
Nashik, Nashik, 422007",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1697520011002_milind_jagnnath_Jadhav_union_Bank_.pdf",
    "path": "cases/652e1a19316e1359cebe378a/
document_1697520011002_milind_jagnnath_Jadhav_union_Bank_.pdf",
    "id": "110415",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Oct 17 2023 10:51:49 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004441",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "391377",
```

```
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 17 2023 10:52:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Milind Jadhav",
    "phone": "9021337843",
    "ownershipShare": "",
    "email": "",
    "id": "914213"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59cc",
    "name":
"externalImg_1697521606246_WhatsApp_Image_20231016_at_40652_PM.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externalImg_1697521606246_WhatsApp_Image_20231016_at_40652_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59cd",
    "name":
"externalImg_1697521606356_WhatsApp_Image_20231016_at_40653_PM.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externalImg_1697521606356_WhatsApp_Image_20231016_at_40653_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```



```
    "_id": "652e1fc7316e1359cebe59ce",
    "name":
"externallmg_1697521606442_WhatsApp_Image_20231016_at_40654_PM_1.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606442_WhatsApp_Image_20231016_at_40654_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59cf",
    "name":
"externallmg_1697521606482_WhatsApp_Image_20231016_at_40654_PM_2.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606482_WhatsApp_Image_20231016_at_40654_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59d0",
    "name":
"externallmg_1697521606551_WhatsApp_Image_20231016_at_40654_PM.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606551_WhatsApp_Image_20231016_at_40654_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59d1",
    "name":
"externallmg_1697521606605_WhatsApp_Image_20231016_at_40655_PM_1.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606605_WhatsApp_Image_20231016_at_40655_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59d2",
    "name":
"externallmg_1697521606647_WhatsApp_Image_20231016_at_40655_PM_2.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606647_WhatsApp_Image_20231016_at_40655_PM_2.jpeg",
    "orientation": "portrait"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652e1fc7316e1359cebe59d3",
  "name":
"externallmg_1697521606717_WhatsApp_Image_20231016_at_40655_PM_3.jpeg",
  "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606717_WhatsApp_Image_20231016_at_40655_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652e1fc7316e1359cebe59d4",
  "name":
"externallmg_1697521606774_WhatsApp_Image_20231016_at_40655_PM.jpeg",
  "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606774_WhatsApp_Image_20231016_at_40655_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652e1fc7316e1359cebe59d5",
  "name":
"externallmg_1697521606815_WhatsApp_Image_20231016_at_40656_PM_1.jpeg",
  "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606815_WhatsApp_Image_20231016_at_40656_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652e1fc7316e1359cebe59d6",
  "name":
"externallmg_1697521606871_WhatsApp_Image_20231016_at_40656_PM_2.jpeg",
  "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606871_WhatsApp_Image_20231016_at_40656_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652e1fc7316e1359cebe59d7",
  "name":
"externallmg_1697521606924_WhatsApp_Image_20231016_at_40656_PM.jpeg",
```

```
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521606924_WhatsApp_Image_20231016_at_40656_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59d8",
    "name":
"externallmg_1697521607020_WhatsApp_Image_20231016_at_40657_PM_1.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521607020_WhatsApp_Image_20231016_at_40657_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59d9",
    "name":
"externallmg_1697521607060_WhatsApp_Image_20231016_at_40657_PM_2.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521607060_WhatsApp_Image_20231016_at_40657_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59da",
    "name":
"externallmg_1697521607163_WhatsApp_Image_20231016_at_40657_PM.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521607163_WhatsApp_Image_20231016_at_40657_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59db",
    "name":
"externallmg_1697521607241_WhatsApp_Image_20231016_at_40658_PM_1.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externallmg_1697521607241_WhatsApp_Image_20231016_at_40658_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "652e1fc7316e1359cebe59dc",
    "name":
"externalImg_1697521607336_WhatsApp_Image_20231016_at_40658_PM_2.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externalImg_1697521607336_WhatsApp_Image_20231016_at_40658_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59dd",
    "name":
"externalImg_1697521607429_WhatsApp_Image_20231016_at_40658_PM.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externalImg_1697521607429_WhatsApp_Image_20231016_at_40658_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652e1fc7316e1359cebe59de",
    "name":
"externalImg_1697521607513_WhatsApp_Image_20231016_at_40908_PM.jpeg",
    "path": "cases/652e1a19316e1359cebe378a/
externalImg_1697521607513_WhatsApp_Image_20231016_at_40908_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-17T05:22:33.220Z",
"updatedAt": "2023-10-17T05:46:47.689Z",
"__v": 0,
"invoiceId": "652e1a19316e1359cebe37c0",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Milind Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
```

"siteVisitContactNo": "9021337843"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other
Composition :
