

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63620dece363ef22db2f8b67"
    },
    "type": "CREDITOFFICER",
    "_id": "63620dece363ef22db2f8b69",
    "firstName": "Priyanka ",
    "lastName": "Rane",
    "mobileNo": "",
    "email": "sms.mmer1@bankofbaroda.com",
    "workMobileNo": "9833634755"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63620dece363ef22db2f8b67",
  "name": "Bhandup West Branch",
  "branchCode": "1234",
  "mobileNo": "02225960751\t",
  "alternateMobileNo": "",
  "email": "sms.mmer@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Regional Office (MMER), 1st Floor, A-Wing, Devdarshan Building,
Station Road, Bhandup (West), Mumbai - 400 078, State - Maharashtra, Country -
India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Industrial",
  "label": "Industrial"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62720e52afd7d55eddedc887",
  "role": "PICKUPPERSON",
  "firstName": "Harshad",
  "email": "harshad@vastukala.org",
  "lastName": "Panchal",
  "mobileNo": "9029575553",
  "shortName": "HP",
  "workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": "",
"checker": "",
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
}
```

```
"location": {
  "latitude": "19.195616955561036",
  "longitude": "73.09586403951916"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-10-23T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-23T04:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-23T04:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Sagaon",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "W-92, ",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
```

```
"name": "Landmark",
"key": "landmark",
"value": "MIDC, Phase II, Dombivli Industrial Area",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```

```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```



```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 203",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
},
"locationMapImg": []
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
}
```

```
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "653399c9619c14402da95a05",
"ownerName": "Mrs. Vinita Rajeev Joshi, Mr. Rajeev Dwaipayam Joshi & Mr. Chetan Ashok Gaonkar",
"ownerPhoneNo": "9930003873",
"fullAddress": "Industrial Land and Building No. Ground Floor, MIDC, Phase II, Dombivli Industrial Area, Plot No. W-92, , Village - Sagaon, Taluka - Kalyan, District - Thane, PIN Code - 421 203, State - Maharashtra, India",
```

```
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2e9",
      "label": "Deed Of Assignment"
    },
    "inputs": {
      "documentDate": "30/06/2022",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "M/s. JSP Metal Works Pvt. Ltd.",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mrs. Vinita Rajeev Joshi, Mr. Rajeev Dwaipayan Joshi & Mr. Chetan Ashok Gaonkar"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1697880430081_W92_deed_agrrement_3.pdf",
    "path": "cases/653399c9619c14402da95a05/document_1697880430081_W92_deed_agrrement_3.pdf",
    "id": "699104",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Sat Oct 21 2023 14:57:58 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004571",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "102264",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 21 2023 14:58:41 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Vinita Rajeev Joshi, Mr. Rajeev Dwaipayan Joshi & Mr. Chetan Ashok Gaonkar",
    "phone": "9930003873",
```



```
    "ownershipShare": "",
    "email": "",
    "id": "964060"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92f4",
    "name":
"externalImg_1698041985614_WhatsApp_Image_20231023_at_114409_AM_19.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externalImg_1698041985614_WhatsApp_Image_20231023_at_114409_AM_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92f5",
    "name":
"externalImg_1698041985617_WhatsApp_Image_20231023_at_114409_AM_20.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externalImg_1698041985617_WhatsApp_Image_20231023_at_114409_AM_20.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92f6",
    "name":
"externalImg_1698041985619_WhatsApp_Image_20231023_at_114407_AM.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externalImg_1698041985619_WhatsApp_Image_20231023_at_114407_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65361081619c14402daa92f7",
    "name":
"externallmg_1698041985625_WhatsApp_Image_20231023_at_114408_AM_1.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698041985625_WhatsApp_Image_20231023_at_114408_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92f8",
    "name":
"externallmg_1698041985629_WhatsApp_Image_20231023_at_114408_AM_2.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698041985629_WhatsApp_Image_20231023_at_114408_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92f9",
    "name":
"externallmg_1698041985634_WhatsApp_Image_20231023_at_114408_AM_3.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698041985634_WhatsApp_Image_20231023_at_114408_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92fa",
    "name":
"externallmg_1698041985637_WhatsApp_Image_20231023_at_114408_AM_4.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698041985637_WhatsApp_Image_20231023_at_114408_AM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92fb",
    "name":
"externallmg_1698041985640_WhatsApp_Image_20231023_at_114408_AM_5.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698041985640_WhatsApp_Image_20231023_at_114408_AM_5.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92fc",
    "name":
"externallmg_1698041985644_WhatsApp_Image_20231023_at_114408_AM_6.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698041985644_WhatsApp_Image_20231023_at_114408_AM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361081619c14402daa92fd",
    "name":
"externallmg_1698041985650_WhatsApp_Image_20231023_at_114408_AM_7.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698041985650_WhatsApp_Image_20231023_at_114408_AM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361092619c14402daa935e",
    "name":
"externallmg_1698042002339_WhatsApp_Image_20231023_at_114408_AM.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002339_WhatsApp_Image_20231023_at_114408_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361092619c14402daa935f",
    "name":
"externallmg_1698042002342_WhatsApp_Image_20231023_at_114409_AM_1.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002342_WhatsApp_Image_20231023_at_114409_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361092619c14402daa9360",
```

```
    "name":  
    "externallmg_1698042002345_WhatsApp_Image_20231023_at_114409_AM_2.jpeg",  
    "path": "cases/653399c9619c14402da95a05/  
externallmg_1698042002345_WhatsApp_Image_20231023_at_114409_AM_2.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65361092619c14402daa9361",  
    "name":  
    "externallmg_1698042002350_WhatsApp_Image_20231023_at_114409_AM_3.jpeg",  
    "path": "cases/653399c9619c14402da95a05/  
externallmg_1698042002350_WhatsApp_Image_20231023_at_114409_AM_3.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65361092619c14402daa9362",  
    "name":  
    "externallmg_1698042002352_WhatsApp_Image_20231023_at_114409_AM_4.jpeg",  
    "path": "cases/653399c9619c14402da95a05/  
externallmg_1698042002352_WhatsApp_Image_20231023_at_114409_AM_4.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65361092619c14402daa9363",  
    "name":  
    "externallmg_1698042002367_WhatsApp_Image_20231023_at_114409_AM_5.jpeg",  
    "path": "cases/653399c9619c14402da95a05/  
externallmg_1698042002367_WhatsApp_Image_20231023_at_114409_AM_5.jpeg",  
    "orientation": "landscape"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "65361092619c14402daa9364",  
    "name":  
    "externallmg_1698042002371_WhatsApp_Image_20231023_at_114409_AM_6.jpeg",  
    "path": "cases/653399c9619c14402da95a05/  
externallmg_1698042002371_WhatsApp_Image_20231023_at_114409_AM_6.jpeg",  
    "orientation": "landscape"  
  },  
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa9365",
  "name":
"externallmg_1698042002375_WhatsApp_Image_20231023_at_114409_AM_7.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002375_WhatsApp_Image_20231023_at_114409_AM_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa9366",
  "name":
"externallmg_1698042002380_WhatsApp_Image_20231023_at_114409_AM_8.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002380_WhatsApp_Image_20231023_at_114409_AM_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa9367",
  "name":
"externallmg_1698042002384_WhatsApp_Image_20231023_at_114409_AM_9.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002384_WhatsApp_Image_20231023_at_114409_AM_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa9368",
  "name":
"externallmg_1698042002389_WhatsApp_Image_20231023_at_114409_AM_10.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002389_WhatsApp_Image_20231023_at_114409_AM_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa9369",
  "name":
"externallmg_1698042002393_WhatsApp_Image_20231023_at_114409_AM_11.jpeg",
```

```
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002393_WhatsApp_Image_20231023_at_114409_AM_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361092619c14402daa936a",
    "name":
"externallmg_1698042002397_WhatsApp_Image_20231023_at_114409_AM_12.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002397_WhatsApp_Image_20231023_at_114409_AM_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361092619c14402daa936b",
    "name":
"externallmg_1698042002406_WhatsApp_Image_20231023_at_114409_AM_13.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002406_WhatsApp_Image_20231023_at_114409_AM_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361092619c14402daa936c",
    "name":
"externallmg_1698042002411_WhatsApp_Image_20231023_at_114409_AM_14.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002411_WhatsApp_Image_20231023_at_114409_AM_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65361092619c14402daa936d",
    "name":
"externallmg_1698042002413_WhatsApp_Image_20231023_at_114409_AM_15.jpeg",
    "path": "cases/653399c9619c14402da95a05/
externallmg_1698042002413_WhatsApp_Image_20231023_at_114409_AM_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65361092619c14402daa936e",
  "name":
"externalImg_1698042002418_WhatsApp_Image_20231023_at_114409_AM_16.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externalImg_1698042002418_WhatsApp_Image_20231023_at_114409_AM_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa936f",
  "name":
"externalImg_1698042002424_WhatsApp_Image_20231023_at_114409_AM_17.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externalImg_1698042002424_WhatsApp_Image_20231023_at_114409_AM_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa9370",
  "name":
"externalImg_1698042002428_WhatsApp_Image_20231023_at_114409_AM_18.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externalImg_1698042002428_WhatsApp_Image_20231023_at_114409_AM_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65361092619c14402daa9371",
  "name":
"externalImg_1698042002431_WhatsApp_Image_20231023_at_114409_AM.jpeg",
  "path": "cases/653399c9619c14402da95a05/
externalImg_1698042002431_WhatsApp_Image_20231023_at_114409_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-21T09:28:41.568Z",
"updatedAt": "2023-10-23T06:20:02.554Z",
"__v": 0,
"invoiceId": "653399c9619c14402da95a10",
```

```
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "62720e52afd7d55eddedc887",
"contactPersonName": "Mrs. Vinita Rajeev Joshi, Mr. Rajeev Dwaipayan Joshi & Mr.
Chetan Ashok Gaonkar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9930003873"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			