

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "masterTypeOfPurpose": {
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002",
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8f2"
    },
    "type": "CREDITOFFICER",
    "_id": "6538a4a22a1baf5f34c1fd16",
    "firstName": "Anand Kumar",
    "lastName": "Trehan",
    "mobileNo": "",
    "workMobileNo": "7830030038",
    "email": "sme.mmcr@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8500000",
    "discussWithPerson": "Anand Kumar",
  }
}
```

```
"expectedFees": 4250,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8f2",
  "branchCode": "000009",
  "type": "BRANCH",
  "name": "MMCR FORT",
  "email": "sme.mmcr@bankofbaroda.com",
  "mobileNo": "22-22619603 ",
  "alternateMobileNo": "",
  "address": "3, Walchand Hirachand Marg,Ground Floor, Ballard Pier, Mumbai - 400
001, State - Maharashtra, Country - India.\n",
  "ledgerName": "",
  "fax": "22-22611259",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
```

```
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
    "email": "shantilal@vastukala.org",
    "lastName": "Patel",
    "mobileNo": "9969039853",
    "shortName": "SHP",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f949ce45132d6a6bddbcc3",
    "role": "SITEENGINEER",
    "firstName": "Tushar ",
    "email": "tusharbhuwad90@gmail.com",
    "lastName": "Bhuwad",
    "mobileNo": "9082053889",
    "designation": "",
    "shortName": "TSB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "62fe044a48a26047e6552796",
```

```

"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": " Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]

```

```
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.104555325234518",
  "longitude": "72.84564374408723"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84564374408723,
    19.104555325234518
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-10-28T05:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-28T05:30:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
},
```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vile Parle",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "8",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vile Parle (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vireshwar Vihar Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tejpal Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "570, 570/1 & 2, 571, 571/1 To 8",
```



```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "801",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 057",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in developed area ",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
}
```

```
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
```

```
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
status": true,
```



```
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "6538cc4c2a1baf5f34c2a215",
"ownerName": "Rangila V Shah",
"ownerPhoneNo": "9019780241",
"appAddress": "801 B vireshwar vihar chs Ltd\nTejpal road vileprle E\n\nparty name
Smt Rangila v shah",
"remark": "NPA Account\n\ncontact number 9019780241\n\ncontact Documents visit
time ",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1698472634065_Vireshwar_Vihar_801B.pdf",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
document_1698472634065_Vireshwar_Vihar_801B.pdf",
    "id": "449229",
    "uploadedBy": "6006d4ce5080a310ac1fd2",
    "createdAt": "Sat Oct 28 2023 11:27:16 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004626",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "928552",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 25 2023 13:35:32 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Rangila V Shah",
    "phone": "9019780241",
    "ownershipShare": "",
    "email": "",
    "id": "709723"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c83d6fbd83553d5549d",
    "name": "externalimg_r_1698643075102_IMG20231028134908.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643075102_IMG20231028134908.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c83d6fbd83553d5549e",
    "name": "externalimg_r_1698643075084_IMG20231028134745.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643075084_IMG20231028134745.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c83d6fbd83553d5549f",
    "name": "externalimg_r_1698643075098_IMG20231028134806.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643075098_IMG20231028134806.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c83d6fbd83553d554a0",
    "name": "externalimg_r_1698643075087_IMG20231028134752.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643075087_IMG20231028134752.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "653f3c83d6fbd83553d554a1",
    "name": "externalimg_r_1698643075117_IMG20231028134916.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643075117_IMG20231028134916.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c83d6fbd83553d554a2",
    "name": "externalimg_r_1698643075108_IMG20231028134913.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643075108_IMG20231028134913.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c83d6fbd83553d554a3",
    "name": "externalimg_r_1698643075112_IMG20231028134914.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643075112_IMG20231028134914.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c93d6fbd83553d555be",
    "name": "externalimg_r_1698643090262_IMG20231028135018.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643090262_IMG20231028135018.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c93d6fbd83553d555bf",
    "name": "externalimg_r_1698643089298_IMG20231028135015.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643089298_IMG20231028135015.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c93d6fbd83553d555c0",
```

```
    "name": "externalimg_r_1698643090747_IMG20231028135820.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643090747_IMG20231028135820.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c93d6fbd83553d555c1",
    "name": "externalimg_r_1698643090508_IMG20231028135812.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643090508_IMG20231028135812.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c93d6fbd83553d555c2",
    "name": "externalimg_r_1698643090811_IMG20231028135821.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643090811_IMG20231028135821.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c93d6fbd83553d555c3",
    "name": "externalimg_r_1698643091035_IMG20231028135825.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643091035_IMG20231028135825.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c93d6fbd83553d555c4",
    "name": "externalimg_r_1698643091038_IMG20231028135835.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643091038_IMG20231028135835.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c9fd6fbd83553d55680",
    "name": "externalimg_r_1698643102397_IMG20231028135900.jpg",
```

```
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643102397_IMG20231028135900.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c9fd6fbd83553d55681",
    "name": "externallmg_r_1698643102394_IMG20231028135843.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643102394_IMG20231028135843.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c9fd6fbd83553d55682",
    "name": "externallmg_r_1698643102390_IMG20231028135842.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643102390_IMG20231028135842.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c9fd6fbd83553d55683",
    "name": "externallmg_r_1698643102419_IMG20231028135903.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643102419_IMG20231028135903.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c9fd6fbd83553d55684",
    "name": "externallmg_r_1698643102424_IMG20231028135906.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643102424_IMG20231028135906.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3c9fd6fbd83553d55685",
    "name": "externallmg_r_1698643102427_IMG20231028135913.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643102427_IMG20231028135913.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3c9fd6fbd83553d55686",
  "name": "externallmg_r_1698643102430_IMG20231028140558.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643102430_IMG20231028140558.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cccd6fbd83553d55825",
  "name": "externallmg_r_1698643148135_IMG20231028140602.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643148135_IMG20231028140602.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cccd6fbd83553d55826",
  "name": "externallmg_r_1698643148145_IMG20231028140736.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643148145_IMG20231028140736.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cccd6fbd83553d55827",
  "name": "externallmg_r_1698643148161_IMG20231028140738.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643148161_IMG20231028140738.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cccd6fbd83553d55828",
  "name": "externallmg_r_1698643148132_IMG20231028140601.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643148132_IMG20231028140601.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3cccd6fbd83553d55829",
    "name": "externallmg_r_1698643148168_IMG20231028140953.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643148168_IMG20231028140953.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3cccd6fbd83553d5582a",
    "name": "externallmg_r_1698643148164_IMG20231028140811.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643148164_IMG20231028140811.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3cccd6fbd83553d5582b",
    "name": "externallmg_r_1698643148184_IMG20231028141010.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643148184_IMG20231028141010.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3cdcd6fbd83553d5593b",
    "name": "externallmg_1698643163427_Screenshot_2023102813484317_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/externallmg_1698643163427_Screensh
ot_2023102813484317_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f3cdcd6fbd83553d5593c",
    "name": "externallmg_r_1698643163241_IMG20231028141014.jpg",
    "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643163241_IMG20231028141014.jpg",
    "orientation": "landscape"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d5593d",
  "name": "externalimg_r_1698643163258_IMG20231028141054.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643163258_IMG20231028141054.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d5593e",
  "name": "externalimg_r_1698643163243_IMG20231028141027.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643163243_IMG20231028141027.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d5593f",
  "name": "externalimg_r_1698643163265_IMG20231028141055.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643163265_IMG20231028141055.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d55940",
  "name": "externalimg_r_1698643163268_IMG20231028141056.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643163268_IMG20231028141056.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d55941",
  "name": "externalimg_r_1698643163278_IMG20231028141118.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externalimg_r_1698643163278_IMG20231028141118.jpg",
  "orientation": "portrait"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d55942",
  "name": "externallmg_r_1698643163282_IMG20231028141119.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643163282_IMG20231028141119.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d55943",
  "name": "externallmg_r_1698643163285_IMG20231028141121.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643163285_IMG20231028141121.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d55944",
  "name": "externallmg_r_1698643163290_IMG20231028141207.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643163290_IMG20231028141207.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d55945",
  "name": "externallmg_r_1698643163374_IMG20231030102910.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643163374_IMG20231030102910.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f3cdcd6fbd83553d55946",
  "name": "externallmg_r_1698643163294_IMG20231030102855.jpg",
  "path": "cases/6538cc4c2a1baf5f34c2a215/
externallmg_r_1698643163294_IMG20231030102855.jpg",
  "orientation": "portrait"
}
],
```

```

"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-25T08:05:32.030Z",
"updatedAt": "2023-10-30T05:19:31.125Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 801, 8th Floor, Wing - B, Vireshwar Vihar Co-Op.
Hsg. Soc. Ltd., Tejpal Road, Village - Vile Parle, Taluka - Andheri , District - Mumbai
Suburban, Vile Parle (East), PIN - 400 057, State - Maharashtra, Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Rangila V Shah",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9019780241"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			