

```
{
  "typeOfReport": {
    "value": "Residential_Bungalow_",
    "label": "Residential Bungalow "
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "645f0853ee6a9735bf7688e8"
    },
    "type": "CREDITOFFICER",
    "_id": "645f0853ee6a9735bf7688ea",
    "firstName": "Rajeevkumar ",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "9827114321",
    "email": "indiranagar.pune@bankofindia.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "2950"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "645f0853ee6a9735bf7688e8",
  "name": "Indira Nagar Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903\t",
  "alternateMobileNo": "",
  "email": "indiranagar.pune@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Bungalow No 23, Shree Samartha Kripa, Gurukrinear Rathachakara
Chowk,\nIndira Nagar, Nashik-422 009, State - Maharashtra,Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fc92f7ce84bf289baa53f9",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": ""
```

```
    "shortName": "Chintamani",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.992638829200008",
  "longitude": "73.76216541675711"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nashik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Nashik",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "537",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "Forest Colony, Parijat Nagar",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Mahatma Nagar Untwadi Road, ",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opposite Ganpati Mandir",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "746/1/8",
  "label": true
},
"hisNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Residential West Side Land and Bungalow on Plot No.65",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422005",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
```

```
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
```

```
"title": "Potential value, if any",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
```

```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6538d6202a1baf5f34c2c6c4",
"ownerName": "Hiren Chaudhari",
"ownerPhoneNo": "9604154626",
"fullAddress": " Residential Bungalow No. Residential West Side Land and Bungalow
on Plot No.65, Basement Floor, Opposite Ganpati Mandir, Plot No. 537, New/Current
Survey No. 746/1/8, Forest Colony, Parijat Nagar, Mahatma Nagar Untwadi Road, ,
Village - Nashik, Taluka - Nashik, District - Nashik, Nashik, 422005",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1698223482157_7_12.pdf",
    "path": "cases/6538d6202a1baf5f34c2c6c4/document_1698223482157_7_12.pdf",
    "id": "340943",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1698223526557_Agreement.pdf",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
document_1698223526557_Agreement.pdf",
    "id": "288519",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
  },
}
```



```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1698223535924_CC__OC.pdf",
"path": "cases/6538d6202a1baf5f34c2c6c4/
document_1698223535924_CC__OC.pdf",
"id": "974264",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698223541984_Chauthari_layout_.pdf",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
document_1698223541984_Chauthari_layout_.pdf",
  "id": "134260",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698223548688_chauthari_Plan.pdf",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
document_1698223548688_chauthari_Plan.pdf",
  "id": "594892",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698223571074_Death_Cert.pdf",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
document_1698223571074_Death_Cert.pdf",
```

```
"id": "831310",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698223577059_docs.pdf",
  "path": "cases/6538d6202a1baf5f34c2c6c4/document_1698223577059_docs.pdf",
  "id": "676192",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698223584032_Docs.pdf",
  "path": "cases/6538d6202a1baf5f34c2c6c4/document_1698223584032_Docs.pdf",
  "id": "807048",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1698223591426_House_Tax.pdf",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
document_1698223591426_House_Tax.pdf",
  "id": "694446",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Wed Oct 25 2023 14:16:40 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004631",
```

```
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "161445",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Oct 25 2023 14:17:28 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Hiren Chaudhari",
    "phone": "9604154626",
    "ownershipShare": "",
    "email": "",
    "id": "960695"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb0e",
    "name":
"externallmg_1698223733105_WhatsApp_Image_20230626_at_10049_PM_1.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733105_WhatsApp_Image_20230626_at_10049_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb0f",
    "name":
"externallmg_1698223733187_WhatsApp_Image_20230626_at_10049_PM.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733187_WhatsApp_Image_20230626_at_10049_PM.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6538d6772a1baf5f34c2cb10",
      "name":
"externallmg_1698223733240_WhatsApp_Image_20230626_at_10050_PM_1.jpeg",
      "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733240_WhatsApp_Image_20230626_at_10050_PM_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6538d6772a1baf5f34c2cb11",
      "name":
"externallmg_1698223733323_WhatsApp_Image_20230626_at_10050_PM_2.jpeg",
      "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733323_WhatsApp_Image_20230626_at_10050_PM_2.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6538d6772a1baf5f34c2cb12",
      "name":
"externallmg_1698223733379_WhatsApp_Image_20230626_at_10050_PM.jpeg",
      "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733379_WhatsApp_Image_20230626_at_10050_PM.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6538d6772a1baf5f34c2cb13",
      "name":
"externallmg_1698223733420_WhatsApp_Image_20230626_at_10051_PM_1.jpeg",
      "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733420_WhatsApp_Image_20230626_at_10051_PM_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "6538d6772a1baf5f34c2cb14",
      "name":
"externallmg_1698223733637_WhatsApp_Image_20230626_at_10051_PM.jpeg",
```

```
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733637_WhatsApp_Image_20230626_at_10051_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb15",
    "name":
"externallmg_1698223733761_WhatsApp_Image_20230626_at_10052_PM_1.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733761_WhatsApp_Image_20230626_at_10052_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb16",
    "name":
"externallmg_1698223733926_WhatsApp_Image_20230626_at_10052_PM_2.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223733926_WhatsApp_Image_20230626_at_10052_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb17",
    "name":
"externallmg_1698223734098_WhatsApp_Image_20230626_at_10052_PM.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734098_WhatsApp_Image_20230626_at_10052_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb18",
    "name":
"externallmg_1698223734257_WhatsApp_Image_20230626_at_10053_PM_1.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734257_WhatsApp_Image_20230626_at_10053_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6538d6772a1baf5f34c2cb19",
  "name":
"externallmg_1698223734333_WhatsApp_Image_20230626_at_10053_PM.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734333_WhatsApp_Image_20230626_at_10053_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6772a1baf5f34c2cb1a",
  "name":
"externallmg_1698223734435_WhatsApp_Image_20230626_at_10054_PM_1.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734435_WhatsApp_Image_20230626_at_10054_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6772a1baf5f34c2cb1b",
  "name":
"externallmg_1698223734554_WhatsApp_Image_20230626_at_10054_PM.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734554_WhatsApp_Image_20230626_at_10054_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6772a1baf5f34c2cb1c",
  "name":
"externallmg_1698223734764_WhatsApp_Image_20230626_at_10055_PM_1.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734764_WhatsApp_Image_20230626_at_10055_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6772a1baf5f34c2cb1d",
  "name":
"externallmg_1698223734848_WhatsApp_Image_20230626_at_10055_PM_2.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734848_WhatsApp_Image_20230626_at_10055_PM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb1e",
    "name":
"externallmg_1698223734932_WhatsApp_Image_20230626_at_10055_PM.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223734932_WhatsApp_Image_20230626_at_10055_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb1f",
    "name":
"externallmg_1698223735049_WhatsApp_Image_20230626_at_10056_PM.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223735049_WhatsApp_Image_20230626_at_10056_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb20",
    "name":
"externallmg_1698223735135_WhatsApp_Image_20230626_at_10057_PM_1.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223735135_WhatsApp_Image_20230626_at_10057_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6772a1baf5f34c2cb21",
    "name":
"externallmg_1698223735324_WhatsApp_Image_20230626_at_10057_PM.jpeg",
    "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223735324_WhatsApp_Image_20230626_at_10057_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6538d6832a1baf5f34c2cb9b",
```

```
    "name":  
    "externallmg_1698223746201_WhatsApp_Image_20230626_at_10058_PM_1.jpeg",  
    "path": "cases/6538d6202a1baf5f34c2c6c4/  
externallmg_1698223746201_WhatsApp_Image_20230626_at_10058_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6538d6832a1baf5f34c2cb9c",  
    "name":  
    "externallmg_1698223746244_WhatsApp_Image_20230626_at_10058_PM.jpeg",  
    "path": "cases/6538d6202a1baf5f34c2c6c4/  
externallmg_1698223746244_WhatsApp_Image_20230626_at_10058_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6538d6832a1baf5f34c2cb9d",  
    "name":  
    "externallmg_1698223746488_WhatsApp_Image_20230626_at_10059_PM_1.jpeg",  
    "path": "cases/6538d6202a1baf5f34c2c6c4/  
externallmg_1698223746488_WhatsApp_Image_20230626_at_10059_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6538d6832a1baf5f34c2cb9e",  
    "name":  
    "externallmg_1698223746526_WhatsApp_Image_20230626_at_10059_PM.jpeg",  
    "path": "cases/6538d6202a1baf5f34c2c6c4/  
externallmg_1698223746526_WhatsApp_Image_20230626_at_10059_PM.jpeg",  
    "orientation": "portrait"  
  },  
  {  
    "type": "EXTERNAL_IMAGES",  
    "status": false,  
    "_id": "6538d6832a1baf5f34c2cb9f",  
    "name":  
    "externallmg_1698223746611_WhatsApp_Image_20230626_at_10100_PM_1.jpeg",  
    "path": "cases/6538d6202a1baf5f34c2c6c4/  
externallmg_1698223746611_WhatsApp_Image_20230626_at_10100_PM_1.jpeg",  
    "orientation": "portrait"  
  },  
  }
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6832a1baf5f34c2cba0",
  "name":
"externallmg_1698223746665_WhatsApp_Image_20230626_at_10100_PM_2.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223746665_WhatsApp_Image_20230626_at_10100_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6832a1baf5f34c2cba1",
  "name":
"externallmg_1698223746720_WhatsApp_Image_20230626_at_10100_PM.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223746720_WhatsApp_Image_20230626_at_10100_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6832a1baf5f34c2cba2",
  "name":
"externallmg_1698223746776_WhatsApp_Image_20230626_at_10101_PM_1.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223746776_WhatsApp_Image_20230626_at_10101_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6538d6832a1baf5f34c2cba3",
  "name":
"externallmg_1698223746900_WhatsApp_Image_20230626_at_10101_PM.jpeg",
  "path": "cases/6538d6202a1baf5f34c2c6c4/
externallmg_1698223746900_WhatsApp_Image_20230626_at_10101_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-25T08:47:28.660Z",
"updatedAt": "2023-10-25T08:49:07.236Z",
```

"__v": 0,
"invoiceId": "6538d6222a1baf5f34c2c6ea",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a1ad14d42487767af3f91",
"contactPersonName": "Hiren Chaudhari",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9604154626"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			