

```
{
  "typeOfReport": {
    "label": "Gala",
    "value": "Gala"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b96f"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f66be948726cc141b47",
    "email": "swapnil.deshmukh@cosmosbank.in",
    "firstName": "Swapnil Deshmukh",
    "mobileNo": "9923243343",
    "workMobileNo": "9923243343",
    "lastName": "Deshmukh"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3200000",
    "discussWithPerson": "Swapnil Deshmukh",
    "expectedFees": 1600,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b96f",
  "branchCode": "0000010",
  "type": "BRANCH",
  "name": "Malad (West) Branch",
  "email": "pooja.mithbhavkar@cosmosbank.in",
  "mobileNo": "02228446591",
  "alternateMobileNo": "",
  "address": "Shop No 6,7,8,Kewal Towers, B.J.Patel Road,Malad (West), \r\nMumbai,
State - Maharashtra, Country – India.\r\n",
  "ledgerName": "COSMOS BANK- MALAD",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Industrial",
  "label": "Industrial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "6401b61f0e28255fb44e636a",
    "role": "SITEENGINEER",
    "firstName": "Sanket",
    "email": "ksanket7414@yahoo.com",
    "lastName": "Karalkar",
    "mobileNo": "8080582858",
    "designation": "",
    "shortName": "SAK",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": "",
  "maker": "",
  "checker": "",
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ]
    }
  ],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
```

```
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.385649651299307",
  "longitude": "72.83677507975966"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83677507975966,
    19.385649651299307
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-04T07:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
```

```
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Navghar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
```

```
"status": true,
"name": "City",
"key": "city",
"value": "Vasai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreepal Industrial Estate CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
```

```
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
```

```
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Gala No 106",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
}
```



```
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
```

```
"monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
```

```
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```

```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "6545e32699ec7e6193df5b98",
"ownerName": "Reshma Ramesh Dhuri ",
"ownerPhoneNo": "9619520507",
"appAddress": "Gala No A-106 1 St floor Bldg Shreepal Industrial Estate Co-operative
Soc Ltd Village -Navghar Tal Vasai ",
"remark": "Old Porpty hey Valution report Madhe Remake Chalega bank la bldg Plan
Occupation Certificate NB nahi ahe )",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6545e32699ec7e6193df5b98/
document_1699078668531_Reshma_R__Dhuri__Gala_no_106_Vasai.pdf",
    "fileName":
"document_1699078668531_Reshma_R__Dhuri__Gala_no_106_Vasai.pdf",
    "displayStatus": false,
    "id": "988583",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Sat Nov 04 2023 11:51:33 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "path": "cases/6545e32699ec7e6193df5b98/
document_1699078707800_Other_documents.pdf",
    "fileName": "document_1699078707800_Other_documents.pdf",
    "displayStatus": false,
    "id": "888035",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Sat Nov 04 2023 11:51:33 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
```



```
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "path": "cases/6545e32699ec7e6193df5b98/
document_1699078800418_Sacrh_report_Reshma_R_Dhuri.pdf",
  "fileName": "document_1699078800418_Sacrh_report_Reshma_R_Dhuri.pdf",
  "displayStatus": false,
  "id": "614628",
  "uploadedBy": "60af6ae22ffdf65bcd65861d",
  "createdAt": "Sat Nov 04 2023 11:51:33 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004880",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "975407",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Nov 04 2023 11:52:30 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Reshma Ramesh Dhuri ",
    "phone": "9619520507",
    "ownershipShare": "",
    "email": "",
    "id": "980173"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df922b",
    "name":
"externallmg_1699081984236_WhatsApp_Image_20231102_at_74852_PM_1.jpeg",
```

```
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984236_WhatsApp_Image_20231102_at_74852_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df922c",
    "name":
"externallmg_1699081984244_WhatsApp_Image_20231102_at_74852_PM_2.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984244_WhatsApp_Image_20231102_at_74852_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df922d",
    "name":
"externallmg_1699081984250_WhatsApp_Image_20231102_at_74852_PM_3.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984250_WhatsApp_Image_20231102_at_74852_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df922e",
    "name":
"externallmg_1699081984254_WhatsApp_Image_20231102_at_74852_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984254_WhatsApp_Image_20231102_at_74852_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df922f",
    "name":
"externallmg_1699081984260_WhatsApp_Image_20231102_at_74853_PM_1.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984260_WhatsApp_Image_20231102_at_74853_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6545ef0099ec7e6193df9230",
    "name":
"externallmg_1699081984266_WhatsApp_Image_20231102_at_74853_PM_2.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984266_WhatsApp_Image_20231102_at_74853_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9231",
    "name":
"externallmg_1699081984271_WhatsApp_Image_20231102_at_74853_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984271_WhatsApp_Image_20231102_at_74853_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9232",
    "name":
"externallmg_1699081984274_WhatsApp_Image_20231102_at_74854_PM_1.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984274_WhatsApp_Image_20231102_at_74854_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9233",
    "name":
"externallmg_1699081984280_WhatsApp_Image_20231102_at_74854_PM_2.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984280_WhatsApp_Image_20231102_at_74854_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9234",
    "name":
"externallmg_1699081984283_WhatsApp_Image_20231102_at_74854_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984283_WhatsApp_Image_20231102_at_74854_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9235",
    "name":
"externallmg_1699081984286_WhatsApp_Image_20231102_at_74855_PM_1.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984286_WhatsApp_Image_20231102_at_74855_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9236",
    "name":
"externallmg_1699081984290_WhatsApp_Image_20231102_at_74855_PM_2.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984290_WhatsApp_Image_20231102_at_74855_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9237",
    "name":
"externallmg_1699081984294_WhatsApp_Image_20231102_at_74855_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984294_WhatsApp_Image_20231102_at_74855_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9238",
    "name":
"externallmg_1699081984300_WhatsApp_Image_20231102_at_74856_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984300_WhatsApp_Image_20231102_at_74856_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef0099ec7e6193df9239",
```

```
    "name":
"externallmg_1699081984304_WhatsApp_Image_20231102_at_74909_PM_1.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984304_WhatsApp_Image_20231102_at_74909_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef0099ec7e6193df923a",
  "name":
"externallmg_1699081984308_WhatsApp_Image_20231102_at_74909_PM_2.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984308_WhatsApp_Image_20231102_at_74909_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef0099ec7e6193df923b",
  "name":
"externallmg_1699081984314_WhatsApp_Image_20231102_at_74909_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984314_WhatsApp_Image_20231102_at_74909_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef0099ec7e6193df923c",
  "name":
"externallmg_1699081984316_WhatsApp_Image_20231102_at_74910_PM_1.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984316_WhatsApp_Image_20231102_at_74910_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef0099ec7e6193df923d",
  "name":
"externallmg_1699081984322_WhatsApp_Image_20231102_at_74910_PM_2.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984322_WhatsApp_Image_20231102_at_74910_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef0099ec7e6193df923e",
  "name":
"externallmg_1699081984326_WhatsApp_Image_20231102_at_74910_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699081984326_WhatsApp_Image_20231102_at_74910_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df9282",
  "name":
"externallmg_1699082004890_WhatsApp_Image_20231102_at_74911_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004890_WhatsApp_Image_20231102_at_74911_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df9283",
  "name":
"externallmg_1699082004894_WhatsApp_Image_20231102_at_74949_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004894_WhatsApp_Image_20231102_at_74949_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df9284",
  "name":
"externallmg_1699082004897_WhatsApp_Image_20231102_at_74835_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004897_WhatsApp_Image_20231102_at_74835_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df9285",
  "name":
"externallmg_1699082004902_WhatsApp_Image_20231102_at_74840_PM_1.jpeg",
```

```
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004902_WhatsApp_Image_20231102_at_74840_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9286",
    "name":
"externallmg_1699082004908_WhatsApp_Image_20231102_at_74840_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004908_WhatsApp_Image_20231102_at_74840_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9287",
    "name":
"externallmg_1699082004913_WhatsApp_Image_20231102_at_74841_PM_1.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004913_WhatsApp_Image_20231102_at_74841_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9288",
    "name":
"externallmg_1699082004916_WhatsApp_Image_20231102_at_74841_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004916_WhatsApp_Image_20231102_at_74841_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9289",
    "name":
"externallmg_1699082004921_WhatsApp_Image_20231102_at_74843_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004921_WhatsApp_Image_20231102_at_74843_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6545ef1599ec7e6193df928a",
  "name":
"externallmg_1699082004927_WhatsApp_Image_20231102_at_74844_PM_1.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004927_WhatsApp_Image_20231102_at_74844_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df928b",
  "name":
"externallmg_1699082004931_WhatsApp_Image_20231102_at_74844_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004931_WhatsApp_Image_20231102_at_74844_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df928c",
  "name":
"externallmg_1699082004934_WhatsApp_Image_20231102_at_74845_PM_1.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004934_WhatsApp_Image_20231102_at_74845_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df928d",
  "name":
"externallmg_1699082004937_WhatsApp_Image_20231102_at_74845_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004937_WhatsApp_Image_20231102_at_74845_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6545ef1599ec7e6193df928e",
  "name":
"externallmg_1699082004939_WhatsApp_Image_20231102_at_74846_PM.jpeg",
  "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004939_WhatsApp_Image_20231102_at_74846_PM.jpeg",
```



```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df928f",
    "name":
"externallmg_1699082004942_WhatsApp_Image_20231102_at_74850_PM_1.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004942_WhatsApp_Image_20231102_at_74850_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9290",
    "name":
"externallmg_1699082004946_WhatsApp_Image_20231102_at_74850_PM_2.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004946_WhatsApp_Image_20231102_at_74850_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9291",
    "name":
"externallmg_1699082004951_WhatsApp_Image_20231102_at_74850_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004951_WhatsApp_Image_20231102_at_74850_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9292",
    "name":
"externallmg_1699082004956_WhatsApp_Image_20231102_at_74851_PM_1.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externallmg_1699082004956_WhatsApp_Image_20231102_at_74851_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6545ef1599ec7e6193df9293",
```

```

    "name":
    "externalImg_1699082004958_WhatsApp_Image_20231102_at_74851_PM.jpeg",
    "path": "cases/6545e32699ec7e6193df5b98/
externalImg_1699082004958_WhatsApp_Image_20231102_at_74851_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-11-04T06:22:30.915Z",
"updatedAt": "2023-11-04T07:13:25.059Z",
"__v": 0,
"invoiceId": "6545e32999ec7e6193df5be3",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": " Gala No. Gala No 106, 1st Floor, Wing - A, Shreepal Industrial Estate
CHSL, Village - Navghar, Vasai, Vasai",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Reshma Ramesh Dhuri ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9619520507"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			